DAM INSPECTION CHECKLIST
POSSUM POINT POWER STATION
POND ABC

INSPECTION DATE: 4-14-15

WEATHER: Rain, 61°F

INSPECTED BY: D. West, K. Homza

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1056 hrs. Standing water along perimeter of road. Standing water behind sandbags and in road ruts. Standing water at base of A.L slope.
Erosion	N	N	
Low Point, B dike*			
Flow	N	N	1100 hrs. Sandbags and rip rap in place. No standing water.
Erosion	N	N	
Outfall water surface El. (top of stoplogs to water)			1104 hrs. 51" Standing water behind sandbags and concrete weir structure. water seeping into concrete weir structure. (DISCHARGE)

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): Rainfall event ongoing with current total of 0.18".

04/07/15 - 04/10/15 RAINFALL = 0.35" Low Tide 0931 High Tide 1628