

MW-1	
Chloroform	<2.0
Tetrachloroethylene	12.7
Trichloroethylene	4.6
Cadmium	<10

HS-02	
Chloroform	1.1
Tetrachloroethylene	1.0
Trichloroethylene	<2.0
Cadmium	<10

HS-03	
Chloroform	3.1
Tetrachloroethylene	2.8
Trichloroethylene	<2.0
Cadmium	18.2

HS-01	
Chloroform	<2.0
Tetrachloroethylene	24.8
Trichloroethylene	5.8
Cadmium	<10

HS-04	
Chloroform	6.0
Tetrachloroethylene	<2.0
Trichloroethylene	<2.0
Cadmium	109

HS-08	
Chloroform	<2.0
Tetrachloroethylene	<2.0
Trichloroethylene	<2.0
Cadmium	<10

HS-05	
Chloroform	2.9
Tetrachloroethylene	<2.0
Trichloroethylene	<2.0
Cadmium	<10

MW-6	
Chloroform	2.1
Tetrachloroethylene	<2.0
Trichloroethylene	<2.0
Cadmium	<10

HS-07	
Chloroform	0.73
Tetrachloroethylene	<2.0
Trichloroethylene	<2.0
Cadmium	<10

LEGEND

HS-07 SOIL AND GROUNDWATER SAMPLE LOCATION

MW-6 EXISTING MONITORING WELL LOCATION

CDPHE COLORADO DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT, REGULATION 41, BASIC STANDARDS FOR GROUNDWATER

(µg/L) MICROGRAMS PER LITER

REFERENCE STANDARD TABLE	
CONSTITUENT	CDPHE EXCEEDANCE (µg/L)
Chloroform	3.5
Tetrachloroethylene	5
Trichloroethylene	5
Cadmium	5

BOLD BLUE TEXT INDICATES EXCEEDANCE

BROWN AND CALDWELL

FIGURE 3 - GROUNDWATER SAMPLE EXCEEDANCES
CITY AND COUNTY OF DENVER
HIGH STREET STORM DRAINAGE PROJECT

ED_002396_00000213-00001