EPA Region 5 Records Ctr.
351340



photo 6
Set 1

12-7-83

Building 107
entrance door open

photo 11
Set 1

12-7-83

Hallway of building #115

photo #19
Set #1

12-7-83
inspection

View of building 115. Hallway from building #115 has chips stored in it to the bricked wall closing off hallway. The brick work can be seen about midway up the hallway and just left of the telephone pole.

photo #17
Set #1

12-7-83

Building 115
Continuation of photo #16

photo #6
Set #2

Inspection 9/26/83

Storage area inside building #107. Dark aggregate is the plastic film chip material (Taken w/flash)

D. Hopkins

photo #1
Set #2

Inspection 9/26/83

Area in front of building #107. Note standing water and pile of soil contaminated with the bluish chips as mentioned in the trip report dated 10/3/83

Dan Hopkins

photo #9
Set #2

Inspection 9/26/83

Hallway from storage area in building #107 This is the same hallway seen (from the opposite direction) in photo #10. (Taken w/flash)

D. Hopkins

photo #5
Set #2

Inspection 9/26/83

Wengrow standing next to pile of contaminated soil

D. Hopkins

photo 14
Set 1

12-7-83

large storage area
building #115 (cont.
from photo 13)

photo 13
Set 1

12-7-83

large storage area
building #115 (continuation
of view from photo #12)

photo #16
Set 1

12-7-83

Building 115 & adjoining
hallway. Entrance to
building can be made
through hole in hallway
wall (just right of
figure)

photo 12
Set 1

12-7-83

large storage area
building 115

photo 8
Set 1

12-7-83

Building #115
ends of concrete
walls indicate
bays. (20' wide x 50' deep)

photo 15
Set #1

12-7-83

Building 115

photo 10
Set 1

12-7-83

Building 115

photo #9
Set 1

12-7-83

Building 115
large storage area &
hall way (background)
~~bay~~ bay (foreground)

photo 1
set 1

12-7-83
inspection
Dixon, Il.
Green River
Industrial Park

Hallway from
building #107
Note snow on chippile near end
of hall

Dan
Hopkins

photo 2
Set 1

12-7-83

Hallway/building
#107

photo 3
set 1

12-7-83

Main storage area
and hallway/building #107

Photo 4
Set 1

12-7-83

Main storage area
building #107



photo #22 Inspection 9/26/83
Set #2

Hallway (right center of photo) connecting to building #115

D. Hopkins

photo #16 Inspection 9/26/83
Set #2

Essentially same photo as #15

photo #19 Inspection 9/26/83
Set #2

This print shows half of two different snapshots, Building #115

D. Hopkins

photo #13
Set #2

Inspection 9/26/83

Close up view of the condition of the hallway in building #107. The outside can clearly be seen through a hole in the wall. (Taken w/ flash)

D. Hopkins

photo #11
Set # 2

Inspection 9/26/83

Hallway within building #107 (Taken w/ flash)

D. Hopkins

photo #15
Set #2

Inspection 9/26/83

Chips in storage area in building #115 (Taken w/ flash)

D. Hopkins

photo #12
Set # 2

Inspection 9/26/83

Essentially same photo as #11

D. Hopkins

Green River Industrial Park
P.O. Box 326
Dixon, Illinois
(Building 115)

photo #17
Set #2

Inspection 9/26/83

Storage area-building #115

D. Hopkins

photo #20
Set #2

Inspection 9/26/83

Cyanide contaminated chips in storage area in building #115 (taken w/ flash).

D. Hopkins

photo #18
Set #2

Inspection 9/26/83

Continuation of view from photo #17 (Taken w/ flash)

D. Hopkins

photo #14
Set #2

Inspection 9/26/83

Storage areas (partitioned by cement walls) in building #115. (Taken w/ flash)

D. Hopkins

Green River Industrial Park
P.O. Box 326
Dixon, Illinois
(Exterior Shots)

photo # 4
Set # 2

Inspection 9/26/83

Building #107

D. Hopkins

photo #3
Set #2

Inspection 9/26/83

Building #107. In foreground is a pile of contaminated soil on a plastic sheet

D. Hopkins

photo #2
Set # 2

Inspection 9/26/83

Corner of building #107 (left corner) & hallway to next building

D. Hopkins

photo #23
set #2

Inspection 9/26/83

Building #115

D. Hopkins

Green River Industrial Park
P.O. Box 326
Dixon, Illinois
(Building 107)

photo #8
Set #2

Inspection 9/26/83

Hallway from storage area in building #107
(Taken w/ flash)

D. Hopkins

photo #7
Set #2

Inspection 9/26/83

Storage area near wall-building #107
(Taken w/ flash)

D. Hopkins

photo #10
Set #2

Inspection 9/26/83

Storage area and entrance to hallway in building #107
(Taken w/ flash)

D. Hopkins

photo #21
Set #2

Inspection 9/26/83

Hallway from building #115. Chips are covering the floor of the hallway to about half the height of the hallway
(Taken w/ flash)

D. Hopkins

Aldens Warehouse
5000 West Roosevelt Road
Chicago, Illinois
(Treated Chips)

photo #20
Set #1

Inspection 9/16/83

Trailer at Aldens, Inc
suspected "clean" chips in
this group of 2 trailers

D. Hopkins

photo #18
Set #1

Inspection 9/16/83

Trailers at Aldens, Inc.
Chicago, Chips spilling from
the back of the trailer. These
chips are suspected of being
"clean" through previous
chemical treatment.

D. Hopkins

photo #23
Set #1

Inspection 9/16/83

Trailers thought to contain
'clean' chips at Aldens, Inc

D. Hopkins

photo #19
Set #1

Inspection 9/16/83

Close-up of Trailer depicted in photo #18

D. Hopkins

Aldens Warehouse
5000 West Roosevelt Road
Chicago, Illinois
(Untreated Chips)

photo #25
Set #1

Inspection 9/16/83

Six trailers in foreground (some w/ red tape across front) are a group suspected of containing "dirty" chips.

D. Hopkins

photo #21
Set #1

Inspection 9/16/83

Trailers at Aldens, Inc
Center trailer badly damaged

D. Hopkins

photo #26
Set #1

Inspection 9/16/83

Trailers at Aldens. Suspected of containing untreated "dirty" chips, note poor condition of trailer wall.

D. Hopkins

photo #22
Set #1

Inspection 9/16/83

Close up of trailer in photo #21 - Aldens Inc

D. Hopkins

photo #13
Set #1

Inspection 9/16/83

Trailers at Livco, Inc, Chicago Ridge. Standing liquid may be due to rain fall which occurred prior to inspection.

D. Hopkins

photo #2
Set #1

Inspection 9/16/83

Same trailer as in photo #1 at J Fiorito Leasing site, Rosemont, Il

D. Hopkins
USEPA-Region V

photo #24
Set #1

Inspection 9/16/83

Trailers at Aldens, Inc.
This trailer is one of a group suspected of containing "dirty" chips. Note corrosion along trailer

D. Hopkins

RED DEVIL
5995 North River Road
Rosemont, Illinois

photo #1
Set #1

Inspec. 9/16/83

Photo of the back of a trailer containing cyanide contaminated chips. Trailer was located at the J. Fiorito Leasing site at 5995 River Rd in Rosemont, Il.

Dan Hopkins
USEPA Region V

Photo 4
Set #1

Inspection 9/16/83

View of south side of site (looking ≈ north) - J. Fiorito Leasing site

D. Hopkins
Region V

photo #3
Set 1

Inspection 9/16/83

photo of corner of trailer containing cyanide chips at J. Fiorito Leasing site in Rosemont, Il. Corrosion of the trailer is severe enough to allow leachate from inside trailer to fall below to the soil - note blue leachate on ground

D. Hopkins
USEPA Region V

photo 5
Set #1

Inspection 9/16/83

View of south side of site (looking ≈ north) - J. Fiorito Leasing

D. Hopkins
Region V

J's Mobile Semi Trailer Yard
8765 West Joliet Road
McCook, Illinois

photo #9
Set #2

Inspection 9/14/83

Underside of trailer at Js Mobile Semi-Trailer Repair, Inc., McCook - Note corrosion on side wall of trailer, underneath leakage and leachate on ground

Dan Hopkins

Gemini Leasing
6021 South East Avenue
Hodgkins, Illinois



photo #10
Set #1

Inspection 9/16/83

Trailers at Gemini Leasing Company, Inc. Hodgkins – Trailers have sunk into the soil to some degree. Standing liquid & blue stains in foreground believed to be leachate from the trailers containing "chip"

Dan Hopkins

photo #11
Set #1

Inspection 9/16/83

Trailers at Gemini Leasing Company, Inc., Hodgkins – Trailers sinking into soil. Leachate from trailers accumulating below trailers as standing liquid (which may contain some rain water) note blue stains on ground.

D. Hopkins

Livico Trailer Yard
6700 West 130th Street
Chicago Ridge, Illinois

photo #16
Set #1

Inspection 9/16/83

Trailers at Livco Inc.
Trailer to right has tape placed between door and floor junction

D. Hopkins

photo #14
set #1

Inspection 9/16/83

Trailers at Livco, Inc. Same trailers depicted in photo 13

D. Hopkins

photo #15
set #1

Inspection 9/16/83

Trailers at Livco Inc.

D. Hopkins

photo #17
Set #1

Inspection 9/16/83

Trailers at Livco, Inc.

D. Hopkins

photo #6
Set 2

Inspection 9/16/83

photo of underside of trailer (using flash) to show corrosion on the underside of the trailer floor. Note corrosion on the outside of the trailer wall as well - Eagle Trailer, Inc, Summit

D. Hopkins
Region V

photo #7
Set #2

Inspection 9/16/83

Trailers at Eagle Trailer Inc. note corrosion near floor of trailer

Dan Hopkins
Region V

photo #12
Set #1

Inspection 9/16/83

Blurred photo of leachate under trailers at Gemini Leasing Inc. This photo is a closer view of the underside of the trailers & standing liquid shown in photo #11

D. Hopkins

photo #8
Set #2

Inspection 9/16/83

View of Eagle Trailer Inc, site from off site, chain link fence (right) divides Eagle Trailers from its neighbor. Fuzzy line thru photo is wire from the fence near the camera.

D. Hopkins