ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C 0 5 5 C
(1) (8) (9)

OBSERVATION REPORT - SITE INVENTORY NO. 1 4 3 8 0 8 0 1
(11) (18)

US EPA RECORDS CENTER REGION 5
498844

PEORIA CO. - L.P.C. Region # C Date 11/27/79
(20) (25)

PEORIA / JANSON
(Location) (Responsible Party)

Letter Sent (Yes or No) N
(26)

Samples Taken: Yes ( ) No (X) Time: From 11:25 Am
Ground Water( ) Surface( ) Other( ) To 12:05 Pm
Photos Taken: Yes (X) No ( ) Interviewed ——

Weather Wet snow falling + 33°F

Inspector A J L
(27) (29)

Previous Inspection 11/20/79 Previous Correspondence 3/20/78 Site Open: Yes( ) No(X)

OPERATIONAL STATUS:		TYPE OF OPERATION:				AUTHORIZATION:	
Operating	( )	Landfill	(X)	Storage	( )	E.P.A. Permit	( )
Temporarily Closed	(X)	Random Dump	( )	Salvage	( )	Variance	( )
Closed Not Covered	( )	Other ____	( )	A.C.D.	( )	21(e)	( )
Closed and Covered	( )	Quantity Received Daily(1-6)		1 (30)		Board Order	( )
						Illegal (5)	(X) 5 (31)

IMPROVED

SAME

LPC 4 1/79 5,000

DETERIORATED

I (S) or D S
(62)

GENERAL REMARKS: Inspection of this illegal site revealed it to be very wet from rain +/or snow on Sun. and today. H_2O was standing in the access road + the center low area. Size of ponds were not measured but a rough estimate is that neither was larger than 10yds².
Little work has been done at this site since last inspection. Approx 2 additional loads had been removed from the "cleared area" (see site sketch) in the center low area.
Smoke vents were noted in the same locations (see site sketch). They were

INTERVIEW: "vigorously spewing" smoke today. Smoke was visible from a distance of 50-80yds. New vents were noted in 2 areas: (A) in the E-central area and (C) in the NE area (see site sketch).

No one was at the site during the inspection. The N ½ of the gate at the site entrance was closed. The dozer near the W side of the center low area was observed. No ~~dozer~~ other dozers were observed.

DIAGRAM:

PEORIA COUNTY - LPC 1 4 3 8 0 8 0 1

DATE: 11/27/79

TIME: 11:25am-12:05

PEORIA JANSON