US EPA RECORDS CENTER REGION 5
498846

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C 0 5 5 C
(1) (8) (9)

**OBSERVATION** REPORT - SITE INVENTORY NO. 1 4 3 8 0 8 0 1
(11) (18)

Peoria CO. - L.P.C. Region # C Date 10/30/79
(20) (25)

Peoria / Janson Letter Sent (Yes or No) N
(Location) (Responsible Party) (26)

Samples Taken: Yes (X) No ( ) Time: From 02:10 Pm Weather 60°'s + cloudy
Ground Water( ) Surface(X) Other( ) To 03:05 Pm
Photos Taken: Yes (X) No ( ) Interviewed MR. Janson Inspector A J L
(27) (29)

Previous ~~Inspection~~ Observation 10/16/79 Previous Correspondence 3/20/78 Site Open: Yes(X) No( )

| OPERATIONAL STATUS: | | TYPE OF OPERATION: | | | | AUTHORIZATION: | |
|---|---|---|---|---|---|---|---|
| Operating | ( ) | Landfill | (X) | Storage | ( ) | E.P.A. Permit | ( ) |
| Temporarily Closed | (X) | Random Dump | ( ) | Salvage | ( ) | Variance | ( ) |
| Closed Not Covered | ( ) | Other | ( ) | A.C.D. | ( ) | 21(e) | ( ) |
| Closed and Covered | ( ) | Quantity Received Daily(1-6) | 1 (30) | | | Board Order | ( ) |
| | | | | | | Illegal (5) | (X) 5 (31) |

IMPROVED

LPC 4 1/79 5,000

SAME

DETERIORATED

I S or D S
(62)

GENERAL REMARKS: Observation of this ~~illegal~~ CMJ site revealed that work was being done to clear out the center area of refuse. The refuse that was removed was dumped in the NE part of the site. Dirt was stockpiled between the refuse + the edge of the slope in this area.
Dirt was also stockpiled in the SE part of the site on top the berm.
Additional cover had been applied to the slopes bordering Kickapoo Ck in the NE area beyond where the refuse was piled.
Refuse was removed so that "virgin" ground was observed in the N part of the center.

INTERVIEW: The site was briefly observed w/ Mr. Janson. He explained that he thought decomposing refuse would generate steam when it was saturated w/ water. Mr. Janson + his sons were repairing a packer truck at time of this observation.
Sampled Kickapoo Ck: S101 - approx 100 yds downstream of Rte 116 bridge.
S301 - approx 15 yds upstream of RR bridge ~~in~~ SE of the site. At the confluence of the small creek on the W boundary of the site and Kickapoo Creek.
The creek on the W boundary of the site was flowing to low to sample at time of this observation.

DIAGRAM:

4 B photos were taken.

County - LPC 14380801

DATE: 10/30/79

TIME: 2:10 - 3:05 P

Jenson