INITIAL INVESTIGATION INSPECTION

DATE: 8/7/97
TIME: 10:00

Report #N26952 Site Name (b) (6) RESIDENCE

County KING Site Location 10118 DES MOINES MEMORIAL WY. S.
Tax Parcel #: _____ Lat _____ Long _____

Site Representative: _____ Title _____
Mailing Address: _____
Telephone Number: _____
Type of Operations: _____
Type of Entry Notice and Permission: _____

SITE INFORMATION

Slope: _____ Soil Type: _____
Wind: _____ Rainfall: _____
Vegetation/cover: _____

Disturbed Soil: _____
Surface Water Features and Drainage: _____

Groundwater: Well(s) _____ Drainfield _____
other: _____

Permit(s) _____

SITE DOCUMENTATION Photographs X Videotape ____ Samples ____
Documents ____ (Specify) _____

Completed: ERTS Form X S&H Checklist X SEF ____ SMIS Ref. ____

Historic Information: _____

Observations: LARGE HOUSE WITH OWNER AND RENTERS LIVING THERE. SIX CARS ON PROPERTY IN VARIOUS STATES OF DISREPAIR. SEVERAL AREAS OF SOIL STAINED WITH MOTOR OIL AND TRANSMISSION FLUID. COULD NOT SEE FULL EXTENT OF SOIL CONTAMINATION DUE TO SOLID WASTE COVERING STAINED AREAS. SEVERAL AUTOMOTIVE BATTERIES ALSO IN AREA.

Inspector(s): C. F. HANSEN

Recomendation: NFA ___ Ed. Mail ___ SMIS List X SHA X IA ___ ER ___
Initials: I.I. ____ Referral: ____ Unit Sup: ____ Sec. Sup: ____

Site Diagram

Site Name: (b) (6) RESIDENCE

N



Site # N26952

Site Location: 10118 DES MOINES MEMORIAL WY S.

Approximate site dimensions:

Date: 8/7/97 Time: 10:00

Inspector: C. THOMSEN / P. ISAKSEN

I.I. EVALUATION FACTORS

HazSub

PRACTICES: Current X Spills __UST's __AST's
__Used at Facility __WAD#_____
__Permitted Discharges __Unpermitted Discharges
__Other_____

SIC Codes_____

Past __Spills __UST's __AST's
__Used at facility __WAD#_____
__Permitted Discharges __Unpermitted Discharges
__Industry Standards __Other_____

SIC Codes_____

CONTAMINANTS (C=confirmed, S=suspected, __=no, u=unknown)

__Metals, P.P.	__Metals, other	C Petroleum
__Solvents,halogenated	__Solvents, other	__BNA's
__Pesticides	__PCB/Dioxins	__Phenolics
__Halogenated Organics	__Radioactive	__Reactive
__Corrosive	__Conventional, Org.	__Conv.,Inorg.

MEDIA

	X Soil	__S. Water
__G. Water	__Air,Vapor	__Air,Partical
__Sediment	__Drinking Water Well	(__Pri__Pub)

PATHWAYS

MEDIUM PATH:	Ingestion	Inhalation	Contact
__S. Water			
__G. Water			
__Soil			
__Air			
__Drink water			

TARGETS

X Human, adult X Human, children __Fetus
__Sensative Environment __Threatened/Endangered Species
X Residential __Industrial __Commercial
__Drinking Water, __Private__Public, Class I__,II__,III__,IV__

GENERAL COMMENTS_____

INSPECTOR C. THOMSEN/P. ISAKSEN DATE 8/7/97

INITIAL INVESTIGATION SITE S&H CHECKLIST

ERTS # N26952 Site Name (b) (6) [redacted] (RESIDENCE)
Site Contact _____ Address 10118 DES MOINES MEMORIAL WY. S
Date 8/7/97 Time 10:00 City SEATTLE

HazSub

Known Contaminants	Det	Prot	Suspected Contaminants	Det	Prot
PETROLEUM					

Note: "no" response to DET or PROT precludes site entry for toxics.
Det=Detectable with instruments on hand Y=yes N=No N/A=not app.
Prot=Protected with PPE on hand Y=Yes N=No N/A=not app.
Specify PPE __Level C/Canister _____ __Level D
Specify Instrument # _____ Calibration Date _____
Instrument type __TIP __Micro-TIP __MSA/CGI
__Other (specify) __Other(Specify) _____

N/A

ACTION LEVELS

HazSub	Instrument	A.L.	Response

Institutional Controls: EXCLUSION ZONES

Physical Hazards 1_Unstable piles or stacks 2_Overhead
3_Pits/trenches 4_Confined Spaces 5_Tripping
6_Construction 7_Uncompacted Soils 8_Visibility
9_Steep slopes 10 Heavy vegetation 11_Slippery
12_Rain/Snow 13_Cold 14_Heat 15_Noise
16_Other (specify) _____

Specify PPE (by hazard #) __Hard Hat __Steel-toed Boots
__Safety Line/Harness __Safety Glasses __Face Shield
__Portable Radio __Work Partner __Hearing Protection
__Insulated clothing __Gloves __Raingear
__Scheduled Breaks __Work Rotation __Electrolyte Liquid
X Other (specify) EXCLUSION ZONES

NOTE: HAZARDS NOT ADEQUATELY PROTECTED FOR PRECLUDE WORK IN THE VICINITY OF THE HAZARD, AND MAY PRECLUDE SITE ENTRY ENTIRELY.
ALLOWABLE SITE ACTIVITIES: __Sampling __Site Entry __No Entry
OFFSITE CONTACT _____
COMMUNICATION INSTRUCTIONS _____
EMERGENCY CONTACT: _____
Plan prepared by: C. THOMSEN

Signature: Carolyn Thomsen Date 8/7/97 Time 10:00

PHOTO No. 7

DATE: 8/7/97

TIME: 1000

TAKEN BY: PJ Isaksen

WITNESS: C. Thomsen

FILM: 35mm

CAMERA: Olympus

10118 Des Moines Mem. Dr. S

DESCRIPTION:

driveway in front of Subject house - Subject house is to the right in photo. Shows some of cars parked, and used tires stockpiled in/around pickup truck - just barely see corner of old truck bed seen in picture #11

COMMENTS:

PHOTO No. 8

DATE: 8/7/97

TIME: 1000

TAKEN BY: PJ Isaksen

WITNESS: C. Thomsen

FILM: 35mm

CAMERA: Olypus

10118 Des Moines Mem Dr. S.

DESCRIPTION:

Subject house showing garage and house. Some staining seen on driveway

COMMENTS:

PHOTO No. 9

DATE: 8/7/97

TIME: 1000

TAKEN BY: PJ Isaksen

WITNESS: C. Thomsen

FILM: 35 mm

CAMERA: Olympus

10118 Des Moines Mem. Dr. S.

DESCRIPTION:

View along North Side of house. Note garbage in Van, assorted Solid Wastes stacked between driveway and North property line

COMMENTS:

PHOTO No. 10

DATE: 8/7/97.

TIME: 1000

TAKEN BY: PJ. Isaksen

WITNESS: C. Thomsen

FILM: 35mm

CAMERA: Olympus

10118 Des Moines Mem. Dr. S.

DESCRIPTION:

Garbage on ground and in Van, general rubish scattered - wood waste and construction debris located along North Side of Property. Old truck bed from photo 11 seen.

COMMENTS:

PHOTO No. 11

DATE: 8/7/97

TIME: 1000

TAKEN BY: PJ Isaksen

WITNESS: C. Thomsen

FILM: 35 mm

CAMERA: Olympus

10118 Des Moines Mem Dr. S.

DESCRIPTION:

Old truck bed showing surface gross contamination - suspect petroleum products - (spilled onto soils in this area.)

COMMENTS:

PHOTO No.

DATE:

TIME:

TAKEN BY:

WITNESS:

FILM:

CAMERA:

DESCRIPTION:

COMMENTS: