3/30f.1357

Project Resources Inc.

SDMS Document ID
1035163

Property Access Checklist

Property ID: 3469	☐ WORK STARTED ON: __/__/__
Property Address: 4660 Race St.	☐ WORK COMPELTED ON: __/__/__

Property Owner: Gerardo Portillo &	Property Renter:
Mailing Address: Guillermina Ortego 4660 Race Street Denver, CO 80216	Home Phone:
	Fax:
	Cell/Pager:
Home Phone: 303.298.0847	Additional Information:
Fax:	
Cell/Pager:	

☒ Notification Letter	Sent: 09/01/04	By: A. James
☒ Access Agreement	Signed: 10/30/04	By: Gerardo Portillo
☒ Restoration Agreement	Signed: 02/21/05	By: Gerardo Portillo
☐ Topsoil Sampling (if applicable)	__/__/__	By:
☐ Disposal Sampling (if applicable)	__/__/__	By:
☐ Garden Sampling (if applicable)	__/__/__	By:
☐ Utility Clearance	Called: __/__/__	By:
☒ Video/Photos (Before)	On: 02/21/05	By: M. Redfern
☐ Video/Photos (During)	On: __/__/__	By:
☐ Video/Photos (After)	On: __/__/__	By:
☐ Video/Photos (30-Day)	On: __/__/__	By:
☐ Property Completion Agreement	Signed: __/__/__	By:
☐ Final Report	Issued: __/__/__	By:

Air Monitoring (as applicable)

☐ Community ☐ Crew	On: __/__/__	By:
Results:		
☐ Community ☐ Crew	On: __/__/__	By:
Results:		
☐ Community ☐ Crew	On: __/__/__	By:
Results:		

- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

☒ **Si, yo permito acceso a mi propiedad.** ☐ **No permito acceso a mi propiedad.**

Gerardo Portillo 10-30-04 Guillermina Ortega 10304

Firma **Fecha** **Firma** **Fecha**

☑ **Me gustaría ser presente durante de cualquier colección de muestras.**

☑ **Mi propiedad tiene un sistema de regar plantas y sacate (sprinkler system).** this not

Gerardo Portillo Guillermina Ortega

3469

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

☐ **I grant access to my properties** ☐ **I do not grant access to my properties**

Signature **Date** **Signature** **Date**

☐ **I would like to be present during any sampling that is required.**

☒ **My property has a working sprinkler system that will need to be replaced.**

Consentimiento para el Acceso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

El otorgante (dueño/a de la propiedad) le da permiso y autoriza la Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) y/o a sus representantes autorizados (Cesionario) a entrar y a llevar a cabo algunas actividades ambientales en la propiedad a continuación:

Dueño/a de la Propiedad:	**Número de Teléfono:**
Gerardo Portillo & Guillermina Ortego	303 298 08 47

Dirección de las Propiedades Cubiertas por este Acuerdo:	Dirección:	**4660 Race St**
	Dirección:	4660 Race st Denver Co 80216
	Dirección:	

PROPÓSITO DE LAS ACTIVIDADES AMBIENTALES

La EPA solicita el acceso a tomar muestras de tierra y a remover la tierra en su propiedad que tiene concentraciones altas de arsénico y/o plomo que podrían ser peligrosos a su salud. La tierra será removida y el(las) área(s) excavada(s) serán reemplazadas con materiales limpios. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de la EPA contactará al Otorgante personalmente para discutir el trabajo que se va a realizar en la propiedad del Otorgante. El Otorgante tendrá la oportunidad de examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termine, el Otorgante revisará el trabajo, confirmará su terminación y cumplirá con su aprobación. Después de la terminación del trabajo, el Otorgante recibirá un documento escrito por la EPA que indicará que la propiedad ha sido remediada.

ACCIONES DE LA ACTIVIDAD AMBIENTAL

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractores y subcontractores el derecho a entrar la propiedad, en tiempos razonables y sin noticia anterior, para el único propósito a realizar el trabajo aquí descrito. Este acceso debería persistir en efecto hasta que el trabajo haya sido terminado. El Ortogante también está de acuerdo con:

Gerardo Portillo Guillermina Ortega

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Gerardo Portillo & Guillermina Ortega	**Phone:** 3032980847

Addresses of Properties covered by this Agreement:	**Address:**	4660 Race St
	Address:	
	Address:	

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 8
999 18th STREET - SUITE 300
DENVER, CO 80202-2466
http://www.epa.gov/region08

26 de Enero de 2006

Señor /Señora Gerardo Portillo & Guillermina Ortego
4660 Race Street
Denver, CO 80216

Estimado(a) Señor/Señora Gerardo Portillo & Guillermina Ortego,

Este carta certifica que tierra en el propiedad 4660 Race Street en Denver Colorado, ha sido remediado de acuerdo con la U.S. Environmental Protection Agency's (EPA) Recuerdo de Decisión para el Vasquez Boulevard y Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, Firmado por EPA en September 25, 2003. El trabajo requerido era realizado de acuerdo con EPA confirmado plan del trabajo. La remediación eliminado con éxito los riesgos asociados con la exposición a arsénico y plomo en la tierra en su propiedad.

La acción de limpieza conductazo por EPA y el U.S. Army Corps of Engineers (USACE) dirigido a residentes donde las concentraciones de plomo y/o arsénico en la tierra excedido el nivel de acción de 400 partes por millón (ppm) y/o 70 ppm respectivamente. La limpieza consistido de la excavación de la primera doce pulgadas de tierra de la propiedad listado. El área excavado era reemplazado con tierras limpias.

Para asegurar que su propiedad permanece protegido de la contaminación de plomo, podría ser necesario a mantener el exterior de su hogar a prevenir cualquier astilla o la pintura a se descascara y deposita en su propiedad. Pintura muy viejo (de 1978 o antes) podría contener contaminantes de plomo. Un representante de EPA les contactará a hacer una reunión para una evaluación de pintura con plomo para la exterior de su hogar. EPA provendrá la primera rebaja de pintura basado con plomo si sea necesario.

Si quisiera mas información especifica en relación de la limpieza de su propiedad, por favor contáctame en U.S. EPA (8EPR-SR), 999 18th Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sinceramente,

Victor Ketellapper
Gerente del Proyecto

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 8
999 18th STREET - SUITE 300
DENVER, CO 80202-2466
http://www.epa.gov/region08

January 26, 2006

Mr./Ms. Gerardo Portillo & Guillermina Ortego
4660 Race Street
Denver, CO 80216

Dear Mr./Ms. Gerardo Portillo & Guillermina Ortego,

This letter certifies that soils on the property at 4660 Race Street in Denver, Colorado, have been remediated in accordance with the U.S. Environmental Protection Agency's (EPA) Record of Decision for the Vasquez Boulevard and Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, signed by EPA on September 25, 2003. The required work was accomplished in accordance with EPA approved work plans. The remediation successfully addressed the health risks associated with exposure to arsenic and lead in soils at this property.

The clean-up action conducted by the EPA and the U.S. Army Corps of Engineers (USACE) addressed residences where the soil concentrations of lead and/or arsenic exceeded the action levels of 400 parts per million (ppm) and/or 70 ppm, respectively. The clean up consisted of excavation of the top 12 inches of soil at the listed property. The excavated area was replaced with clean soils.

In order to assure that your property remains protected from lead contamination, it may be necessary to maintain the exterior of your home to prevent any chipping or peeling paint from being deposited in your yard. Very old paint (from 1978 or before) could contain lead contaminates. An EPA representative will be contacting you to schedule a lead based paint assessment of the exterior of your home. EPA will provide for the initial abatement of lead based paint if necessary.

If you require more specific information concerning the clean-up of your property, please contact me at U.S. EPA (8EPR-SR), 999 18th Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sincerely,

Victor Ketellapper
Project Manager

3469

PROPERTY INFORMATION

Property ID:	3469
House Number:	4660
Street:	RACE ST
Address:	4660 RACE ST
Unit:	
ZIP Code:	80216
Neighborhood:	ELYRIA
Zone:	R2

Find Record

OWNER INFORMATION

Owner Name:	MICHAEL D SMITH
Mailing Address:	303 S BROADWAY ST #B446
Mailing City State Zip:	DENVER CO 80209

DECISION CRITERIA

Target Property?	Yes
Soil Sampled?	Yes
Removal Required?	Yes
Removal Complete?	

SOIL SAMPLE RESULTS

Phase	3B
Arsenic Decision Value	19
Lead Decision Value	436

OTHER SAMPLE RESULTS

Media Description		
Arsenic		
Lead		

Real Property Records

Date last updated: Thursday, December 30, 2004

Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to sale information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Parcel: 0223115034000

Name and Address Information

PORTILLO,GERARDO &
ORTEGA,GUILLERMINA
4660 RACE ST
DENVER, CO 80216

Legal Description

L 9 & 10 EXC REAR 5FT TO CITY BLK 15 ELYRIA RESIDENTIAL

Property Address:

4660 RACE ST

Tax District

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	23700	1890		
Improvements	129400	10300		
Total	153100	12190	0	12190
Prior Year				
Land	23700	1890		
Improvements	129400	10300		
Total	153100	12190	0	12190

Style: One Story
Year Built: 1896
Building Sqr. Foot: 959
Bedrooms: 2
Baths Full/Half: 1/0
Basement/Finished: 0/0
Lot Size: 5,750
Zoning: R2

Reception No.: JT00139419
Recording Date: 08/09/02
Document Type: Warranty
Sale Price: 145000
Mill Levy: 64.162


50x2 DG
12' gate
Shed
Shed
28x50 DG
Brick can take
28x27 DG
13x5 DG
8x2
58x26 DG
4660 Pace St.
Veranda Pavilio
tree
tree
tree
tree
6x6 Sod
30x24 Sod
9x1 RM
18x1½ Sod
14x2 RM
29x2
50x4 RM
water meter

Meagan Redfern

#3469

From: OCARS_Pro@uncc.org
Sent: Monday, November 07, 2005 7:39 AM
To: Meagan Redfern
Subject: UNCC EMLCFM 2005/11/07 #00003 B0203506-00B NORM NEW

```
EMLCFM 00003 UNCCb 11/07/05 07:39 AM B0203506-00B NORM NEW STRT LREQ

Ticket Nbr: B0203506-00B
Original Call Date: 11/07/05  Time: 07:38 AM  Op: MRE
Locate By Date    : 11/09/05  Time: 11:59 PM  Meet: N  Extended job: N
State: CO     County: DENVER          City:
Addr:   4660  Street: RACE ST
Grids: 03S068W23NE              :              :                Legal: N
Lat/Long: 39.782581/-104.964358 39.782581/-104.962566
        : 39.779693/-104.964358 39.779693/-104.962566
Type of Work: SOIL EXCAVATION                              Exp.: N
Boring: N
Location: LOC ENTIRE LOT*ACCESS OPEN*TO INCLUDE ALL EASEMENTS AND CITY
        : PROPERTY*INDIVIDUAL STRUCTURE
Company : PROJECT RESOURCES INC.                     Type: OTHR
Caller  : MEAGAN REDFERN             Phone: (303)487-0377
Alt Cont: AMY JAMES                  Phone: (303)487-0377
Fax:   Email: MREDFERN@PROJECTRESOURCESINC.COM
Done for: EPA/ARMY CORPS OF ENGINEERS
Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA    CDOT06 = CDOT--REGION 6
Members CMSND00= COMCAST - NORTH DENVER       LVL311 = LEVEL 3
COMMUNICATIONS
Members MCI01  = MCI                          PCNDU0 = XCEL ENERGY-NORTH
DENVER
Members PSND14 = XCEL ENGY--APPT SCHEDULE     QLNCND0= QWEST LOCAL
NETWORK
Members QLNCND1= QWEST LOCAL NETWORK          QWSTEN0= QWEST/ENRON COMM
Members SPRN01 = U.S. SPRINT                  TWTEL1 = TIME WARNER
TELECOM
Members WCG01  = WILTEL COMMUNICATION
You are responsible for contacting any other utilities that are not
listed above
including the following tier 2 members not notified by the center:
DNVH20 DENVER WATER DEPT              (303)628-6666
DTEO01 DNVR TRAFFIC ENG OPERAT.       (720)865-4001
WWMG01 WASTEWATER MGMT DIVISION       (303)446-3744
```

Project Resources Inc.

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID:	3469
Property Address:	4660 Race Street
Owner:	Gerardo Portillo & Guillermina Ortego
Phone:	303-298-0847

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation:

(Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item: all cars & broken down Dodge Ram, ALL misc stuff.
Item: bikes, soccer balls, pipes, hoses, lawn chairs.
Item: BBQ, trashcans, dog house, mop bucket, toys etc.
Item: Kids swing in front yard.
Item:
Item:
Item:
Item:

Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Not Replaced
(Use additional sheets as necessary)

Item: trees along NORTH fence
Item: all edging
Item:
Item:
Item:
Item:
Item:

Items To Be Removed By Contractor During Remediation And Replaced
(Use additional sheets as necessary)

Item: fence for access
Item:
Item:
Item:
Item:
Item:
Item:

Project Resources Inc.

Landscape Inventory
(Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	5222	Square Feet	
Number of trees > 2 inch trunk diameter	3		
Number of trees < 2 inch trunk diameter	miscellaneous on front northfence		(Remove)
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	none		Zones: _____ Heads: _____ Control Valves: _____
Number of and total size of all gardens / flower beds. Attach a sketch of relative sizes and locations.	# Of Beds: — # Of Gardens: NA		Ft^2 Of Beds: NA Ft^2 Of Gardens: NA

Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	$	Total Ft^2 Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	NA	Each	Only Use For Plants That Are Being Saved and Re-planted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	1044	SF	Total Ft^2 Of Sod To Be Laid: 1044
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft^2: 200	SF	Sod: NA Brown Mulch: NA Red Mulch: 200
Agreed upon area of property to be replaced with mulch.	Total Ft^2 Of Mulch: 299	SF	Red: 299 Brown: NA

Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft^2 Of Rock: 3829	SF	Large: — Medium: — Small (pea gravel): — Driveway Gravel: 3829
Agreed upon area to be replaced with no groundcover.	Total Ft^2 With No Groundcover: 50		

Additional Comments / Instructions:

Project Resources Inc.

Additional Comments / Instructions Continued:

N/A ☑ Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.

☒ **I agree** ☐ **I do not agree** ☒ **I agree** ☐ **I do not agree**

Fernando Portillo 2-26-05 — **Owner's Signature** **Date**

Jaime Reyes 2/21/05 — **Contractor's Signature** **Date**

Project Resources Inc.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID:	3469
Property Address:	4600 Race St.
Owner:	Gerardo Portillo / Guillermina Ortego
Phone:	

Restoration Items in Question:

Item:
Item:
Item:
Item:
Item:
Item:

Additional Comments:

☒ **I agree restoration is completed, except as noted**

☐ **I do not agree restoration is completed**

☐ **I agree that the sprinkler system is working properly following reinstallation by contractor**

Guillermina Portillo 12-9-05 — **Owner's Signature** **Date**

[illegible] 12/9/05 — **Contractor's Signature** **Date**

Property ID:	3469
Address: 4660 RACE STREET	Date: 8-13-05
Owner:	Telephone #:
Inspector/Assessor:	CO Certification #: 12860

Plot Plan:



	Exterior Walls				Doors/Trim			
	Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
North								
South					WOOD TRIM	—	—	—
East								
West					WOOD	—	—	11.4
Total					Total			

	Window Trim/Fascia/Soffit				Patios/Decks/Porches			
	Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
North								
South	WOOD	—	—	8.3				
East	WOOD	—	—	19.3	WOOD COLUMN	—	—	22.2
West					WOOD	—	—	11.1
Total					Total			

	Metal Trim/Gutters/Downspouts				Misc Structures/Garage/Fences			
	Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
North								
South								
East								
West								
Total					Total			

Time	Site	Component	Substrate	Side	Condition	Color	Floor	Room	Results	Depth Ind	PbC	PbC Error
8/13/2005 13:49	3469	WALL	BRICK	WEST	CRACKED	WHITE	FIRST	PORCH	Negative	10	-0.13	0.41
8/13/2005 13:51	3469	FLOOR	CONCRETE	WEST	CRACKED	WHITE	FIRST	PORCH	Negative	7.85	0.03	0.05
8/13/2005 13:52	3469	TRIM	WOOD	WEST	CRACKED	TAN	FIRST	PORCH	Positive	5.92	11.4	1.5
8/13/2005 13:52	3469	CEILING	WOOD	WEST	CRACKED	TAN	FIRST	PORCH	Positive	4.6	11.1	1.4
8/13/2005 13:54	3469	EXT. SIDING	METAL	WEST	INTACT	GREEN	FIRST	OUTSIDE	Negative	1	0	0.02
8/13/2005 13:55	3469	WINDOW FRAME	WOOD	SOUTH	CRACKED	GREEN	FIRST	OUTSIDE	Positive	10	8.3	1.2
8/13/2005 13:57	3469	DOOR FRAME	WOOD	EAST	CRACKED	WHITE	FIRST	OUTSIDE	Negative	2.52	0.01	0.02
8/13/2005 13:59	3469	SOFFIT	WOOD	SOUTH	CRACKED	BLUE	FIRST	OUTSIDE	Negative	2.52	0.02	0.03
8/13/2005 14:17	3469	COLUMN	WOOD	EAST	CRACKED	WHITE	FIRST	PORCH	Positive	10	22.2	2.1
8/13/2005 14:21	3469	WINDOW FRAME	WOOD	EAST	INTACT	WHITE	FIRST	PORCH	Positive	7.52	19.3	1.8

Note: Readings are in mg/cm²

Painted surfaces not tested were assessed to be in "intact" condition at time of site visit.

Color Photo(s)

The following pages contain color that does not appear in the scanned images.

To view the actual images, contact the Region VIII Records Center at (303) 312-6473.

Property ID # 3469 / 4660 Race Street

House has new metal siding & new paint throughout

TARGET SHEET

EPA REGION VIII

SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1035163

SITE NAME: VASQUEZ BOULEVARD AND I-70

DOCUMENT DATE: 01/26/2006

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☑ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
  (Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

3 - DVDs OF PROPERTY VIDEO, PROPERTY #3469

Contact the Superfund Records Center to view available document.
(303) 312-6473