BACKGROUND READINGS

Location	Reading	Units
Adjacent to CS03, no block, no cart	374	c/m^{10}
Church Background Area, cart and block (a)	515	c/m^{10}
Church Background Area, cart and block (b)	544	c/m^{10}



0 2.5 5 10 Feet

Legend

Concrte Reading Location

Decon Area

Notes:
Readings presented in counts per ten minutes (c/m^{10})

N

Weston Solutions, Inc.
East Division

In Association With
Scientific and Environmental Associates, Inc.,
Environmental Compliance Consultants, Inc.,
Avatar Environmental, LLC, On-Site Environmental,
Inc.and Sovereign Consulting, Inc

DATE MODIFIED: 8/9/2016

Figure X:
Concrete Scans

Niagara Falls Boulevard Site
Niagara Falls, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
REMOVAL SUPPORT TEAM 3
CONTRACT # EP-S2-14-01

GIS ANALYST:	P. Lisichenko
EPA OSC:	E. Daly
RST SPM:	P. Lisichenko
FILENAME:	160809_NFB_CONCRETEBKGRD.MXD

F:\GIS\00070014\MXD\160809_NFB_CONCRETEBKGRD.MXD