

Legend

- Gamma Scan Result
- Structure Walls
- 2-Foot by 2-Foot Grid
- Sewer Point Structure
- Exposed Sewer Lines
- Poured Concrete Footers

N

Distance measurements presented in feet.
Gamma measurements presented in counts per minute (CPM).
Measurements captured over a one minute interval.

Weston Solutions, Inc.
East Division

In Association With
Scientific and Environmental Associates, Inc.,
Environmental Compliance Consultants, Inc.,
Avatar Environmental, LLC, On-Site Environmental,
Inc.and Sovereign Consulting, Inc

DATE MODIFIED: 8/25/2016

Figure X:
ST-5 Gamma Survey

Niagara Falls Boulevard Site
Niagara Falls, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
REMOVAL SUPPORT TEAM 3
CONTRACT # EP-S2-14-01

GIS ANALYST:	P. Lisichenko
EPA OSC:	E. Daly
RST SPM:	B. Nwosu
FILENAME:	160825_NFB_OFFICEGAMMA.MXD

F:\GIS\00070014\MXD\160825_NFB_OFFICEGAMMA.MXD