138543



EXPLANATION

T8 ———	Approximate Location of Exploratory Test Pit
SS-12 ▲	Soil Sample
SB-22 ●	Soil Boring
117	Operational Oil Well
114 ○	Abandoned Oil Well
	Approximate Location of Suspect Boneyard Area (Based on Historic Aerial Photographs)
	Approximate Location of Former Above-Ground Storage Tank Farm (Based on Historic Aerial Photographs)
1,200 +	Surveyed Measured Intervals (100 foot)
—x—	Chain Link Fence
—o—o—	Gate
— — —	Property Boundary

A	Approximate Areas of Crude Oil-Affected Soils Above Typical Action Levels (1,000 ppm TPH) Requiring Remediation
B	Approximate Areas of TPH-Affected Soils Apparently Due to Off-Site Sources
C	Approximate Areas of TPH-Affected Soils Below Typical Action Levels (1,000 ppm TPH) Requiring Remediation
D	Approximate Area of Fuel-Affected Soils
E	Approximate Area of Metals (Pb, Zn & Cu) in Soils Exceeding STLC Limits
F	Approximate Area of PCE & TCE-Affected Soils

NOTES: All area approximations are based on analytical results. Area estimations concerning active oil wells, existing tank farm, and "B" areas are also based on visual observations.

N

SCALE
50 25 0 50 FEET
1 INCH = 50 FEET

LEVINE·FRICKE
CONSULTING ENGINEERS AND HYDROGEOLOGISTS
Irvine, California

Mobil Exploration & Producing U.S., Inc.
Jalk Fee
Santa Fe Springs, California

Figure 7 :
SITE PLAN SHOWING APPROXIMATE EXTENT OF AFFECTED AREAS

Project No. 2193
Date SEPT 1991
Sheet 7 of 7

2193-35