

Primarily featureless record (with minor weak parabolic reflections from inferred terrace deposit cobbles)

Figure 4-B

Example GPR Profile:
Suspected Trench Area

Flow Laboratories Site
Dublin, Pulaski Co., VA

Enviroscan, Inc.
Project No.069911
Rev. 06/25/99

GPR Acquisition Parameters:
GSSI SIR-3 Controller, 38-VDU Process
Gains: S-3, C-0, D-5
Filters: Low Pass-25, High Pass-12