ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C 0 5 5 C
(1) (8) (9)

INSPECTION REPORT - SITE INVENTORY NO. 2970501
(11)

EPA Region 5 Records Ctr.
343092

Will CO. - L.P.C. Region # N Date 09/09/81
(20) (25)

Lockport / Wasteland #2 Letter Sent (Yes or No) N
(Location) (Responsible Party) (26)

Samples Taken: Yes ( ) No (X) Time: From 12:30 pm Weather clear ≈75° dry
Ground Water( ) Surface( ) Other( ) To 01:40 pm
Photos Taken: Yes (5) No ( ) Interviewed — Inspector J A S
(27) (29)

Previous Inspection 9/1/81 Previous Correspondence — Site Open: Yes(x) No( )

OPERATIONAL STATUS:		TYPE OF OPERATION:				AUTHORIZATION:	
Operating	(X)	Landfill	( )	Storage	( )	E.P.A. Permit	( )
Temporarily Closed	( )	Random Dump	( )	Salvage	(x)	Variance	( )
Closed Not Covered	( )	Other open dump	(x)	A.C.D.	( )	21(e)	( )
Closed and Covered	( )	Quantity Received Daily(1-6)	1 (30)			Board Order	( )
						Illegal (5)	(X) 5 (31)

IMPROVED

SAME

DETERIORATED I S or D 5 (62)

GENERAL REMARKS: This inspection revealed that the cardboard re-baleing operation is still active, and that no remedial actions, ie. removal of openly dumped refuse, have taken place. It does appear that additional Pielet refuse may have been dumped and spread around (A). Leachate was seen in several spots throughout the site, and oil remains on the ground near the old tank at (B). Bales remain in contact with ponded water at (C); leachate was also observed to be seeping into this water. More bales have been added at (D), numerous flies and a rank garbage odor were noted here.

INTERVIEW:

DIAGRAM: SEE ACCOMPANYING DIAGRAM

RECEIVED
OCT 29 1981
E.P.A. - D.L.P.C.
STATE OF ILLINOIS

Will County LPC

Lockport / Wasteland #2

Date 9/9/81

Time 12:30 p.m. -> 1:40 p.m.



RECEIVED
OCT 29 1981
E.P.A. — D.L.P.C.
STATE OF ILLINOIS

HAZ WASTE WEC

01667 SEP 17

Time Collected: 6:30 pm

Lab #

SPECIAL ANALYSIS FORM

Date Collected: 9/10/81

Date Received 9-17-81 12:45 PM K. Patel

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY
DIVISION OF LAND/NOISE POLLUTION CONTROL

COUNTY:	FILE HEADING:	FILE NUMBER:
will	Lockport/wasteland	19706002

SOURCE OF SAMPLE: (Exact Location)

At days fill face, in center of site x101

PHYSICAL OBSERVATIONS, REMARKS: spongy, greyish material w/ visible fibers - operator claims material mixture of ground up paper and ink

TESTS REQUESTED: 48 hr water leach - metals

COLLECTED BY: Jeff Stafferahn TRANSPORTED BY: Jeff Stafferahn

LABORATORY

RECEIVED BY: DATE COMPLETED: DATE FORWARDED NOV. -5. 1981

Zn - 0.0

Pb - <0.03

Hg - insufficient sample

Mn - 0.18

Mg - 4.2

Cr (hexavalent) - Interference

Cu - 0.00

Cyanide - 0.49

As - <0.001

RECEIVED
NOV 16 1981
E.P.A. - D.L.P.C.
STATE OF ILLINOIS

Results expressed in mg/liter based on a 10% sample to dist. water ratio

LPC-8A 4/77 (NOT FOR DATA PROCESSING)

C001667

Date: 9/9/81

Time: 12:30-71:40 A.M. P.M.

Photograph By:

JAS

Location: LPC-19705015

Will Co.

Lockport / Wasteland #2

Comments: Photograph taken toward the northeast from north end of site

Date: 9/9/81

Time: 12:30-71:40 A.M. P.M.

Photograph By:

JAS

Location: LPC-19705015

Will Co.

Lockport / Wasteland #2

Comments: Photograph taken toward the northwest from center of site

RECEIVED
OCT 08 1981
I.E.P.A. — D.L.P.C.
STATE OF ILLINOIS

L/NPC 24 6/78

Date: 9/9/81

Time: 12:30-1:40 A.M. P.M.

Photograph By:

JAS

Location: LPC-19705015

Will Co.

Lockport / Wasteland #2

Comments: Photograph taken toward the north-west from northwest portion of site

Date: 9/9/81

Time: 12:30-1:40 A.M. P.M.

Photograph By:

JAS

Location: LPC-19705015

Will Co.

Lockport / Wasteland #2

Comments: Photograph taken toward the west-northwest from west portion of site

OCT 08 1981

I.E.P.A. — D.L.P.C.
STATE OF ILLINOIS