445485

404035

This needs to be separate site from UTD980952782

**EPA** POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION: 8

SITE NUMBER: UTD981545932

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME: Denver & Rio Grande Roper Yard South

B. STREET (or other identifier): 2400 South 600 West

C. CITY: South Salt Lake City

D. STATE: Utah

E. ZIP CODE:

F. COUNTY NAME: Salt Lake

G. OWNER/OPERATOR (If known)

1. NAME: Denver & Rio Grande Western Railroad

2. TELEPHONE NUMBER:

H. TYPE OF OWNERSHIP (If known)

☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☒ 5. PRIVATE ☐ 6. UNKNOWN

I. SITE DESCRIPTION

All the area in Salt Lake County bounded on the North by Millcreek, the East by I-15, the South by 3300 South Street and the West by Vitro Uranium Co.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.): Salt Lake City County Health Dept. Investigation

K. DATE IDENTIFIED (mo., day, & yr.): 05/01/84

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

Organics of unknown origin were observed to be seeping into the Vitro Uranium site. The area has a high ground water table and direction of flow is toward the Jordan River (Vitro Uranium Co.). Numerous past spills reported by D&RG Western Railroad (1973-1976) of organic materials (Fuels and waste oils & solvents) may be the source of the organic materials.

Organic sheens have been observed on surface water ditches originating on the D&RG South Site

M. PREPARER INFORMATION

1. NAME: Jim Sherman RSHWM

2. TELEPHONE NUMBER: (801) 533-4145

3. DATE (mo., day, & yr.): 05/01/84

EPA Form 2070-8 (5-80)

# CORRECTION

THE PRECEDING DOCUMENTS HAVE BEEN REMICROFILMED TO ASSURE LEGIBILITY AND ITS IMAGE APPEARS IMMEDIATELY HEREAFTER



This needs to be separate site from UTD980952782

404035

**EPA** POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION: 8 | SITE NUMBER: UTD981545932

**NOTE:** The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME: Denver & Rio Grande Roper Yard South

B. STREET (or other identifier): 2400 South 600 West

C. CITY: South Salt Lake City

D. STATE: Utah

E. ZIP CODE:

F. COUNTY NAME: Salt Lake

G. OWNER/OPERATOR (if known)

1. NAME: Denver & Rio Grande Western Railroad

2. TELEPHONE NUMBER:

H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☒ 5. PRIVATE ☐ 6. UNKNOWN

I. SITE DESCRIPTION

All the area in Salt Lake County bounded on the North by Millcreek, the East by I-15, the South by 3300 South Street and the West by Vitro Uranium Co.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.): Salt Lake City County Health Dept. Investigation

K. DATE IDENTIFIED (mo., day, & yr.): 05/01/84

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

Organics of unknown origin were observed to be seeping into the Vitro Uranium site. The area has a high ground water table and direction of flow is toward the Jordan River (Vitro Uranium Co.). Numerous past spills reported by D&RG Western Railroad (1973-1976) of organic materials (fuels and waste oils & solvents) may be the source of the organic materials.

Organic sheens have been observed on surface water ditches origionating on the D&RG South Site

M. PREPARER INFORMATION

1. NAME: Jim Salmon BSHWM

2. TELEPHONE NUMBER: (801) 533-4145

3. DATE (mo., day, & yr.): 05/01/84

EPA Form 2070-8 (5-80)