Pic 1. SE Phase Rehab 1 (very obvious bedding, tallow along edge).

Pic 2. SE Phase Rehab 2

Pic 3. SE Phase. Flatwood pond overgrown with hardwoods (should look marsh-like).



Pic 4. SE Phase. Existing road with ditches.

Pic 5. NE Phase.

Pic 6. NE Phase. Rehab 1 in the background.



Pic 7. SW Phase. Typical existing.



Pic 8. NW Phase. Typical existing.

Pic 9. Off-site. Flatwood pond surrounded by longleaf pine savannah.