"Rite in the Rain"®
ALL-WEATHER WRITING PAPER

Name MURPHY BUILDING EA

Address 230 COLLINSVILLE AVE,
ST CLAIR COUNTY, ~~HCB~~
EAST ST LOUIS, IL 62201

Phone

Project MURPHY BUILDING EA
START 5
East St Louis, IL

Chris Brewer
Professional Environmental
Engineers

Clear Vinyl Protective Slipcovers (Item No. 30) are available for this style of notebook.
Helps protect your notebook from wear & tear. Contact your dealer or the J. L. Darling Corporation

CONTENTS

PAGE	REFERENCE	DATE

30 MAY 2012

0800 PE Crew Bill Pietro Burso, Tom Binz, Willie Clay and Chris Brewer mobilize to site. Weather Sunny 68°F no precip.

0900 PE crew arrives on site (Bill Pietro Burso, Willie Clay and Chris Brewer). Kevin Turner (USEPA), Tom Miller (IEPA) and Ted Deecke (WESTON) on-site. General discussion of project takes place.

0915 Tom Binz (PE) on-site

0930 Tailgate health & safety meeting conducted by Bill Pietro Burso. This discussion is followed by a discussion of the field sampling plan.

0945 East St Louis Fire Dept. on-site & closes Collinsville Ave. Access to building will be via East STL FD ladder through 3rd floor window as staircase from 1st to 2nd floor is missing.

1000 Bill Pietro Burso & Ted Deecke enter building

Photo Log

Photo #	Description
1	Building S.
2	Building NW
3	CRZ NW
4	HA-1, 2 & 3
5	HA-4
6	HA-6
7	HA-7
8	HA-8
9	HA-9
10	HA-11
11	Floor tile on upper floor
12	Ceramic tile on upper floor
13	Floor tile on upper floor
14	Ceramic tile and debris on upper floor
15	Hallway on upper floor
16	Debris on upper floor
17	Rooms in SE corner

to conduct structural safety inspection on upper floors.
1100 Bill P. & Ted D. exit building & conclude it is safe for inspection teams to enter building.
1130 Three inspection teams enter building. Bill P. and Tom B. start on upper floors, Willie C. & Ted D. start on lower floors, Chris B. & Tom M. work as SACM bulk sample collection team.

Observations:

- extensive scrap removal
- loose, damaged, friable SACM
- extensive damage due to water infiltration
- evidence of trespassers
- interior stairwells passable but contain safety hazards
- evidence of past fires
- most windows missing
- elevators are non-operational
- debris scattered throughout
- less than ten pint, quart or gallon sized paint containers

Photo Log (Continued)

Photo #	Description
18	Room in SE corner E.
19	SE corner on 6th Fl. E.
20	SACM pipe insulation on upper floor
21	Ceramic tile under carpet on upper floor.
22	Debris on first floor
23	Stone tile mastic on first floor
24	HA-9 in basement.
25	SACM on heat exchanger in basement
26	SACM duct insulation in boiler room in basement
27	SACM duct insulation in basement boiler room
28	HA-9 in basement
29	HA-11 outdoors SE of building
30	HA-11 outdoors SE of building

Observations (Continued)

• poor natural light on first floor and basement

1300 Three teams exit building Collinsville Ave opened. Crew decons

1330 - 1430 lunch break

1445 Kevin Turner, Tom Miller & Alan Grimmett (IEPA), Bill A., Tom B., Chris B., & Willie C. walk through first floor & basement.

1500 Two sampling teams begin sampling. Bill P. & Tom B. quantify first floor, Chris B. and sample, Tom M., & Willie C. quantify basement. Rain begins falling

1645 Two teams exit and decon. Debrief meeting with Kevin Turner.

5-30-2012

Sample Log

Sample #	Date	Description
MA01	5/30/12	9"x9" Red/White Floor Tile 3rd Floor N. Room
MA02	5/30/12	Linoleum under MA-01
MA03	5/30/12	Green Floor tile under MA-02
MA-04	5/30/12	Black mastic on white 12"x12" ceiling tile 3rd Floor N. Room
MA-05	5/30/12	Window Caulk 5th Floor NW Corner
MA-06	5/30/12	Debris 1st Floor SW Corner
MA-07	5/30/12	Boiler Insulation Basement SW
MA-08	5/30/12	Fire Crete Basement Central
MA-09	5/30/12	Aircell pipe insulation Basement SE
MA-10	5/30/12	Trowded on surfaces @ Collinsville Entry
MA-11	5/31/12	Debris outdoor SW

5 May 2012

0900 Health & Safety meeting with Kevin Turner, Bill Pietroburiso, Tom Binz, Willie Clay and Chris Brewer and Tom Miller

0945 Two teams enter, Bill and Tom B. quantify SACM on first floor. Chris B., Willie G. and Tom M. quantify SACM in basement.

Rain falling 65°F

1120 DeSnis outdoors SE on ground sampled

1130 Teams exit and decon.

1140 Demob