REDACTED VERSION

ecology and environment, inc.

International Specialists in the Environment

Job Number T51313

Larry Landry Dump
Intracoastal City
Vermillion Parish, LA
TDD 06-8003-04
PAN TLA036JAA
CERCLIS LAD985169804

9117290

E & E Job Number TS1313

Telephone Code Number

Site Name Larry Landry Dump

State/City LA / Intracoastal City

TDD 06-9003-04

PAN TLAØ361JAA

SSID

Start/Finish Date 3/12/90 /

Book 1 of 1

E & E Emergency Response Center: (716) 684-8940

5/12 TDD No. 06-9003-04

Landry Dump - (LLD)

OSC Mike Ryan has requested a "drive-by" assessment

Site was subject of 1989 FIT Preliminary assessment.

Background

Harry Landry Dump is located off LA 333 1 mi N. of Intracoastal City.

Site was operated as an open dump which accepted oil field and solid wastes from off-shore drill rigs. Material was dumped in an unlined area and no containment was installed.

In 1984, samples were collected by concerned citizens. Analysis was for metals and indicated that arsenic, barium, cadmium, chromium, and lead were present in addition to oil and grease.

FIT PA lists site as located near a marsh. Site is fenced, gate is locked; signs are posted "No trespassing". Drainage from site eventually enters Vermillion River. Drums are present

Ron R Looney Jr

TDD No. 06-9003-04 3/13

0630 Arrived ~~office~~ warehouse - packed ~~supplies~~ blazer

- TAT Jarboe

0645 TAT Jarboe met TATs Ezell, Henry, & Sherman at office; packed equipment and blazer (EPA 706)

0720 Depart office

Investigation will be conducted in conjunction with DL Mud TDD No. 06-9002-33

Gulf Coast Vaccum TDD No. 06-9002-32

PAB Oil TDD No. 06-9002-34

0915 TATs met OSC Ryan in Abbeville

0920 TATs & OSC depart for Larry Landry Dump

4

3/13

TDD No. 06-9003-04

SITE SAFETY/ HORS PLAN MEETING

TIME: 0922 WEATHER: Partly Cloudy, 80°

PROPOSED WORK/SAFETY TOPICS:

Drive-by LLD and conduct perimeter Reconnaissance and photodocumentation/be careful walking

Level D - no site entry will be conducted

Site is a dump which accepted oil field waste.

Contaminantes include: oil, grease, arsenic, lead, chromium, and cadmium

SIGNATURE	PRINTED	DUTIES/AFFIL.
Robt W Sherman	Robert W Sherman	Sherman SSO
Vera R Henry	VERA R. HENRY	Jarboe TL
Mark Ezell	MARK EZELL	

CONDUCTED BY: Ann L Looney Jarboe

Ann L Looney Jarboe

TDD No. 06-9003-04 3/13

1012 TATs and OSC at or rather near site
met NR Broussard - land owner across
the way met us near site
said we need to speak to landowner
Mr. (b) (6) [redacted] re. entry
S. ARLD
Land is guarded by a fence and locked
gate.
LLD is not visible from road.
1015 Mr (b) (6) [redacted] ask OSC about Superfund
1016 OSC explained what Superfund is
and what it means
1023 (b) (6) [redacted] departs ~~site~~ ARLD area
1024 TATs and OSC depart area
1025 TATs & OSC at (b) (6) [redacted] house
*her ~~home~~ ARLD well was sampled according
to FIT report
OSC wanted (b) (6) [redacted] #; (b) (6) [redacted]
wasn't home
1030 TATs and OSC depart (b) (6) [redacted]
1032 TATs and OSC at Richards Marina to
make a phone call - try to contact
(b) (6) [redacted]
Tel. (b) (6) [redacted]

Ann Looney Jarboe

3/13 TDD No. 06-9003-04

TAT provided info. to OSC

1038 OSC calls (b) (6) [redacted] - No answer

OSC decides to do other sites and try LLD later

1040 TATs and OSC depart Intracoastal City

1158 OSC attempted to contact (b) (6) [redacted] again

(b) (6) [redacted] - no answer

2010 TAT called OSC to learn plans for tomorrow

OSC successfully contacted (b) (6) [redacted]

(b) (6) [redacted] was not sure whether he wants to let us on his property - he doesn't think he can afford it.

(b) (6) [redacted] requested OSC Ryan to call him at 0800 for an answer.

2220 TAT Jarboe notifies TAT members.

LATE Entry

OSC Ryan was unable to contact (b) (6) [redacted] earlier in the day so work day ended at 1700 hrs -

Ann L Cooney Jarboe

TDD No. 06-9003-04 3/14

TATs contact OSC regarding what will be done

OSC has contacted [redacted] this morning -

[redacted] said he wants OSC to talk [redacted] sons - [redacted] said dump has been covered over and larger debris be [illegible] removed

[redacted] said [redacted] has purchased some of the propert behind dump (maybe part of dump)

[redacted] gave OSC telephone for harry Landry [redacted]

OSC attempted to contact [redacted] will be in around 0900 he's [illegible] He's currently in a meeting

OSC will meet TAT when more is learned

0930 TATs met OSC

OSC has permission to go on-site

We will know in a few minutes

[redacted] told OSC that site has been "cleaned up" and waste is buried

Am L L Garboe

3/14 TND No. 06-9003-C4

OSC wants to conduct PA
may want to come back later
and do subsurface sampling
1002 OSC get permission from
(b) (6) [redacted] to go on-site
TAT awaits OSC to check out of
motel

TDD No. 06-9003-04

3/14

9

SITE SAFETY/ WORK PLAN MEETING

TIME: 1000 WEATHER: Cloudy, Windy, 70°

PROPOSED WORK/SAFETY T

TAT will conduct a ~~wr~~ ALLG perimeter assessment; photodocument.
Latest information indicates that large debris has been removed and site covered over with fill
Beware of flying sticks, dust, leaves - wind is at 15-25 mph
Watch where walking; avoid tripping and mud hazards

SIGNATURE	[illegible]	[illegible]/AFFIL.
Mark Ezell	MARK EZELL	ME SSO
Robt W Sherman	Robert W Sherman	RHHG TL
Vera R Henry	Vera R. Henry	

CONDUCTED BY: Ann L Rooney Jarboe

Ann L Rooney Jarboe

3/14 TAD No. 06-9003-04

1010 TATs and OSC depart for site via

1036 TATs and OSC met (b) (6) [redacted]

1041 TATs, OSC, and (b) (6) [redacted]

at perimeter of site

no odor at perimeter

Site is ~1 acre according to Pierce

Duck blind on property

No mounds are present,

Surface is flat, and firm

Larry Landry cleaned site.

Site is revegetating slowly with blue grass and several forms of weeds.

Vegetation is patchy filling in

Evidence of animal activity

rabbit ~~ex~~ all droppings

Cables, glass, buried metal, boards

Vetation growing in backfill

same as around zone

lots of Seat

* on Denuded areas - salt water was mentioned in FIT report

[signature]

12

3/14

TDD No. 06-9003-04

PHOTOGRAPH LOG

CAMERA/LENS (MODEL) Nikon N400045 55 mm

SERIAL # EPA 724900 ; Serial ~~2628~~ 2627692

TIME	SQ/FR	ROLL	D/R	SUBL	P/N
1058	1/10	1	S	S backfill	RS/AJ
1108	2/11	1	SW	Backfill ~~from~~ all	
1109	3/12	1	W	Backfill (* Dear stand)	
1110	4/13	1	Down	Debris	
1113	5/14	1	SW	Denuded area (* 2 dear stands	
1114	6/15	1	W	Backfill area	
1116	7/16	1	SW	Patchy veg.	
1120	8/17	1	N	Acetylene tank	
1121	9/18	1	Down	Label on tank	

Ann L Looney Garbo

TDD No. 06-9003-04 3/14

x = dearstands

marshy areas



oxygen
acetylene

3/4 TDD No. 06-2003-04

Debris includes:
cables, glass, steel scraps,
iron scraps, plastic, wood,
concrete

3 Compressed gas cylinders:
1- acetylene tank - poor condition
label is still on (should be
pulled when empty)
2 oxygen cylinders, no tags - better
condition

Photo 10/19 SW largest aboveground
debris RS/ALJ

1126 TAT Jarboe asked OSC if he'd
like a POLREP - No

1131 TATs and OSC depart
*Site is on fenced property but
site itself isn't fenced along

1400 TATs back at office

TAT hrs:
Jarboe: 6
Henry: 6
Ezell: 6
Sherman: 6

WLL Jarboe