PHOTOGRAPH LOG

Project Name:	Site Location:	Project No.
Gold King Mine – September 11, 2014	Silverton, San Juan County, Colorado	NA

Photo No.	Date:
1	09/11/2014

Direction Photo Taken:

North

Description:

Gold King Mine prior to 2014 site work. Photo taken on 9/11/2014 at 12:37 pm prior to start of work. 3-inch Parshall flume is at the right of the photo, in the plastic structure.

Photo No.	Date:
2	09/11/2014

Direction Photo Taken:

East

Description:

Gold King Mine prior to 2014 site work. Photo taken on 9/11/2014 at 12:38 prior to start of work. Low flow in discharge channel.

PHOTOGRAPH LOG

Project Name:	Site Location:	Project No.
Gold King Mine – September 11, 2014	Silverton, San Juan County, Colorado	NA

Photo No.	Date:
3	09/11/2014

Direction Photo Taken:

South

Description:

Gold King Mine 3-inch Parshall flume. Note low flow in channel. Photo taken on 9/11/2014 at 12:42 prior to the start of work. Water is at 0.1 feet, which corresponds to 12.55 gallons per minute flow.



Photo No.	Date:
4	09/11/2014

Direction Photo Taken:

South

Description:

Gold King Mine 3-inch Parshall flume. Note low flow in channel. Photo taken on 9/11/2014 at 12:43 prior to the start of work. Water is at 0.1 feet, which corresponds to 12.55 gallons per minute flow.



PHOTOGRAPH LOG

Project Name:	Site Location:	Project No.
Gold King Mine – September 11, 2014	Silverton, San Juan County, Colorado	NA

Photo No.	Date:
5	09/11/2014

Direction Photo Taken:

Northwest

Description:

Small amount of flow from side adit approximately 100 feet west of main adit/flume. Photo taken on 9/11/2014 at 12:53.

Photo No.	Date:
6	09/11/2014

Direction Photo Taken:

Northwest

Description:

Start of 2014 excavation work. Photo taken on 9/11/2014 at 15:10.