

9540 Niagara Falls Boulevard (N002)

Legend

- Soil Sample Location
- Exterior Wall
- Interior Wall
- Transect/ Row Grid lines

OF - Office
ST - Storage
WH - Warehouse
HW - Hallway
CL - Customer Lounge
CR - Communications Room
WA - Wood Work Area
FY - Foyer
BT - Bathroom
LB - Lobby
SR - Showroom

Soil Sample Location Gamma Screening Results collected at Waist (W) and Contact (C.)
Gamma Screening was conducted using Ludlum-2241.
Gamma Screening Results are in counts per minutes (cpm)

Weston Solutions, Inc.

In Association With Scientific and Environmental Associates, Inc.,
Environmental Compliance Consultants, Inc.,
Avatar Environmental, LLC,
On-Site Environmental, Inc., and
Sovereign Consulting, Inc.

Figure 2: Property N002 Soil Sample Gamma Screening Results Map

Niagara Falls Boulevard Radiological Site
Niagara Falls, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
Removal Support Team 3
CONTRACT # EP-S2-13-01

EPA OSC:	E. DALY
RST SPM:	B. NWOSU
PROJECT #:	30400.021.006.2061