Arimetco VLT Pond Flow (January 2015)



Arimetco Slot Pond Weir Flow (January 2015)



Arimetco FMS Evaporation Pond B and C Flow (January 2015)



Arimetco FMS Ponds Transducer Levels (January 2015)



Arimetco FMS Evaporation Pond Freeboard Status (January 2015)



2015 Monthly Leak Detector Data													
Leak Detector ID[1]	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Monthly Totals
VLTSP	W												3,922
	3,922												
VLTP1	D												0
	0												
VLTD1	W												12,920
	12,920												
VLTD2	W												1,124
	1,124												
VLTD3	D												0
	0												
EP"B"	D												0
	0												
EP"C"	D												0
	0												
I FX	W												91
	91												
II FX	W												38
	38												
III FX	D												0
	0												
SSP1	D												0
	0												
SD1	W												8,988
	8,988												
SD2	D												0
	0												
SD3	D												0
	0												
MD1	W												21
	21												
Total	27,104	0	0	0	0	0	0	0	0	0	0	0	27,104

Notes: 1) Leak Detector Locations shown on Figure 2-1 of the 2010 Annual O&M Report (June 2, 2011)

2) W=Wet; and D = Dry