Armstrong Chicken Farms Clean Water Act inspection (__ of 88 photos)
All photos taken by Kristine Karlson, EPA, on March 26, 2014.

Photo 5 –Manure piles, located in the center of the facility. Manure is piled in rows to dry on a paved area. View is to the west. This image represents three photographs, stitched together.

Armstrong Chicken Farms Clean Water Act inspection (__ of 88 photos)
All photos taken by Kristine Karlson, EPA, on March 26, 2014.

Photo 6 – View of hen houses to the north of the manure piles. View is to the northwest. There is an area between the manure piles and the hen house immediately to the north that is unpaved. This image represents two photographs stitched together.

Armstrong Chicken Farms Clean Water Act inspection (__ of 88 photos)
All photos taken by Kristine Karlson, EPA, on March 26, 2014.



Photo 7 – View of canal running alongside and above the Armstrong Egg Farms facility. The canal is located uphill from the facility and does not appear to be able to receive flows from it. Circle marks hen houses downhill and to the west.

Photo 24 – Stitched photograph showing the curb along the western perimeter of the facility, leading to the main discharge point (circled). On the right is the red truck seen in Photos 22 and 23. This shows the relative distance between the conveyor belt and discharge point.