
H12
Pipe Breach to Basin 1 on 6/2020 Cd, Pb HW
Skimmer Pond Sol – Cd & Pb
14
Raff Pond Liq - Cd
100 Area Storm Drain Sol – Cd & Pb
PLNT Sol- CD & Pb
H09
H05
H03
H13
East Ponds metals below liner above PSRG 2/2018
Depleted Solution Pond Sol - Cd
10
H04
WOX Storm Drain Sol – Cd and Pb
Maintenance Pond Liq – Cd ; Sol - Pb
H08
Gypsum exceedence Cd 9/2020
H07
West Stormwater Pond Sol - Cd
Spring
H06
H01
West SW Pond clean-out 2016 ?
Sol: Solids/Sediments
Liq: Liquid Phase
Cd: Cadmium
Pb: Lead
HControl
0 150 300 600 900 1,200 1,500
Feet