

Gamma Scan - (µR/hr)

- 12 - 20
- 20 - 30
- 30 - 50
- 50 - 80
- 80 - 620

Notes:
- µR/hr – micro Roentgen / hour
- Gamma Scans conducted with a Ludlum 2241 with 3x3 Sodium Iodide Scintillator.

0 5 10 20 30 Feet

N

Figure 3B:
First Floor Gamma Scan

789 UPPER MOUNTAIN ROAD
LEWISTON, NEW YORK

U.S. ENVIRONMENTAL PROTECTION AGENCY
REGION II: SUPERFUND AND EMERGENCY MANAGEMENT DIVISION
REMOVAL ACTION BRANCH

DATE MODIFIED: 8/24/2020

CREATED BY:	P. LISICHENKO
EPA OSC:	P. LISICHENKO
FILENAME:	200805_789UMR_GammaHouseFirst.mxd

Document Path: C:\Users\plisiche\Documents\ArcGIS\Projects\2020032401\MXD\200805_789UMR_GammaHouseFirst.mxd