

Legend

VC Concentration (ug/l)

- Non Detect
- 1 - 10
- 10 - 100
- 100 - 1000

Isocontour Levels (ug/l)

- 10 - 100
- 100 - 1000

Property Owner

- Allison Transmission Site
- Genuine Parts Site
- Michigan Meadows Apartments
- Michigan Plaza Site
- Residential Area

MW-170D: 105 — Monitoring Well and Analytical Result (Mundell 2007)

MW-166D: 410 — Monitoring Well and Analytical Result (ENVIRON 2012)

MW-169D: 1 — Monitoring Well and Analytical Result (Keramida 2010)

N

0 250 Feet

Deep- Monitoring wells where the top of the screen is greater or equal to 10' below the water table or potentiometric surface.

Prepared For:
U.S. EPA REGION V
Contract No.: EP-S5-06-04
TDD: S05-0001-1205-013
DCN: 1856-2A-BBKP

Prepared By:
WESTON SOLUTIONS, INC.
2501 Jolly Road
Suite 100
Okemos, MI 48864

Figure 4
Vinyl Chloride Isoconcentration Contours for Deep Monitoring Wells
East of Holt Road - 1st Quarter 2007
West Vermont Street
Speedway, Marion County, Indiana

FILE: T:\GIS_Projects\START\West_Vermont\mxd\TechMemo_Hydro_Evaluation\Revision_10\Fig_31_VC_EHolt_1q_2007_deep.mxd 2:15:08 PM 1/11/2013 stolzs