

Legend

cis-1,2-DCE Concentration (ug/l)

- Non Detect
- 1 - 10
- 10 - 100
- > 100

Isocontour Level (ug/l)

- 10 - 100
- 100 - 1000

Property Owner

- Allison Transmission Site
- Genuine Parts Site
- Michigan Meadows Apartments
- Michigan Plaza Site
- Residential Area

Shallow- Monitoring wells where the top of the screen is at or above the water table or potentiometric surface to a depth of approximately 10' below the water table

MMW-1S:ND — Monitoring Well and Analytical Result (Mundell 2007)

MW-166S:44 — Monitoring Well and Analytical Result (ENVIRON 2012)

N

0 200 Feet

Prepared For:
U.S. EPA REGION V
Contract No.: EP-S5-06-04
TDD: S05-0001-1205-013
DCN: 1856-2A-BBKP

Prepared By:
WESTON SOLUTIONS, INC.
2501 Jolly Road
Suite 100
Okemos, MI 48864

Figure 24
cis-1,2-DCE Isoconcentration Contours for Shallow Monitoring Wells
East of Holt Road - 1st Quarter 2007
West Vermont Street
Speedway, Marion County, Indiana

FILE: T:\GIS_Projects\START\West_Vermont\mxd\TechMemo_Hydro_Evaluation\Revision_10\Fig_24_DCE_EHolt_2007_Q1_SHALLOW.mxd 2:29:30 PM 1/11/2013 stolzs