

Legend

cis-1,2-DCE Concentration (ug/l)

- Non Detect
- 1 - 10
- 10 - 100
- 100 - 1000
- > 1000

Isocontour Level (ug/l)

- 10 - 100
- 100 - 1000
- > 1000

Property Owner

- Allison Transmission Site
- Genuine Parts Site
- Michigan Meadows Apartments
- Michigan Plaza Site
- Residential Area

MW-166D:2400 Monitoring Well and Analytical Result (ENVIRON 2012)

N

0 200 Feet

Deep- Monitoring wells where the top of the screen is greater or equal to 10' below the water table or potentiometric surface.

Prepared For:
U.S. EPA REGION V
Contract No.: EP-S5-06-04
TDD: S05-0001-1205-013
DCN: 1856-2A-BBKP

Prepared By:
WESTON SOLUTIONS, INC.
2501 Jolly Road
Suite 100
Okemos, MI 48864

Figure 25
cis-1,2-DCE Isoconcentration Contours for Deep Monitoring Wells
East of Holt Road - 1st Quarter 2007
West Vermont Street
Speedway, Marion County, Indiana

FILE: T:\GIS_Projects\START\West_Vermont\mxd\TechMemo_Hydro_Evaluation\Revision_10\Fig_25_DCE_EHolt_2007_Q1_DEEP.mxd 2:28:28 PM 1/11/2013 stolzs