ORIGINAL
(Red)

Site Name: Kerr Glass Mfg. Co, Huntington, W. Virg.
EPA No:
TDD No:
Date: June 1, 1983
Env. Cond. Sunny, warm, 68°
Personnel:
NUS (b) (4)

Kerr Glass: Lester Rusk
home (b) (6)
Former Traffic Manager
Office "
Raw Materials
Purchaser

NUS FIT III rep. (b) (4) arrived at closed plant 1526. Facility closed. DJM parked on paved area (parking lot) immediately west of the plant. Lot bordered on north by road and hillside with a few homes. C&E railroad tracks run east to west south of the site and plant. Homes and vacant dirt lots border the parking lot to west. Plant borders lot to east.

DJM and L. Rusk recon perimeter of inactive disposal area (parking lot). No observable discharges of leachate, stained soil, stressed vegetation or noticeable odors

Mr. Rusk stated that to his knowledge, no couldn't remember any waste being deposited in the area

ORIGINAL (Red)

of the lot (he was a long-time employee). All other wastes from the plant were either recycled (ie broken glass) or transported to the Huntington Municipal Landfill. No hazardous or toxic materials were used in the process or therefore stored on the property.

Plant closed (Dec. 1982) due to combination of economics (plant age) and the burning down of the warehouse facility across the tracks (see dwg.) on 5 July 82. Plant employed 250-300 persons - 88,000 people in armed. Huntington area

No other visible dumps or disposal sites on premises although soda ash, lime and/or fine quartz sand covered portions of the Kerr Glass plant RR siding track. Photos taken

No regul. action or disposal permits were ever obtained by Kerr to Mr. Rusk's knowledge

Left site at 1607 after photographing parking lot



ORIGINAL (Red)