Plasti-Clad Metal Products Inc (2) 4-29-92
2601 Ridgewood Road.
Wall Township, N.J. NJD011417516
• Depicts 6000 gallon Hazardous waste D002/D007 AST. -NO Hazardous waste /Date label.
insp: Vitone

- Plasti-Clad Metal Products Inc. 4-29-92
2601 Ridgewood Road. NJD011417516 (4)
Wall Township, NJ.
• Recycling Area - drums contain D002/D007 - 11Q waste containing Chromium(+6) insp: A Vitone

Plasti Clad Metal Products Inc 4-29-92
2601 Ridgewood Road
Wall Township, NJ. NJD011417516
Drum storage area. (1) insp: Vitone

Plasti-Clad Metal Products Inc 4-29-92
2601 Ridgewood Road
Wall Township, N.J. NJD011417516
• Onsite Lagoon - installed under CERCLA action (3)
Vitone

Plasti Clad Metal Products Inc. 4-29-92
2601 Ridgewood Road - NJD011417516
Wall Township, N.J.
Depicts staining on floor next to ion sept unit - possibly chromium
5
A. Vitone

Plasti-Clad Metal Products Inc 4-29-92
2601 Ridgewood Road NJD011417516
Wall Township, N.J.
6
• Nonhazardous waste (sludge from wastewater treat plant under CERCLA cleanup). 20 of 27.
insp: Vitone



Plasti-Clad Metal Products Inc. 4-29-92
2601 Ridgewood Road
Wall Township, N.J. NJD011417516
7
• Ion Sept Area - contains substantial staining due to spills of chromium waste
Vitone