

ANCHOR QEA

integral consulting inc.

DRAFT

9753269

Figure 4
Dioxin and Furan Fingerprints for 2015 Sediment Samples Collected from Within the Delineated Area
SJRWP Superfund/MIMC and IPC