Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Barton 3 (220)
Red Mesa Chapter, Navajo Nation



Legend

Gamma Radiation Measurements

- < 2X Backgound
- > 2X Background

Gamma survey conducted 06/2010
Measured as counts per minute (cpm)

Average background = 8,232 cpm

General Direction Down-Slope
Mine Claim Boundaries
Observed Reclamation Cap
Observed Housing Structure
Observed Church

N

Feet
0 **400**

9758703