Metropolitan
St. Louis Sewer
District

Department of Environmental Compliance
10 East Grand Avenue
St. Louis, MO 63147-2913
(314) 436-8710
FAX (314) 436-8753

November 27, 1995

NOV 30 1995
Sverdrup Environmental, Inc.
Site: MOUND ST. PCB
ID #: MO0000093682
Break: 15.2
Other: 11-27-95

Michael T. May
SVERDRUP ENVIRONMENTAL, INC.
4100 College Boulevard
Suite 160
Overland Park, KS 66211

Dear Mr. May:

We have reviewed your letter dated November 21, 1995 requesting information we may have for the "Mound Street PCB Site" in St. Louis. This site is bounded by Mound Street, First Street, Mullanphy Street and the Mississippi River flood wall.

The type of information requested was sampling information from 1993, any additional sampling or information from that time period or other time periods, and a storm sewer map of the adjacent pump station and the area. A search of our files revealed the following information: sampling results from 1993, a special problem investigation report from 1993, correspondence from the Terminal Railroad manager received September 30, 1993, and previous investigation reports from 1982 and 1983. We have also included a copy of the portion of our most current base maps that covers the area in question. If you desire more detailed information regarding the sewers or pump station, you may want to contact our Mapping Division at (314) 768-6200.

Pursuant to MSD Board Resolution No. 1931, you will be billed by invoice for the enclosed copies. By copy of this letter, we have advised our Finance Department to bill you as follows:

10 pages at $.10 per page.....	= $ 1.00
9 pages at $.04 per page.....	= $ 0.36
Postage.....	= $ 1.01
Labor for locating and retrieving documents.....	= $26.60
Total to be billed	= $28.97

Do not pay the amount shown until you receive an invoice from our Finance Department. If you have any questions, please call me at (314) 436-8717.

Sincerely,
METROPOLITAN ST. LOUIS SEWER DISTRICT

Douglas M. Mendoza, P.E.
Industrial Waste Engineer

30024364
Superfund

ph
Enclosures
pc: Helen Williams, Finance Dept.

SPECIAL PROBLEM INVESTIGATION
DEPARTMENT OF ENVIRONMENTAL COMPLIANCE

CONTROL NUMBER: 93 07 08
YR MO DAY

CROSS REFERENCE:

NEW FILE: BROOKLYN STREET PUMP STATION

TO: HOWARD EDMOND FROM: SI SMITH
DATE ASSIGNED: 07-08-93 TIME: 0800
SUBJECT: OIL IN BROOKLYN STREET PUMP STATION
SPECIAL INSTRUCTIONS: LOCATE SOURCE OF OIL ENTERING BROOKLYN STREET PUMP STATION AND TAKE CORRECTIVE ACTION

STREET ADDRESS: FOOT OF BROOKLYN STREET ZIP CODE: 63102
NEAREST INTERSECTION: MULLANPHY MAP COORDINATES: 28-D-19

TYPE OF PROBLEM: OIL ENTERING PUMP STATION
TRUNK SEWER: BCH TRTMT PLANT: BISSELL WATER COURSE: N/A

VOLUME: UNKNOWN QUANTITY: UNKNOWN
CAUSE: SOURCE: POSSIBLE LEAKING TANK

PERSON REPORTING: TELEPHONE:
CONTACT PERSON: JAMES GARAVAGLIA TELEPHONE: 622-3588

DATE OF INCIDENT: ON GOING RESPONSIBLE PARTY: CITY OF ST. LOUIS
REGULATORY AGENCY CONTACTED: MSD, MODNR, FIRE DEPT, & CITY OF ST. LOUIS
CLEAN UP BY: REACT ENVIRONMENTAL ENGINEERS

COMPLETION DATE: 08-19-93 DAMAGES BILLED ($):

INVESTIGATIVE ACTION SUMMARY: 07-08-93 Call from MSD pump station stating oil was entering Brooklyn pump station. I obtained a sample for analysis. Started looking for possible source. Located an under ground storage tank, which has large hole in the top, on the south side of a vacant building located just west of the pump station and south of Brooklyn Street. A sample of the oil still in this tank was collected. The analysis of the oil from the pump sta contained 47 mg/l of 1254 pcb's and the oil from the tank contained 39 mg/l of 1254 pcb's. I contacted Charlie Gay of the Fire Marshall's office and met him at the site on 07-16-93 to show him the problem and to obtain help in finding owner of property. Charlie contacted Chief Horn, informed him of the situation, Chief Horn contacted James Garavaglia of the comptroller's office. We met at site. It was determined at this time that the City of St. Louis is the owner of the east half of the property between 1st St. and the flood wall and Wheeler Ferry Company owns the west half. Cont. Page two

CONCLUSION: It appears at this time an underground storage tank is the cause of this problem. Also the possibility exist of ground saturation of oil from an old Union Electric building.

Copy sent to: Date:

SPECIAL PROBLEM INVESTIGATION continued:

93 Yr 07 Mo 08 Day
BROOKLYN PUMP STATION

DETAILS OF INVESTIGATION: The City is to locate owners of the property and take action on getting area cleaned up. They contacted React Environmental Engineers.

07-16-93 Met with city engineers and React to determine what is to be done. At the present time React is placing booms in the wet well of the pump station to soak up the oil entering. It was not determined at this time what to do with the underground tank. React wanted to trench along the sewer entering the pump station but due to the high water table and the possibility of causing a major problem with the flood waters no trench at this time.

07-26-93 Returned to the pump station to follow up on the clean up. React did not place booms in station they only put absorbent pads. The pump station maintenance crew removed the pads to prevent them from being pulled into the pumps since they were not tied down. I contacted the city comptroller and informed him of this problem. React contacted me and I told them that they had to use booms inside the station and tied to prevent any possibility of being pulled into the pumps or move outside station into the first manhole up stream to collect the oil.

07-27-93 Met Chief Horn at the pump station. React has installed boom and they are tied. Checked the underground tank and nothing has been done to the tank. It still has oil standing in the bottom. It appears that there could be at least 6 to 8 inches of oil in the tank. There is still a small oil sheen on the water entering the station. Chief Horn is to find out what is to be done with the tank and let me know.

07-28-93 Met Chief Horn and Clifford Trice, chief engineer for Terminal Railroad Association at the site of the underground tank. It has been determined that the property belongs to Terminal Railroad. They are to take steps to remove the tank.

07-29-93 Received call from Daryl Bowles, Gehm Corp, rep for Terminal Railroad requesting copies of analysis on pump station and tank. They are to preform an infrared test on area to try and determine just where the oil is entering the sewer. Test is to be done first week of August. Copies of analysis sent.

08-03-93 Made follow up on progress of clean up. The area around the tank has been cleaned up and graded but the opening to the tank has been covered. No way at this time to tell if tank has been pumped. The booms at the pump station do not appear to have been serviced since they were last installed. TE

SPECIAL PROBELM INVESTIGATION continued

93	07	08
Yr	Mo	Day

BROOKLYN PUMP STATION

08-04-08 Met with Terminal Railroad, consulting company and fire department underground tank is being pumped out today. Tank will be removed as soon as the water level goes down. The infrared pictures that were taken do not indicate the source of oil in pump station is from tank. They did indicated a possible location of another underground tank on the city property just south of Mound Street. Fire department was notified.

08-08-93 1015 Hrs Received call from Chief Horne requesting my presents at 1st & Mullanphy. Three manholes were located along the flood wall which contained a large amount of oil. Could not determine at this time where oil is coming from. The manholes are holding water. I will return 08-09-93 to collect samples to find out if pcb's are present. There is some question as to the manholes belonging to MSD or the City.

08-09-93 Collected oil samples from all three manholes. Waiting on analysis.

08-10-93 Met Charlie Gay of fire department. He wanted to know where the manholes were located that contain this last source of oil. Also wanted to look at clean up that was preformed on the underground tank. The tank has been pumped and washed out. The oil has been remove.

08-17-93 The analysis of the samples taken from the manholes indicated they also contained a small amount of pcb 1254. These manhole belong to the city and Fire Marshall Horne was notified of this fact and also the results of the analysis on the manholes. The pads at the pump station have not been changed as of 08-17-93. Chief Horne was also informed of this situation.

08-19-93 The pads at the pump station were changed yesterday 08-18-93. The City of St. Louis is now taking care of having this problem cleaned up.

Petroleum Fuel & Terminal
Foot of Mullanphy Street
St. Louis, Missouri 63102
(314) 621-0522

Charles Gay
Fire Inspector
Fire Prevention Bureau
1421 North Jefferson
St. Louis, Missouri 63106

Dear Mr. Gay

Per our conversation on September 8, 1993. We discovered the leak during our yearly hydro teasting of our pipe lines/hoses. When we experienced a loss of 25# lb of pressure.

We then started to isolate the most likly place and this would be in the expansion joint at the sea wall. After excavating the site we then found a small pen hole in a 6 inch pipe line. After making the necessary repairs we decided to take this pipe line out of service.

We recovered 2 1/2 bbls of oil/soil to be disposed of. If you feel the need to contact me on this mater please feel free to do so at (314) 621-0522.

Thank you

Randel H. Lewis
Terminal Manager

HE 9/30/93

Post-it™ brand fax transmittal memo 7671 | # of pages ▸

To Howard Edmond	From Charles Gay
Co.	Co.
Dept.	Phone #
Fax #	Fax #

** TOTAL PAGE.001 **

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
SPECIAL SAMPLE FORM

Lab. No. 886 ☐ Comp ☒ Grab Date Received 8/9/93

Sample Date 8/9/93 Sample Time: 0845 to

Requested by: HEDMOND Collected by: SAME

Sample Source: MH # MH12 F-6A1 Truck No.

Sampling Location: NEXT TO FLOOD WALL + MULLANIPAY

Reason for sample: TO DETERMINE IF PCB'S PRESENT

☐ Trunk ☐ Sanitary ☐ Stream ☐ Storm ☐ Seepage ☐ STP ☐ Hauler

☐ Industry ☐ Other (explain)

Analysis: except as noted ☐ mg/L ☐ ug/L ☐ mg/kg ☐ % comp ☐ other

☐ pH	(units)	☐ F		☐ Hg	
☐ SPC	(umhos/cm)	☐ Cl		☐ As	
☐ ALK		☐ CN		☐ Ba	
☐ ACI		☐ CNA		☐ Be	
☐ TS		☐ KJN		☐ Cd	
☐ SS		☐ NH_3		☐ Cr	
☐ VSS		☐ NO_3		☐ Cu	
☐ %V		☐ NO_2		☐ Fe	
☐ SET	(ml/L)	☐ PHT		☐ Pb	
☐ GRE		☐ PHO		☐ Ni	
☐ BOD		☐ SO_4		☐ Se	
☐ COD		☐ SO_3		☐ Ag	
☐ TOC		☐ S		☐ Zn	
☐ PHE		☐ SUR		☐ Tl	
☐		☐		☐ Sb	
☐		☐		☐	
☐		☐		☐	
☐ Color:		☐ Cr^{+6}		☐	

☐ Odor: ☐ Tot. Hardness

☐ Appearance: ☐ Tot. Chlorine

☐ Organics ☐ IR ☐ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☒ ID

☐ Biological: ☐ Bioassay: ☐ Total Coli: No./100ml

☐ Fecal Coli: No./100ml

☐ Microscopic: ☐ FecalStrep: No./100ml

Remarks: CHECK FOR PCB'S

Date Transmitted: 8/17/93 by: MARIO J. DRVAIM

75 - DEC/LAB

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
INSTRUMENTATION ANALYSIS

Lab. No. 886 Sample Source: Manhole F-CA1 (#12) Date Received 8/9/93

Sample Date 8/9/93 Time: 0845 ☒ Grab ☐ Comp Collected by:

☒ IR ☒ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☐ TLC ☐

☐ **Priority Pollutant** mg/L (except as noted)

☐ **VOLATILES:**

	acrolein	
	acrylonitrile	
X	benzene	<1.0
	bromodichloromethane	
	bromoform	
	bromomethane	
	carbon tetrachloride	
	chlorobenzene	
	chloroethane	
	2-chloroethyl vinyl ether	
	chloroform	
	chloromethane	
	dibromochloromethane	
	1,2-dichlorobenzene	
	1,3-dichlorobenzene	
	1,4-dichlorobenzene	
	1,1-dichloroethane	
	1,2-dichloroethane	
	1,1-dichloroethene	
	trans-1, 2-dichloroethene	
	1,2-dichloropropane	
	1, 3-dichloropropene, cis	
	1, 3-dichloropropene, trans	
X	ethyl benzene	32.0
	methylene chloride	
	1,1,2,2-tetrachloroethane	
	tetrachloroethene	
X	toluene	<1.0
	1,1,1-trichloroethane	
	1,1,2-trichloroethane	
	trichloroethene	
	vinyl chloride	

☐ **ACIDS:**

	4-chloro-3-methylphenol	
	2-chlorophenol	
	2,4-dichlorophenol	
	2,4-dimethylphenol	
	4, 6-dinitro-2-methylphenol	

ACIDS: (Cont'd)

	2,4-dinitrophenol	
	2-nitrophenol	
	4-nitrophenol	
	pentachlorophenol	
	phenol	
	2,4,6-trichlorophenol	

☐ **BASE/NEUTRALS**

	acenaphthene	
	acenaphthylene	
	anthracene	
	benzidine	
	benzo(a)anthracene	
	benzo(a)pyrene	
	benzo (b) fluoranthene	
	benzo (g,h,i) perylene	
	benzo (k) fluoranthene	
	bis (2-chloroethoxy) methane	
	bis (2-chloroethyl) ether	
	bis (2-chloroisopropyl) ether	
	bis (2-ethylhexyl) phthalate	
	4-bromophenyl phenyl ether	
	butyl benzyl phthalate	
	2-chloronaphthalene	
	4-chlorophenyl phenyl ether	
	chrysene	
	dibenzo (a,h) anthracene	
	3,3-dichlorobenzidine	
	diethyl phthalate	
	dimethyl phthalate	
	di-n-butyl phthalate	
	di-n-octyl phthalate	
	2,4-dinitrotoluene	
	2,6-dinitrotoluene	
	1,2-diphenylhydrazine	
	fluoranthene	
	fluorene	
	hexachlorobenzene	
	hexachlorobutadiene	

BASE/NEUTRALS: (Cont'd)

	hexachlorocyclopentadiene	
	hexachloroethane	
	indeno (1,2,3-cd) pyrene	
	isophorone	
	naphthalene	
	nitrobenzene	
	N-nitrosodimethylamine	
	N-nitrosodi-n-propylamine	
	N-nitrosodiphenylamine	
	phenanthrene	
	pyrene	
	2,3,7,8-tetrachlorodibenzo-p-dioxin	
	1,2,4-trichlorobenzene	

☐ **PESTICIDES:**

	aldrin	
	alpha-BHC	
	beta-BHC	
	gamma-BHC	
	delta-BHC	
	chlordane	
	4,4'-DDD	
	4,4-DDE	
	4,4-DDT	
	dieldrin	
	alpha-endosulfan	
	beta-endosulfan	
	endousulfan sulfate	
	endrin	
	endrin aldehyde	
	heptachlor epoxide	
	heptachlor	
X	PCB-1016	<1.0
X	PCB-1221	
X	PCB-1232	
X	PCB-1242	
X	PCB-1248	<1.0
X	PCB-1254	25.4
X	PCB-1260	<1.0
	toxaphene	

☐ Gas Chromatography results: Run Method 203 on Volatiles

GC/FID resemble Diesel Fuel

☐ Thin-Layer Chromatography results:

☐ Appearance:

☒ Infrared Spectroscopy (a) methods utilized: Smear test

(b) results: 2920 cm⁻¹ - Triplet - Strong
1460 cm⁻¹ - Singlet - Moderate
1375 cm⁻¹ - Singlet - Moderate
1590 cm⁻¹ - Singlet - Moderate

☐ Odor:

☐ API Gravity:

☐ Solubilities:

☐ Ultraviolet/Visible Spectroscopy results:

☐ Distillation Range:

☐ Flash Point:

☐

☐ Special Tests: (specify)

Conclusions Both Infrared spectra and GC/FID resemble Diesel Fuel.

Date Transmitted: 8/13/93 by: Daniel Florida

64-130WW

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
SPECIAL SAMPLE FORM

Lab. No. 887 ☐ Comp ☒ Grab Date Received 8/9/93

Sample Date 8/9/93 Sample Time: 0835 to

Requested by: HEDMOND Collected by: SAME

Truck No.

Sample Source: MH # MH013 F-641

Sampling Location: NEXT TO FLOOD WALL AT MULLANPHY

Reason for sample: TO DETERMINE IF PCB'S PRESENT

☐ Trunk ☐ Sanitary ☐ Stream ☐ Storm ☐ Seepage ☐ STP ☐ Hauler

☐ Industry ☐ Other (explain)

Analysis: except as noted ☐ mg/L ☐ ug/L ☐ mg/kg ☐ % comp ☐ other

☐ pH	(units)	☐ F		☐ Hg	
☐ SPC	(umhos/cm)	☐ Cl		☐ As	
☐ ALK		☐ CN		☐ Ba	
☐ ACI		☐ CNA		☐ Be	
☐ TS		☐ KJN		☐ Cd	
☐ SS		☐ NH_3		☐ Cr	
☐ VSS		☐ NO_3		☐ Cu	
☐ %V		☐ NO_2		☐ Fe	
☐ SET	(ml/L)	☐ PHT		☐ Pb	
☐ GRE		☐ PHO		☐ Ni	
☐ BOD		☐ SO_4		☐ Se	
☐ COD		☐ SO_3		☐ Ag	
☐ TOC		☐ S		☐ Zn	
☐ PHE		☐ SUR		☐ Tl	
☐		☐		☐ Sb	
☐		☐		☐	
☐		☐		☐	
☐ Color:		☐ Cr^{+6}		☐	

☐ Odor: ☐ Tot. Hardness

☐ Appearance: ☐ Tot. Chlorine

☐ Organics ☐ IR ☐ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☒ ID

☐ Biological: ☐ Bioassay: ☐ Total Coli: No./100ml

☐ Fecal Coli: No./100ml

☐ Microscopic: ☐ FecalStrep: No./100ml

Remarks: CHECK FOR PCB'S

Date Transmitted: 8/17/93 by: MARIO J. DEPAUL

75 - DEC/LAB

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
INSTRUMENTATION ANALYSIS

Lab. No. 887 Sample Source: Manhole F-6A1 (#13) Date Received: 8/9/93

Sample Date: 8/9/93 Time: 0835 ☒ Grab ☐ Comp Collected by:

☒ IR ☒ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☐ TLC ☐

☐ **Priority Pollutant** mg/L (except as noted)

☐ **VOLATILES:**

	acrolein	
	acrylonitrile	
X	benzene	<1.0
	bromodichloromethane	
	bromoform	
	bromomethane	
	carbon tetrachloride	
	chlorobenzene	
	chloroethane	
	2-chloroethyl vinyl ether	
	chloroform	
	chloromethane	
	dibromochloromethane	
	1,2-dichlorobenzene	
	1,3-dichlorobenzene	
	1,4-dichlorobenzene	
	1,1-dichloroethane	
	1,2-dichloroethane	
	1,1-dichloroethene	
	trans-1, 2-dichloroethene	
	1,2-dichloropropane	
	1, 3-dichloropropene, cis	
	1, 3-dichloropropene, trans	
X	ethyl benzene	<1.0
	methylene chloride	
	1,1,2,2-tetrachloroethane	
	tetrachloroethene	
X	toluene	<1.0
	1,1,1-trichloroethane	
	1,1,2-trichloroethane	
	trichloroethene	
	vinyl chloride	

☐ **ACIDS:**

	4-chloro-3-methylphenol	
	2-chlorophenol	
	2,4-dichlorophenol	
	2,4-dimethylphenol	
	4, 6-dinitro-2-methylphenol	

ACIDS: (Cont'd)

	2,4-dinitrophenol	
	2-nitrophenol	
	4-nitrophenol	
	pentachlorophenol	
	phenol	
	2,4,6-trichlorophenol	

☐ **BASE/NEUTRALS**

	acenaphthene	
	acenaphthylene	
	anthracene	
	benzidine	
	benzo(a)anthracene	
	benzo(a)pyrene	
	benzo (b) fluoranthene	
	benzo (g,h,i) perylene	
	benzo (k) fluoranthene	
	bis (2-chloroethoxy) methane	
	bis (2-chloroethyl) ether	
	bis (2-chloroisopropyl) ether	
	bis (2-ethylhexyl) phthalate	
	4-bromophenyl phenyl ether	
	butyl benzyl phthalate	
	2-chloronaphthalene	
	4-chlorophenyl phenyl ether	
	chrysene	
	dibenzo (a,h) anthracene	
	3,3-dichlorobenzidine	
	diethyl phthalate	
	dimethyl phthalate	
	di-n-butyl phthalate	
	di-n-octyl phthalate	
	2,4-dinitrotoluene	
	2,6-dinitrotoluene	
	1,2-diphenylhydrazine	
	fluoranthene	
	fluorene	
	hexachlorobenzene	
	hexachlorobutadiene	

BASE/NEUTRALS: (Cont'd)

	hexachlorocyclopentadiene	
	hexachloroethane	
	indeno (1,2,3-cd) pyrene	
	isophorone	
	naphthalene	
	nitrobenzene	
	N-nitrosodimethylamine	
	N-nitrosodi-n-propylamine	
	N-nitrosodiphenylamine	
	phenanthrene	
	pyrene	
	2,3,7,8-tetrachlorodibenzo-p-dioxin	
	1,2,4-trichlorobenzene	

☐ **PESTICIDES:**

	aldrin	
	alpha-BHC	
	beta-BHC	
	gamma-BHC	
	delta-BHC	
	chlordane	
	4,4'-DDD	
	4,4-DDE	
	4,4-DDT	
	dieldrin	
	alpha-endosulfan	
	beta-endosulfan	
	endousulfan sulfate	
	endrin	
	endrin aldehyde	
	heptachlor epoxide	
	heptachlor	
X	PCB-1016	<1.0
X	PCB-1221	↓
X	PCB-1232	
X	PCB-1242	
X	PCB-1248	<1.0
X	PCB-1254	11.7
X	PCB-1260	<1.0
	toxaphene	

☐ Gas Chromatography results: Run Method 203 on Volatiles

GC/FID resembles Diesel Fuel

☐ Thin-Layer Chromatography results:

☐ Appearance:

☒ Infrared Spectroscopy (a) methods utilized: Smear test

(b) results: 2920 cm⁻¹ - Strong - Triplet
1460 cm⁻¹ - Moderate - Singlet
1330 cm⁻¹ - Moderate - Singlet
1590 cm⁻¹ - Moderate - Singlet

☐ Odor:

☐ API Gravity:

☐ Solubilities:

☐ Ultraviolet/Visible Spectroscopy results:

☐ Distillation Range:

☐ Flash Point:

☐

☐ Special Tests: (specify)

Conclusions: Infrared spectra and GC/FID resemble Diesel Fuel

Date Transmitted: 8/13/93 by: Daniel Florida

64-130WW

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
SPECIAL SAMPLE FORM

Lab. No. 888 ☐ Comp ☒ Grab Date Received 8/9/93

Sample Date 8/9/93 Sample Time 0825 to

Requested by: HEDMOND Collected by: SAME

Truck No.

Sample Source: MH F MH 14 F-6A1

Sampling Location: NEXT TO FLUID WALL AT MULLANPHY

Reason for sample: TO DETERMINE IF PCB'S PRESENT

☐ Trunk ☐ Sanitary ☐ Stream ☐ Storm ☐ Seepage ☐ STP ☐ Hauler

☐ Industry ☐ Other (explain)

Analysis: except as noted ☐ mg/L ☐ ug/L ☐ mg/kg ☐ % comp ☐ other

☐ pH	(units)	☐ F		☐ Hg	
☐ SPC	(umhos/cm)	☐ Cl		☐ As	
☐ ALK		☐ CN		☐ Ba	
☐ ACI		☐ CNA		☐ Be	
☐ TS		☐ KJN		☐ Cd	
☐ SS		☐ NH_3		☐ Cr	
☐ VSS		☐ NO_3		☐ Cu	
☐ %V		☐ NO_2		☐ Fe	
☐ SET	(ml/L)	☐ PHT		☐ Pb	
☐ GRE		☐ PHO		☐ Ni	
☐ BOD		☐ SO_4		☐ Se	
☐ COD		☐ SO_3		☐ Ag	
☐ TOC		☐ S		☐ Zn	
☐ PHE		☐ SUR		☐ Tl	
☐		☐		☐ Sb	
☐		☐		☐	
☐		☐		☐	
☐ Color:		☐ Cr^{+6}		☐	

☐ Odor: ☐ Tot. Hardness

☐ Appearance: ☐ Tot. Chlorine

☐ Organics ☐ IR ☐ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☒ ID

☐ Biological: ☐ Bioassay: ☐ Total Coli: No./100ml

☐ Fecal Coli: No./100ml

☐ Microscopic: ☐ FecalStrep: No./100ml

Remarks: CHECK FOR PCB'S

Date Transmitted: 8/17/93 by: MARIO J. DEPRIM

75 - DEC/LAB

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
INSTRUMENTATION ANALYSIS

Lab. No. 888 Sample Source: Manhole F-6A1 (#14) Date Received 8/9/93

Sample Date 8/9/93 Time: 0825 ☒ Grab ☐ Comp Collected by:

☒ IR ☒ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☐ TLC ☐

☐ **Priority Pollutant** mg/L (except as noted)

☐ **VOLATILES:**

	acrolein	
	acrylonitrile	
X	benzene	<1.0
	bromodichloromethane	
	bromoform	
	bromomethane	
	carbon tetrachloride	
	chlorobenzene	
	chloroethane	
	2-chloroethyl vinyl ether	
	chloroform	
	chloromethane	
	dibromochloromethane	
	1,2-dichlorobenzene	
	1,3-dichlorobenzene	
	1,4-dichlorobenzene	
	1,1-dichloroethane	
	1,2-dichloroethane	
	1,1-dichloroethene	
	trans-1, 2-dichloroethene	
	1,2-dichloropropane	
	1, 3-dichloropropene, cis	
	1, 3-dichloropropene, trans	
X	ethyl benzene	[illegible]
	methylene chloride	
	1,1,2,2-tetrachloroethane	
	tetrachloroethene	
X	toluene	<1.
	1,1,1-trichloroethane	
	1,1,2-trichloroethane	
	trichloroethene	
	vinyl chloride	

☐ **ACIDS:**

	4-chloro-3-methylphenol	
	2-chlorophenol	
	2,4-dichlorophenol	
	2,4-dimethylphenol	
	4, 6-dinitro-2-methylphenol	

ACIDS: (Cont'd)

	2,4-dinitrophenol	
	2-nitrophenol	
	4-nitrophenol	
	pentachlorophenol	
	phenol	
	2,4,6-trichlorophenol	

☐ **BASE/NEUTRALS**

	acenaphthene	
	acenaphthylene	
	anthracene	
	benzidine	
	benzo(a)anthracene	
	benzo(a)pyrene	
	benzo (b) fluoranthene	
	benzo (q,h,i) perylene	
	benzo (k) fluoranthene	
	bis (2-chloroethoxy) methane	
	bis (2-chloroethyl) ether	
	bis (2-chloroisopropyl) ether	
	bis (2-ethylhexyl) phthalate	
	4-bromophenyl phenyl ether	
	butyl benzyl phthalate	
	2-chloronaphthalene	
	4-chlorophenyl phenyl ether	
	chrysene	
	dibenzo (a,h) anthracene	
	3,3-dichlorobenzidine	
	diethyl phthalate	
	dimethyl phthalate	
	di-n-butyl phthalate	
	di-n-octyl phthalate	
	2,4-dinitrotoluene	
	2,6-dinitrotoluene	
	1,2-diphenylhydrazine	
	fluoranthene	
	fluorene	
	hexachlorobenzene	
	hexachlorobutadiene	

BASE/NEUTRALS: (Cont'd)

	hexachlorocyclopentadiene	
	hexachloroethane	
	indeno (1,2,3-cd) pyrene	
	isophorone	
	naphthalene	
	nitrobenzene	
	N-nitrosodimethylamine	
	N-nitrosodi-n-propylamine	
	N-nitrosodiphenylamine	
	phenanthrene	
	pyrene	
	2,3,7,8-tetrachlorodibenzo-p-dioxin	
	1,2,4-trichlorobenzene	

☐ **PESTICIDES:**

	aldrin	
	alpha-BHC	
	beta-BHC	
	gamma-BHC	
	delta-BHC	
	chlordane	
	4,4'-DDD	
	4,4-DDE	
	4,4-DDT	
	dieldrin	
	alpha-endosulfan	
	beta-endosulfan	
	endousulfan sulfate	
	endrin	
	endrin aldehyde	
	heptachlor epoxide	
	heptachlor	
X	PCB-1016	<1.0
X	PCB-1221	↓
X	PCB-1232	↓
X	PCB-1242	↓
X	PCB-1248	<1.0
X	PCB-1254	36.6
X	PCB-1260	<1.0
	toxaphene	

☐ Gas Chromatography results: Run Method 203 on Volatiles

GC/FID resembles Diesel Fuel

☐ Thin-Layer Chromatography results:

☐ Appearance:

☒ Infrared Spectroscopy (a) methods utilized: Smear test

(b) results: 2920 cm⁻¹ - Strong - Triplet
1460 cm⁻¹ - Moderate - Singlet
1380 cm⁻¹ - Moderate - Singlet
1600 cm⁻¹ - Moderate - Singlet

☐ Odor:

☐ API Gravity:

☐ Solubilities:

☐ Distillation Range:

☐ Flash Point:

☐ Ultraviolet/Visible Spectroscopy results:

☐

☐ Special Tests: (specify)

Conclusions Infrared spectra and GC/FID resemble Diesel Fuel.

Date Transmitted: 8/13/93 by: Daniel Florida

64-130WW

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
INSTRUMENTATION ANALYSIS

Lab. No. 434 Sample Source: UST Brooklyn & Mound Date Received 7/15/93

Sample Date 7/14/93 Time: _____ ☒ Grab ☐ Comp Collected by: _____

☒ IR ☒ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☐ TLC ☐ _____

☐ **Priority Pollutant** mg/L (except as noted)

☐ **VOLATILES:**

- acrolein
- acrylonitrile
- benzene
- bromodichloromethane
- bromoform
- bromomethane
- carbon tetrachloride
- chlorobenzene
- chloroethane
- 2-chloroethyl vinyl ether
- chloroform
- chloromethane
- dibromochloromethane
- 1,2-dichlorobenzene
- 1,3-dichlorobenzene
- 1,4-dichlorobenzene
- 1,1-dichloroethane
- 1,2-dichloroethane
- 1,1-dichloroethene
- trans-1, 2-dichloroethene
- 1,2-dichloropropane
- 1, 3-dichloropropene, cis
- 1, 3-dichloropropene, trans
- ethyl benzene
- methylene chloride
- 1,1,2,2-tetrachloroethane
- tetrachloroethene
- toluene
- 1,1,1-trichloroethane
- 1,1,2-trichloroethane
- trichloroethene
- vinyl chloride

☐ **ACIDS:**

- 4-chloro-3-methylphenol
- 2-chlorophenol
- 2,4-dichlorophenol
- 2,4-dimethylphenol
- 4, 6-dinitro-2-methylphenol

ACIDS: (Cont'd)

- 2,4-dinitrophenol
- 2-nitrophenol
- 4-nitrophenol
- pentachlorophenol
- phenol
- 2,4,6-trichlorophenol

☐ **BASE/NEUTRALS**

- acenaphthene
- acenaphthylene
- anthracene
- benzidine
- benzo(a)anthracene
- benzo(a)pyrene
- benzo (b) fluoranthene
- benzo (q,h,i) perylene
- benzo (k) fluoranthene
- bis (2-chloroethoxy) methane
- bis (2-chloroethyl) ether
- bis (2-chloroisopropyl) ether
- bis (2-ethylhexyl) phthalate
- 4-bromophenyl phenyl ether
- butyl benzyl phthalate
- 2-chloronaphthalene
- 4-chlorophenyl phenyl ether
- chrysene
- dibenzo (a,h) anthracene
- 3,3-dichlorobenzidine
- diethyl phthalate
- dimethyl phthalate
- di-n-butyl phthalate
- di-n-octyl phthalate
- 2,4-dinitrotoluene
- 2,6-dinitrotoluene
- 1,2-diphenylhydrazine
- fluoranthene
- fluorene
- hexachlorobenzene
- hexachlorobutadiene

BASE/NEUTRALS: (Cont'd)

- hexachlorocyclopentadiene
- hexachloroethane
- indeno (1,2,3-cd) pyrene
- isophorone
- naphthalene
- nitrobenzene
- N-nitrosodimethylamine
- N-nitrosodi-n-propylamine
- N-nitrosodiphenylamine
- phenanthrene
- pyrene
- 2,3,7,8-tetrachlorodibenzo-p-dioxin
- 1,2,4-trichlorobenzene

☐ **PESTICIDES:**

- aldrin
- alpha-BHC
- beta-BHC
- gamma-BHC
- delta-BHC
- chlordane
- 4,4'-DDD
- 4,4-DDE
- 4,4-DDT
- dieldrin
- alpha-endosulfan
- beta-endosulfan
- endousulfan sulfate
- endrin
- endrin aldehyde
- heptachlor epoxide
- heptachlor

X	PCB-1016	<1.0
X	PCB-1221	<1.0
X	PCB-1232	<1.0
X	PCB-1242	<1.0
X	PCB-1248	<1.0
X	PCB-1254	39.0
X	PCB-1260	<1.0
	toxaphene	

☐ Gas Chromatography results: _____

☐ Thin-Layer Chromatography results: _____

☒ Appearance: Dark oil

☒ Infrared Spectroscopy (a) methods utilized: Smear test

(b) results: 2920 – Strong – Triplet
1460 – Moderate – Singlet
1380 – Moderate – Singlet

☒ Odor: Gasoline & Oil

☐ API Gravity: _____

☐ Solubilities: _____

☐ Ultraviolet/Visible Spectroscopy results: _____

☐ Distillation Range: _____

☐ Flash Point: _____

☐ _____

☐ Special Tests: (specify)

Conclusions Infrared spectra on Samples # 434 and #270 are similar.

Date Transmitted: 7/19/93 by: Daniel Florida

64-130WW

MSD ENVIRONMENTAL COMPLIANCE LABORATORY
INSTRUMENTATION ANALYSIS

Lab. No. 270 Sample Source: Wet Well Date Received 7-9-93

Sample Date 7-8-93 Time: _____ ☐ Grab ☐ Comp Collected by: _____

☒ IR ☐ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☐ TLC ☐ _____

☐ **Priority Pollutant** mg/L (except as noted)

☐ **VOLATILES:**

- acrolein
- acrylonitrile
- benzene
- bromodichloromethane
- bromoform
- bromomethane
- carbon tetrachloride
- chlorobenzene
- chloroethane
- 2-chloroethyl vinyl ether
- chloroform
- chloromethane
- dibromochloromethane
- 1,2-dichlorobenzene
- 1,3-dichlorobenzene
- 1,4-dichlorobenzene
- 1,1-dichloroethane
- 1,2-dichloroethane
- 1,1-dichloroethene
- trans-1, 2-dichloroethene
- 1,2-dichloropropane
- 1, 3-dichloropropene, cis
- 1, 3-dichloropropene, trans
- ethyl benzene
- methylene chloride
- 1,1,2,2-tetrachloroethane
- tetrachloroethene
- toluene
- 1,1,1-trichloroethane
- 1,1,2-trichloroethane
- trichloroethene
- vinyl chloride

☐ **ACIDS:**

- 4-chloro-3-methylphenol
- 2-chlorophenol
- 2,4-dichlorophenol
- 2,4-dimethylphenol
- 4, 6-dinitro-2-methylphenol

ACIDS: (Cont'd)

- 2,4-dinitrophenol
- 2-nitrophenol
- 4-nitrophenol
- pentachlorophenol
- phenol
- 2,4,6-trichlorophenol

☐ **BASE/NEUTRALS**

- acenaphthene
- acenaphthylene
- anthracene
- benzidine
- benzo(a)anthracene
- benzo(a)pyrene
- benzo (b) fluoranthene
- benzo (g,h,i) perylene
- benzo (k) fluoranthene
- bis (2-chloroethoxy) methane
- bis (2-chloroethyl) ether
- bis (2-chloroisopropyl) ether
- bis (2-ethylhexyl) phthalate
- 4-bromophenyl phenyl ether
- butyl benzyl phthalate
- 2-chloronaphthalene
- 4-chlorophenyl phenyl ether
- chrysene
- dibenzo (a,h) anthracene
- 3,3-dichlorobenzidine
- diethyl phthalate
- dimethyl phthalate
- di-n-butyl phthalate
- di-n-octyl phthalate
- 2,4-dinitrotoluene
- 2,6-dinitrotoluene
- 1,2-diphenylhydrazine
- fluoranthene
- fluorene
- hexachlorobenzene
- hexachlorobutadiene

BASE/NEUTRALS: (Cont'd)

- hexachlorocyclopentadiene
- hexachloroethane
- indeno (1,2,3-cd) pyrene
- isophorone
- naphthalene
- nitrobenzene
- N-nitrosodimethylamine
- N-nitrosodi-n-propylamine
- N-nitrosodiphenylamine
- phenanthrene
- pyrene
- 2,3,7,8-tetrachlorodibenzo-p-dioxin
- 1,2,4-trichlorobenzene

☐ **PESTICIDES:**

- aldrin
- alpha-BHC
- beta-BHC
- gamma-BHC
- delta-BHC
- chlordane
- 4,4'-DDD
- 4,4-DDE
- 4,4-DDT
- dieldrin
- alpha-endosulfan
- beta-endosulfan
- endousulfan sulfate
- endrin
- endrin aldehyde
- heptachlor epoxide
- heptachlor
- ☒ PCB-1016 <1.0
- ☒ PCB-1221
- ☒ PCB-1232
- ☒ PCB-1242
- ☒ PCB-1248 <1.0
- ☒ PCB-1254 ~~19.5~~ 47.0
- ☒ PCB-1260 <1.0
- toxaphene

☐ Gas Chromatography results: _____

☐ Thin-Layer Chromatography results: _____

☒ Appearance: Dark oil

☒ Infrared Spectroscopy (a) methods utilized: Smear test

(b) results: 2920 cm⁻¹ - Triplet - Strong
1460 cm⁻¹ - Singlet - Moderate
1380 cm⁻¹ - Singlet - Moderate

☒ Odor: Gasoline

☐ API Gravity: _____

☐ Solubilities: _____

☐ Ultraviolet/Visible Spectroscopy results: _____

☐ Distillation Range: _____

☐ Flash Point: _____

☐ _____

☒ Special Tests: (specify) Dexsil "Clor-n-Oil" PCB screening Kit 1/50 Dilution > 50ppm PC

Conclusions Infrared Spectra on Sample # 0434 and #270 are similar.

Date Transmitted: 7/19/93 by: Daniel Florida

64-130WW

SURVEILLANCE SECTION

ACTION MEMO

INDUSTRIAL WASTE DIVISION

TO: H. Edmond

FILE DISPOSITION: SPECIAL PROBLEM [X] ROUTINE IND. INVES. [ ] GENERAL MEMO [ ]

FROM: L. Perreis

SUBJECT: Mullanphy St Outfall (Wharf)

DATE: 2/16/82 TIME:

SPECIAL INSTRUCTIONS: Investigate report of oil slick in river from Mullanphy st. outfall. - check apex Oil see attached report. Report findings to coast guard. Determine source + have discharge stopped.

CONTACT PERSON: Lt. Ennis Coast Guard TEL. NO.: 425-4657

RESULTS OF INVESTIGATION: 2/16/82 Met BM3 Al Robinson and QM3 Mark Winkler The film on water coming from outfall was very light. Coast Guard and I felt that this is due to street run-off Gave copy of report to Coast Guard (H. Edmore)

FOLLOW-UP REQUIRED YES [ ] NO [ ]

SIGNED:

cc of Final Report To:

64-136

MEMO TO: B. A. Rains

FROM: B. Schuchman

SUBJECT: Oil Spill

DATE: January 7, 1975

On Monday, January 6, 1975 at 16:00 hours, I was instructed by Bill Breidenbach to join the U.S.C.G. at the foot of Mullanphy Street in regards to a large oil spill. Upon arriving at the scene I found Ensign Taylor, BMI O'Neil and two other U.S.C.G. personnel present and boarding a petroleum barge in the fleet tie-up area at the foot of Mound Street. Together we inspected the Apex Oil Facility at Mullanphy and Wharf Street. It was here where we located the source of the Heavy Bunker class oil. Of the six huge storage tanks at this facility, the Southeast tank had overflowed during a recent fuel transfer. We also located in the burm area a rain water drain which drains to a trench which in turn runs into a catch basin attached to the storm drain on Wharf Street. At 16:50 hours Bill Breidenbach relieved me.

On Tuesday, January 7, 1975, I was instructed to meet with the U.S.C.G. to dye the catch basin and storm sewer at the Northwest corner of Mullanphy and Wharf to locate the discharge point of the line to the Mississippi River. With the assistance of MSD Crew 55 we opened a fire hydrant to speed the flow of water. Approximately 1000 gals. of water was introduced as a vehicle, along with a liter of Rhodamine Red Dye, at 10:15 hours. At approximately 11:00 hours the crew of 55 and myself located the outfall. The outfall lies buried beneath bank Rip-Rap at Florida Street. The Rhodamine Dye was observed flowing freely and entering the Mississippi River at this point (M.M. 180.5 approx.).

I issued a written statement, at the U.S.C.G. request, to this effect, "Heavy Black Oil was noted in both the catch basin and storm sewer. This line was dyed and the Dye appeared at the foot of Florida Street entering the Mississippi River."

At 11:10 hours I concluded the Dye investigation.

cc: B. Breidenbach


17
18
19
20
Joins
Page 26
27
H
G
F
E
D
Joins Page 38
Copyright 1980
St. Louis Area Maps, Inc.
RIVER
WATER WORKS
RESERVOIR
FAIRGROUND PARK
NATURAL BRIDGE
ST LOUIS
MONTGOMERY
NORTH MARKET
MADISON
MULLANPHY
CHAMBERS
BROOKLYN
CLINTON
TYLER
CASS
CARR
WASHINGTON
LACLEDE
MARKET
FRANKLIN
COCHRAN
WEST PINE
LINDELL
OLIVE
ST CHARLES
VETERANS BRIDGE EADS
BRANCH
NORTH MARKET
CLINTON
MADISON
CHAMBERS
TYLER
BROOKLYN
MOUND
MULLANPHY
FLORIDA
SMITH
DICKSON
O'FALLON
ASHLEY
BIDDLE
CARR
COLUMBUS
BROADWAY
WAB RR
TERM RY
INTERSTATE 70
ST L BELT
CB & Q RR
RIVER FRONT
PENROSE
ANGELICA
BREMEN
HYDE PARK
SALISBURY
MALLINCKRODT
GARDEN
AGNES
HERDER
BUCHANAN
ANGELROOT
DESTREHAN
KLEIN
BLAIR
FARRAR
NEWHOUSE
BENJAMIN
FARRAGUT
PENROSE
ANGELICA
NEWHOUSE
BISSELL
FERRY
PROCTOR
BROADWAY
EAST GRAND
STURGEON
RANDALL
PRAIRIE
GANO
JOHN
OBEAR
PECK
PLEASANT
GROVE
BAILEY
BARRETT
HARPER
PARNELL
LISMORE
HEBERT
SULLIVAN
DODIER
UNIVERSITY
ST LOUIS
MONTGOMERY
WARREN
BENTON
MAIDEN
HOWARD
MAGAZINE
MADISON
GLASGOW PL
BRANTNER
SHERIDAN
THOMAS
DICKSON
DAYTON
GAMBLE
PARK
STODDARD
MILLS
CARVER
COLE
MARTIN LUTHER KING
DELMAR BL
LUCAS
LINDEN
GAY
LOCUST
PINE
SUGAR
MAPLE KNOLL
CLARK
MARKET
FEDERAL BLVD
EUGENIA
SCOTT
BERNARD
CLAYTON
SARPY
FOREST
DUNCAN
PARK
VANDEVENTER
WEST PINE
LACLEDE
MARKET
LINDELL
WASHINGTON
LUCAS
LOCUST
COLLEGE
RED MAPLE
WYTON PL
LACLEDE
MARKET
COCHRAN
WINDSOR PL
ALPHONSUS
RED FOX
WEST BELLE PL
ENRIGHT
DELMAR
WASHINGTON
OLIVE
WESTMINISTER
MC PHERSON
LINDELL
FRANKLIN
SCHOOL
BELL
GRANDELL SQ
CARPENTER
CLARKSON
CULVER WAY
FAIRFAX
FINNEY
COOK
EVANS
PAGE BLVD
MARTIN LUTHER KING DR
COTE BRILLIANTE
N MARKET
ST FERDINAND
LINCOLN
COTTAGE
SARAH
WHITTIER
GARFIELD
ALDINE
ENDLETON
NEWSTEAD
TAYLOR
PENDLETON WAY
MARNICE
LAMBOIN
NEW ASHLAND
ROLLA PL
FAIR
CLAY
LABADIE
SULLIVAN
GREER
HEBERT
HYAMS
PALM
LEXINGTON
ASHLAND
ELM BANK
PALM
LEXINGTON
SACRAMENTO
SAN FRANCISCO
MARGARETTA
FARLIN
LEE
TURNER
ROSH PL
ATHLONE
HARRIS
PENROSE
KOSSUTH
LEA
CLAY
HULL
SHERMAN PL
GREENLEE PL
ADELAIDE
ALICE
WARNE
FLORISSANT
LINTON
DE SOTO
PRAIRIE
LEE
GANO
JOHN
OBEAR
GRAND
PECK
PLEASANT
GROVE
BAILEY
HARPER
PARNELL
LISMORE
GLASGOW
GARRISON
DODIER
UNIVERSITY
GREER
FALL
GRAND BLVD
SPRING
PRAIRIE
VANDEVENTER
WARNE
LINCOLN
SARAH
WHITTIER
GLADE
GOODE
GARFIELD
ALDINE
MARTIN LUTHER KING DR
COZENS
EVANS
KRUM
RED FOX
JONES
GRANT CT
WINDSOR PL
ALPHONSUS
CARPENTER
CLARKSON
SPRING
GRANDELL SQ
CULVER WAY
FAIRFAX
WEST BELLE PL
ENRIGHT
DELMAR
WASHINGTON
OLIVE
MC PHERSON
LINDELL
WEST
THERESA
CHANNING
LEONARD
COMPTON
LUTHER KING
BELL
RED FOX
DELMAR BLVD
LUCAS
WEBSTER
CARDINAL
COLLEGE
RED MAPLE
WYTON PL
LACLEDE
MARKET
SPRING
CLARK
GRAND
FOREST
VANDEVENTER
PARK
DUNCAN
MARKET
CLAYTON
SARPY
BERNARD
SCOTT
CLARK
EVANS
BRANTNER
SHERIDAN
THOMAS
MARTIN
COLEMAN
LAFIN
BACON
SLATTERY
BALDWIN
BENTON
YEATMAN
MAGAZINE
MADISON
GLASGOW PL
GARRISON
GLASGOW
LEFFINGWELL
DICKSON
DAYTON
GAMBLE
PARK
STODDARD
MILLS
CALL ST
BEAUMONT
JEFFERSON
HOWARD
MONTGOMERY
ST LOUIS
PARNELL
LISMORE
HEBERT
SULLIVAN
DODIER
UNIVERSITY
ST LOUIS
MONTGOMERY
WARREN
BENTON
MAIDEN
HOWARD
MULLANPHY
KNAPP
HELEN
HOGAN
RAUSCHENBACH
ST LOUIS PARK
FLORISSANT
BLAIR
MARION
JACKSON
MONROE
WALT BOWERS
MADISON
CLINTON
TYLER
CHAMBERS
BROOKLYN
MOUND
HOWARD
MULLANPHY
HADLEY
CASS
FALLON
DIVISION
CARR
COLE
CARVER
MARTIN LUTHER KING
ATCHISON
BIDDLE
COLUMBUS
DELMAR BL
LUCAS
LINDEN
GAY
LOCUST
ST CHARLES
WASHINGTON
OLIVE
EXPRESS WAY
EUGENIA
MARKET
FEDERAL BLVD
BROADWAY
WADDINGHAM
COLLINS
BIDDLE
CARR
ASHLEY
O'FALLON
DICKSON
SMITH
FLORIDA
BROADWAY
HEMPSTEAD
LA BEAUME
BROOKLYN
MOUND
MULLANPHY
BRANCH
NORTH MARKET
CLINTON
MADISON
CHAMBERS
TYLER
WAB
VETERANS BRIDGE EADS
VINE


MATCH LINE - STA. 9+00
MULLANPHY
59'W. ST.
COAL BIN
8" DIA. PLUMB HOLE @ STA. 10+00
(ABANDONED)
6"P
6"W
6"G
5'6"
17'
18'
1'
CURB
INLET L.S.
U.E.M.H.
SIG. STD.
6"W
24"G
10"G
4"G
6"G
W.M.H.
BIT. MAC. PAV'T OVER GRANITE
U.E.M.H.
CURB
P.P.
INLET
M.H.
SIG. BOX
SIGNAL STAND 1-ST'Y
BR. BLDG.
8.M. - ELEV. 446.39
□ CUT ON N.E. CORNER OF BLDG.
CHAIN LINK FENCE
C.B. & Q. R.R. TRACKS
2½" x 3½"
T.R.
#118
SIG. BOXES
SURVEY LINE & ℄ 90"x90" TUNNEL
P.P.
FIR

SURVEILLANCE SECTION

ACTION MEMO

INDUSTRIAL WASTE DIVISION

TO: D. Fuller

FROM: L. Powers

FILE DISPOSITION: SPECIAL PROBLEM [X] ROUTINE IND. INVES. [ ] GENERAL MEMO [ ]

SUBJECT: 21 Brooklyn (Continental Conc.)

DATE: 3/4/83 TIME:

SPECIAL INSTRUCTIONS: Investigate report of chemical subst. draining from RR yard across parking lot to sewer on above facility.

CONTACT PERSON: Mr. Tannehill TEL. NO.:

RESULTS OF INVESTIGATION: On March 4, 1983 I made a site visit to Brooklyn St. I found a flow of 50 GPM going to our sewer on Tyler. I traced the flow to the base of the retaining wall on Mound St. and collected a sample.

On March 17, 1983 I returned with MSD Crew #111. We checked the sewers in the area. The seepage was coming from a 15" main which collapsed. Mike Merlin the crew leader said he would begin repair proceedings immediately.

FOLLOW-UP REQUIRED YES [ ] NO [X]

SIGNED: D. Fuller

cc of Final Report To:

HL 3/18/83

64-136

MSD Industrial Waste Laboratory
Special Sample Form

Lab. No. 4349 ☐ Comp ☒ Grab Date Received 4 MARCH 83

Sample Date: 4 MARCH '83 Sample Time: 15:45 to

Requested by: L. POWERS Collected by: D. FULLER

Truck No.

Sample Source: GROUND WATER

Sampling Location: BROOKLYN ST & RR TRACKS

Reason for sample: COMPLAINT

☐ Trunk ☐ Sanitary ☐ Stream ☐ Storm ☒ Seepage ☐ STP ☐ Hauler

☐ Other (explain)

Analysis: except as noted ☐ mg/L ☐ ug/L ☐ mg/kg ☐ % comp ☐ other

☒ pH	4.8 (units)	☐ F		☐ Hg	
☐ SPC	(umhos/cm)	☐ Cl		☐ As	
☒ ALK	548	☐ CN		☐ Ba	
☐ ACI		☐ CNA		☐ Be	
☐ TS		☐ KJN	4/4/1983 INCIDE A SITE VISIT	☐ Cd	
☐ SS		☐ NH_3	LOW OF 50 GPM GOING TO OUR	☐ Cr	
☐ VSS		☐ NO_3	THE FLOW	☐ Cu	
☐ %V		☐ NO_2		☐ Fe	THE BASE OF THE
☐ SET	(ml/L)	☐ PHT		☐ Pb	
☐ GRE		☐ PHO	AND COLLECTED A SAMPLE.	☐ Ni	
☐ BOD	ON MARCH 17, 1983	☐ SO_4	RETURNED W.	☐ Se	MSD CREW #111.
☒ COD	2100	☐ SO_3		☐ Ag	
☐ TOC		☐ S		☐ Zn	
☐ PHE		☐ SUR		☐ Tl	
☐		☐		☐ Sb	
☐		☐		☐	
☐		☐		☐	
☐ Color:		☐ Cr^{+6}		☐	

WE CHECKED THE SEWERS IN THE AREA. THE SEEPAGE WAS COMING FROM A 15" MAIN WHICH COLLAPSED. MIKE MERLIN THE CREW LEADER SAID HE WOULD BEGIN REPAIR PROCEEDINGS IMMEADIATELY.

☒ Odor: YEAST-LIKE ☐ Tot. Hardness

☐ Appearance: ☐ Tot. Chlorine

☐ Organics: ☐ IR ☐ GC ☐ LEL ☐ RAD ☐ UV ☐ FLUOR ☐ ID

☐ Biological: ☐ Coliform: ☐ Total: No./100ml

☐ Fecal: No./100ml

☐ Microscopic: ☐ Bioassay: ☐ Fecal Strep: No./100ml

Remarks:

D. Fuller

Date Transmitted: 3/9/83 by: [signature]

64 — 140WW


P-13330
Burlington Railroad
N BROADWAY ST
HEMPSTEAD ST
BROOKLYN ST
MOUND ST
N 8TH ST
HOWARD ST
N 7TH ST
MULLANPHY ST
FLORIDA ST
CASS AV
N 2ND ST
DICKSON ST
NOT NAMED
Terminal Railroad
P-2350
P-5628
P-9009
P-3900
656
655
654
607
606
605
VAC. ORD.