
PIC 89790
FRAME 4
PREVIOUS LOCATION OF POND
EROSION
DEMOLISHED BUILDINGS
TAILINGS
DEMOLISHED BUILDINGS
EROSION
DISCHARGE PIPE
TAILINGS
SPILLWAY
DISCHARGE PIPE
GATE
Tollar
Branch
DRAINAGE DITCH
DISCHARGE PIPES
PIPELINE
TAILINGS
MOUNDED MATERIAL
BERM/DIKE
FENCE
DRAINAGE
EPA Environmental Monitoring Systems Laboratory-Las Vegas
MADISON MINE
FREDRICKTOWN, MISSOURI
PIC 89790
DATE FLOWN: MAY 2, 1989
SOURCE: EMSL FRAME NO. 4
APPROX. SCALE 1 inch = 190 feet
(2 OF 3)
N
30096581
Superfund