RAYMARK INDUSTRIES, INC

Manheim, P.



BCM Project No. 00-4174-23

PHOTOGRAPH INDEX MAP

Raymark Industries, Inc.

P-1 View to West. Uncovered Waste Eroding from the Landfill.



Raymark Industries, Inc.

P-2 View to West. Exposed waste material on bench at base of landfill

Raymark Industries, Inc.

P-3 View to SE. Waste material beyond containment fence.

Raymark Industries, Inc.

P-4 View to N. Exposed waste at edge of the landfill.

Raymark Industries, Inc.

P-5 View W. toward RR Track.
Uncovered waste.



Raymark Industries, Inc.

P-6 View S. Waste in swale along base of RR embankment.



Raymark Industries, Inc.

P-7 View S. from asphalt covered landfill. Manheim Auto auction cars.



Raymark Industries, Inc.

P-8 View to NW. Soil covered landfill. Erosion of cover material.