# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|---|---|---|---|---|---|---|---|
| S1028-073 | Smoke | 9/9/2008 | ADS/TM | S15YY_006MH | Dry | Yes | 1,569.92 |



# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|---|---|---|---|---|---|---|---|
| S1028-073 | Smoke | 9/9/2008 | ADS/TM | S15YY_006MH | Dry | Yes | 1,569.92 |

### Isolated Pipes

| Pipe ID | Upstream MH | Downstream MH | Length (ft) | Diameter (In) |
|---|---|---|---|---|
| S15YY_013G1 | S15YY_013MH | S15YY_010MH | 338.3036 | 8 |
| S15YY_015G1 | S15YY_015MH | S15YY_006MH | 73.34718 | 8 |
| S15YY_010G1 | S15YY_010MH | S15YY_025MH | 144.9348 | 8 |
| S15YY_020G1 | S15YY_020MH | S15YY_010MH | 272.0655 | 8 |
| S15YY_028G1 | S15YY_028DE | S15YY_006MH | 78.91200 | 8 |
| S15YY_019G1 | S15YY_019MH | S15YY_026MH | 76.47563 | 8 |
| S15YY_029G1 | S15YY_029DE | S15YY_026MH | 79.89445 | 8 |
| S15YY_026G1 | S15YY_026MH | S15YY_013MH | 278.7302 | 8 |
| S15YY_006G1 | S15YY_006MH | S15YY_020MH | 227.2553 | 8 |

### Observations & Photos

**Obs_ID** S1028-073-OB01
**Address** 2815 Hilldale Ave
**Status** Private
**Source** Cleanout
**Location** Yard - back
**Nearest MH** S15YY_013MH
**Comments** Smoke from cleanout in back yard. 2815 Hilldale Ave

**Picture** \S1028-073-OB01-P01.jpg
**Comments** Back of house, 2815 Hilldale Ave

**Obs_ID** S1028-073-OB02
**Address** 2801 Norfolk Ave
**Status** Private
**Source** Cleanout
**Location** Yard - back
**Nearest MH** S15YY_006MH
**Comments** Smoke from cleanout in back yard. 2801 Norfolk Ave.

**Picture** \S1028-073-OB02-P01.jpg
**Comments** Back of house, 2801 Norfolk Ave.

# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|---|---|---|---|---|---|---|---|
| S1028-073 | Smoke | 9/9/2008 | ADS/TM | S15YY_006MH | Dry | Yes | 1,569.92 |

**Obs_ID** S1028-073-OB03

**Address** 2803 Norfolk Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S15YY_006MH

**Comments** Smoke from cleanout in back yard. 2803 Norfolk Ave.

**Picture** \S1028-073-OB03-P01.jpg

**Comments** Back of house, 2803 Norfolk Ave.