Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-141	Smoke	11/17/2008	ADS/TM	S11SS1007MH	Dry	Yes	1,057.63



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-141	Smoke	11/17/2008	ADS/TM	S11SS1007MH	Dry	Yes	1,057.63

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11SS1018G1	S11SS1018DE	S11SS1007MH	86.78027	8
S11SS1007G2	S11SS1007MH	S09QQ1012MH	240.8737	8
S11SS1007G1	S11SS1007MH	S11QQ1019MH	275.7660	8
S11QQ1019G1	S11QQ1019MH	S11QQ1011MH	227.0827	8
S11QQ1011G1	S11QQ1011MH	S11QQ1016MH	227.1288	8

Observations & Photos

Obs_ID S1028-141-OB01
Address 5016 Pembridge Ave
Status Private
Source Cleanout
Location Yard - back
Nearest MH S11QQ1011MH
Comments Smoke from cleanout in back yard. 5016 Pembridge Ave.



Picture \S1028-141-OB01-P01.jpg
Comments Back of house, 5016 Pembridge Ave.

Obs_ID S1028-141-OB02
Address 5015 Chalgrove Ave
Status Private
Source Cleanout
Location Yard - back
Nearest MH S11QQ1011MH
Comments Smoke from cleanout in back yard. 5015 Chalgrove Ave.



Picture \S1028-141-OB02-P01.jpg
Comments Back of house, 5015 Chalgrove Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-141	Smoke	11/17/2008	ADS/TM	S11SS1007MH	Dry	Yes	1,057.63

Obs_ID S1028-141-OB03
Address 5110 Pembridge Ave
Status Private
Source Cleanout
Location Yard - back
Nearest MH S11SS1007MH
Comments Smoke from cleanout in back yard. 5110 Pembridge Ave.

Picture \S1028-141-OB03-P01.jpg
Comments Back of house, 5110 Pembridge Ave.

Obs_ID S1028-141-OB04
Address 5123 Chalgrove Ave
Status Private
Source Cleanout
Location Yard - back
Nearest MH S11SS1007MH
Comments Smoke from cleanout in back yard. 5123 Chalgrove Ave.

Picture \S1028-141-OB04-P01.jpg
Comments Back of house, 5123 Chalgrove Ave.