MEMORANDUM

DATE: April 24, 2008

SUBJECT: Inspection Report for Summit, Inc. Addendum
6901 West Chicago Avenue/Industrial Highway, Gary, Indiana 46406

FROM: Sue Rodenbeck Brauer, RCRA Used Oil Expert
CS-2, RCRA Branch, Land and Chemicals Division

THROUGH: Paul Little
Chief, CS-2

TO: Mary S. Setnicar
Acting Chief, CS-1

This memorandum supplements my report of the April 2, 2008 inspection of the Summit Inc. ("Summit") scrap yard at 6901 West Chicago Avenue, Gary, Indiana 46406 ("the facility") for compliance with used oil management standards for used oil generators. On April 18, 2008, I observed and photographed the exterior of Summit, Inc. along Industrial Highway. These April 18, 2008 photographs document observations of the north side of the privacy fence near the locations of photographs 10 to 16 taken on the south side of the fence on April 2, 2008. Regarding the extent of oil-stained vegetation and soil, the wet ground on the north side of the privacy fence was not oil stained as far southeast as the pond pictured in the April 2, 2008 photo 17.

Date: April 18, 2008
Location: Summit Inc., 6901 W. Chicago Avenue, Gary, Indiana 46406
Camera: disposable
Film: Kodak Max 800 ASA
Compact Disk Image Number: 854430-R-023
Photographer: Sue Rodenbeck Brauer, Region 5 RCRA Used Oil Expert
Description of photograph: This photograph was taken facing northwest. The stoplight is for the intersection of Industrial Highway and Chicago Avenue. Note that the darkened grassy area extends beyond the fence's shadow, toward Industrial Highway on the right.

Date: April 18, 2008
Location: Summit Inc., 6901 W. Chicago Avenue, Gary, Indiana 46406
Camera: disposable
Film: Kodak Max 800 ASA
Compact Disk Image Number: 854430-R-022
Photographer: Sue Rodenbeck Brauer, Region 5 RCRA Used Oil Expert
Description of photograph: This photograph was taken facing southwest and looking down at the oily dirt on the grass. The outer margin of a puddle, apparently on both sides of the fence, is indicated by the oily film on the grass and dirt.

Date: April 18, 2008
Location: Summit Inc., 6901 W. Chicago Avenue, Gary, Indiana 46406
Camera: disposable
Film: Kodak Max 800 ASA
Compact Disk Image Number: 854430-R-021
Photographer: Sue Rodenbeck Brauer, Region 5 RCRA Used Oil Expert
Description of photograph: This photograph was taken facing southeast along Industrial Highway with Summit Inc.'s privacy fence on the right. Additional signs of oil releases are to the southeast of photos 23 and 22 and extend toward Industrial Highway farther than the fence's shadow. The shed where gasoline was removed from cars on April 2, 2008, is visible over the fence.

Date: April 18, 2008
Location: Summit Inc., 6901 W. Chicago Avenue, Gary, Indiana 46406
Camera: disposable
Film: Kodak Max 800 ASA
Compact Disk Image Number: 854430-R-020
Photographer: Sue Rodenbeck Brauer, Region 5 RCRA Used Oil Expert
Description of photograph: This photograph was taken facing southeast and looking down at the oily dirt on the grass. Note the oily waste residue remaining on the ground as the puddle dries up. The width of the puddle in the ditch corresponds to the height of the oil line on the fence. Also, note the space between fence sections allowing flow from one side to the other.



Date: April 18, 2008
Location: Summit Inc., 6901 W. Chicago Avenue, Gary, Indiana 46406
Camera: disposable
Film: Kodak Max 800 ASA
Compact Disk Image Number: 854430-R-019
Photographer: Sue Rodenbeck Brauer, Region 5 RCRA Used Oil Expert
Description of photograph: This photograph was taken facing southwest from the middle of Industrial Highway from a location northeast (perpendicular to the fence) of the photographer's location for taking photo 20.

cc: Spiros Bourgikos
Dale Meyer
Sandra Siler
Richard Clarizio