RISK-BASED REMEDIATION PLAN FOR PCB-CONTAMINATED CONCRETE

SPX LINDBERG FACILITY

304 HART STREET

WATERTOWN, WISCONSIN

DELTA PROJECT NO. 9M0909245

EPA I.D # WIT 560 011 942.

Prepared for:

SPX Corporation
13515 Ballantyne Corporate Place
Charlotte, North Carolina 28277
(704) 752-4430

Prepared by:

Delta Consultants
5910 Rice Creek Parkway, Suite 100
Shoreview, Minnesota 55126
(651) 639-9449

August 11, 2010

TABLE OF CONTENTS

1.0 INTRODUCTION 1
1.1 Purpose 1
1.2 Background Information 1

2.0 NATURE OF CONTAMINATION 2
2.1 PCB Wipe Sampling 3
2.2 PCB Bulk Concrete Sampling 4

3.0 CLEANUP PLAN 6
3.1 Bulk PCB Remediation Waste Removal and Disposal 7
3.2 Continued Use Authorization 8
3.2.1 PCB Source Control 8
3.2.2 Decontamination and Coating Methods 9
3.2.3 Disposal 10
3.3 Subpart S Cleaning 10
3.4 Schedule 11

4.0 RECORDKEEPING 11

5.0 REMARKS 12

List of Tables

Table 1 PCB Wipe Sample Analytical Results
Table 2 PCB Bulk Concrete Analytical Results

List of Figures

Figure 1 Site Location Map
Figure 2 PCB Wipe Sample Results Map
Figure 3 Concrete Sample Location Map
Figure 4 PCB Results – 0-1 Inch
Figure 5 PCB Results – Deeper Samples
Figure 6 Proposed Areal Extent of Remediation
Figure 7 Proposed Remediation Methods

List of Appendices

Appendix A Photograph Log
Appendix B Wipe Sample Analytical Reports
Appendix C Bulk Concrete Sample Analytical Reports
(Contained on CD in rear cover)

RISK-BASED REMEDIATION PLAN FOR
PCB-CONTAMINATED CONCRETE

SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN
DELTA PROJECT NO. 9M0909245

1.0 INTRODUCTION

1.1 Purpose

Delta Consultants (Delta), on behalf of SPX Corporation (SPX), is pleased to present this *Risk-based Remediation Plan for PCB-Contaminated Concrete* for management of polychlorinated biphenyl (PCB)-contaminated concrete at the SPX Lindberg facility located at 304 Hart Street in Watertown, Wisconsin (**Figure 1**). The purpose of this report is to fulfill the application requirements of the Environmental Protection Agency (EPA) Toxic Substance Control Act (TSCA) PCB regulations, 40 CFR 761.61(c) *Risk-based disposal approval* for PCB remediation waste. This report presents the following:

- Site characterization data collected to date;
- Proposed cleanup plan for the facility; and
- Plan for future management of the PCB-contaminated soil and concrete.

where to?

Since the proposed cleanup plan includes off-site disposal of PCB remediation waste, engineered controls, and a deed restriction to limit exposure, this Risk-based Remediation Plan is being submitted with the goal of allowing PCB remediation waste to remain at the facility at a concentration of 10 milligrams per kilogram (mg/kg) PCBs.

Deed defaults? (Wisc.?) County...

1.2 Background Information

The SPX Lindberg facility is located 1,000 feet east of the Rock River and immediately south of the Chicago, Milwaukee, St. Paul and Pacific railroad in Watertown, Jefferson County, Wisconsin (**Figure 1**). The subject property consists of approximately 5.3 acres of land that is occupied by an approximately 174,000 square foot manufacturing and office building. The Subject Property is bordered by a storage warehouse and railroad tracks to the north, a JohnsonDiversey (formerly U.S. Chemical Company) facility to the east, Hart Street and a parking lot to the south, and residential buildings to the west.

The subject property was originally developed in the early 1920s as a woodworking/ manufacturing facility. The majority of the current building infrastructure was constructed in the 1950s, when it was occupied by Hevi-Duty Electric Company, a manufacturer of electrical transformers, heat treating furnaces, and hot plates. According to historical documents, the combined operations of transformer and furnace manufacturing were moved to Watertown, Wisconsin in 1953. In 1962, a limited portion of the Watertown facility produced the larger transformers with a maximum rating of 2000 KVA. All transformer production at the facility ended in 1971.

According to Mr. Jeff Raabe, former manufacturing supervisor at the facility and facility employee since 1973, recent operations consisted of the manufacture of a wide array of industrial ovens, refrigeration units, environmental test chambers, industrial manufacturing furnaces, and custom products. Manufacturing operations were terminated at the facility in late 2005. The facility is currently unoccupied and largely vacant and is being placed on the market for sale. The potential future facility use is anticipated to remain industrial.

No PCB releases have been reported or are known to have occurred within the facility. The presence of PCB-contaminated concrete was discovered during routine Phase II Environmental Assessment (EA) activities performed on October 1, 2009, prior to SPX placing the facility up for sale. Sampling activities were performed to evaluate for the potential presence of PCBs on the concrete floor surface. Surface wipe sampling was performed in an approximate 60-foot square-based grid pattern throughout the facility. Of the 49 surface wipe samples collected during the initial testing, five samples indicated PCB concentrations greater than 10 micrograms (µg) per 100 square centimeters (cm^2) total PCBs.

2.0 NATURE OF CONTAMINATION

Between October 2009 and May 2010, Delta has performed six PCB delineation events at the SPX Lindberg facility to assess the extent and magnitude of PCBs on top of and within the concrete floor. These sampling events included both PCB wipe and bulk concrete sampling and occurred on October 1, October 27, and December 28-30, 2009 and January 25-28, March 16-April 2, and May 4-11, 2010. Photographs taken during the sampling events are presented in **Appendix A**.

2.1 PCB Wipe Sampling

In order to initially characterize the horizontal extent of PCBs on the concrete floor surface, a PCB wipe sampling program was performed. A total of 72 wipe samples were collected from the floor in an approximate 60-foot square-based grid pattern throughout the facility. The sample locations are shown on **Figure 2**. No floor coverings were compromised during sample collection; sample locations which were proposed in areas covered with carpeting were moved to the nearest non-carpeted area.

The wipe samples were collected using hexane-preserved sorbent pads provided by Pace Analytical Services, Inc. (Pace). The procedure for obtaining a wipe sample for PCB analysis consisted of rubbing the hexane-soaked pad within a 10 cm by 10 cm (100 cm^2) sample area, using a prescribed wiping pattern that followed the horizontal and vertical axes of the area. The pad was then placed into a 4-ounce amber glass container and the cover was secured tightly on the jar. The wipe samples were submitted to Pace for analysis for PCBs by EPA Method 8082. Laboratory analytical reports for the wipe samples are presented in **Appendix B**.

Analytical results for surface wipe samples are summarized on **Table 1** and **Figure 2**. PCB concentrations ranged from less than the laboratory reporting limit of 1.0 µg per 100 cm^2 to 59.7 µg/100 cm^2. The PCB concentrations were compared against the TSCA PCB surface cleanup standard of 10 µg/100 cm^2. Twenty-six of the wipe samples did not indicate the presence of PCBs. Thirty-six wipe samples contained PCBs at concentrations between 1 and 10 µg/100 cm^2. Ten wipe samples indicated PCB concentrations greater than 10 µg/100 cm^2. These samples included:

26
36
10

- B1 (59.7 µg/100 cm^2) and W3 (13.0 µg/100 cm^2), located near the northeast corner of the "Big Bay" area in the vicinity of a loading area;
- W5 (11.7 µg/100 cm^2), B4 (23.7 µg/100 cm^2), W9 (14.4 µg/100 cm^2), B6 (23.2 µg/100 cm^2), and W10 (10.8 µg/100 cm^2), located along the "Heavy Assembly Materials" storage corridor;
- B7 (11.5 µg/100 cm^2) and W33 (12.4 µg/100 cm^2), located south of the "Heavy Assembly Materials" storage corridor near the old shipping office; and
- A8 (10.4 µg/100 cm^2), located in a loading dock area near the southwest corner of the facility.

According to Mr. Raabe, the "Heavy Assembly Materials" area, an approximately 16-foot wide by 315-foot room located in the west-central portion of the facility, was formerly used

as a staging area for parts and equipment prior to being moved into the product assembly rooms.

2.2 PCB Bulk Concrete Sampling

In order to evaluate whether PCBs have penetrated the concrete floor, 585 bulk concrete samples were collected from 406 locations throughout the facility. The locations of these samples are shown on **Figure 3**.

- Concrete samples B1, B4, B6, B7, and A8 were collected at five locations previously sampled using PCB wipe sampling techniques and exhibiting PCB concentrations exceeding the surface standard of 10 µg/100 cm^2 PCBs.
- Concrete samples 1 through 36 were collected within three areas (the northwest loading area, the southwest loading dock, and the "Heavy Assembly Materials" corridor) previously sampled using PCB wipe sampling techniques and exhibiting PCB concentrations exceeding the surface standard of 10 µg/100 cm^2 PCBs.
- Concrete samples 37 through 171 were collected at approximately 10-foot intervals to expand on the areas where PCB impacted concrete was previously identified at concentrations greater than the bulk concrete standard of 1 mg/kg PCBs.
- Concrete samples 172 through 273 were collected at approximately 20-foot intervals to expand on the areas where PCB impacted concrete was previously identified at concentrations greater than the bulk concrete standard of 1 mg/kg PCBs.
- Concrete samples 274 through 401 were collected at approximately 20-foot intervals throughout the remaining manufacturing portions of the facility.

All manufacturing areas of the facility were sampled with the exception of an 11,000-square foot room in the eastern side and a 1,600-square foot room on the northern side. According to Mr. Raabe, the room on the eastern side was constructed circa 1978, which was after the date that transformer production ended at the facility (1971), and was used for oven assembly. The room to the north was added in the early 1990s and was used as a cutting room.

Bulk concrete samples were collected in general accordance with EPA Region 1 *Standard Operating Procedure for Sampling Concrete in the Field* (December 30, 1997). The sample holes were advanced using a hand-held rotary hammer/impact drill equipped with 1-inch and ½-inch masonry bits. The 0-1 inch sample was collected by advancing a hole into the concrete to a depth of one inch using the 1-inch bit. Concrete dust generated from the

drilling of the sample interval was collected using clean disposable sampling tools and placed into a sample jar. The drill hole was vacuumed thoroughly to prevent cross-contamination between sampling intervals. The hole was further advanced to a depth of either 3 (or 4) inches using the ½-inch bit and the concrete dust was collected for the 1-3 (or 2-4) inch sample. The drill bits were decontaminated between holes using a soap and water solution and potable water rinse. Three to four holes were advanced at each sample location to obtain a sufficient sample weight for analysis. The bulk concrete samples were submitted for laboratory analysis for PCBs by EPA Method 8082. Laboratories utilized throughout this project include Pace Analytical Services (Minneapolis, Minnesota), TestAmerica (Watertown, Wisconsin), and New Age/Landmark Mobile Analytical Services (New Haven, Michigan). Laboratory analytical reports for the bulk concrete samples are presented in **Appendix C**.

Analytical results for the bulk concrete samples are summarized on **Table 2** and **Figures 4 and 5**. PCBs were detected throughout the manufacturing portion of the facility. PCB concentrations in the bulk concrete samples ranged from below the detection limit to 3,310 mg/kg.

The bulk concrete sample PCB concentrations were compared against the EPA cleanup level of 1 mg/kg PCBs for bulk remediation waste in high occupancy (an average of 6.7 hours or more a week) areas. Of the 406 near-surface (0 to 1 inch deep) concrete samples collected, 294 samples exhibited PCB concentrations above 1 mg/kg PCBs. Deeper samples (1 to 3 inches deep or 2 to 4 inches deep) were collected from 177 of these locations. PCB concentrations were observed to decrease with depth at 176 of the 177 locations, with only 19 of the deeper samples exhibiting PCB concentrations above 1 mg/kg PCBs.

Two locations which exhibited PCB concentrations above 1 mg/kg PCBs at a depth of 1 to 3 inches were sampled from a depth of 3 to 6 inches. Concrete 31, located in the northwest loading area, contained 3,310 mg/kg PCBs in the 0 to 1 inch deep sample and 1,440 mg/kg in the 1 to 3 inch deep sample. No PCBs were detected in the bulk concrete sample collected at a depth of 3 to 6 inches (reporting limit of 0.1 mg/kg for each Aroclor). Concrete sample B6, located near the center of the "Heavy Assembly Materials" area, contained 7.53 mg/kg PCBs in the 0 to 1 inch deep sample and 2.49 mg/kg in the 1 to 3 inch deep sample. No PCBs were detected in the bulk concrete sample collected at a depth of 3 to 6 inches (reporting limit of 0.1 mg/kg for each Aroclor).

Bulk concrete samples were collected from 3 areas located on the outside of the facility: the loading ramp near the southwest corner; the truck ramp located on the east side; and the rail spur loading area on the north side. Four of the six samples collected from the rail spur loading area (Concrete 36, 39, 40, and 41) contained PCBs at concentrations exceeding 1 mg/kg PCBs. None of the samples collected from the other two areas contained PCBs at concentrations above 1 mg/kg PCBs.

3.0 CLEANUP PLAN

The SPX Lindberg facility is a manufacturing and office building. PCB-contaminated concrete is present throughout the manufacturing portion of the facility. Should a self-implementing cleanup be conducted, a cleanup level for bulk PCB remediation waste of ≤1 mg/kg would be required without further conditions per 40 CFR 761.61(a)(4)(i)(A). However, an alternative, risk-based cleanup level may be used, pending EPA approval, in accordance with 40 CFR 761.61(c). Based on preliminary conversations with personnel from EPA Region 5 and the Wisconsin Department of Natural Resources (WDNR), a risk-based cleanup level of ≤10 mg/kg PCBs may be an acceptable site-specific cleanup level for this facility.

Note

A quantitative human health or environmental risk assessment has not been conducted. With the exception of the concrete pad in the rail spur loading area, the PCB contamination is located within the confines of the facility building. Vertical bulk concrete sampling results demonstrate that the PCBs have not penetrated the concrete floor to the underlying soil. Since the contaminated areas which will remain at the property following the proposed cleanup are confined within the physical enclosure of the building, no associated risks to the environment are anticipated. Access to the contaminated areas is provided by entrance doors which are currently locked. Under potential future use conditions, the anticipated use of the building is industrial. The potential occupational exposure in this scenario stems primarily from dermal contact with the contaminated floor.

Concern

The proposed site cleanup presented below includes off-site disposal, engineered controls, and a deed restriction to limit exposure. Based on its industrial use and limited accessibility, a risk-based cleanup level of ≤10 mg/kg is being requested for this facility. Approximately 20,650 square feet of concrete contains PCBs at concentrations greater than 10 mg/kg (**Figure 6**).

The following remediation methods are proposed for the facility in order to address the PCBs at concentrations greater than 10 mg/kg:

- Bulk PCB Remediation Waste removal and off-site disposal of the 700 square-foot concrete pad in the rail spur loading area.
- Continued Use Authorization, which includes cleaning per Subpart S and two coats of epoxy, for the in-place management of 12,150 square feet of PCB-contaminated, bare concrete flooring.
- Continued Use Authorization, which includes superficial cleaning and two coats of epoxy, for the in-place management of 7,000 square feet of PCB-contaminated, epoxy-coated concrete flooring.
- Cleaning per Subpart S for the in-place management of approximately 800 square-feet of PCB-contaminated concrete flooring located at 8 non-contiguous locations.

The locations within the facility proposed to be cleaned by these remediation methods are shown in **Figure 7**.

3.1 Bulk PCB Remediation Waste Removal and Disposal

A 16-foot by 43-foot concrete pad located in the in the rail spur loading area to the north the facility building was found to contain PCBs at concentrations greater than 10 mg/kg (**Figure 7; Appendix A, Photograph 1**). A bulk concrete sample collected from Concrete 36 contained 201 mg/kg PCBs in the 0 to 1 inch sample interval. In order to manage the PCBs in this area, SPX will remove the entire concrete pad in accordance with 40 CFR 761.61(a)(5)(i). The bulk PCB remediation wastes will be managed and disposed off-site according to the applicable waste classification and disposal regulations as specified under 40 CFR 761.61(a)(5)(i)(B)(2).

Following removal of the concrete pad, a confirmation sample will be collected from the soil beneath the location of Concrete 36. This sample will be analyzed for PCBs by EPA Method 8082. A bulk concrete sample previously collected from Concrete 36 contained 2.29 mg/kg PCBs in the 1 to 3 inch sample interval. Bulk concrete samples collected from the other five locations in the concrete pad did not detect the presence of PCBs at a depth of 1 to 3 inches, so no additional confirmation sampling will be performed beneath the concrete pad.

3.2 Continued Use Authorization

The 40 CFR 761.30(p) *continued use of porous surfaces contaminated with PCBs regulated for disposal by spills of liquid PCBs* authorization will be implemented for the in-place management of 19,150 square feet of PCB-contaminated concrete located within the facility. The proposed cleanup level for the work described in this section is ≤10 mg/kg PCBs.

The proposed cleanup area has been subdivided into two distinct areas with respect to the surface condition of the concrete. The first area consists of 12,150 square feet of bare concrete flooring stretching from the north end of the facility to approximately 440 feet to the south, including the loading dock located on the west side of the building (**Figure 7; Appendix A, Photographs 2 through 5 and 8**). The second area consists of a 7,000-square foot former assembly area near the southern end of the facility (**Figure 7; Appendix A, Photographs 6 and 7**). The floor in this area is covered with a white epoxy coating.

more @ present

3.2.1 PCB Source Control

The first step of implementing the 761.30(p) continued use authorization requires the removal of the source causing the release of PCBs. No PCB releases have been reported or are known to have occurred within the facility. The results of the investigation discussed above do not indicate a point source of the PCB contamination. The results of a Phase I Environmental Site Assessment (EA) performed at the facility indicated the potential historical presence of PCBs related to the former manufacture of electrical transformers at the facility. According to information presented in the EA report, dated September 23, 2009:

Recognized Environmental (REC)

> *The second suspect REC consists of the former manufacture of electric transformers at the Subject Property by the Hevi-Duty Company in the 1950's. Historically, manufacturers of transformers were known to employ dielectric fluids containing polychlorinated biphenyls (PCBs). This condition is characterized as a suspect REC since no direct evidence in the form of spills or releases of transformer fluids are known, nor have any indications of the use of PCB-containing fluids been directly identified at the Subject Property. However, the manufacturing of electric transformers at the Subject Property is indicated in a 1956 Sanborn map and the Hevi-Duty Company is known to have historically used PCB containing transformer fluids at other facility locations in the United States.*

Information regarding Hevi-Duty Company historical operations was obtained from the SolaHD website (http://www.solaheviduty.com). According to the company's historical summary, the combined operations of transformer and furnace manufacturing were moved

to Watertown, Wisconsin in 1953. In 1962, a limited portion of the Watertown facility produced the larger transformers with a maximum rating of 2000 KVA. All transformer production at the facility ended in 1971.

3.2.2 Decontamination and Coating Methods

Prior to the initiation of cleanup activities at the facility, all moveable equipment and materials will be removed from the areas to be cleaned. The 12,150 square feet of bare, PCB-contaminated concrete floor will be cleaned in accordance with the double wash/rinse procedure described in 40 CFR 761 Subpart S. This procedure is intended for the decontamination of non-porous surfaces, but 761.30(p) requires that this method be used to prepare PCB-contaminated concrete for encapsulation. Following an initial vacuum to remove loose dust and bird waste, the surface washing steps in this area will include 1) high-pressure steam wash with concrete cleaner/degreaser, 2) potable water rinse, 3) power scrub with a cleaning/degreasing and muriatic acid etchant solution, and 4) high-pressure steam rinse.

Review

The 7,000 square feet of epoxy-coated, PCB-contaminated concrete floors will be cleaned in a manner less stringent that the double wash/rinse procedure. The reason for this is that while bulk concrete samples collected from below the epoxy-coated surface in this area contained elevated levels of PCBs, wipe samples taken from the top of the epoxy-coated surface did not exhibit PCBs above 10 µg/100 cm^2. Following an initial vacuum to remove loose dust and bird waste, the surface washing steps in this area will include a 1) high-pressure steam wash with concrete cleaner/degreaser, 2) a light scuffing of the epoxy-coated surface with 100+ grit sandpaper, and 3) a final vacuum and rinse.

Following the surface washing activities and once the surface has been allowed to dry for a minimum of 24 hours, an epoxy encapsulant will be placed on the concrete surface according to the requirements of 40 CFR 761.30(p)(1)(iii)(A). Two coats of epoxy will be applied to the floor surface. The two coats of epoxy will consist of contrasting colors so that any wearing of the topcoat can be detected. In the area where a white epoxy coating already exists, one additional coat will be applied in a contrasting color.

Once the epoxy has dried, labels will be placed on the encapsulated floor surfaces to indicate that PCBs remain in the underlying concrete as specified under 40 CFR

761.30(p)(1)(iii)(B). The labels, described in 761.45, will be applied at the entrances, corners, and central portions of the encapsulated area.

3.2.3 Disposal

Wastes generated during the double wash/rinse procedure and encapsulation may include water mixed with detergent, water mixed with spent degreaser, used absorbent materials, and other equipment. These wastes will be managed according to applicable waste classification and disposal regulations as specified under 40 CFR 761.378(c). ok

3.3 Subpart S Cleaning

Besides the 19,150 square feet of PCB-contaminated concrete described above, there were eight non-contiguous concrete sample locations exhibiting PCB concentrations greater than 10 mg/kg (**Figure 7**). These locations include the following:

- Concrete 53 - 12.67 mg/kg PCBs at 0-1 inch, 1.06 mg/kg PCBs at 1-3 inches (Wipe B5 had 2.0 µg/100 cm^2 PCBs),
- Concrete 103 – 40.0 mg/kg PCBs at 0-1 inch, non-detect at 1-3 inches,
- Concrete 178 – 11.00 mg/kg PCBs at 0-1 inch (Wipe A7 had 4.6 µg/100 cm^2 PCBs),
- Concrete 230 – 11.50 mg/kg PCBs at 0-1 inch, non-detect at 2-4 inches (Wipe C3 had 5.6 µg/100 cm^2 PCBs),
- Concrete 239 – 22.0 mg/kg PCBs at 0-1 inch, (Wipe C6 was non-detect),
- Concrete 252 – 11.0 mg/kg PCBs at 0-1 inch, non-detect at 2-4 inches,
- Concrete 272 – 10.3 mg/kg PCBs at 0-1 inch, non-detect at 2-4 inches (Wipe C4 had 4.5 µg/100 cm^2), and
- Concrete 370 – 16.0 mg/kg PCBs at 0-1 inch.

Given the limited areal and vertical extent of PCBs in these eight locations, the Subpart S double wash/rinse procedure will be used to decontaminate the shallow concrete. A 10-foot by 10-foot (100-square foot) area surrounding each sample location will be cleaned using the method for bare floors as described in **Section 3.2.2**. Following the surface washing activities, confirmation bulk concrete samples will be collected from 0 to 1 inch in each of these areas and analyzed for PCBs by EPA Method 8082. Should the sample result indicate a PCB concentration of ≤10 mg/kg, the cleanup will be considered complete. If the sample result should indicate a PCB concentration greater than 10 mg/kg PCBs, an epoxy encapsulant will be placed on the 100 square-foot area as described in **Section 3.2.2**.

3.4 Schedule

It is anticipated that the cleanup will begin within approximately one month of EPA authorization and will take approximately one month to complete. The following is an estimated timeline to complete the site cleanup:

Item	***Date***
EPA Approval	*October 2010*
Initiate Site Cleanup	*November 2010*
Complete Site Cleanup	*December 2010*
Reporting and Deed Restriction Filing	*February 2011*

4.0 RECORDKEEPING

As requested in 40 CFR 761.61(a)(3)(i)(E), a file containing all sampling plans, sample collection procedures, sample preparation procedures, extraction procedures, and instrumental/chemical analysis procedures used to assess the PCB contamination at the facility will be maintained at the facility and will be available for EPA inspection. The written certification, signed by a representative of SPX as both property owner and party conducting the cleanup, will be submitted as a separate document.

Because cleanup activities include the use of an encapsulant and PCB-contaminated concrete will remain at concentrations which exceed the regulatory cleanup levels, a deed restriction will be recorded within 60 days of the completion of the cleanup activities in accordance with 40 CFR 761.61(a)(8)(i). A written certification indicating that the deed restriction has been filed will be submitted to the EPA Regional Manager. NOTE!!

Long-term management of the PCB-affected concrete will be necessary. An operations and maintenance management plan will be developed to maximize employee protection. Components of the management plan will include training information for facility workers to inspect the encapsulant for wear and damage, procedures for repairing the encapsulant as needed, and a safety plan for workers in the event that they need to penetrate the encapsulant and drill into the concrete. The management plan will also include a plan for addressing the ultimate removal and disposal of PCB-contaminated concrete and soil remaining beneath the encapsulant for the point in time when the property is adapted for another use or the building demolished.

5.0 REMARKS

The recommendations contained in this report represent Delta's professional opinions based upon the currently available information and are arrived at in accordance with currently acceptable professional standards. This report is based upon a specific scope of work requested by the client. The contract between Delta and its client, SPX Corporation, outlines the scope of work, and only those tasks specifically authorized by that contract or outlined in this report were performed. This report is intended only for the use of Delta's client and anyone else specifically identified in writing as a user this report. Delta will not and cannot be liable for unauthorized reliance by any other third party. Other than as contained in this paragraph, Delta makes no express or implied warranty as to the contents of this report.

This report was prepared by **DELTA CONSULTANTS.**

Karen J. Thole, P.G.
Project Hydrogeologist

Date: August 11, 2010

Peter J. Schwalbach
Project Manager

Date: August 11, 2010

TABLES

TABLES

TABLE 1
PCB Wipe Sample Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Surface wipe sample location	Sample collection date	Total PCBs (µg per 100 cm^2)
W1	10/27/09	8.1
W2	10/27/09	9.6
W3	10/27/09	**13.0**
W4	10/27/09	4.7
W5	10/27/09	**11.7**
W6	10/27/09	8.1
W8	10/27/09	Not Detected
W9	10/27/09	**14.4**
W10	10/27/09	**10.8**
W11	10/27/09	6.4
W12	10/27/09	7.4
W13	10/27/09	1.7
W14	10/27/09	6.6
W15	10/27/09	3.8
W16	10/27/09	5.7
W17	10/27/09	6.3
W18	10/27/09	Not Detected
W19	10/27/09	7.4
W20	10/27/09	Not Detected
W23	10/27/09	4.7
W24	10/27/09	Not Detected
W25	10/27/09	9.9
W33	10/27/09	**12.4**
Field blank	10/27/09	Not Detected
TSCA surface cleanup standard for new PCB spills		10.0

Where are
B1
B4
B6 ?
B7
A8 ?
See page (3)

Abbreviations:

PCBs	polychlorinated biphenyls
µg	microgram
cm^2	square centimeter
Not Detected	Not detected at or above 1.0 µg per 100 cm^2 PCBs
TSCA	Toxic Substance Control Act
Bold	Exceedance of TSCA standard

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
B1	10/27/09	0 - 1	**10.89**
		1 - 3	Not Detected
B4	10/27/09	0 - 1	**15.20**
		1 - 3	0.42
B6	10/27/09	0 - 1	**7.53**
		1 - 3	**2.49**
	12/29/09	3 - 6	Not Detected
B7	10/27/09	0 - 1	**12.10**
		1 - 3	0.22
A8	10/27/09	0 - 1	**16.40**
		1 - 3	Not Detected
Concrete 1	12/28/09	0 - 1	**11.50**
		1 - 3	0.51
Concrete 2	12/28/09	0 - 1	**16.60**
		1 - 3	0.56
Concrete 3	12/28/09	0 - 1	**6.68**
		1 - 3	0.05
Concrete 4	12/28/09	0 - 1	**16.70**
		1 - 3	0.79
Concrete 5	12/28/09	0 - 1	**12.60**
		1 - 3	0.28
Concrete 6	12/28/09	0 - 1	**18.90**
		1 - 3	0.95
Concrete 7	12/28/09	0 - 1	**7.48**
		1 - 3	0.15
Concrete 8	12/28/09	0 - 1	**10.50**
		1 - 3	0.24
Concrete 9	12/28/09	0 - 1	**25.70**
		1 - 3	0.27
Concrete 10	12/29/09	0 - 1	**18.30**
		1 - 3	0.17
Concrete 11	12/29/09	0 - 1	**14.60**
		1 - 3	**1.83**
Concrete 12	12/29/09	0 - 1	**21.30**
		1 - 3	**3.65**
Concrete 13	12/29/09	0 - 1	**7.58**
		1 - 3	Not Detected
Concrete 14	12/29/09	0 - 1	**2.93**
		1 - 3	Not Detected
Concrete 15	12/29/09	0 - 1	**20.40**
		1 - 3	**1.90**
Concrete 16	12/29/09	0 - 1	**20.30**
		1 - 3	0.68
Concrete 17	12/29/09	0 - 1	**7.01**
		1 - 3	Not Detected
Concrete 18	12/29/09	0 - 1	**6.84**
		1 - 3	Not Detected
Concrete 19	12/29/09	0 - 1	**9.30**
		1 - 3	**3.31**
Concrete 20	12/29/09	0 - 1	**55.40**
		1 - 3	**1.41**
Concrete 21	12/29/09	0 - 1	**10.50**
		1 - 3	**7.21**

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 22	12/29/09	0 - 1	**14.90**
		1 - 3	Not Detected
Concrete 23	12/30/09	0 - 1	**25.20**
		1 - 3	**5.11**
Concrete 24	12/30/09	0 - 1	**6.29**
		1 - 3	Not Detected
Concrete 25	12/30/09	0 - 1	**10.20**
		1 - 3	Not Detected
Concrete 26	12/30/09	0 - 1	**35.10**
		1 - 3	0.11
Concrete 27	12/30/09	0 - 1	**9.70**
		1 - 3	Not Detected
Concrete 28	12/30/09	0 - 1	0.38
		1 - 3	Not Detected
Concrete 29	12/30/09	0 - 1	0.31
		1 - 3	Not Detected
Concrete 30	12/30/09	0 - 1	0.40
		1 - 3	Not Detected
Concrete 31	12/30/09	0 - 1	**3310.00**
		1 - 3	**1440.00**
	01/26/10	3 - 6	Not Detected
Concrete 32	12/30/09	0 - 1	**10.70**
		1 - 3	**1.89**
Concrete 33	12/30/09	0 - 1	**11.30**
		1 - 3	0.42
Concrete 34	12/30/09	0 - 1	**12.80**
		1 - 3	Not Detected
Concrete 35	12/30/09	0 - 1	**1.18**
		1 - 3	Not Detected
Concrete 36	12/30/09	0 - 1	**201.00**
		1 - 3	**2.29**
Concrete 37	01/25/10	0 - 1	Not Detected
		1 - 3	Not Detected
Concrete 38	01/25/10	0 - 1	Not Detected
		1 - 3	Not Detected
Concrete 39	01/25/10	0 - 1	**2.09**
		1 - 3	Not Detected
Concrete 40	01/25/10	0 - 1	**1.18**
		1 - 3	Not Detected
Concrete 41	01/25/10	0 - 1	**2.57**
		1 - 3	Not Detected
Concrete 42	01/25/10	0 - 1	**4.46**
		1 - 3	Not Detected
Concrete 43	01/25/10	0 - 1	**7.12**
		1 - 3	0.12
Concrete 44	01/25/10	0 - 1	**13.90**
		1 - 3	**1.83**
Concrete 45	01/26/10	0 - 1	**1.98**
		1 - 3	Not Detected
Concrete 46	01/26/10	0 - 1	**3.45**
		1 - 3	Not Detected
Concrete 47	01/26/10	0 - 1	0.17
		1 - 3	Not Detected

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 48	01/26/10	0 - 1	0.23
		1 - 3	Not Detected
Concrete 49	01/26/10	0 - 1	**10.80**
		1 - 3	0.97
Concrete 50	01/26/10	0 - 1	**115.39**
		1 - 3	**8.89**
Concrete 51	01/26/10	0 - 1	**7.62**
		1 - 3	Not Detected
Concrete 52	01/26/10	0 - 1	**6.68**
		1 - 3	0.32
Concrete 53	01/26/10	0 - 1	**12.67**
		1 - 3	**1.06**
Concrete 54	01/27/10	0 - 1	**1.78**
		1 - 3	Not Detected
Concrete 55	01/27/10	0 - 1	**7.79**
		1 - 3	Not Detected
Concrete 56	01/27/10	0 - 1	**2.43**
		1 - 3	Not Detected
Concrete 57	01/27/10	0 - 1	**8.17**
		1 - 3	0.17
Concrete 58	01/27/10	0 - 1	**17.14**
		1 - 3	0.16
Concrete 59	01/27/10	0 - 1	**6.52**
		1 - 3	Not Detected
Concrete 60	01/27/10	0 - 1	**13.99**
		1 - 3	Not Detected
Concrete 61	01/27/10	0 - 1	**10.73**
		1 - 3	**1.33**
Concrete 62	01/27/10	0 - 1	**17.74**
		1 - 3	0.26
Concrete 63	01/27/10	0 - 1	**1.82**
		1 - 3	Not Detected
Concrete 64	01/27/10	0 - 1	**39.10**
		1 - 3	**1.34**
Concrete 65	01/27/10	0 - 1	**1.53**
		1 - 3	Not Detected
Concrete 66	01/28/10	0 - 1	**20.47**
		1 - 3	**1.03**
Concrete 67	01/28/10	0 - 1	**6.18**
		1 - 3	Not Detected
Concrete 68	01/28/10	0 - 1	**21.60**
		1 - 3	0.86
Concrete 69	01/28/10	0 - 1	**12.70**
		1 - 3	No Sample Collected
Concrete 70	01/27/10	0 - 1	**3.25**
		1 - 3	0.51
Concrete 71	01/25/10	0 - 1	0.41
		1 - 3	Not Detected
Concrete 72	01/25/10	0 - 1	0.18
		1 - 3	Not Detected
Concrete 73	01/28/10	0 - 1	**10.80**
		1 - 3	Not Detected

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 74	03/16/10	0 - 1	0.75
Concrete 75	03/16/10	0 - 1	0.17
Concrete 76	03/16/10	0 - 1	0.87
Concrete 77	03/16/10	0 - 1	0.75
Concrete 78	03/16/10	0 - 1	**3.08**
Concrete 79	03/16/10	0 - 1	**11.76**
	05/11/10	2 - 4	Not Detected
Concrete 80	03/16/10	0 - 1	**1.86**
Concrete 81	03/16/10	0 - 1	**1.86**
Concrete 82	03/16/10	0 - 1	**11.62**
	05/11/10	2 - 4	Not Detected
Concrete 83	03/16/10	0 - 1	**13.94**
	05/11/10	2 - 4	Not Detected
Concrete 84	03/16/10	0 - 1	**17.30**
	05/11/10	2 - 4	Not Detected
Concrete 85	03/16/10	0 - 1	**57.21**
	05/11/10	2 - 4	Not Detected
Concrete 86	03/16/10	0 - 1	**14.48**
	05/11/10	2 - 4	Not Detected
Concrete 87	03/16/10	0 - 1	**1.31**
	03/17/10	2 - 4	Not Detected
Concrete 88	03/16/10	0 - 1	**19.39**
	03/17/10	2 - 4	Not Detected
Concrete 89	03/16/10	0 - 1	0.96
	03/17/10	2 - 4	Not Detected
Concrete 90	03/16/10	0 - 1	0.25
	03/17/10	2 - 4	Not Detected
Concrete 91	03/16/10	0 - 1	**4.85**
	03/17/10	2 - 4	Not Detected
Concrete 92	03/16/10	0 - 1	**2.88**
	03/17/10	2 - 4	Not Detected
Concrete 93	03/16/10	0 - 1	**3.73**
	03/17/10	2 - 4	Not Detected
Concrete 94	03/16/10	0 - 1	0.26
	03/17/10	2 - 4	Not Detected
Concrete 95	03/16/10	0 - 1	**3.26**
	03/17/10	2 - 4	Not Detected
Concrete 96	03/16/10	0 - 1	**8.22**
	03/17/10	2 - 4	Not Detected
Concrete 97	03/16/10	0 - 1	**2.87**
	03/17/10	2 - 4	Not Detected
Concrete 98	03/17/10	0 - 1	**15.40**
	03/31/10	2 - 4	Not Detected
Concrete 99	03/21/10	0 - 1	**1.75**
	03/22/10	2 - 4	Not Detected

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 100	03/21/10	0 - 1	**2.10**
Concrete 101	03/21/10	0 - 1	**2.80**
	03/22/10	2 - 4	Not Detected
Concrete 102	03/21/10	0 - 1	**7.10**
	03/22/10	2 - 4	Not Detected
Concrete 103	03/21/10	0 - 1	**40.00**
	03/22/10	2 - 4	Not Detected
Concrete 104	03/21/10	0 - 1	**3.50**
	03/22/10	2 - 4	0.20
Concrete 105	03/21/10	0 - 1	**36.00**
	03/29/10	2 - 4	Not Detected
Concrete 106	03/21/10	0 - 1	**2.20**
Concrete 107	03/21/10	0 - 1	**26.00**
	05/11/10	2 - 4	Not Detected
Concrete 108	03/21/10	0 - 1	**9.20**
	03/31/10	2 - 4	Not Detected
Concrete 109	03/21/10	0 - 1	**1.60**
	03/31/10	2 - 4	Not Detected
Concrete 110	03/21/10	0 - 1	**2.62**
	03/22/10	2 - 4	0.12
Concrete 111	03/21/10	0 - 1	**57.30**
	04/01/10	2 - 4	0.15
Concrete 112	03/21/10	0 - 1	**4.72**
	04/01/10	2 - 4	Not Detected
Concrete 113	03/21/10	0 - 1	**5.50**
Concrete 114	03/21/10	0 - 1	**17.00**
	03/22/10	2 - 4	Not Detected
Concrete 115	03/22/10	0 - 1	**1.75**
	03/22/10	2 - 4	Not Detected
Concrete 116	03/22/10	0 - 1	0.60
	03/22/10	2 - 4	Not Detected
Concrete 117	03/22/10	0 - 1	**2.10**
	03/22/10	2 - 4	0.34
Concrete 118	03/22/10	0 - 1	**16.00**
	03/31/10	2 - 4	Not Detected
Concrete 119	03/22/10	0 - 1	**1.60**
	03/31/10	2 - 4	Not Detected
Concrete 120	03/22/10	0 - 1	**3.60**
	03/29/10	2 - 4	Not Detected
Concrete 121	03/22/10	0 - 1	**5.60**
	03/29/10	2 - 4	Not Detected
Concrete 122	03/22/10	0 - 1	0.98
Concrete 123	03/22/10	0 - 1	0.72
Concrete 124	03/23/10	0 - 1	**9.00**
	03/29/10	2 - 4	Not Detected
Concrete 125	03/23/10	0 - 1	**13.00**
	03/29/10	2 - 4	Not Detected

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 126	03/23/10	0 - 1	**22.00**
	03/29/10	2 - 4	**2.17**
Concrete 127	03/23/10	0 - 1	**15.00**
	03/29/10	2 - 4	Not Detected
Concrete 128	03/23/10	0 - 1	**18.00**
	03/29/10	2 - 4	0.81
Concrete 129	03/23/10	0 - 1	**35.00**
	03/31/10	2 - 4	Not Detected
Concrete 130	03/23/10	0 - 1	**6.00**
	03/31/10	2 - 4	Not Detected
Concrete 131	03/23/10	0 - 1	**62.00**
	04/01/10	2 - 4	Not Detected
Concrete 132	03/23/10	0 - 1	**2.10**
	04/01/10	2 - 4	Not Detected
Concrete 133	03/23/10	0 - 1	**35.00**
	04/02/10	2 - 4	Not Detected
Concrete 134	03/23/10	0 - 1	**28.00**
	04/02/10	2 - 4	Not Detected
Concrete 135	03/23/10	0 - 1	**100.00**
	04/02/10	2 - 4	Not Detected
Concrete 136	03/23/10	0 - 1	**19.00**
	04/02/10	2 - 4	Not Detected
Concrete 137	03/23/10	0 - 1	**5.20**
Concrete 138	03/23/10	0 - 1	**4.40**
	03/29/10	2 - 4	Not Detected
Concrete 139	03/23/10	0 - 1	**1.82**
	03/29/10	2 - 4	Not Detected
Concrete 140	03/23/10	0 - 1	**1.90**
Concrete 141	03/23/10	0 - 1	0.90
Concrete 142	03/23/10	0 - 1	**9.00**
	03/31/10	2 - 4	Not Detected
Concrete 143	03/23/10	0 - 1	**4.60**
Concrete 144	03/23/10	0 - 1	0.30
Concrete 145	03/23/10	0 - 1	**22.00**
	03/29/10	2 - 4	Not Detected
Concrete 146	03/23/10	0 - 1	**28.00**
	03/29/10	2 - 4	Not Detected
Concrete 147	03/23/10	0 - 1	**7.40**
	03/29/10	2 - 4	Not Detected
Concrete 148	03/24/10	0 - 1	**6.20**
	04/02/10	2 - 4	Not Detected
Concrete 149	03/24/10	0 - 1	**50.00**
	04/02/10	2 - 4	Not Detected
Concrete 150	03/24/10	0 - 1	**64.00**
	04/02/10	2 - 4	**2.26**
Concrete 151	03/24/10	0 - 1	**68.00**
	04/02/10	2 - 4	**3.60**

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 152	03/24/10	0 - 1	**7.40**
	04/02/10	2 - 4	Not Detected
Concrete 153	03/24/10	0 - 1	**5.20**
Concrete 154	03/24/10	0 - 1	0.34
Concrete 155	03/24/10	0 - 1	**2.00**
	03/29/10	2 - 4	Not Detected
Concrete 156	03/24/10	0 - 1	**4.40**
	03/29/10	2 - 4	Not Detected
Concrete 157	03/24/10	0 - 1	**5.00**
	03/29/10	2 - 4	Not Detected
Concrete 158	03/24/10	0 - 1	Not Detected
Concrete 159	03/24/10	0 - 1	**4.50**
Concrete 160	03/24/10	0 - 1	0.78
Concrete 161	03/24/10	0 - 1	**28.00**
	03/29/10	2 - 4	Not Detected
Concrete 162	03/24/10	0 - 1	**34.00**
	03/29/10	2 - 4	Not Detected
Concrete 163	03/24/10	0 - 1	**440.00**
	03/30/10	2 - 4	0.14
Concrete 164	03/24/10	0 - 1	**15.00**
	03/30/10	2 - 4	Not Detected
Concrete 165	03/24/10	0 - 1	**22.00**
	03/30/10	2 - 4	Not Detected
Concrete 166	03/24/10	0 - 1	**88.00**
	04/02/10	2 - 4	Not Detected
Concrete 167	03/24/10	0 - 1	**100.00**
	04/02/10	2 - 4	Not Detected
Concrete 168	03/24/10	0 - 1	**1.70**
	04/02/10	2 - 4	**2.80**
Concrete 169	03/24/10	0 - 1	**48.00**
	03/30/10	2 - 4	Not Detected
Concrete 170	03/25/10	0 - 1	**1.40**
Concrete 171	03/25/10	0 - 1	**4.40**
Concrete 172	03/25/10	0 - 1	**2.40**
	03/29/10	2 - 4	Not Detected
Concrete 173	03/25/10	0 - 1	**2.20**
	03/29/10	2 - 4	Not Detected
Concrete 174	03/25/10	0 - 1	**3.00**
	03/29/10	2 - 4	Not Detected
Concrete 175	03/25/10	0 - 1	0.64
Concrete 176	03/25/10	0 - 1	**9.40**
	03/29/10	2 - 4	Not Detected
Concrete 177	03/25/10	0 - 1	**1.00**
	03/29/10	2 - 4	Not Detected

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 178	03/25/10	0 - 1	**11.00**
Concrete 179	03/25/10	0 - 1	0.82
Concrete 180	03/25/10	0 - 1	**30.00**
	03/30/10	2 - 4	Not Detected
Concrete 181	03/25/10	0 - 1	**48.00**
	03/30/10	2 - 4	Not Detected
Concrete 182	03/25/10	0 - 1	**11.00**
	03/30/10	2 - 4	Not Detected
Concrete 183	03/25/10	0 - 1	**640.00**
	03/30/10	2 - 4	0.16
Concrete 184	03/25/10	0 - 1	**2.00**
Concrete 185	03/25/10	0 - 1	**1.20**
Concrete 186	03/25/10	0 - 1	**2.60**
Concrete 187	03/25/10	0 - 1	**4.20**
Concrete 188	03/25/10	0 - 1	**10.00**
Concrete 189	03/25/10	0 - 1	**7.70**
Concrete 190	03/25/10	0 - 1	**7.00**
Concrete 191	03/25/10	0 - 1	**2.40**
Concrete 192	03/26/10	0 - 1	**2.20**
Concrete 193	03/26/10	0 - 1	**2.20**
Concrete 194	03/26/10	0 - 1	**4.60**
Concrete 195	03/26/10	0 - 1	**110.00**
	03/30/10	2 - 4	Not Detected
Concrete 196	03/26/10	0 - 1	**55.80**
	03/30/10	2 - 4	Not Detected
Concrete 197	03/26/10	0 - 1	**3.20**
	04/01/10	2 - 4	Not Detected
Concrete 198	03/26/10	0 - 1	**1.40**
	04/01/10	2 - 4	Not Detected
Concrete 199	03/26/10	0 - 1	0.70
Concrete 200	03/26/10	0 - 1	**1.60**
	04/01/10	2 - 4	Not Detected
Concrete 201	03/26/10	0 - 1	**2.70**
Concrete 202	03/26/10	0 - 1	**3.60**
Concrete 203	03/26/10	0 - 1	**1.70**

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 204	03/26/10	0 - 1	0.60
Concrete 205	03/29/10	0 - 1	0.46
Concrete 206	03/29/10	0 - 1	**1.50**
Concrete 207	03/29/10	0 - 1	0.50
Concrete 208	03/29/10	0 - 1	0.94
Concrete 209	03/29/10	0 - 1	**5.60**
Concrete 210	03/29/10	0 - 1	**3.50**
Concrete 211	03/29/10	0 - 1	**2.10**
Concrete 212	03/29/10	0 - 1	**2.30**
Concrete 213	03/29/10	0 - 1	**1.90**
Concrete 214	03/29/10	0 - 1	**1.50**
Concrete 215	03/29/10	0 - 1	**7.30**
Concrete 216	03/29/10	0 - 1	**2.60**
Concrete 217	03/30/10	0 - 1	**120.00**
	03/30/10	2 - 4	Not Detected
Concrete 218	03/30/10	0 - 1	**27.20**
	03/30/10	2 - 4	Not Detected
Concrete 219	03/30/10	0 - 1	**1.40**
	04/01/10	2 - 4	0.74
Concrete 220	03/30/10	0 - 1	**1.60**
	04/01/10	2 - 4	0.11
Concrete 221	03/30/10	0 - 1	**1.10**
	04/01/10	2 - 4	Not Detected
Concrete 222	03/30/10	0 - 1	**1.46**
Concrete 223	03/30/10	0 - 1	0.76
Concrete 224	03/30/10	0 - 1	**2.40**
Concrete 225	03/30/10	0 - 1	Not Detected
Concrete 226	03/30/10	0 - 1	**2.00**
Concrete 227	03/30/10	0 - 1	**4.10**
Concrete 228	03/30/10	0 - 1	1.00
Concrete 229	03/30/10	0 - 1	**10.00**

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 230	03/30/10	0 - 1	**11.50**
	05/11/10	2 - 4	Not Detected
Concrete 231	03/30/10	0 - 1	**3.60**
Concrete 232	03/30/10	0 - 1	**2.40**
Concrete 233	03/30/10	0 - 1	**4.80**
Concrete 234	03/30/10	0 - 1	**13.70**
	05/11/10	2 - 4	Not Detected
Concrete 235	03/30/10	0 - 1	**8.10**
Concrete 236	03/31/10	0 - 1	**2.20**
Concrete 237	03/31/10	0 - 1	0.92
Concrete 238	03/31/10	0 - 1	**1.40**
Concrete 239	03/31/10	0 - 1	**22.00**
Concrete 240	03/31/10	0 - 1	**4.50**
Concrete 241	03/31/10	0 - 1	**10.00**
Concrete 242	03/31/10	0 - 1	**1.40**
Concrete 243	03/31/10	0 - 1	**5.20**
Concrete 244	03/31/10	0 - 1	**6.30**
Concrete 245	03/31/10	0 - 1	0.44
Concrete 246	03/31/10	0 - 1	0.96
Concrete 247	03/31/10	0 - 1	**2.80**
Concrete 248	03/31/10	0 - 1	**12.00**
	05/11/10	2 - 4	Not Detected
Concrete 249	03/31/10	0 - 1	**17.50**
	05/11/10	2 - 4	Not Detected
Concrete 250	03/31/10	0 - 1	**3.90**
Concrete 251	03/31/10	0 - 1	**1.10**
Concrete 252	03/31/10	0 - 1	**11.00**
	05/11/10	2 - 4	Not Detected
Concrete 253	03/31/10	0 - 1	**1.40**
Concrete 254	03/31/10	0 - 1	**2.50**
Concrete 255	03/31/10	0 - 1	**2.40**

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 256	04/01/10	0 - 1	**9.30**
Concrete 257	04/01/10	0 - 1	**12.30**
	05/11/10	2 - 4	Not Detected
Concrete 258	04/01/10	0 - 1	**8.00**
Concrete 259	04/01/10	0 - 1	**1.90**
Concrete 260	04/01/10	0 - 1	**1.40**
Concrete 261	04/01/10	0 - 1	**1.70**
Concrete 262	04/01/10	0 - 1	**3.80**
Concrete 263	04/01/10	0 - 1	0.50
Concrete 264	04/01/10	0 - 1	**1.70**
Concrete 265	04/01/10	0 - 1	**1.80**
Concrete 266	04/01/10	0 - 1	0.76
Concrete 267	04/01/10	0 - 1	**2.20**
Concrete 268	04/01/10	0 - 1	0.93
Concrete 269	04/01/10	0 - 1	**2.20**
Concrete 270	04/01/10	0 - 1	**2.40**
Concrete 271	04/01/10	0 - 1	**1.70**
Concrete 272	04/01/10	0 - 1	**10.30**
	05/11/10	2 - 4	Not Detected
Concrete 273	04/01/10	0 - 1	**3.10**
Concrete 274	05/04/10	0 - 1	0.58
Concrete 275	05/04/10	0 - 1	Not Detected
Concrete 276	05/04/10	0 - 1	0.18
Concrete 277	05/04/10	0 - 1	0.49
Concrete 278	05/04/10	0 - 1	**1.90**
Concrete 279	05/04/10	0 - 1	0.36
Concrete 280	05/04/10	0 - 1	**3.00**
Concrete 281	05/04/10	0 - 1	**5.90**

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 282	05/04/10	0 - 1	0.62
Concrete 283	05/04/10	0 - 1	**3.30**
Concrete 284	05/04/10	0 - 1	**2.90**
Concrete 285	05/04/10	0 - 1	0.91
Concrete 286	05/04/10	0 - 1	0.20
Concrete 287	05/04/10	0 - 1	**3.90**
Concrete 288	05/04/10	0 - 1	**3.00**
Concrete 289	05/04/10	0 - 1	0.69
Concrete 290	05/04/10	0 - 1	0.42
Concrete 291	05/04/10	0 - 1	**1.19**
Concrete 292	05/04/10	0 - 1	0.67
Concrete 293	05/04/10	0 - 1	1.00
Concrete 294	05/04/10	0 - 1	0.57
Concrete 295	05/04/10	0 - 1	**1.70**
Concrete 296	05/04/10	0 - 1	**2.50**
Concrete 297	05/04/10	0 - 1	**1.50**
Concrete 298	05/04/10	0 - 1	**1.30**
Concrete 299	05/04/10	0 - 1	**2.30**
Concrete 300	05/04/10	0 - 1	**2.60**
Concrete 301	05/04/10	0 - 1	**2.30**
Concrete 302	05/04/10	0 - 1	Not Detected
Concrete 303	05/04/10	0 - 1	0.63
Concrete 304	05/04/10	0 - 1	0.23
Concrete 305	05/04/10	0 - 1	0.15
Concrete 306	05/04/10	0 - 1	0.23
Concrete 307	05/04/10	0 - 1	0.10

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 308	05/04/10	0 - 1	Not Detected
Concrete 309	05/04/10	0 - 1	Not Detected
Concrete 310	05/04/10	0 - 1	Not Detected
Concrete 311	05/04/10	0 - 1	Not Detected
Concrete 312	05/04/10	0 - 1	0.13
Concrete 313	05/04/10	0 - 1	0.14
Concrete 314	05/04/10	0 - 1	Not Detected
Concrete 315	05/04/10	0 - 1	Not Detected
Concrete 316	05/04/10	0 - 1	0.39
Concrete 317	05/04/10	0 - 1	Not Detected
Concrete 318	05/04/10	0 - 1	Not Detected
Concrete 319	05/04/10	0 - 1	Not Detected
Concrete 320	05/04/10	0 - 1	Not Detected
Concrete 321	05/04/10	0 - 1	**3.20**
Concrete 322	05/04/10	0 - 1	**2.00**
Concrete 323	05/04/10	0 - 1	Not Detected
Concrete 324	05/04/10	0 - 1	Not Detected
Concrete 325	05/04/10	0 - 1	Not Detected
Concrete 326	05/04/10	0 - 1	**1.10**
Concrete 327	05/04/10	0 - 1	Not Detected
Concrete 328	05/04/10	0 - 1	1.00
Concrete 329	05/04/10	0 - 1	Not Detected
Concrete 330	05/04/10	0 - 1	Not Detected
Concrete 331	05/04/10	0 - 1	**3.50**
Concrete 332	05/04/10	0 - 1	Not Detected
Concrete 333	05/04/10	0 - 1	Not Detected

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 334	05/04/10	0 - 1	**1.90**
Concrete 335	05/04/10	0 - 1	Not Detected
Concrete 336	05/04/10	0 - 1	1.00
Concrete 337	05/04/10	0 - 1	0.66
Concrete 338	05/04/10	0 - 1	**7.10**
Concrete 339	05/04/10	0 - 1	0.22
Concrete 340	05/04/10	0 - 1	0.37
Concrete 341	05/04/10	0 - 1	**3.80**
Concrete 342	05/06/10	0 - 1	**2.00**
Concrete 343	05/06/10	0 - 1	**3.40**
Concrete 344	05/06/10	0 - 1	**1.70**
Concrete 345	05/06/10	0 - 1	**3.50**
Concrete 346	05/06/10	0 - 1	Not Detected
Concrete 347	05/06/10	0 - 1	Not Detected
Concrete 348	05/06/10	0 - 1	Not Detected
Concrete 349	05/06/10	0 - 1	Not Detected
Concrete 350	05/06/10	0 - 1	Not Detected
Concrete 351	05/06/10	0 - 1	Not Detected
Concrete 352	05/06/10	0 - 1	**7.00**
Concrete 353	05/06/10	0 - 1	**2.00**
Concrete 354	05/06/10	0 - 1	1.00
Concrete 355	05/06/10	0 - 1	**1.90**
Concrete 356	05/06/10	0 - 1	Not Detected
Concrete 357	05/06/10	0 - 1	Not Detected
Concrete 358	05/06/10	0 - 1	Not Detected
Concrete 359	05/06/10	0 - 1	1.00

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 360	05/06/10	0 - 1	**2.60**
Concrete 361	05/06/10	0 - 1	**2.00**
Concrete 362	05/06/10	0 - 1	**1.30**
Concrete 363	05/06/10	0 - 1	**3.70**
Concrete 364	05/06/10	0 - 1	Not Detected
Concrete 365	05/06/10	0 - 1	Not Detected
Concrete 366	05/06/10	0 - 1	Not Detected
Concrete 367	05/06/10	0 - 1	Not Detected
Concrete 368	05/06/10	0 - 1	**1.20**
Concrete 369	05/06/10	0 - 1	**2.30**
Concrete 370	05/06/10	0 - 1	**16.00**
Concrete 371	05/06/10	0 - 1	Not Detected
Concrete 372	05/06/10	0 - 1	**2.00**
Concrete 373	05/06/10	0 - 1	**2.50**
Concrete 374	05/06/10	0 - 1	Not Detected
Concrete 375	05/06/10	0 - 1	**1.90**
Concrete 376	05/06/10	0 - 1	**1.90**
Concrete 377	05/06/10	0 - 1	Not Detected
Concrete 378	05/06/10	0 - 1	**2.50**
Concrete 379	05/06/10	0 - 1	**2.70**
Concrete 380	05/06/10	0 - 1	Not Detected
Concrete 381	05/06/10	0 - 1	1.00
Concrete 382	05/06/10	0 - 1	**6.40**
Concrete 383	05/06/10	0 - 1	**18.30**
Concrete 384	05/06/10	0 - 1	**1.90**
Concrete 385	05/06/10	0 - 1	1.00

TABLE 2
PCB Bulk Concrete Analytical Results
SPX Lindberg Facility
304 Hart Street
Watertown, Wisconsin
Delta Project No. 9M0909245

Bulk Concrete Sample Location	Sample Collection Date	Sample Depth Interval (inches below floor)	Total PCBs (mg per kg)
Concrete 386	05/06/10	0 - 1	1.00
Concrete 387	05/07/10	0 - 1	**4.00**
Concrete 388	05/07/10	0 - 1	**1.50**
Concrete 389	05/07/10	0 - 1	**4.10**
Concrete 390	05/07/10	0 - 1	**7.50**
Concrete 391	05/07/10	0 - 1	**2.90**
Concrete 392	05/07/10	0 - 1	**3.20**
Concrete 393	05/07/10	0 - 1	**3.00**
Concrete 394	05/07/10	0 - 1	Not Detected
Concrete 395	05/07/10	0 - 1	Not Detected
Concrete 396	05/07/10	0 - 1	Not Detected
Concrete 397	05/07/10	0 - 1	**1.80**
Concrete 398	05/07/10	0 - 1	**5.40**
Concrete 399	05/07/10	0 - 1	**1.40**
Concrete 400	05/07/10	0 - 1	**1.10**
Concrete 401	05/07/10	0 - 1	Not Detected
Bulk PCB Remediation Waste Cleanup Level for High Occupancy Areas			1.00

Abbreviations:

PCBs	Polychlorinated biphenyls
mg	Milligram per kilogram
Not Detected	Not detected at or above the laboratory reporting limit
Bold	Exceedance of cleanup level

(1.0) 1mg/kg

FIGURES

FIGURES



WATERTOWN QUADRANGLE
WISCONSIN
7.5 MINUTE SERIES (TOPOGRAPHIC)

SCALE 1:24000

FIGURE 1
SITE LOCATION MAP
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY
9M0909245	KT	DD
DATE	REVIEWED BY	FILE NAME
9/30/09		Watertown-2

DELTA



FIGURE 2
PCB WIPE SAMPLE RESULTS MAP
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY
9MC909245	KT	DD
DATE	REVIEWED BY	FILE NAME
1/12/09		Watertown-4

DELTA®



LEGEND:

- ☒ – UNUSED DOORWAY
- ▭ – CURRENT DOORWAY
- • – CONCRETE SAMPLE LOCATION

North

0 40

SCALE IN FEET

FIGURE 3
CONCRETE SAMPLE LOCATION MAP
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY
9M0909245	KT	DD
DATE	REVIEWED BY	FILE NAME
5/21/10		Watertown-7

DELTA®

Corrected



LEGEND:

- UNUSED DOORWAY
- CURRENT DOORWAY
- CONCRETE SAMPLE LOCATION
- 10.89 – PCB SAMPLE RESULTS IN MILLIGRAMS PER KILOGRAM (mg/kg)
- ND – NOT DETECTED

– ?? 11'-3" Deep Concrete ? 10 cm

North

0 40

SCALE IN FEET

FIGURE 4
PCB RESULTS – 0–1 INCH
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY
9M0909245	KT	DD
DATE	REVIEWED BY	FILE NAME
6/1/10		Watertown-8

DELTA

← Corrected in 7/12/10 version



LEGEND:

- UNUSED DOORWAY
- CURRENT DOORWAY
- 1-3" DEEP CONCRETE SAMPLE LOCATION
- 2-4" DEEP CONCRETE SAMPLE LOCATION
- LOCATION HAS 0-1" SAMPLE WITH RESULT LESS THAN OR EQUAL TO 1 mg/kg PCBs – NO DEEP SAMPLE COLLECTED
- LOCATION HAS 0-1" SAMPLE WITH RESULT LESS THAN OR EQUAL TO 10 mg/kg PCBs – NO DEEP SAMPLE COLLECTED
- 5.11 – PCB SAMPLE RESULTS IN MILLIGRAMS PER KILOGRAM (mg/kg)
- ND – NOT DETECTED AT OR ABOVE THE LABORATORY REPORTING LIMIT

FIGURE 5
PCB RESULTS – DEEPER SAMPLES
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY
9M0909245	KT	DD
DATE	REVIEWED BY	FILE NAME
7/20/10		Watertown-9

DELTA®



LEGEND:

- UNUSED DOORWAY
- CURRENT DOORWAY
- CONCRETE SAMPLE LOCATION
- 10.89 – PCB SAMPLE RESULTS IN MILLIGRAMS PER KILOGRAM (mg/kg)
- ND – NOT DETECTED
- PCB RESULTS WARRANTING REMEDIATION

FIGURE 6
PROPOSED AREAL EXTENT OF REMEDIATION
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY	
9M0909245	KT	DD	DELTA®
DATE	REVIEWED BY	FILE NAME	
7/9/10		Watertown-8	

Key?



FIGURE 7
PROPOSED REMEDIATION METHODS
SPX LINDBERG FACILITY
304 HART STREET
WATERTOWN, WISCONSIN

PROJECT NO.	PREPARED BY	DRAWN BY
9M0909245	KT	DD
DATE	REVIEWED BY	FILE NAME
7/9/10		Watertown-8

DELTA®

APPENDICES

A

APPENDIX A

Photograph Log

SPX Lindberg Facility
304 Hart Street, Watertown, Wisconsin
Delta Project No. 9M0909245



Photograph 1. Rail spur loading area on north side of facility, facing southwest.



Photograph 2. Northwest loading dock, facing east.



Photograph 3. Heavy Assembly Materials Storage Corridor, facing south from the northern end.



Photograph 4. Heavy Assembly Materials Storage Corridor ramp, facing south.



Photograph 5. Southern extent of concrete sampling near Old Shipping Office, facing south.



Photographs 6 and 7. Epoxy-coated floor in Environmental Assembly Room, near southwest corner of facility.



Photograph 8. Southwest loading dock, facing north.

B

APPENDIX B

Wipe Sample Analytical Reports

Pace Analytical®
www.pacelabs.com

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

October 12, 2009

Ms. Karen Thole
Delta Consultants
5910 Rice Creek Parkway
Saint Paul, MN 55126

RE: Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Dear Ms. Thole:
Enclosed are the analytical results for sample(s) received by the laboratory on October 03, 2009. The results relate only to the samples included in this report. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Carolynne Trout

Carolynne Trout

carolynne.trout@pacelabs.com
Project Manager

Enclosures

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

nelac

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

CERTIFICATIONS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Minnesota Certification IDs

Alaska Certification #: UST-078
1700 Elm Street SE, Suite 200 Minneapolis, MN 55414
California Certification #: 01155CA
Florida/NELAP Certification #: E87605
Illinois Certification #: 200011
Iowa Certification #: 368
Kansas Certification #: E-10167
Louisiana Certification #: 03086
Louisiana Certification #: LA080009
Maine Certification #: 2007029
Minnesota Certification #: 027-053-137
Montana Certification #: MT CERT0092
New Jersey Certification #: MN-002
New York Certification #: 11647
North Carolina Certification #: 530
North Dakota Certification #: R-036
Oregon Certification #: MN200001
Pennsylvania Certification #: 68-00563
Tennessee Certification #: 02818
Washington Certification #: C754
Wisconsin Certification #: 999407970
Arizona Certification #: AZ-0014

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE SUMMARY

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Lab ID	Sample ID	Matrix	Date Collected	Date Received
10113975001	A1	Wipe	10/01/09 10:30	10/03/09 09:50
10113975002	A.5-2	Wipe	10/01/09 10:45	10/03/09 09:50
10113975003	A3	Wipe	10/01/09 10:55	10/03/09 09:50
10113975004	A.5-4	Wipe	10/01/09 11:00	10/03/09 09:50
10113975005	A5	Wipe	10/01/09 11:10	10/03/09 09:50
10113975006	A5.6	Wipe	10/01/09 11:15	10/03/09 09:50
10113975007	A7	Wipe	10/01/09 02:15	10/03/09 09:50
10113975008	A8	Wipe	10/01/09 04:15	10/03/09 09:50
10113975009	A9	Wipe	10/01/09 04:20	10/03/09 09:50
10113975010	A10	Wipe	10/01/09 04:25	10/03/09 09:50
10113975011	B1	Wipe	10/01/09 10:40	10/03/09 09:50
10113975012	B2	Wipe	10/01/09 11:20	10/03/09 09:50
10113975013	B3	Wipe	10/01/09 10:50	10/03/09 09:50
10113975014	B4	Wipe	10/01/09 02:00	10/03/09 09:50
10113975015	B5	Wipe	10/01/09 11:05	10/03/09 09:50
10113975016	B6	Wipe	10/01/09 02:10	10/03/09 09:50
10113975017	B7	Wipe	10/01/09 02:20	10/03/09 09:50
10113975018	B8	Wipe	10/01/09 03:55	10/03/09 09:50
10113975019	B9	Wipe	10/01/09 04:05	10/03/09 09:50
10113975020	A.5-9.5	Wipe	10/01/09 04:10	10/03/09 09:50
10113975021	C2	Wipe	10/01/09 11:30	10/03/09 09:50
10113975022	C.5-2.5	Wipe	10/01/09 11:35	10/03/09 09:50
10113975023	C3	Wipe	10/01/09 01:30	10/03/09 09:50
10113975024	C4	Wipe	10/01/09 01:35	10/03/09 09:50
10113975025	C5	Wipe	10/01/09 01:50	10/03/09 09:50
10113975026	C6	Wipe	10/01/09 02:30	10/03/09 09:50
10113975027	C.5-6.5	Wipe	10/01/09 12:55	10/03/09 09:50
10113975028	C7	Wipe	10/01/09 02:35	10/03/09 09:50
10113975029	C8	Wipe	10/01/09 02:40	10/03/09 09:50
10113975030	C.5-8.5	Wipe	10/01/09 02:55	10/03/09 09:50
10113975031	C9	Wipe	10/01/09 02:50	10/03/09 09:50
10113975032	C.5-9	Wipe	10/01/09 03:15	10/03/09 09:50
10113975033	D2	Wipe	10/01/09 11:40	10/03/09 09:50
10113975034	D3	Wipe	10/01/09 12:30	10/03/09 09:50
10113975035	D4	Wipe	10/01/09 12:40	10/03/09 09:50
10113975036	D5	Wipe	10/01/09 12:45	10/03/09 09:50
10113975037	D6	Wipe	10/01/09 12:50	10/03/09 09:50

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE SUMMARY

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Lab ID	Sample ID	Matrix	Date Collected	Date Received
10113975038	**D7**	Wipe	10/01/09 01:00	10/03/09 09:50
10113975039	**D8**	Wipe	10/01/09 03:00	10/03/09 09:50
10113975040	**D9**	Wipe	10/01/09 03:05	10/03/09 09:50
10113975041	**A.5-8.5**	Wipe	10/01/09 04:00	10/03/09 09:50
10113975042	**E2**	Wipe	10/01/09 11:45	10/03/09 09:50
10113975043	**E.5-2.5**	Wipe	10/01/09 11:50	10/03/09 09:50
10113975044	**D.5-3.5**	Wipe	10/01/09 01:20	10/03/09 09:50
10113975045	**E6**	Wipe	10/01/09 03:35	10/03/09 09:50
10113975046	**E7**	Wipe	10/01/09 03:30	10/03/09 09:50
10113975047	**E8**	Wipe	10/01/09 03:25	10/03/09 09:50
10113975048	**E9**	Wipe	10/01/09 03:20	10/03/09 09:50
10113975049	**C.5-4.5**	Wipe	10/01/09 01:40	10/03/09 09:50
10113975050	**FIELD BLANK**	Wipe	10/01/09 04:30	10/03/09 09:50

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE ANALYTE COUNT

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Lab ID	Sample ID	Method	Analysts	Analytes Reported
10113975001	A1	EPA 8082	KL1	10
10113975002	A.5-2	EPA 8082	KL1	10
10113975003	A3	EPA 8082	KL1	10
10113975004	A.5-4	EPA 8082	KL1	10
10113975005	A5	EPA 8082	KL1	10
10113975006	A5.6	EPA 8082	KL1	10
10113975007	A7	EPA 8082	KL1	10
10113975008	A8	EPA 8082	KL1	10
10113975009	A9	EPA 8082	KL1	10
10113975010	A10	EPA 8082	KL1	10
10113975011	B1	EPA 8082	KL1	10
10113975012	B2	EPA 8082	KL1	10
10113975013	B3	EPA 8082	KL1	10
10113975014	B4	EPA 8082	KL1	10
10113975015	B5	EPA 8082	KL1	10
10113975016	B6	EPA 8082	KL1	10
10113975017	B7	EPA 8082	KL1	10
10113975018	B8	EPA 8082	KL1	10
10113975019	B9	EPA 8082	KL1	10
10113975020	A.5-9.5	EPA 8082	KL1	10
10113975021	C2	EPA 8082	KL1	10
10113975022	C.5-2.5	EPA 8082	KL1	10
10113975023	C3	EPA 8082	KL1	10
10113975024	C4	EPA 8082	KL1	10
10113975025	C5	EPA 8082	KL1	10
10113975026	C6	EPA 8082	KL1	10
10113975027	C.5-6.5	EPA 8082	KL1	10
10113975028	C7	EPA 8082	KL1	10
10113975029	C8	EPA 8082	KL1	10
10113975030	C.5-8.5	EPA 8082	KL1	10
10113975031	C9	EPA 8082	KL1	10
10113975032	C.5-9	EPA 8082	KL1	10
10113975033	D2	EPA 8082	KL1	10
10113975034	D3	EPA 8082	KL1	10
10113975035	D4	EPA 8082	KL1	10
10113975036	D5	EPA 8082	KL1	10
10113975037	D6	EPA 8082	KL1	10

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE ANALYTE COUNT

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Lab ID	Sample ID	Method	Analysts	Analytes Reported
10113975038	D7	EPA 8082	KL1	10
10113975039	D8	EPA 8082	KL1	10
10113975040	D9	EPA 8082	KL1	10
10113975041	A.5-8.5	EPA 8082	KL1	10
10113975042	E2	EPA 8082	KL1	10
10113975043	E.5-2.5	EPA 8082	KL1	10
10113975044	D.5-3.5	EPA 8082	KL1	10
10113975045	E6	EPA 8082	KL1	10
10113975046	E7	EPA 8082	KL1	10
10113975047	E8	EPA 8082	KL1	10
10113975048	E9	EPA 8082	KL1	10
10113975049	C.5-4.5	EPA 8082	KL1	10
10113975050	FIELD BLANK	EPA 8082	KL1	10

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A1 **Lab ID: 10113975001** Collected: 10/01/09 10:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	11097-69-1	
PCB-1260 (Aroclor 1260)	**2.1**	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 21:45	11100-14-4	
Tetrachloro-m-xylene (S)	87	%	47-150	1	10/06/09 14:51	10/07/09 21:45	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:51	10/07/09 21:45	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A.5-2 **Lab ID: 10113975002** Collected: 10/01/09 10:45 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	11097-69-1	
PCB-1260 (Aroclor 1260)	**4.1**	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:01	11100-14-4	
Tetrachloro-m-xylene (S)	78	%	47-150	1	10/06/09 14:51	10/07/09 22:01	877-09-8	
Decachlorobiphenyl (S)	66	%	40-150	1	10/06/09 14:51	10/07/09 22:01	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A3 **Lab ID: 10113975003** Collected: 10/01/09 10:55 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	11097-69-1	
PCB-1260 (Aroclor 1260)	1.9	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:17	11100-14-4	
Tetrachloro-m-xylene (S)	102	%	47-150	1	10/06/09 14:51	10/07/09 22:17	877-09-8	
Decachlorobiphenyl (S)	87	%	40-150	1	10/06/09 14:51	10/07/09 22:17	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A.5-4 **Lab ID: 10113975004** Collected: 10/01/09 11:00 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	11097-69-1	
PCB-1260 (Aroclor 1260)	**2.4**	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:33	11100-14-4	
Tetrachloro-m-xylene (S)	85	%	47-150	1	10/06/09 14:51	10/07/09 22:33	877-09-8	
Decachlorobiphenyl (S)	77	%	40-150	1	10/06/09 14:51	10/07/09 22:33	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A5 **Lab ID: 10113975005** Collected: 10/01/09 11:10 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	11097-69-1	
PCB-1260 (Aroclor 1260)	1.5	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 22:49	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/06/09 14:51	10/07/09 22:49	877-09-8	
Decachlorobiphenyl (S)	71	%	40-150	1	10/06/09 14:51	10/07/09 22:49	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A5.6 **Lab ID: 10113975006** Collected: 10/01/09 11:15 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:05	11100-14-4	
Tetrachloro-m-xylene (S)	80	%	47-150	1	10/06/09 14:51	10/07/09 23:05	877-09-8	
Decachlorobiphenyl (S)	74	%	40-150	1	10/06/09 14:51	10/07/09 23:05	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A7 **Lab ID: 10113975007** Collected: 10/01/09 02:15 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	53469-21-9	
PCB-1248 (Aroclor 1248)	**1.2**	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	11097-69-1	
PCB-1260 (Aroclor 1260)	**3.4**	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/07/09 23:21	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/06/09 14:51	10/07/09 23:21	877-09-8	
Decachlorobiphenyl (S)	71	%	40-150	1	10/06/09 14:51	10/07/09 23:21	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A8 **Lab ID: 10113975008** Collected: 10/01/09 04:15 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	11097-69-1	
PCB-1260 (Aroclor 1260)	**10.4**	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:25	11100-14-4	
Tetrachloro-m-xylene (S)	78	%	47-150	1	10/06/09 14:51	10/08/09 00:25	877-09-8	
Decachlorobiphenyl (S)	72	%	40-150	1	10/06/09 14:51	10/08/09 00:25	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A9 **Lab ID: 10113975009** Collected: 10/01/09 04:20 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	11097-69-1	
PCB-1260 (Aroclor 1260)	5.3	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:41	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/06/09 14:51	10/08/09 00:41	877-09-8	
Decachlorobiphenyl (S)	72	%	40-150	1	10/06/09 14:51	10/08/09 00:41	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A10 **Lab ID: 10113975010** Collected: 10/01/09 04:25 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	11097-69-1	
PCB-1260 (Aroclor 1260)	**6.6**	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 00:56	11100-14-4	
Tetrachloro-m-xylene (S)	88	%	47-150	1	10/06/09 14:51	10/08/09 00:56	877-09-8	
Decachlorobiphenyl (S)	81	%	40-150	1	10/06/09 14:51	10/08/09 00:56	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B1 **Lab ID: 10113975011** Collected: 10/01/09 10:40 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	11097-69-1	
PCB-1260 (Aroclor 1260)	59.7	Total ug	5.0	5	10/06/09 14:51	10/09/09 00:42	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:12	11100-14-4	
Tetrachloro-m-xylene (S)	89	%	47-150	1	10/06/09 14:51	10/08/09 01:12	877-09-8	
Decachlorobiphenyl (S)	78	%	40-150	1	10/06/09 14:51	10/08/09 01:12	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B2 **Lab ID: 10113975012** Collected: 10/01/09 11:20 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	11097-69-1	
PCB-1260 (Aroclor 1260)	**9.2**	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:28	11100-14-4	
Tetrachloro-m-xylene (S)	75	%	47-150	1	10/06/09 14:51	10/08/09 01:28	877-09-8	
Decachlorobiphenyl (S)	60	%	40-150	1	10/06/09 14:51	10/08/09 01:28	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B3 **Lab ID: 10113975013** Collected: 10/01/09 10:50 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 01:44	11100-14-4	
Tetrachloro-m-xylene (S)	82	%	47-150	1	10/06/09 14:51	10/08/09 01:44	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:51	10/08/09 01:44	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B4 **Lab ID: 10113975014** Collected: 10/01/09 02:00 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	11097-69-1	
PCB-1260 (Aroclor 1260)	**23.7**	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:00	11100-14-4	
Tetrachloro-m-xylene (S)	78	%	47-150	1	10/06/09 14:51	10/08/09 02:00	877-09-8	
Decachlorobiphenyl (S)	80	%	40-150	1	10/06/09 14:51	10/08/09 02:00	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical®
www.pacelabs.com

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B5 **Lab ID: 10113975015** Collected: 10/01/09 11:05 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	11097-69-1	
PCB-1260 (Aroclor 1260)	**2.0**	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:16	11100-14-4	
Tetrachloro-m-xylene (S)	79	%	47-150	1	10/06/09 14:51	10/08/09 02:16	877-09-8	
Decachlorobiphenyl (S)	73	%	40-150	1	10/06/09 14:51	10/08/09 02:16	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B6 **Lab ID: 10113975016** Collected: 10/01/09 02:10 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	11097-69-1	
PCB-1260 (Aroclor 1260)	**23.2**	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 02:32	11100-14-4	
Tetrachloro-m-xylene (S)	82	%	47-150	1	10/06/09 14:51	10/08/09 02:32	877-09-8	
Decachlorobiphenyl (S)	70	%	40-150	1	10/06/09 14:51	10/08/09 02:32	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B7 **Lab ID: 10113975017** Collected: 10/01/09 02:20 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	11097-69-1	
PCB-1260 (Aroclor 1260)	**11.5**	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:20	11100-14-4	
Tetrachloro-m-xylene (S)	85	%	47-150	1	10/06/09 14:51	10/08/09 03:20	877-09-8	
Decachlorobiphenyl (S)	71	%	40-150	1	10/06/09 14:51	10/08/09 03:20	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B8 **Lab ID: 10113975018** Collected: 10/01/09 03:55 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	11097-69-1	
PCB-1260 (Aroclor 1260)	**2.1**	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:36	11100-14-4	
Tetrachloro-m-xylene (S)	75	%	47-150	1	10/06/09 14:51	10/08/09 03:36	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:51	10/08/09 03:36	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: B9 **Lab ID: 10113975019** Collected: 10/01/09 04:05 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 03:52	11100-14-4	
Tetrachloro-m-xylene (S)	100	%	47-150	1	10/06/09 14:51	10/08/09 03:52	877-09-8	
Decachlorobiphenyl (S)	91	%	40-150	1	10/06/09 14:51	10/08/09 03:52	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A.5-9.5 **Lab ID: 10113975020** Collected: 10/01/09 04:10 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:51	10/08/09 04:08	11100-14-4	
Tetrachloro-m-xylene (S)	88	%	47-150	1	10/06/09 14:51	10/08/09 04:08	877-09-8	
Decachlorobiphenyl (S)	78	%	40-150	1	10/06/09 14:51	10/08/09 04:08	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C2 **Lab ID: 10113975021** Collected: 10/01/09 11:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	11097-69-1	
PCB-1260 (Aroclor 1260)	**3.0**	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:02	11100-14-4	
Tetrachloro-m-xylene (S)	69	%	47-150	1	10/06/09 14:50	10/08/09 18:02	877-09-8	
Decachlorobiphenyl (S)	64	%	40-150	1	10/06/09 14:50	10/08/09 18:02	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C.5-2.5 **Lab ID: 10113975022** Collected: 10/01/09 11:35 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	11097-69-1	
PCB-1260 (Aroclor 1260)	**4.0**	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:18	11100-14-4	
Tetrachloro-m-xylene (S)	70	%	47-150	1	10/06/09 14:50	10/08/09 18:18	877-09-8	
Decachlorobiphenyl (S)	67	%	40-150	1	10/06/09 14:50	10/08/09 18:18	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C3 **Lab ID: 10113975023** Collected: 10/01/09 01:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	11097-69-1	
PCB-1260 (Aroclor 1260)	5.6	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:34	11100-14-4	
Tetrachloro-m-xylene (S)	78	%	47-150	1	10/06/09 14:50	10/08/09 18:34	877-09-8	
Decachlorobiphenyl (S)	64	%	40-150	1	10/06/09 14:50	10/08/09 18:34	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C4 **Lab ID: 10113975024** Collected: 10/01/09 01:35 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	11097-69-1	
PCB-1260 (Aroclor 1260)	**4.5**	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 18:50	11100-14-4	
Tetrachloro-m-xylene (S)	87	%	47-150	1	10/06/09 14:50	10/08/09 18:50	877-09-8	
Decachlorobiphenyl (S)	73	%	40-150	1	10/06/09 14:50	10/08/09 18:50	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C5 **Lab ID: 10113975025** Collected: 10/01/09 01:50 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:06	11100-14-4	
Tetrachloro-m-xylene (S)	79	%	47-150	1	10/06/09 14:50	10/08/09 19:06	877-09-8	
Decachlorobiphenyl (S)	73	%	40-150	1	10/06/09 14:50	10/08/09 19:06	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C6 **Lab ID: 10113975026** Collected: 10/01/09 02:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:22	11100-14-4	
Tetrachloro-m-xylene (S)	83	%	47-150	1	10/06/09 14:50	10/08/09 19:22	877-09-8	
Decachlorobiphenyl (S)	77	%	40-150	1	10/06/09 14:50	10/08/09 19:22	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C.5-6.5 **Lab ID: 10113975027** Collected: 10/01/09 12:55 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 19:38	11100-14-4	
Tetrachloro-m-xylene (S)	79	%	47-150	1	10/06/09 14:50	10/08/09 19:38	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:50	10/08/09 19:38	2051-24-3	

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C7 **Lab ID: 10113975028** Collected: 10/01/09 02:35 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	11097-69-1	
PCB-1260 (Aroclor 1260)	**1.8**	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:42	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/06/09 14:50	10/08/09 20:42	877-09-8	
Decachlorobiphenyl (S)	71	%	40-150	1	10/06/09 14:50	10/08/09 20:42	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C8 **Lab ID: 10113975029** Collected: 10/01/09 02:40 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	11097-69-1	
PCB-1260 (Aroclor 1260)	7.2	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 20:58	11100-14-4	
Tetrachloro-m-xylene (S)	85	%	47-150	1	10/06/09 14:50	10/08/09 20:58	877-09-8	
Decachlorobiphenyl (S)	79	%	40-150	1	10/06/09 14:50	10/08/09 20:58	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C.5-8.5 **Lab ID: 10113975030** Collected: 10/01/09 02:55 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:14	11100-14-4	
Tetrachloro-m-xylene (S)	79	%	47-150	1	10/06/09 14:50	10/08/09 21:14	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:50	10/08/09 21:14	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical
www.pacelabs.com

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C9 **Lab ID: 10113975031** Collected: 10/01/09 02:50 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:30	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/06/09 14:50	10/08/09 21:30	877-09-8	
Decachlorobiphenyl (S)	70	%	40-150	1	10/06/09 14:50	10/08/09 21:30	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C.5-9 **Lab ID: 10113975032** Collected: 10/01/09 03:15 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 21:46	11100-14-4	
Tetrachloro-m-xylene (S)	79	%	47-150	1	10/06/09 14:50	10/08/09 21:46	877-09-8	
Decachlorobiphenyl (S)	73	%	40-150	1	10/06/09 14:50	10/08/09 21:46	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D2 **Lab ID: 10113975033** Collected: 10/01/09 11:40 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:02	11100-14-4	
Tetrachloro-m-xylene (S)	91	%	47-150	1	10/06/09 14:50	10/08/09 22:02	877-09-8	
Decachlorobiphenyl (S)	87	%	40-150	1	10/06/09 14:50	10/08/09 22:02	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D3 **Lab ID: 10113975034** Collected: 10/01/09 12:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:18	11100-14-4	
Tetrachloro-m-xylene (S)	78	%	47-150	1	10/06/09 14:50	10/08/09 22:18	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:50	10/08/09 22:18	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D4 **Lab ID: 10113975035** Collected: 10/01/09 12:40 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:34	11100-14-4	
Tetrachloro-m-xylene (S)	79	%	47-150	1	10/06/09 14:50	10/08/09 22:34	877-09-8	
Decachlorobiphenyl (S)	75	%	40-150	1	10/06/09 14:50	10/08/09 22:34	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D5 **Lab ID: 10113975036** Collected: 10/01/09 12:45 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 22:50	11100-14-4	
Tetrachloro-m-xylene (S)	82	%	47-150	1	10/06/09 14:50	10/08/09 22:50	877-09-8	
Decachlorobiphenyl (S)	80	%	40-150	1	10/06/09 14:50	10/08/09 22:50	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D6 **Lab ID: 10113975037** Collected: 10/01/09 12:50 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	11097-69-1	
PCB-1260 (Aroclor 1260)	1.0	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:38	11100-14-4	
Tetrachloro-m-xylene (S)	81	%	47-150	1	10/06/09 14:50	10/08/09 23:38	877-09-8	
Decachlorobiphenyl (S)	74	%	40-150	1	10/06/09 14:50	10/08/09 23:38	2051-24-3	

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D7 **Lab ID: 10113975038** Collected: 10/01/09 01:00 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	11097-69-1	
PCB-1260 (Aroclor 1260)	**3.1**	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/08/09 23:54	11100-14-4	
Tetrachloro-m-xylene (S)	86	%	47-150	1	10/06/09 14:50	10/08/09 23:54	877-09-8	
Decachlorobiphenyl (S)	79	%	40-150	1	10/06/09 14:50	10/08/09 23:54	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D8 **Lab ID: 10113975039** Collected: 10/01/09 03:00 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:10	11100-14-4	
Tetrachloro-m-xylene (S)	84	%	47-150	1	10/06/09 14:50	10/09/09 00:10	877-09-8	
Decachlorobiphenyl (S)	80	%	40-150	1	10/06/09 14:50	10/09/09 00:10	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D9 **Lab ID: 10113975040** Collected: 10/01/09 03:05 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 14:50	10/09/09 00:26	11100-14-4	
Tetrachloro-m-xylene (S)	90	%	47-150	1	10/06/09 14:50	10/09/09 00:26	877-09-8	
Decachlorobiphenyl (S)	82	%	40-150	1	10/06/09 14:50	10/09/09 00:26	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: A.5-8.5 **Lab ID: 10113975041** Collected: 10/01/09 04:00 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	11097-69-1	
PCB-1260 (Aroclor 1260)	1.1	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 18:49	11100-14-4	
Tetrachloro-m-xylene (S)	70	%	47-150	1	10/06/09 15:53	10/07/09 18:49	877-09-8	
Decachlorobiphenyl (S)	66	%	40-150	1	10/06/09 15:53	10/07/09 18:49	2051-24-3	

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: E2 **Lab ID: 10113975042** Collected: 10/01/09 11:45 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:05	11100-14-4	
Tetrachloro-m-xylene (S)	75	%	47-150	1	10/06/09 15:53	10/07/09 19:05	877-09-8	
Decachlorobiphenyl (S)	71	%	40-150	1	10/06/09 15:53	10/07/09 19:05	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: E.5-2.5 **Lab ID: 10113975043** Collected: 10/01/09 11:50 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:21	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/06/09 15:53	10/07/09 19:21	877-09-8	
Decachlorobiphenyl (S)	70	%	40-150	1	10/06/09 15:53	10/07/09 19:21	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: D.5-3.5 **Lab ID: 10113975044** Collected: 10/01/09 01:20 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:37	11100-14-4	
Tetrachloro-m-xylene (S)	73	%	47-150	1	10/06/09 15:53	10/07/09 19:37	877-09-8	
Decachlorobiphenyl (S)	69	%	40-150	1	10/06/09 15:53	10/07/09 19:37	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: E6 **Lab ID: 10113975045** Collected: 10/01/09 03:35 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 19:53	11100-14-4	
Tetrachloro-m-xylene (S)	90	%	47-150	1	10/06/09 15:53	10/07/09 19:53	877-09-8	
Decachlorobiphenyl (S)	83	%	40-150	1	10/06/09 15:53	10/07/09 19:53	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: E7 **Lab ID: 10113975046** Collected: 10/01/09 03:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	11097-69-1	
PCB-1260 (Aroclor 1260)	**3.5**	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:09	11100-14-4	
Tetrachloro-m-xylene (S)	80	%	47-150	1	10/06/09 15:53	10/07/09 20:09	877-09-8	
Decachlorobiphenyl (S)	73	%	40-150	1	10/06/09 15:53	10/07/09 20:09	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: E8 **Lab ID: 10113975047** Collected: 10/01/09 03:25 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/07/09 20:25	11100-14-4	
Tetrachloro-m-xylene (S)	74	%	47-150	1	10/06/09 15:53	10/07/09 20:25	877-09-8	
Decachlorobiphenyl (S)	72	%	40-150	1	10/06/09 15:53	10/07/09 20:25	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: E9 **Lab ID: 10113975048** Collected: 10/01/09 03:20 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	11097-69-1	
PCB-1260 (Aroclor 1260)	**1.0**	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:24	11100-14-4	
Tetrachloro-m-xylene (S)	84	%	47-150	1	10/06/09 15:53	10/08/09 04:24	877-09-8	
Decachlorobiphenyl (S)	77	%	40-150	1	10/06/09 15:53	10/08/09 04:24	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: C.5-4.5 **Lab ID: 10113975049** Collected: 10/01/09 01:40 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:40	11100-14-4	
Tetrachloro-m-xylene (S)	87	%	47-150	1	10/06/09 15:53	10/08/09 04:40	877-09-8	
Decachlorobiphenyl (S)	81	%	40-150	1	10/06/09 15:53	10/08/09 04:40	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

Sample: FIELD BLANK **Lab ID: 10113975050** Collected: 10/01/09 04:30 Received: 10/03/09 09:50 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/06/09 15:53	10/08/09 04:56	11100-14-4	
Tetrachloro-m-xylene (S)	63	%	47-150	1	10/06/09 15:53	10/08/09 04:56	877-09-8	
Decachlorobiphenyl (S)	59	%	40-150	1	10/06/09 15:53	10/08/09 04:56	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

QC Batch: OEXT/11661 Analysis Method: EPA 8082
QC Batch Method: EPA 3580 (Wipe) Analysis Description: 8082 GCS PCB Wipe
Associated Lab Samples: 10113975001, 10113975002, 10113975003, 10113975004, 10113975005, 10113975006, 10113975007, 10113975008, 10113975009, 10113975010, 10113975011, 10113975012, 10113975013, 10113975014, 10113975015, 10113975016, 10113975017, 10113975018, 10113975019, 10113975020

METHOD BLANK: 692567 Matrix: Wipe
Associated Lab Samples: 10113975001, 10113975002, 10113975003, 10113975004, 10113975005, 10113975006, 10113975007, 10113975008, 10113975009, 10113975010, 10113975011, 10113975012, 10113975013, 10113975014, 10113975015, 10113975016, 10113975017, 10113975018, 10113975019, 10113975020

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1221 (Aroclor 1221)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1232 (Aroclor 1232)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1242 (Aroclor 1242)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1248 (Aroclor 1248)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1254 (Aroclor 1254)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1260 (Aroclor 1260)	Total ug	ND	1.0	10/07/09 21:13	
PCB-1268 (Aroclor 1268)	Total ug	ND	1.0	10/07/09 21:13	
Decachlorobiphenyl (S)	%	99	40-150	10/07/09 21:13	
Tetrachloro-m-xylene (S)	%	111	47-150	10/07/09 21:13	

LABORATORY CONTROL SAMPLE & LCSD: 692568 692569

Parameter	Units	Spike Conc.	LCS Result	LCSD Result	LCS % Rec	LCSD % Rec	% Rec Limits	RPD	Max RPD	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	10	10.6	10.7	106	107	75-146	1	20	
PCB-1260 (Aroclor 1260)	Total ug	10	10.4	10.6	104	106	75-142	2	20	
Decachlorobiphenyl (S)	%				106	106	40-150			
Tetrachloro-m-xylene (S)	%				130	138	47-150			

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

QC Batch: OEXT/11662 Analysis Method: EPA 8082
QC Batch Method: EPA 3580 (Wipe) Analysis Description: 8082 GCS PCB Wipe
Associated Lab Samples: 10113975021, 10113975022, 10113975023, 10113975024, 10113975025, 10113975026, 10113975027, 10113975028, 10113975029, 10113975030, 10113975031, 10113975032, 10113975033, 10113975034, 10113975035, 10113975036, 10113975037, 10113975038, 10113975039, 10113975040

METHOD BLANK: 692636 Matrix: Wipe
Associated Lab Samples: 10113975021, 10113975022, 10113975023, 10113975024, 10113975025, 10113975026, 10113975027, 10113975028, 10113975029, 10113975030, 10113975031, 10113975032, 10113975033, 10113975034, 10113975035, 10113975036, 10113975037, 10113975038, 10113975039, 10113975040

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1221 (Aroclor 1221)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1232 (Aroclor 1232)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1242 (Aroclor 1242)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1248 (Aroclor 1248)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1254 (Aroclor 1254)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1260 (Aroclor 1260)	Total ug	ND	1.0	10/08/09 17:30	
PCB-1268 (Aroclor 1268)	Total ug	ND	1.0	10/08/09 17:30	
Decachlorobiphenyl (S)	%	97	40-150	10/08/09 17:30	
Tetrachloro-m-xylene (S)	%	109	47-150	10/08/09 17:30	

LABORATORY CONTROL SAMPLE & LCSD: 692637 692638

Parameter	Units	Spike Conc.	LCS Result	LCSD Result	LCS % Rec	LCSD % Rec	% Rec Limits	RPD	Max RPD	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	10	10.7	10.5	107	105	75-146	2	20	
PCB-1260 (Aroclor 1260)	Total ug	10	10.2	10.5	102	105	75-142	2	20	
Decachlorobiphenyl (S)	%				103	103	40-150			
Tetrachloro-m-xylene (S)	%				130	125	47-150			

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

QC Batch: OEXT/11664 Analysis Method: EPA 8082
QC Batch Method: EPA 3580 (Wipe) Analysis Description: 8082 GCS PCB Wipe
Associated Lab Samples: 10113975041, 10113975042, 10113975043, 10113975044, 10113975045, 10113975046, 10113975047, 10113975048, 10113975049, 10113975050

METHOD BLANK: 692713 Matrix: Wipe
Associated Lab Samples: 10113975041, 10113975042, 10113975043, 10113975044, 10113975045, 10113975046, 10113975047, 10113975048, 10113975049, 10113975050

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1221 (Aroclor 1221)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1232 (Aroclor 1232)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1242 (Aroclor 1242)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1248 (Aroclor 1248)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1254 (Aroclor 1254)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1260 (Aroclor 1260)	Total ug	ND	1.0	10/07/09 18:17	
PCB-1268 (Aroclor 1268)	Total ug	ND	1.0	10/07/09 18:17	
Decachlorobiphenyl (S)	%	97	40-150	10/07/09 18:17	
Tetrachloro-m-xylene (S)	%	107	47-150	10/07/09 18:17	

LABORATORY CONTROL SAMPLE & LCSD: 692714 692715

Parameter	Units	Spike Conc.	LCS Result	LCSD Result	LCS % Rec	LCSD % Rec	% Rec Limits	RPD	Max RPD	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	10	10.1	11.6	101	116	75-146	14	20	
PCB-1260 (Aroclor 1260)	Total ug	10	10.1	11.3	101	113	75-142	10	20	
Decachlorobiphenyl (S)	%				104	110	40-150			
Tetrachloro-m-xylene (S)	%				118	130	47-150			

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALIFIERS

Project: SPX LINDBERG 9M0909245
Pace Project No.: 10113975

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

Pace Analytical is NELAP accredited. Contact your Pace PM for the current list of accredited analytes.

U - Indicates the compound was analyzed for, but not detected.

BATCH QUALIFIERS

Batch: GCSV/6068

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

Batch: GCSV/6069

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

Batch: GCSV/6077

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

1013975

Chain of Custody Record

DELTA

YEAR 2009

Project Name

State of Lead Regulatory Agency Wisconsin

Requested Due Date (mm/dd/yy) Standard TAT

COC TRACKING No.

On-site Time:	8:30AM	Temp:	Indoors
Off-site Time:	5:30PM	Temp:	NA
Sky Conditions:	Indoors		
Meteorological Events:	NA		
Wind Speed and Direction:	NA		

Lab Name:	Pace Analytical Services, Inc.	Facility No.	SPX Lindberg	Consultant	Delta Consultants
Lab Address:	1700 Elm Street, Ste. 200	Facility Address	304 Hart Street, Watertown, WI 53094	Address:	5910 Rice Creek Parkway, Ste. 10
	Minneapolis, MN 55414	Delta Project No.	9M0909245		Shoreview, MN 55126
Lab PM:	Carolynne Trout			e-mail EDD report to:	kthole@deltaenv.com
Telephone	(612) 607-1700	Reimbursement Project	Non-Reimbursement Proj / Mark one	Delta Project Mgr	Karen Thole
Fax		Invoice to:	Karen Thole, Delta PM	Delta Tele/Fax:	651-697-5203 / 651-639-9473
Lab PM Email	ctrout@pacelabs.com	Phase		Delta Contact:	Karen Thole / Adam McIlheran
	INVOICE INFORMATION	Subphase/Task		Hardcopy Report Needed	Y/N Circle One
		Cost Element		Report Type and QC level:	

Lab Bottle Order No:

Item No.	Sample ID	Time	Date	Soil	Water	Wipe	Laboratory Tracking Number	No. of containers	Unpreserved	H2SO4	HNO3	HCl	Hexane	Other	PCB by 8082	Sample Point Lat/Long Comments
1	A1	10:30 AM	10/1/09			X		1					X		X	001
2	A.5-2	10:45 AM	10/1/09			X		1					X		X	002
3	A3	10:55 AM	10/1/09			X		1					X		X	003
4	A.5-4	11:00 AM	10/1/09			X		1					X		X	004
5	A5	11:10 AM	10/1/09			X		1					X		X	005
6	A.5-6	11:15 AM	10/1/09			X		1					X		X	006
7	A7	2:15 AM	10/1/09			X		1					X		X	007
8	A8	4:15 PM	10/1/09			X		1					X		X	008
9	A9	4:20 PM	10/1/09			X		1					X		X	009
10	A10	4:25 PM	10/1/09			X		1					X		X	010

		Relinquished By / Affiliation	Date	Time	Accepted By / Affiliation	Date	Time
Sampler's Name:	Adam McIlheran	Adam D. McIlheran	10/2/09	9:30 AM	[illegible]	10/13	0950
Sampler's Company:	Delta Consultants						
Shipment Date:	10/2/09						
Shipment Method:	Fedex						
Shipment Tracking No:							

Special Instructions:

Custody seals in place (circle one) Y N | Temp Blank (circle one) Y N | Cooler Temperature on Receipt 1.0 F C (circle one) | Trip Blank? Y / N (circle one)

2.2

10113975

DELTA

YEAR 2009

Chain of Custody Record

On-site Time:	8:30AM	Temp:	indoors
Off-site Time:	5:30PM	Temp:	NA
Sky Conditions:	indoors		
Meteorological Events:	NA		
Wind Speed and Direction:	NA		

Project Name
State of Lead Regulatory Agency Wisconsin

Requested Due Date (mm/dd/yy) Standard TAT

COC TRACKING No.

Lab Name:	Pace Analytical Services, Inc.	Facility No.	SPX Lindberg	Consultant	Delta Consultants
Lab Address:	1700 Elm Street, Ste. 200	Facility Address	304 Hart Street, Watertown, WI 53094	Address:	5910 Rice Creek Parkway, Ste. 10
	Minneapolis, MN 55414	Delta Project No.	9M0909245		Shoreview, MN 55126
Lab PM:	Carolynne Trout			e-mail EDD report to:	kthole@deltaenv.com
Telephone	(612) 607-1700	Reimbursement Project	Non-Reimbursement Proj / Mark one	Delta Project Mgr	Karen Thole
Fax		Invoice to:	Karen Thole, Delta PM	Delta Tele/Fax:	651-697-5203 / 651-639-9473
Lab PM Email	ctrout@pacelabs.com	Phase		Delta Contact:	Karen Thole / Adam McIlheran
	INVOICE INFORMATION	Subphase/Task		Hardcopy Report Needed	Y/N Circle One
		Cost Element		Report Type and QC level:	

Lab Bottle Order No:

Item No.	Sample ID	Time	Date	Soil	Water	Wipe	Laboratory Tracking Number	No. of containers	Unpreserved	H2SO4	HNO3	HCl	Hexane	Other	PCB by 8082	Sample Point Lat/Long Comments
1	B1	10:40 AM	10/1/09			X		1					X		X	011
2	B2	11:20 AM	10/1/09			X		1					X		X	012
3	B3	10:50 AM	10/1/09			X		1					X		X	013
4	B4	2:00 PM	10/1/09			X		1					X		X	014
5	B5	11:05 AM	10/1/09			X		1					X		X	015
6	B6	2:10 PM	10/1/09			X		1					X		X	016
7	B7	2:20 PM	10/1/09			X		1					X		X	017
8	B8	3:55 PM	10/1/09			X		1					X		X	018
9	B9	4:05 PM	10/1/09			X		1					X		X	019
10	A.5-9.5	4:10 PM	10/1/09			X		1					X		X	020

		Relinquished By / Affiliation	Date	Time	Accepted By / Affiliation	Date	Time
Sampler's Name:	Adam McIlheran						
Sampler's Company:	Delta Consultants		10/2/09	9:30 AM		10/5	0950
Shipment Date:	10/2/09						
Shipment Method:	Fedex						
Shipment Tracking No:							

Special Instructions:

Custody seals in place (circle one) Y N | Temp Blank (circle one) Y N | Cooler Temperature on Receipt 1.0 F C (circle one) | Trip Blank? Y / N (circle one)

2.2

1013975

Chain of Custody Record

DELTA

YEAR 2009

Project Name

State of Lead Regulatory Agency Wisconsin

Requested Due Date (mm/dd/yy) Standard TAT

COC TRACKING No.

On-site Time:	8:30AM	Temp:	indoors
Off-site Time:	5:30PM	Temp:	NA
Sky Conditions:	indoors		
Meteorological Events:	NA		
Wind Speed and Direction:	NA		

Lab Name:	Pace Analytical Services, Inc.	Facility No.	SPX Lindberg	Consultant	Delta Consultants
Lab Address:	1700 Elm Street, Ste. 200	Facility Address	304 Hart Street, Watertown, WI 53094	Address:	5910 Rice Creek Parkway, Ste. 10
	Minneapolis, MN 55414	Delta Project No.	9M0909245		Shoreview, MN 55126
Lab PM:	Carolynne Trout			e-mail EDD report to:	kthole@deltaenv.com
Telephone	(612) 607-1700	Reimbursement Project	Non-Reimbursement Proj	Mark one	Delta Project Mgr: Karen Thole
Fax		Invoice to:	Karen Thole, Delta PM	Delta Tele/Fax:	651-697-5203 / 651-639-9473
Lab PM Email	ctrout@pacelabs.com	Phase		Delta Contact:	Karen Thole / Adam McIlheran
	INVOICE INFORMATION	Subphase/Task		Hardcopy Report Needed	Y/N Circle One
		Cost Element		Report Type and QC level:	

Lab Bottle Order No:

Item No.	Sample ID	Time	Date	Soil	Water	Wipe	Laboratory Tracking Number	No. of containers	Unpreserved	H2SO4	HNO3	HCl	Hexane	Other	PCB by 8082	Sample Point Lat/Long Comments
1	C2	11:30 AM	10/1/09			X		1					X		X	021
2	C.5-2.5	11:35 AM	10/1/09			X		1					X		X	022
3	C3	1:30 PM	10/1/09			X		1					X		X	023
4	C4	1:35 PM	10/1/09			X		1					X		X	024
5	C5	1:50 AM	10/1/09			X		1					X		X	025
6	C6	2:30 PM	10/1/09			X		1					X		X	026
7	C.5-6.5	12:55 PM	10/1/09			X		1					X		X	027
8	C7	2:35 PM	10/1/09			X		1					X		X	028
9	C8	2:40 PM	10/1/09			X		1					X		X	029
10	C.5-8.5	2:55 PM	10/1/09			X		1					X		X	030

		Relinquished By / Affiliation	Date	Time	Accepted By / Affiliation	Date	Time
Sampler's Name:	Adam McIlheran	Adam S. McIlheran	10/2/09	9:30 AM	Pace	10/5	0950
Sampler's Company:	Delta Consultants						
Shipment Date:	10/2/09						
Shipment Method:	Fedex						
Shipment Tracking No:							

Special Instructions:

Custody seals in place (circle one) Y N | Temp Blank (circle one) Y N | Cooler Temperature on Receipt 1.0 F C (circle one) | Trip Blank? Y / N (circle one)

2.2

3085

1013975

DELTA

YEAR 2009

Chain of Custody Record

On-site Time:	8:30AM	Temp:	indoors
Off-site Time:	5:30PM	Temp:	NA
Sky Conditions:	indoors		
Meteorological Events:	NA		
Wind Speed and Direction:	NA		

Project Name

State of Lead Regulatory Agency Wisconsin

Requested Due Date (mm/dd/yy) Standard TAT

COC TRACKING No.

Lab Name:	Pace Analytical Services, Inc.	Facility No.	SPX Lindberg	Consultant	Delta Consultants
Lab Address:	1700 Elm Street, Ste. 200	Facility Address	304 Hart Street, Watertown, WI 53094	Address:	5910 Rice Creek Parkway, Ste. 10
	Minneapolis, MN 55414	Delta Project No.	9M0909245		Shoreview, MN 55126
Lab PM:	Carolynne Trout			e-mail EDD report to:	kthole@deltaenv.com
Telephone	(612) 607-1700	Reimbursement Project	Non-Reimbursement Proj (Mark one)	Delta Project Mgr	Karen Thole
Fax		Invoice to:	Karen Thole, Delta PM	Delta Tele/Fax:	651-697-5203 / 651-639-9473
Lab PM Email	ctrout@pacelabs.com	Phase		Delta Contact:	Karen Thole / Adam McIlheran
	INVOICE INFORMATION	Subphase/Task		Hardcopy Report Needed	Y/N Circle One
		Cost Element		Report Type and QC level:	

Lab Bottle Order No:

Item No.	Sample ID	Time	Date	Matrix: Soil	Matrix: Water	Matrix: Wipe	Laboratory Tracking Number	No. of containers	Preservatives: Unpreserved	H2SO4	HNO3	HCl	Hexane	Other	Requested Analysis: PCB by 8082	Sample Point Lat/Long Comments
1	C9	2:50 PM	10/1/09			X		1					X		X	031
2	C.5-9	3:15 PM	10/1/09			X		1					X		X	032
3	D2	11:40 AM	10/1/09			X		1					X		X	033
4	D3	12:30 PM	10/1/09			X		1					X		X	034
5	D4	12:40 PM	10/1/09			X		1					X		X	035
6	D5	12:45 PM	10/1/09			X		1					X		X	036
7	D6	12:50 PM	10/1/09			X		1					X		X	037
8	D7	1:00 PM	10/1/09			X		1					X		X	038
9	D8	3:00 PM	10/1/09			X		1					X		X	039
10	D9	3:05 PM	10/1/09			X		1					X		X	040

		Relinquished By / Affiliation	Date	Time	Accepted By / Affiliation	Date	Time
Sampler's Name:	Adam McIlheran						
Sampler's Company:	Delta Consultants						
Shipment Date:	10/2/09						
Shipment Method:	Fedex						
Shipment Tracking No:							

Special Instructions:

Custody seals in place (circle one) Y N | Temp Blank (circle one) Y N | Cooler Temperature on Receipt 4.0 2.2 F C (circle one) | Trip Blank? Y / N (circle one)

1013975

On-site Time:	8:30AM	Temp:	indoors
Off-site Time:	5:30PM	Temp:	NA
Sky Conditions:	indoors		
Meteorological Events:	NA		
Wind Speed and Direction:	NA		

DELTA

Chain of Custody Record

YEAR 2009

Project Name

State of Lead Regulatory Agency Wisconsin

Requested Due Date (mm/dd/yy) Standard TAT

COC TRACKING No.

Lab Name:	Pace Analytical Services, Inc.	Facility No.	SPX Lindberg	Consultant	Delta Consultants
Lab Address:	1700 Elm Street, Ste. 200	Facility Address	304 Hart Street, Watertown, WI 53094	Address:	5910 Rice Creek Parkway, Ste. 10
	Minneapolis, MN 55414	Delta Project No.	9M0909245		Shoreview, MN 55126
Lab PM:	Carolynne Trout			e-mail EDD report to:	kthole@deltaenv.com
Telephone	(612) 607-1700	Reimbursement Project	Non-Reimbursement Proj (Mark one)	Delta Project Mgr	Karen Thole
Fax		Invoice to:	Karen Thole, Delta PM	Delta Tele/Fax:	651-697-5203 / 651-639-9473
Lab PM Email	ctrout@pacelabs.com	Phase		Delta Contact:	Karen Thole / Adam McIlheran
	INVOICE INFORMATION	Subphase/Task		Hardcopy Report Needed	Y/N Circle One
		Cost Element		Report Type and QC level:	

Lab Bottle Order No:

Item No.	Sample ID	Time	Date	Matrix: Soil	Matrix: Water	Matrix: Wipe	Laboratory Tracking Number	No. of containers	Preservatives: Unpreserved	H2SO4	HNO3	HCl	Hexane	Other	Requested Analysis: PCB by 8082	Sample Point Lat/Long Comments
1	A.5-8.5	4:00 PM	10/1/09			X		1					X		X	041
2	E2	11:45 AM	10/1/09			X		1					X		X	042
3	E.5-2.5	11:50 AM	10/1/09			X		1					X		X	043
4	D.5-3.5	1:20 PM	10/1/09			X		1					X		X	044
5	E6	3:35 PM	10/1/09			X		1					X		X	045
6	E7	3:30 PM	10/1/09			X		1					X		X	046
7	E8	3:25 PM	10/1/09			X		1					X		X	047
8	E9	3:20 PM	10/1/09			X		1					X		X	048
9	C.5-4.5	1:40 PM	10/1/09			X		1					X		X	049
10	FIELD BLANK	4:30 PM	10/1/09			X		1					X		X	050

		Relinquished By / Affiliation	Date	Time	Accepted By / Affiliation	Date	Time
Sampler's Name:	Adam McIlheran						
Sampler's Company:	Delta Consultants		10/2/09	9:30 AM		10/3	0450
Shipment Date:	10/2/09						
Shipment Method:	Fedex						
Shipment Tracking No:							

Special Instructions:

Custody seals in place (circle one) Y N | Temp Blank (circle one) Y N | Cooler Temperature on Receipt 2.2 °F °C (circle one) | Trip Blank? Y / N (circle one)

Sample Condition Upon Receipt

Pace Analytical

Client Name: DeHn-wi **Project #** 10113975

Courier: ☑ Fed Ex ☐ UPS ☐ USPS ☐ Client ☐ Commercial ☐ Pace Other _____

Tracking #: 797984837134, 796997185299

Custody Seal on Cooler/Box Present: ☑ yes ☐ no **Seals Intact:** ☑ yes ☐ no

Packing Material: ☐ Bubble Wrap ☑ Bubble Bags ☐ None ☐ Other _____ **Temp Blank:** Yes ✓ No _____

Thermometer Used ~~80344042 or~~ 179425 **Type of Ice:** Wet Blue None ☐ Samples on ice, cooling process has begun

Cooler Temperature 1.0°C, 2.2°C **Biological Tissue is Frozen:** Yes No

Temp should be above freezing to 6°C

Date and initials of person examining contents: 10/3/09

Comments:

Chain of Custody Present:	☑Yes ☐No ☐N/A	1.
Chain of Custody Filled Out:	☑Yes ☐No ☐N/A	2.
Chain of Custody Relinquished:	☑Yes ☐No ☐N/A	3.
Sampler Name & Signature on COC:	☑Yes ☐No ☐N/A	4.
Samples Arrived within Hold Time:	☑Yes ☐No ☐N/A	5.
Short Hold Time Analysis (<72hr):	☐Yes ☑No ☐N/A	6.
Rush Turn Around Time Requested:	☐Yes ☑No ☐N/A	7.
Sufficient Volume:	☑Yes ☐No ☐N/A	8.
Correct Containers Used:	☑Yes ☐No ☐N/A	9.
-Pace Containers Used:	☑Yes ☐No ☐N/A	
Containers Intact:	☑Yes ☐No ☐N/A	10.
Filtered volume received for Dissolved tests	☐Yes ☐No ☑N/A	11.
Sample Labels match COC:	☑Yes ☐No ☐N/A	12.
-Includes date/time/ID/Analysis Matrix: wipes		
All containers needing acid/base preservation have been checked. Noncompliance are noted in 13.	☐Yes ☐No ☑N/A	13. ☐ HNO3 ☐ H2SO4 ☐ NaOH ☐ HCl
All containers needing preservation are found to be in compliance with EPA recommendation.	☐Yes ☐No ☑N/A	Samp #
Exceptions: VOA,Coliform, TOC, Oil and Grease, WI-DRO (water	☐Yes ☑No	Initial when completed / Lot # of added preservative
Samples checked for dechlorination:	☐Yes ☐No ☑N/A	14.
Headspace in VOA Vials (>6mm):	☐Yes ☐No ☑N/A	15.
Trip Blank Present:	☐Yes ☐No ☑N/A	16.
Trip Blank Custody Seals Present	☐Yes ☐No ☑N/A	
Pace Trip Blank Lot # (if purchased): _____		

Client Notification/ Resolution: Field Data Required? Y / N

Person Contacted: _____ Date/Time: _____

Comments/ Resolution: _____

Project Manager Review: CDmt **Date:** 10/5/09

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR, Inc.

F-L213Rev.00, 05Aug2009 1700 Elm Street SE, Suite 200, Minneapolis, MN 55414

Pace Analytical
www.pacelabs.com

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

November 06, 2009

Ms. Karen Thole
Delta Consultants
5910 Rice Creek Parkway
Saint Paul, MN 55126

RE: Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Dear Ms. Thole:
Enclosed are the analytical results for sample(s) received by the laboratory on October 29, 2009. The results relate only to the samples included in this report. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Carolynne Trout

Carolynne Trout

carolynne.trout@pacelabs.com
Project Manager

Enclosures

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

nelac

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

CERTIFICATIONS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Minnesota Certification IDs
1700 Elm Street SE, Suite 200 Minneapolis, MN 55414
Alaska Certification #: UST-078
Washington Certification #: C754
Tennessee Certification #: 02818
Pennsylvania Certification #: 68-00563
Oregon Certification #: MN200001
North Dakota Certification #: R-036
North Carolina Certification #: 530
New York Certification #: 11647
New Jersey Certification #: MN-002
Montana Certification #: MT CERT0092
Minnesota Certification #: 027-053-137
Maine Certification #: 2007029
Louisiana Certification #: LA080009
Louisiana Certification #: 03086
Kansas Certification #: E-10167
Iowa Certification #: 368
Illinois Certification #: 200011
Florida/NELAP Certification #: E87605
California Certification #: 01155CA
Arizona Certification #: AZ-0014
Wisconsin Certification #: 999407970

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE SUMMARY

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Lab ID	Sample ID	Matrix	Date Collected	Date Received
10115796001	W1	Wipe	10/27/09 10:15	10/29/09 09:48
10115796002	W2	Wipe	10/27/09 10:20	10/29/09 09:48
10115796003	W3	Wipe	10/27/09 10:25	10/29/09 09:48
10115796004	W4	Wipe	10/27/09 10:50	10/29/09 09:48
10115796005	W5	Wipe	10/27/09 11:00	10/29/09 09:48
10115796006	W6	Wipe	10/27/09 11:15	10/29/09 09:48
10115796007	W7	Wipe	10/27/09 11:30	10/29/09 09:48
10115796008	W8	Wipe	10/27/09 11:20	10/29/09 09:48
10115796009	W9	Wipe	10/27/09 11:35	10/29/09 09:48
10115796010	W10	Wipe	10/27/09 11:45	10/29/09 09:48
10115796011	W11	Wipe	10/27/09 11:50	10/29/09 09:48
10115796012	W12	Wipe	10/27/09 11:55	10/29/09 09:48
10115796013	W13	Wipe	10/27/09 12:00	10/29/09 09:48
10115796014	W14	Wipe	10/27/09 12:10	10/29/09 09:48
10115796015	W15	Wipe	10/27/09 12:20	10/29/09 09:48
10115796016	W16	Wipe	10/27/09 12:25	10/29/09 09:48
10115796017	W17	Wipe	10/27/09 12:30	10/29/09 09:48
10115796018	W18	Wipe	10/27/09 12:50	10/29/09 09:48
10115796019	W19	Wipe	10/27/09 12:55	10/29/09 09:48
10115796020	W20	Wipe	10/27/09 13:00	10/29/09 09:48
10115796021	FIELD BLANK	Wipe	10/27/09 00:00	10/29/09 09:48

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE ANALYTE COUNT

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Lab ID	Sample ID	Method	Analysts	Analytes Reported
10115796001	W1	EPA 8082	KL1	10
10115796002	W2	EPA 8082	KL1	10
10115796003	W3	EPA 8082	KL1	10
10115796004	W4	EPA 8082	KL1	10
10115796005	W5	EPA 8082	KL1	10
10115796006	W6	EPA 8082	KL1	10
10115796008	W8	EPA 8082	KL1	10
10115796009	W9	EPA 8082	KL1	10
10115796010	W10	EPA 8082	KL1	10
10115796011	W11	EPA 8082	KL1	10
10115796012	W12	EPA 8082	KL1	10
10115796013	W13	EPA 8082	KL1	10
10115796014	W14	EPA 8082	KL1	10
10115796015	W15	EPA 8082	KL1	10
10115796016	W16	EPA 8082	KL1	10
10115796017	W17	EPA 8082	KL1	10
10115796018	W18	EPA 8082	KL1	10
10115796019	W19	EPA 8082	KL1	10
10115796020	W20	EPA 8082	KL1	10
10115796021	FIELD BLANK	EPA 8082	KL1	10

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W1 **Lab ID: 10115796001** Collected: 10/27/09 10:15 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	11097-69-1	
PCB-1260 (Aroclor 1260)	**8.1**	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:29	11100-14-4	
Tetrachloro-m-xylene (S)	85	%	47-150	1	10/30/09 18:57	11/02/09 19:29	877-09-8	
Decachlorobiphenyl (S)	73	%	40-150	1	10/30/09 18:57	11/02/09 19:29	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W2 **Lab ID: 10115796002** Collected: 10/27/09 10:20 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	11097-69-1	
PCB-1260 (Aroclor 1260)	**9.6**	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 19:45	11100-14-4	
Tetrachloro-m-xylene (S)	86	%	47-150	1	10/30/09 18:57	11/02/09 19:45	877-09-8	
Decachlorobiphenyl (S)	70	%	40-150	1	10/30/09 18:57	11/02/09 19:45	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W3 **Lab ID: 10115796003** Collected: 10/27/09 10:25 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	11097-69-1	
PCB-1260 (Aroclor 1260)	**13.0**	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:01	11100-14-4	
Tetrachloro-m-xylene (S)	72	%	47-150	1	10/30/09 18:57	11/02/09 20:01	877-09-8	
Decachlorobiphenyl (S)	62	%	40-150	1	10/30/09 18:57	11/02/09 20:01	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W4 **Lab ID: 10115796004** Collected: 10/27/09 10:50 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	11097-69-1	
PCB-1260 (Aroclor 1260)	**4.7**	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:17	11100-14-4	
Tetrachloro-m-xylene (S)	72	%	47-150	1	10/30/09 18:57	11/02/09 20:17	877-09-8	
Decachlorobiphenyl (S)	60	%	40-150	1	10/30/09 18:57	11/02/09 20:17	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W5 **Lab ID: 10115796005** Collected: 10/27/09 11:00 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	11097-69-1	
PCB-1260 (Aroclor 1260)	11.7	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:33	11100-14-4	
Tetrachloro-m-xylene (S)	73	%	47-150	1	10/30/09 18:57	11/02/09 20:33	877-09-8	
Decachlorobiphenyl (S)	65	%	40-150	1	10/30/09 18:57	11/02/09 20:33	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W6 **Lab ID: 10115796006** Collected: 10/27/09 11:15 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	11097-69-1	
PCB-1260 (Aroclor 1260)	**8.1**	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 20:48	11100-14-4	
Tetrachloro-m-xylene (S)	72	%	47-150	1	10/30/09 18:57	11/02/09 20:48	877-09-8	
Decachlorobiphenyl (S)	61	%	40-150	1	10/30/09 18:57	11/02/09 20:48	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W8 **Lab ID: 10115796008** Collected: 10/27/09 11:20 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 21:05	11100-14-4	
Tetrachloro-m-xylene (S)	73	%	47-150	1	10/30/09 18:57	11/02/09 21:05	877-09-8	
Decachlorobiphenyl (S)	67	%	40-150	1	10/30/09 18:57	11/02/09 21:05	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W9 **Lab ID: 10115796009** Collected: 10/27/09 11:35 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	11097-69-1	
PCB-1260 (Aroclor 1260)	**14.4**	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:08	11100-14-4	
Tetrachloro-m-xylene (S)	71	%	47-150	1	10/30/09 18:57	11/02/09 22:08	877-09-8	
Decachlorobiphenyl (S)	60	%	40-150	1	10/30/09 18:57	11/02/09 22:08	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W10 **Lab ID: 10115796010** Collected: 10/27/09 11:45 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	11097-69-1	
PCB-1260 (Aroclor 1260)	10.8	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:24	11100-14-4	
Tetrachloro-m-xylene (S)	77	%	47-150	1	10/30/09 18:57	11/02/09 22:24	877-09-8	
Decachlorobiphenyl (S)	65	%	40-150	1	10/30/09 18:57	11/02/09 22:24	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W11 **Lab ID: 10115796011** Collected: 10/27/09 11:50 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	11097-69-1	
PCB-1260 (Aroclor 1260)	**6.4**	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:40	11100-14-4	
Tetrachloro-m-xylene (S)	70	%	47-150	1	10/30/09 18:57	11/02/09 22:40	877-09-8	
Decachlorobiphenyl (S)	62	%	40-150	1	10/30/09 18:57	11/02/09 22:40	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W12 **Lab ID: 10115796012** Collected: 10/27/09 11:55 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	11097-69-1	
PCB-1260 (Aroclor 1260)	7.4	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 22:56	11100-14-4	
Tetrachloro-m-xylene (S)	61	%	47-150	1	10/30/09 18:57	11/02/09 22:56	877-09-8	
Decachlorobiphenyl (S)	57	%	40-150	1	10/30/09 18:57	11/02/09 22:56	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W13 **Lab ID: 10115796013** Collected: 10/27/09 12:00 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	11097-69-1	
PCB-1260 (Aroclor 1260)	**1.7**	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:12	11100-14-4	
Tetrachloro-m-xylene (S)	64	%	47-150	1	10/30/09 18:57	11/02/09 23:12	877-09-8	
Decachlorobiphenyl (S)	60	%	40-150	1	10/30/09 18:57	11/02/09 23:12	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W14 **Lab ID: 10115796014** Collected: 10/27/09 12:10 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	11097-69-1	
PCB-1260 (Aroclor 1260)	6.6	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:28	11100-14-4	
Tetrachloro-m-xylene (S)	70	%	47-150	1	10/30/09 18:57	11/02/09 23:28	877-09-8	
Decachlorobiphenyl (S)	63	%	40-150	1	10/30/09 18:57	11/02/09 23:28	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W15 **Lab ID: 10115796015** Collected: 10/27/09 12:20 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	11097-69-1	
PCB-1260 (Aroclor 1260)	**3.8**	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 23:44	11100-14-4	
Tetrachloro-m-xylene (S)	75	%	47-150	1	10/30/09 18:57	11/02/09 23:44	877-09-8	
Decachlorobiphenyl (S)	69	%	40-150	1	10/30/09 18:57	11/02/09 23:44	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W16 **Lab ID: 10115796016** Collected: 10/27/09 12:25 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	11097-69-1	
PCB-1260 (Aroclor 1260)	**5.7**	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:00	11100-14-4	
Tetrachloro-m-xylene (S)	72	%	47-150	1	10/30/09 18:57	11/03/09 00:00	877-09-8	
Decachlorobiphenyl (S)	66	%	40-150	1	10/30/09 18:57	11/03/09 00:00	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W17 **Lab ID: 10115796017** Collected: 10/27/09 12:30 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	11097-69-1	
PCB-1260 (Aroclor 1260)	**6.3**	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 00:16	11100-14-4	
Tetrachloro-m-xylene (S)	70	%	47-150	1	10/30/09 18:57	11/03/09 00:16	877-09-8	
Decachlorobiphenyl (S)	62	%	40-150	1	10/30/09 18:57	11/03/09 00:16	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W18 **Lab ID: 10115796018** Collected: 10/27/09 12:50 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:04	11100-14-4	
Tetrachloro-m-xylene (S)	67	%	47-150	1	10/30/09 18:57	11/03/09 01:04	877-09-8	
Decachlorobiphenyl (S)	61	%	40-150	1	10/30/09 18:57	11/03/09 01:04	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W19 **Lab ID: 10115796019** Collected: 10/27/09 12:55 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	11097-69-1	
PCB-1260 (Aroclor 1260)	**7.4**	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:20	11100-14-4	
Tetrachloro-m-xylene (S)	65	%	47-150	1	10/30/09 18:57	11/03/09 01:20	877-09-8	
Decachlorobiphenyl (S)	60	%	40-150	1	10/30/09 18:57	11/03/09 01:20	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: W20 **Lab ID: 10115796020** Collected: 10/27/09 13:00 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:36	11100-14-4	
Tetrachloro-m-xylene (S)	71	%	47-150	1	10/30/09 18:57	11/03/09 01:36	877-09-8	
Decachlorobiphenyl (S)	66	%	40-150	1	10/30/09 18:57	11/03/09 01:36	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

Sample: FIELD BLANK **Lab ID: 10115796021** Collected: 10/27/09 00:00 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/03/09 01:52	11100-14-4	
Tetrachloro-m-xylene (S)	60	%	47-150	1	10/30/09 18:57	11/03/09 01:52	877-09-8	
Decachlorobiphenyl (S)	58	%	40-150	1	10/30/09 18:57	11/03/09 01:52	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

QC Batch: OEXT/11819 Analysis Method: EPA 8082
QC Batch Method: EPA 3580 (Wipe) Analysis Description: 8082 GCS PCB Wipe
Associated Lab Samples: 10115796001, 10115796002, 10115796003, 10115796004, 10115796005, 10115796006, 10115796008, 10115796009, 10115796010, 10115796011, 10115796012, 10115796013, 10115796014, 10115796015, 10115796016, 10115796017, 10115796018, 10115796019, 10115796020, 10115796021

METHOD BLANK: 705646 Matrix: Wipe
Associated Lab Samples: 10115796001, 10115796002, 10115796003, 10115796004, 10115796005, 10115796006, 10115796008, 10115796009, 10115796010, 10115796011, 10115796012, 10115796013, 10115796014, 10115796015, 10115796016, 10115796017, 10115796018, 10115796019, 10115796020, 10115796021

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1221 (Aroclor 1221)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1232 (Aroclor 1232)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1242 (Aroclor 1242)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1248 (Aroclor 1248)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1254 (Aroclor 1254)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1260 (Aroclor 1260)	Total ug	ND	1.0	11/02/09 18:57	
PCB-1268 (Aroclor 1268)	Total ug	ND	1.0	11/02/09 18:57	
Decachlorobiphenyl (S)	%	102	40-150	11/02/09 18:57	
Tetrachloro-m-xylene (S)	%	107	47-150	11/02/09 18:57	

LABORATORY CONTROL SAMPLE & LCSD: 705647 705648

Parameter	Units	Spike Conc.	LCS Result	LCSD Result	LCS % Rec	LCSD % Rec	% Rec Limits	RPD	Max RPD	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	10	11.4	11.2	114	112	75-146	1	20	
PCB-1260 (Aroclor 1260)	Total ug	10	10.4	10.2	104	102	75-142	2	20	
Decachlorobiphenyl (S)	%				109	104	40-150			
Tetrachloro-m-xylene (S)	%				117	118	47-150			

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALIFIERS

Project: 9M0909245 SPX LINDBERG
Pace Project No.: 10115796

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

Pace Analytical is NELAP accredited. Contact your Pace PM for the current list of accredited analytes.

U - Indicates the compound was analyzed for, but not detected.

BATCH QUALIFIERS

Batch: GCSV/6149

[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical®
www.pacelabs.com

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

November 13, 2009

Ms. Karen Thole
Delta Consultants
5910 Rice Creek Parkway
Saint Paul, MN 55126

RE: Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Dear Ms. Thole:
Enclosed are the analytical results for sample(s) received by the laboratory on October 29, 2009. The results relate only to the samples included in this report. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Carolynne Trout

Carolynne Trout

carolynne.trout@pacelabs.com
Project Manager

Enclosures

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

nelac

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

CERTIFICATIONS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Minnesota Certification IDs
1700 Elm Street SE, Suite 200 Minneapolis, MN 55414
Alaska Certification #: UST-078
Washington Certification #: C754
Tennessee Certification #: 02818
Pennsylvania Certification #: 68-00563
Oregon Certification #: MN200001
North Dakota Certification #: R-036
North Carolina Certification #: 530
New York Certification #: 11647
New Jersey Certification #: MN-002
Montana Certification #: MT CERT0092
Minnesota Certification #: 027-053-137
Maine Certification #: 2007029
Louisiana Certification #: LA080009
Louisiana Certification #: 03086
Kansas Certification #: E-10167
Iowa Certification #: 368
Illinois Certification #: 200011
Florida/NELAP Certification #: E87605
California Certification #: 01155CA
Arizona Certification #: AZ-0014
Wisconsin Certification #: 999407970

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE SUMMARY

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Lab ID	Sample ID	Matrix	Date Collected	Date Received
10115807003	**W23**	Wipe	10/27/09 10:40	10/29/09 09:48
10115807004	**W24**	Wipe	10/27/09 10:45	10/29/09 09:48
10115807005	**W25**	Wipe	10/27/09 10:55	10/29/09 09:48
10115807013	**W33**	Wipe	10/27/09 12:40	10/29/09 09:48

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE ANALYTE COUNT

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Lab ID	Sample ID	Method	Analysts	Analytes Reported
10115807003	**W23**	EPA 8082	KL1	10
10115807004	**W24**	EPA 8082	KL1	10
10115807005	**W25**	EPA 8082	KL1	10
10115807013	**W33**	EPA 8082	KL1	10

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Sample: W23 **Lab ID: 10115807003** Collected: 10/27/09 10:40 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	53469-21-9	
PCB-1248 (Aroclor 1248)	**1.2**	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	11097-69-1	
PCB-1260 (Aroclor 1260)	**3.5**	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:05	11100-14-4	
Tetrachloro-m-xylene (S)	82	%	47-150	1	11/09/09 20:09	11/10/09 14:05	877-09-8	
Decachlorobiphenyl (S)	66	%	40-150	1	11/09/09 20:09	11/10/09 14:05	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Sample: W24 **Lab ID: 10115807004** Collected: 10/27/09 10:45 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:21	11100-14-4	
Tetrachloro-m-xylene (S)	63	%	47-150	1	11/09/09 20:09	11/10/09 14:21	877-09-8	
Decachlorobiphenyl (S)	58	%	40-150	1	11/09/09 20:09	11/10/09 14:21	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Sample: W25 **Lab ID: 10115807005** Collected: 10/27/09 10:55 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	11097-69-1	
PCB-1260 (Aroclor 1260)	9.9	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	11/09/09 20:09	11/10/09 14:37	11100-14-4	
Tetrachloro-m-xylene (S)	66	%	47-150	1	11/09/09 20:09	11/10/09 14:37	877-09-8	
Decachlorobiphenyl (S)	56	%	40-150	1	11/09/09 20:09	11/10/09 14:37	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

Sample: W33 **Lab ID: 10115807013** Collected: 10/27/09 12:40 Received: 10/29/09 09:48 Matrix: Wipe

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB Wipe	Analytical Method: EPA 8082 Preparation Method: EPA 3580 (Wipe)							
PCB-1016 (Aroclor 1016)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	11097-69-1	
PCB-1260 (Aroclor 1260)	**12.4**	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	11096-82-5	
PCB-1268 (Aroclor 1268)	ND	Total ug	1.0	1	10/30/09 18:57	11/02/09 15:56	11100-14-4	
Tetrachloro-m-xylene (S)	55	%	47-150	1	10/30/09 18:57	11/02/09 15:56	877-09-8	
Decachlorobiphenyl (S)	47	%	40-150	1	10/30/09 18:57	11/02/09 15:56	2051-24-3	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

QC Batch: OEXT/11875 Analysis Method: EPA 8082
QC Batch Method: EPA 3580 (Wipe) Analysis Description: 8082 GCS PCB Wipe
Associated Lab Samples: 10115807003, 10115807004, 10115807005

METHOD BLANK: 710649 Matrix: Wipe
Associated Lab Samples: 10115807003, 10115807004, 10115807005

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1221 (Aroclor 1221)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1232 (Aroclor 1232)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1242 (Aroclor 1242)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1248 (Aroclor 1248)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1254 (Aroclor 1254)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1260 (Aroclor 1260)	Total ug	ND	1.0	11/10/09 13:17	
PCB-1268 (Aroclor 1268)	Total ug	ND	1.0	11/10/09 13:17	
Decachlorobiphenyl (S)	%	99	40-150	11/10/09 13:17	
Tetrachloro-m-xylene (S)	%	110	47-150	11/10/09 13:17	

LABORATORY CONTROL SAMPLE & LCSD: 710650 710651

Parameter	Units	Spike Conc.	LCS Result	LCSD Result	LCS % Rec	LCSD % Rec	% Rec Limits	RPD	Max RPD	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	10	11.0	11.3	110	113	75-146	3	20	
PCB-1260 (Aroclor 1260)	Total ug	10	10.5	10.6	105	106	75-142	1	20	
Decachlorobiphenyl (S)	%				108	104	40-150			
Tetrachloro-m-xylene (S)	%				112	111	47-150			

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

QC Batch: OEXT/11820 | Analysis Method: EPA 8082
QC Batch Method: EPA 3580 (Wipe) | Analysis Description: 8082 GCS PCB Wipe
Associated Lab Samples: 10115807013

METHOD BLANK: 705649 | Matrix: Wipe
Associated Lab Samples: 10115807013

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1221 (Aroclor 1221)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1232 (Aroclor 1232)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1242 (Aroclor 1242)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1248 (Aroclor 1248)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1254 (Aroclor 1254)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1260 (Aroclor 1260)	Total ug	ND	1.0	11/02/09 15:24	
PCB-1268 (Aroclor 1268)	Total ug	ND	1.0	11/02/09 15:24	
Decachlorobiphenyl (S)	%	104	40-150	11/02/09 15:24	
Tetrachloro-m-xylene (S)	%	117	47-150	11/02/09 15:24	

LABORATORY CONTROL SAMPLE & LCSD: 705650 705651

Parameter	Units	Spike Conc.	LCS Result	LCSD Result	LCS % Rec	LCSD % Rec	% Rec Limits	RPD	Max RPD	Qualifiers
PCB-1016 (Aroclor 1016)	Total ug	10	11.5	11.9	115	119	75-146	4	20	
PCB-1260 (Aroclor 1260)	Total ug	10	10.8	10.7	108	107	75-142	1	20	
Decachlorobiphenyl (S)	%				110	131	40-150			
Tetrachloro-m-xylene (S)	%				136	143	47-150			

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALIFIERS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115807

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.
ND - Not Detected at or above adjusted reporting limit.
J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.
MDL - Adjusted Method Detection Limit.
S - Surrogate
1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.
Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.
LCS(D) - Laboratory Control Sample (Duplicate)
MS(D) - Matrix Spike (Duplicate)
DUP - Sample Duplicate
RPD - Relative Percent Difference
NC - Not Calculable.
Pace Analytical is NELAP accredited. Contact your Pace PM for the current list of accredited analytes.
U - Indicates the compound was analyzed for, but not detected.

BATCH QUALIFIERS

Batch: GCSV/6147
[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.
Batch: GCSV/6177
[M5] A matrix spike/matrix spike duplicate was not performed for this batch due to insufficient sample volume.

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

APPENDIX B

Bulk Concrete Sample Analytical Reports

Pace Analytical Services, Inc.
New Age/Landmark Mobile Laboratory Services
TestAmerica

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

November 17, 2009

Ms. Karen Thole
Delta Consultants
5910 Rice Creek Parkway
Saint Paul, MN 55126

RE: Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Dear Ms. Thole:
Enclosed are the analytical results for sample(s) received by the laboratory on October 29, 2009. The results relate only to the samples included in this report. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Carolynne Trout

Carolynne Trout

carolynne.trout@pacelabs.com
Project Manager

Enclosures

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

CERTIFICATIONS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Minnesota Certification IDs
1700 Elm Street SE, Suite 200 Minneapolis, MN 55414
Alaska Certification #: UST-078
Washington Certification #: C754
Tennessee Certification #: 02818
Pennsylvania Certification #: 68-00563
Oregon Certification #: MN200001
North Dakota Certification #: R-036
North Carolina Certification #: 530
New York Certification #: 11647
New Jersey Certification #: MN-002
Montana Certification #: MT CERT0092
Minnesota Certification #: 027-053-137
Maine Certification #: 2007029
Louisiana Certification #: LA080009
Louisiana Certification #: 03086
Kansas Certification #: E-10167
Iowa Certification #: 368
Illinois Certification #: 200011
Florida/NELAP Certification #: E87605
California Certification #: 01155CA
Arizona Certification #: AZ-0014
Wisconsin Certification #: 999407970

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE SUMMARY

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Lab ID	Sample ID	Matrix	Date Collected	Date Received
10115805001	**B1, 0"-1"**	Solid	10/27/09 17:30	10/29/09 09:48
10115805002	**B4, 0"-1"**	Solid	10/27/09 18:00	10/29/09 09:48
10115805003	**B6, 0"-1"**	Solid	10/27/09 15:30	10/29/09 09:48
10115805004	**B7, 0"-1"**	Solid	10/27/09 14:45	10/29/09 09:48
10115805005	**A8, 0"-1"**	Solid	10/27/09 14:00	10/29/09 09:48
10115805006	**B1, 1"-3"**	Solid	10/27/09 17:45	10/29/09 09:48
10115805007	**B4, 1"-3"**	Solid	10/27/09 18:15	10/29/09 09:48
10115805008	**B6, 1"-3"**	Solid	10/27/09 16:00	10/29/09 09:48
10115805009	**B7, 1"-3"**	Solid	10/27/09 15:00	10/29/09 09:48
10115805010	**A8, 1"-3"**	Solid	10/27/09 14:15	10/29/09 09:48

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

SAMPLE ANALYTE COUNT

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Lab ID	Sample ID	Method	Analysts	Analytes Reported
10115805001	B1, 0"-1"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805002	B4, 0"-1"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805003	B6, 0"-1"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805004	B7, 0"-1"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805005	A8, 0"-1"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805006	B1, 1"-3"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805007	B4, 1"-3"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805008	B6, 1"-3"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805009	B7, 1"-3"	% Moisture	JDL	1
		EPA 8082	KL1	11
10115805010	A8, 1"-3"	% Moisture	JDL	1
		EPA 8082	KL1	11

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B1, 0"-1" **Lab ID: 10115805001** Collected: 10/27/09 17:30 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	53469-21-9	
PCB-1248 (Aroclor 1248)	**590**	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	11097-69-1	
PCB-1260 (Aroclor 1260)	**10300**	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 19:53	11100-14-4	
Tetrachloro-m-xylene (S)	0	%	30-150	10	11/02/09 13:02	11/05/09 19:53	877-09-8	S4
Decachlorobiphenyl (S)	0	%	30-150	10	11/02/09 13:02	11/05/09 19:53	2051-24-3	S4
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**0.95**	%	0.10	1		11/02/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B4, 0"-1" **Lab ID: 10115805002** Collected: 10/27/09 18:00 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	11097-69-1	
PCB-1260 (Aroclor 1260)	**15200**	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	667	20	11/02/09 13:02	11/05/09 20:57	11100-14-4	
Tetrachloro-m-xylene (S)	0	%	30-150	20	11/02/09 13:02	11/05/09 20:57	877-09-8	S4
Decachlorobiphenyl (S)	0	%	30-150	20	11/02/09 13:02	11/05/09 20:57	2051-24-3	S4
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**1.0**	%	0.10	1		11/02/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B6, 0"-1" **Lab ID: 10115805003** Collected: 10/27/09 15:30 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	11097-69-1	
PCB-1260 (Aroclor 1260)	**7530**	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	333	10	11/02/09 13:02	11/05/09 20:40	11100-14-4	
Tetrachloro-m-xylene (S)	0	%	30-150	10	11/02/09 13:02	11/05/09 20:40	877-09-8	S4
Decachlorobiphenyl (S)	0	%	30-150	10	11/02/09 13:02	11/05/09 20:40	2051-24-3	S4
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**1.0**	%	0.10	1		11/02/09 00:00		

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B7, 0"-1" **Lab ID: 10115805004** Collected: 10/27/09 14:45 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	11097-69-1	
PCB-1260 (Aroclor 1260)	**12100**	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	666	20	11/02/09 13:02	11/05/09 21:12	11100-14-4	
Tetrachloro-m-xylene (S)	0	%	30-150	20	11/02/09 13:02	11/05/09 21:12	877-09-8	S4
Decachlorobiphenyl (S)	0	%	30-150	20	11/02/09 13:02	11/05/09 21:12	2051-24-3	S4
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**0.94**	%	0.10	1		11/02/09 00:00		

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: A8, 0"-1" **Lab ID: 10115805005** Collected: 10/27/09 14:00 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	11097-69-1	
PCB-1260 (Aroclor 1260)	**16400**	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	668	20	11/02/09 13:02	11/05/09 21:28	11100-14-4	
Tetrachloro-m-xylene (S)	0	%	30-150	20	11/02/09 13:02	11/05/09 21:28	877-09-8	S4
Decachlorobiphenyl (S)	0	%	30-150	20	11/02/09 13:02	11/05/09 21:28	2051-24-3	S4
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**1.2**	%	0.10	1		11/02/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B1, 1"-3" **Lab ID: 10115805006** Collected: 10/27/09 17:45 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:01	11100-14-4	
Tetrachloro-m-xylene (S)	90	%	30-150	1	11/10/09 08:59	11/13/09 00:01	877-09-8	
Decachlorobiphenyl (S)	79	%	30-150	1	11/10/09 08:59	11/13/09 00:01	2051-24-3	CL
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**2.7**	%	0.10	1		11/10/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B4, 1"-3" **Lab ID: 10115805007** Collected: 10/27/09 18:15 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	11097-69-1	
PCB-1260 (Aroclor 1260)	**422**	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:17	11100-14-4	
Tetrachloro-m-xylene (S)	92	%	30-150	1	11/10/09 08:59	11/13/09 00:17	877-09-8	
Decachlorobiphenyl (S)	79	%	30-150	1	11/10/09 08:59	11/13/09 00:17	2051-24-3	CL
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**2.4**	%	0.10	1		11/10/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B6, 1"-3" **Lab ID: 10115805008** Collected: 10/27/09 16:00 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	53469-21-9	
PCB-1248 (Aroclor 1248)	**60.2**	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	11097-69-1	
PCB-1260 (Aroclor 1260)	**2430**	ug/kg	169	5	11/10/09 08:59	11/13/09 17:59	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	33.8	1	11/10/09 08:59	11/13/09 00:33	11100-14-4	
Tetrachloro-m-xylene (S)	94	%	30-150	1	11/10/09 08:59	11/13/09 00:33	877-09-8	
Decachlorobiphenyl (S)	80	%	30-150	1	11/10/09 08:59	11/13/09 00:33	2051-24-3	CL
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**2.4**	%	0.10	1		11/10/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: B7, 1"-3" **Lab ID: 10115805009** Collected: 10/27/09 15:00 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	11097-69-1	
PCB-1260 (Aroclor 1260)	**221**	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	33.9	1	11/10/09 08:59	11/13/09 00:50	11100-14-4	
Tetrachloro-m-xylene (S)	90	%	30-150	1	11/10/09 08:59	11/13/09 00:50	877-09-8	
Decachlorobiphenyl (S)	83	%	30-150	1	11/10/09 08:59	11/13/09 00:50	2051-24-3	CL
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**2.6**	%	0.10	1		11/10/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

ANALYTICAL RESULTS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

Sample: A8, 1"-3" **Lab ID: 10115805010** Collected: 10/27/09 14:15 Received: 10/29/09 09:48 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8082 GCS PCB	Analytical Method: EPA 8082 Preparation Method: EPA 3550							
PCB-1016 (Aroclor 1016)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	12674-11-2	
PCB-1221 (Aroclor 1221)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	11104-28-2	
PCB-1232 (Aroclor 1232)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	11141-16-5	
PCB-1242 (Aroclor 1242)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	53469-21-9	
PCB-1248 (Aroclor 1248)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	12672-29-6	
PCB-1254 (Aroclor 1254)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	11097-69-1	
PCB-1260 (Aroclor 1260)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	11096-82-5	
PCB-1262 (Aroclor 1262)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	37324-23-5	
PCB-1268 (Aroclor 1268)	ND	ug/kg	33.7	1	11/10/09 08:59	11/13/09 01:06	11100-14-4	
Tetrachloro-m-xylene (S)	87	%	30-150	1	11/10/09 08:59	11/13/09 01:06	877-09-8	
Decachlorobiphenyl (S)	79	%	30-150	1	11/10/09 08:59	11/13/09 01:06	2051-24-3	CL
Dry Weight	Analytical Method: % Moisture							
Percent Moisture	**2.2**	%	0.10	1		11/10/09 00:00		

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

QC Batch: OEXT/11828 Analysis Method: EPA 8082
QC Batch Method: EPA 3550 Analysis Description: 8082 GCS PCB
Associated Lab Samples: 10115805001, 10115805002, 10115805003, 10115805004, 10115805005

METHOD BLANK: 706354 Matrix: Solid
Associated Lab Samples: 10115805001, 10115805002, 10115805003, 10115805004, 10115805005

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1221 (Aroclor 1221)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1232 (Aroclor 1232)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1242 (Aroclor 1242)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1248 (Aroclor 1248)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1254 (Aroclor 1254)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1260 (Aroclor 1260)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1262 (Aroclor 1262)	ug/kg	ND	33.0	11/05/09 19:05	
PCB-1268 (Aroclor 1268)	ug/kg	ND	33.0	11/05/09 19:05	
Decachlorobiphenyl (S)	%	77	30-150	11/05/09 19:05	
Tetrachloro-m-xylene (S)	%	93	30-150	11/05/09 19:05	

LABORATORY CONTROL SAMPLE: 706355

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
PCB-1016 (Aroclor 1016)	ug/kg	667	575	86	49-150	
PCB-1260 (Aroclor 1260)	ug/kg	667	496	74	42-150	
Decachlorobiphenyl (S)	%			73	30-150	
Tetrachloro-m-xylene (S)	%			89	30-150	

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 706356 706357

Parameter	Units	10115805001 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	RPD	Max RPD	Qual
PCB-1016 (Aroclor 1016)	ug/kg	ND	673	673	1110	1110	165	165	38-150	0	30	M3
PCB-1260 (Aroclor 1260)	ug/kg	10300	673	673	10900	11000	81	99	30-150	1	30	
Decachlorobiphenyl (S)	%						0	0	30-150			S4
Tetrachloro-m-xylene (S)	%						0	0	30-150			S4

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

QC Batch: MPRP/18195 Analysis Method: % Moisture
QC Batch Method: % Moisture Analysis Description: Dry Weight/Percent Moisture
Associated Lab Samples: 10115805006, 10115805007, 10115805008, 10115805009, 10115805010

SAMPLE DUPLICATE: 710724

Parameter	Units	10116481008 Result	Dup Result	RPD	Max RPD	Qualifiers
Percent Moisture	%	11.2	10.2	9	30	

SAMPLE DUPLICATE: 710827

Parameter	Units	10116410001 Result	Dup Result	RPD	Max RPD	Qualifiers
Percent Moisture	%	21.9	22.3	2	30	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

QC Batch: OEXT/11877 Analysis Method: EPA 8082
QC Batch Method: EPA 3550 Analysis Description: 8082 GCS PCB
Associated Lab Samples: 10115805006, 10115805007, 10115805008, 10115805009, 10115805010

METHOD BLANK: 711071 Matrix: Solid
Associated Lab Samples: 10115805006, 10115805007, 10115805008, 10115805009, 10115805010

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
PCB-1016 (Aroclor 1016)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1221 (Aroclor 1221)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1232 (Aroclor 1232)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1242 (Aroclor 1242)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1248 (Aroclor 1248)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1254 (Aroclor 1254)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1260 (Aroclor 1260)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1262 (Aroclor 1262)	ug/kg	ND	33.0	11/12/09 12:49	
PCB-1268 (Aroclor 1268)	ug/kg	ND	33.0	11/12/09 12:49	
Decachlorobiphenyl (S)	%	89	30-150	11/12/09 12:49	
Tetrachloro-m-xylene (S)	%	98	30-150	11/12/09 12:49	

LABORATORY CONTROL SAMPLE: 711072

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
PCB-1016 (Aroclor 1016)	ug/kg	667	590	89	49-150	
PCB-1260 (Aroclor 1260)	ug/kg	667	560	84	42-150	
Decachlorobiphenyl (S)	%			88	30-150	
Tetrachloro-m-xylene (S)	%			93	30-150	

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 711167 711168

Parameter	Units	10116547001 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	RPD	Max RPD	Qual
PCB-1016 (Aroclor 1016)	ug/kg	ND	842	842	ND	ND	105	116	38-150		30	
PCB-1260 (Aroclor 1260)	ug/kg	ND	842	842	ND	ND	98	124	30-150		30	
Decachlorobiphenyl (S)	%						81	94	30-150			
Tetrachloro-m-xylene (S)	%						61	66	30-150			D3

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALITY CONTROL DATA

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

QC Batch: MPRP/18062 Analysis Method: % Moisture
QC Batch Method: % Moisture Analysis Description: Dry Weight/Percent Moisture
Associated Lab Samples: 10115805001, 10115805002, 10115805003, 10115805004, 10115805005

SAMPLE DUPLICATE: 706304

Parameter	Units	10116010007 Result	Dup Result	RPD	Max RPD	Qualifiers
Percent Moisture	%	2.1	1.6	26	30	

SAMPLE DUPLICATE: 706315

Parameter	Units	10116032001 Result	Dup Result	RPD	Max RPD	Qualifiers
Percent Moisture	%	23.8	22.9	4	30	

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

Pace Analytical Services, Inc.
1700 Elm Street - Suite 200
Minneapolis, MN 55414
(612)607-1700

QUALIFIERS

Project: 9M0909245 SPX Lindberg
Pace Project No.: 10115805

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

Pace Analytical is NELAP accredited. Contact your Pace PM for the current list of accredited analytes.

U - Indicates the compound was analyzed for, but not detected.

ANALYTE QUALIFIERS

CL	The continuing calibration for this compound is outside of Pace Analytical acceptance limits. The results may be biased low.
D3	Sample was diluted due to the presence of high levels of non-target analytes or other matrix interference.
M3	Matrix spike recovery was outside laboratory control limits due to matrix interferences.
S4	Surrogate recovery not evaluated against control limits due to sample dilution.

This report shall not be reproduced, except in full,
without the written consent of Pace Analytical Services, Inc..

1131

DELTA

YEAR 2009

Chain of Custody Record

Project Name

State of Lead Regulatory Agency Wisconsin

Requested Due Date (mm/dd/yy) Standard TAT

COC TRACKING No.

 10115805

On-site Time:	8:30AM		50s F
Off-site Time:	7PM	Temp:	
Sky Conditions:	NA (inside building)		
Meteorological Events:	NA		
Wind Speed and Direction:	NA		

Lab Name:	Pace Analytical Services, Inc.	Facility No.	SPX Lindberg	Consultant	Delta Consultants
Lab Address:	1700 Elm Street, Ste. 200	Facility Address	304 Hart Street, Watertown, WI 53094	Address:	5910 Rice Creek Parkway, Ste. 10
	Minneapolis, MN 55414	Delta Project No.	9M0909245		Shoreview, MN 55126
Lab PM:	Carolynne Trout			e-mail EDD report to:	kthole@deltaenv.com
Telephone	(612) 607-1700	Reimbursement Project	Non-Reimbursement Proj / Mark one	Delta Project Mgr	Karen Thole
Fax		Invoice to:	Karen Thole, Delta PM	Delta Tele/Fax:	651-697-5203 / 651-639-9473
Lab PM Email	ctrout@pacelabs.com	Phase		Delta Contact:	Karen Thole / Adam McIlheran
	INVOICE INFORMATION	Subphase/Task		Hardcopy Report Needed	Y/N Circle One
		Cost Element		Report Type and QC level:	

Lab Bottle Order No:

Item No.	Sample ID	Time	Date	Matrix: Soil	Matrix: Water	Matrix: Wipe	Laboratory Tracking Number	No. of containers	Preservatives: Unpreserved	H2SO4	HNO3	HCl	Hexane	Other	Requested Analysis: PCB by 8082	dry weight					Sample Point Lat/Long Comments
1	B1, 0"-1"	5:30PM	10/27/09	X				2	X						X	X					Extra sample Volume for Lab QA/QC 001
2	B4, 0"-1"	6:00PM	10/27/09	X				2	X						X	X					002
3	B6, 0"-1"	3:30PM	10/27/09	X				2	X						X	X					003
4	B7, 0"-1"	2:45PM	10/27/09	X				2	X						X	X					004
5	A8, 0"-1"	2:00PM	10/27/09	X				2	X						X	X					005
6	B1, 1"-3"	5:45PM	10/27/09	X				2	X						X	X					Hold analysis until approved 006
7	B4, 1"-3"	6:15PM	10/27/09	X				2	X						X	X					Hold analysis until approved 007
8	B6, 1"-3"	4:00PM	10/27/09	X				2	X						X	X					Hold analysis until approved 008
9	B7, 1"-3"	3:00PM	10/27/09	X				2	X						X	X					Hold analysis until approved 009
10	A8, 1"-3"	2:15PM	10/27/09	X				2	X						X	X					Hold analysis until approved 010

		Relinquished By / Affiliation	Date	Time	Accepted By / Affiliation	Date	Time
Sampler's Name:	Adam McIlheran						
Sampler's Company:	Delta Consultants	[signature] Delta Cons.	10/28/09	12 PM	[signature]	10/29/09	948
Shipment Date:	10/28/09						
Shipment Method:	Fedex						
Shipment Tracking No:							

Special Instructions:

Custody seals in place (circle one) Y N | Temp Blank (circle one) Y N | Cooler Temperature on Receipt 2.5 F C (circle one) | Trip Blank? Y N (circle one)

Sample Condition Upon Receipt

Pace Analytical

Client Name: Delta **Project #** 10115805

Courier: ☑ Fed Ex ☐ UPS ☐ USPS ☐ Client ☐ Commercial ☐ Pace Other _____

Tracking #: 7960 7115 3715

Custody Seal on Cooler/Box Present: ☑ yes ☐ no **Seals intact:** ☐ yes ☐ no

Packing Material: ☐ Bubble Wrap ☑ Bubble Bags ☐ None ☐ Other _____ **Temp Blank: Yes** ✓ **No** _____

Thermometer Used 80344042 or 179425 **Type of Ice:** (Wet) Blue None ☐ **Samples on ice, cooling process has begun**

Cooler Temperature 2.5 **Biological Tissue is Frozen:** Yes No

Temp should be above freezing to 6°C

Date and initials of person examining contents: 10/29/09 SL

Comments:

Chain of Custody Present:	☑Yes ☐No ☐N/A	1.
Chain of Custody Filled Out:	☑Yes ☐No ☐N/A	2.
Chain of Custody Relinquished:	☑Yes ☐No ☐N/A	3.
Sampler Name & Signature on COC:	☑Yes ☐No ☐N/A	4.
Samples Arrived within Hold Time:	☑Yes ☐No ☐N/A	5.
Short Hold Time Analysis (<72hr):	☐Yes ☑No ☐N/A	6.
Rush Turn Around Time Requested:	☐Yes ☑No ☐N/A	7.
Sufficient Volume:	☑Yes ☐No ☐N/A	8.
Correct Containers Used:	☑Yes ☐No ☐N/A	9.
-Pace Containers Used:	☑Yes ☐No ☐N/A	
Containers Intact:	☑Yes ☐No ☐N/A	10.
Filtered volume received for Dissolved tests	☐Yes ☑No ☐N/A	11.
Sample Labels match COC:	☑Yes ☐No ☐N/A	12.
-Includes date/time/ID/Analysis Matrix: SL		
All containers needing acid/base preservation have been checked. Noncompliance are noted in 13.	☐Yes ☐No ☑N/A	13. ☐ HNO3 ☐ H2SO4 ☐ NaOH ☐ HCl Samp #
All containers needing preservation are found to be in compliance with EPA recommendation.	☐Yes ☐No ☑N/A	
Exceptions: VOA,Coliform, TOC, Oil and Grease, WI-DRO (water)	☐Yes ☐No	Initial when completed / Lot # of added preservative
Samples checked for dechlorination:	☐Yes ☐No ☑N/A	14.
Headspace in VOA Vials (>6mm):	☐Yes ☐No ☑N/A	15.
Trip Blank Present:	☐Yes ☐No ☑N/A	16.
Trip Blank Custody Seals Present	☐Yes ☐No ☐N/A	
Pace Trip Blank Lot # (if purchased):		

Client Notification/ Resolution: **Field Data Required?** Y / N

Person Contacted: _____ Date/Time: _____

Comments/ Resolution: _____

Project Manager Review: [signature] **Date:** 10/29/09

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DENR.

F-L213Rev.00, 05Aug2009