POOR LEGIBILITY

ONE OR MORE PAGES IN THIS DOCUMENT ARE DIFFICULT TO READ
DUE TO THE QUALITY OF THE ORIGINAL

SFUND RECORDS CTR
2127143

Fed Express Acct #
094142664-4

MEP441 001318

486-7652

Phone .20

MEP441 001319

FEBRUARY 1979

2/6 → Met w/ Wakifumi Asai } Kumai Chemical Ind
Hirohisa Mochizuk } Tokyo, Japan
Yasuhiko Tominaga } Agro Chemical Int.
Koichi Yamamoto } S.F. CA
Sylvia Gamino
Bob Kaneshiro
(Discussed herbicide product registration. Procedures for registering establishments.)

2/7 → Mail Reg Kit to: Brown Manufacturing
PO Box 571
Boron CA 93516
(Provided a list of Data Submitters)

→ Spoke w/ Jim Knutson, East Bay MUD, 835-3000 x 404
2127 Adeline Street, Oakland CA 94623
Provided product information, sent FR's concerning restricted use chemicals, will meet w/ him next week concerning pesticide product information on MF.

→ Provided information to OER regarding pesticide products to treat crown gall on willow trees (there are none) Suggested that he contact local ag. commissioner.
JIM ROLLER

→ MAIL REG. KIT: FAST SUPPLY
455 10th Street
S.F. CA 94103

2/8 → Spoke w/ Greg Hanson concerning supplemental registration. He already has 8570-5.
Sent him info on labeling (draft guidelines)
CHEM LAB PRODUCTS
2850 E. Coronado Street
Anaheim CA 92806

673
NEWPORT BCH CA → (714) [redacted] 4190

2/12 Reg kit to: Carl Clawson (415) 757 8230
man - Copper Sulfate Imperial West Chemical Co
2nd Copper Hydroxide P.O Box 696
Copper Oxychloride Antioch CA 94509
Sent above person 2 application sets & list of data submitters
Carl Clawson called again - add copper oxychloride and send another set of forms.

2/13
ZINC PHOSPHIDE REG KIT → BILL ANDERSON
Zn_3P_2 (88601) AMERICAN WEST
RODENTICIDE 6245 DESCANSO AVE
BUENA PARK 90620
(714) 994-2371

2/15 Sent complete info on PERF 78-1103
TO LOIS STICLE IN MIAMI

Called Bill Grusse, HQ, about missing data on microfiche - Halazone (Chem #077201)

Called HEMB HQ about NATL HOUSEHOLD STUDY ON PEST USAGE - NOT OUT YET

2/21 ~~MET W/CARL CLAWSON~~
MET W/CARL CLAWSON (SEE 2/12)
DISCUSSED REGISTRATION

2/28 CALLED Bill Curry (HQ) about script to ENTOMOLOGY SLIDES.

~~2/28~~
3/5 Recieved call from: Walfred Reed
Eureka Laboratories
215 26th Street
Sacramento CA 95816

Works under contract from ARB - wants info. on status of chlorobenzate — will send FR 2/13/79 and news release DONE

3/9 (1) Sent Bill Anderson (see 2/13) FIFRA. done

(2) Sent data sub. list to: Marvin Rezac done
McGrayel Co.
PO Box 12362
Fresno CA 93777

3/14 INSIDE LABELING HAS ~~Ken Ross~~ (2)
NAME OF MANUFACTURER [redacted]
OUTSIDE CARTON HAS Hal. Bramble
ONLY ~~BOTH MANU~~ DISTRIBUTOR (213) 841-3350
~~CALLED HQ~~ Reg # 5464-1-23685 — Suppl Reg
Distributes to medical, dental quatenary ammonia

MEP441 001323

Called Sandra ENGLISH → PM 15 GARDNER

ONLY TIME YOU NEED A SUB-REGISTRATION IS WHEN YOU WANT TO MARKET PRODUCT UNDER YOUR BRAND NAME.

Spoke w/ Mr. Bramble and asked him to submit copies of his labeling

(a) REG: DISINFECTANT JIM STEWART
REFERRED TO PM BECAUSE HE'S ALREADY SUBMITTED HIS APPLICATION

(5)

3/19 Call back 3/20 after 2 D. James Schwedler
Colusa Chemical Co
11641 PIKE ST
201 ~~[illegible] Street~~
Sante Fe Springs
90670 ~~[illegible] Angeles CA 90012~~
(213) 695-0761 ~~(213) 624-4151~~

Pine Oil Disinfectant → at Pine Oil 30%
Fabric Softener (pending) Ethanol 2.7%
None
6- Supplemental Distributors
2. ~~Reg kits~~ sets of forms
Child Packaging inert ??? Anionic Cleaning Agent 11.8%
Has list of data submitters. (Alcohol Ether Sulfate Ammonium Salt)
How soon do you have to pay the contains compensation?
If he relies on efficacy data in EPA files does he have to submit his own efficacy data?
Name of Product Manager
If so, what tests are involved.

He will send me a list of packaging companies.

MEP441 001324

Done

3/20

RON EDDINGTON
CANNERS ~~CROP~~ LEAGUE
1007 L Street
Sacramento CA 95814
(916) 444-9260

LOOK UP BASIL
IN MF.

~~QUICK REFERENCE~~
~~SEND HIM A NEW SET OF MICROFICHE~~ CAN'T
AMend Act, PR 78-5, 78-6 ✓
LIST OF RE-ENTRY ENTERVALS MAY 16, 1975
1/9/79 FR-RESTRICTED CHEMICALS

BILL GIUESPIE

HAS REGION IX RECIEVED MEMO TO REGIONS
INSPECTION PROCEDURES AND LEGAL BASIS

3/21 Spoke with Dean Saito regarding pesticidal efficacy of wood preservatives bearing EPA Reg #. Appears that the company is making claims that EPA has approved/substantiate their product. He will send me the literature. Referred him to CDFA to get listings of all preservatives that would not ~~nee~~ be registered thru EPA because they don't make pesticidal claims

3/26 Sent 2 copies of Hi-Level # 55-LA-78 to Bill Conigliaro, HEMB

3/27
Copper Sulfate — Carl Clawson (See 2/12)

Made appt for 1030
Wants to know at what point is tech. grade material come under FIFRA

Relayed info to Bill Chase re: FL SLN Reg.
Appears that different company has used ORTHO label
Mentioned "switching" employees for a day — Check w/ Nancy to see if OK

4/5 Sent labels for reg# 3314-1, 2, 14, 15, 24, 26, 27, 28, 29
(1) to Marilyn Dryden, Chevron Research Co. SF.

(2) Sent list of data submitters to Carl Clawson, Imperial West

Returned Catalog of available slides to Mike Stimmann
4/6 Sent J. Knutson new RRAR list & Canner's League Schedule
4/10 Called Frank Davido & left message that Reg IX had no additional reports on Lindane.

4/18 explain MF Data Sub. — Dan Vernon, Rockwood Chem Co., PO Box 34, Brawley CA 92227
(3) Send "the Label" Regs — Done

Sent reg. kits to: Bon Del Marketing, Inc.
(4) 2605 E. Geneva Drive
Tempe AZ 85282

Done

(5) Desert Fly Control Spray Systems
15839 N. 40th Street
Phoenix AZ 85032

Bob Murphy, Region VI - sending report on:
PERF - Tulare - 2, 4, 5-T

4/19

~~Ed~~ Needs to find local cert. program
referred to local comm. college district

JESSE HIZEMSKI
CHIEF OF BUILDING ~~MAINTENANCE~~
~~[illegible]~~ 5-450-0293
VA HOSPITAL
MARTINEZ CA 94553

4/20

Supplemental Reg (2) → (6) GILBERT BARAJAS
LADCO Laboratories
4939 Earle Ave
Rosemead CA 91770
(213) 286-1167

Done

MEP441 001326

Done RPAR, SPC Pest
hydrocarbon emissions
(213) 571-1887

Carolyn Watanabe
1900 Conejos
Fullerton CA 92633

Done RPAR SPC PEST
FIFRA

David Humes
Trinity Co. Health Dept.
Box AJ
Weaverville CA 96093

4/23
new labeling
- methyl p

(9)

Allen Dunlap
AZ Agrochemical Co.
PO Box 21537
Phoenix AZ 85036

6/ 8570-1
8570-4
-10
-11
Done

2/
Appendix B (PR)
PM assignment
label amend.

4/24
Greater than 10%
Sodium Hypo Regs?

(2)

GREG HANSEN
Chem Lab
Referred to PM

4/25 Called Jim Knutson to give info on toy cat.
Called Jim Boland HQ - need to get memo to him.

4/27 Sent generic standard request elist to: ~~[illegible]~~ Linda Stockdale
Chevron Chemical Co.
575 Market St (rm 3100)
S.F. 94104

MEP441 001327

Sent bulk pest safety literature to Ray Sullivan
1150 BAYHILL DRIVE, SAN BRUNO CA 94066

4/30 Reg Kit ? Dave ① Robert Shayne
Sterilizing fluid Infec-no-mor Corp.
formaldehyde 9150 Sepulveda Blvd
Sepulveda CA 91343

5/4 Martha Powers Tox info on Cryolite (Chem # 075101)
Info on Demand — Dave Seagull 12225-6 12333-12341
841-1145 1) EFFECTS ON SOIL & FARMWORKERS
Dave Seagull 2) NEG EFFECTS ON BENEFICIAL
Infor. on Demand apple orchard situation
PO Box 4536 X3) Source of cryolite
Berkeley CA 94704
apple orchard

5/14 Ortho Weed-b-Gon Ray Barraza
781-4211 x 1452
Suspended? No — told to use according to label
35166-35049... FGAGCBI
Dutch Elm Disease - ceratocystis ulmi
Bark Beetle Mrs. C.J. FITZHARIS
456-9031
~~Methyxchlor~~
~~Lignasan~~ 099102
~~Arboral~~
~~Arbotect~~ 060101
gave list of products, tox categories etc
Label → ~~80~~ 7840 E. Broadway Suite 214 Tucson AZ 85710
5/16 MR. RON KAMINSKY (602) 296-7141
FIREMAN'S FUND INS CO
info on ingredients Reg # 35900-PA-01
BON-DEL INC 35900-2

MEP441 001328

156/2/5 149/2/1-2

5/17 pyrethrins # 11525-26-1913 Wade Utsunomiya
10258-4 (213) 259-2254
Bottled water → Cockroaches
Returned call, gave label into p referred him to CA DOH which regulates his establish.

Done Reg kit ② to ~~Dave~~ ~~SF Ecology Center~~

5/21 quat. ammonia ALLSTATE MINE SUPPLY INC
→ Mckesson Chem PO BOX 15292
→ Lonza Chem PHOENIX AZ 85060
Barquat MB-50 + Dye + perfume Reg 8636-2 (602)968-6892
~~Formaldehyde for use in outdoor toilet~~
HQ mail List

5/22 Called Bob Rollins — phenoxy herbicides on rice
Done Will Send Specific Exemption on Toxaphene

~~Cond Regs~~
~~Impl Plan~~

All 6/14

③ ~~Jack Wackerman~~
~~L.A. Chemical Co~~
~~#4545 ARDINE ST~~
~~Southgate CA 90280~~
~~(213) 583-4761~~
~~home (714) 481-8320~~

Act → Donald C Hirsch
211 San Rey Pl.
Done Danville CA 94526
(415) 837-8337

MEP441 001329

Ronilan
EUP Strawberries - 10
7969-EUP-10
~~Portritus Fruit~~
Protritus Fruit Rot

Done

Ray Nelson
Food & Drug
L.A. 8-798-3356

5 ppm temp tol.

15 8570-11, -4

(4) RACHEL OPPEDAHL
CUTTER LABS
4th & Parker Streets
Berkeley CA 94710

CONF STATE 8570-4
LABEL Tech
APPL FOR PES PROD REG

(5) DEXOE INC
1450 W 228th St.
TORRANCE CA 90501

Sent T into
to: Done

Seth Benezra
PO Box 3106
Stanford CA 94305

5/23 Called Ron Kaminsky (see 5/16) and told him that there appears to be a "problem" with basic registration — only the media, not the device is registered. Will send label after HQ sends.

Minor Crop Use - Jojoba

Tom Camp
PO Box 14516
Phoenix AZ 853063
(602) 846-5993

MEP441 001330

Reg Kit to:

5/25 ~~ROGER BROWN~~ Done (6) Desert Chemical Inc
PO Box 416
Buckeye AZ 85326
602-386-5934

Import / Export / FIFRA to → (7) Maria Peck, Maha Export Co.
Done
2211 Jardin Drive
Oxnard CA 93030

Sus & Canc. Pesticides → GEORGE SPANOS
Done
4344 CHELSEA WAY
CONCORD CA 94521

Reg Kit to → (8) John Jasnosz
Done
Foremost - McKesson Chemical Group
5353 Jillson Street
Los Angeles CA 90040

~~28276-7~~ Cond Regs A. Melzer
~~2698~~ ~~26896~~ (9) A.G.M. International
Po Box 77
Cupertino CA 95014
(408) 742-9210
253-3554

Sodium ~~sulphur~~ chloride
silver
talked to E. Brown, HQ home
5/31

Done

PM: MR JON LEE
MR BANKS
" MACK - - -
YOUNG

AUG

May 11, 1979

MEP441 001331

MARIO

W SACTO - PARATHION SPILL

6/1

NO CHILD HAZARD - BUT PREFER ONE

2 weeks - product - me too, offer to pay

2-3 days - label amendment

Type size depends

"For manufacturing use only"

Signal Word - Type Size

Storage and Disposal

Optional

Technical Bulletin w/ Labeling
Directions for use
Phys & Chem. properties

MEP441 001332

6/5

man. drugs Done
wants 7 U.S.C. 135

Sent the Act

(1)

M.
MR. ~~BARRETT~~ BARAK
MEDI-PHYSICS INC
5801 CHRISTIE AVE
EMERYVILLE CA 94608

6/6

Roy Kit

Done

(2)

Virgil Greenley
Cook Laboratory Products
PO Box 877
Pico Rivera CA 90660

Reg. Poison Oak foliar Done

Mr. DE ~~[illegible]~~ Rapieri
348-3266

Gave list of products, referred to ag comm, UC Ext

6/6 4:45 PM MR. BEECHER GILBERT DELIVERED A ROLL OF UNDEVELOPED 8mm Kodachrome 40 movie film. MR. GILBERT STATED THAT FOOTAGE WAS TAKEN DURING THE MONTH OF MAY 79. IT IS LABELED: "TAKEN AT THE IH RANCH OF AND BY BEECHER B. GILBERT & MARY BELL GILBERT OF G.N. DIBBLE INC CROP DUSTERS FLYING IN ON INDERBITZEN RICE FIELDS." ALL FOOTAGE WAS TAKEN WITHIN 100 of GILBERT RESIDENCE

6/11 Reg kit to: Done (3)

Robert Laws
Great Western Chemical Co
860 Wharf Street
Richmond CA 94804

6/11 Called Frank Davido for copy of agreement (EPA news release Tues, May 15)

MEP441 001333

Fifra, 40 CFR Part 162, IR Phase Out.

labeling instructions Done
government regulations
Chlordane

(4) Suzanne ~~Dorton~~ Durden
Freitas Firm
960 5th Ave
San Rafael CA 94901

Impl. Plan
Send: (2) Cond. Regs
Reg Kit
(6) FORMS (3) Done
Est. form to add
state products
Amended FIFRA
Child-proof regs
(6) Label amendment
"The Label"

(5) Jack E. Wackerman
Registration Coordinator
Los Angeles Chemical Co.
4545 Ardine Street
South Gate CA 90280
(714) 481-8320

MEP441 001334

BATS IN
between stone
fireplace & wall

PAT BOOTH
office 877-0446 730-4
268 Mastick Ave
San Bruno CA 94066

Sent info & referred her to Vector control, Berkeley

6/14
Est. Reg forms & regs.
mail list

(6) ~~Lane~~ C. Lanesfield Remme
Bon-Del Distributing Co
157 S. Pomeroy
Mesa AZ 85202
(602) 969-7520

Done

6/15

Sent Reg Kit to (1) Ross M. Roll, President
San Juan Industries Inc
PO Box 5020
Chandler AZ 85224

Done

Est Reg to (8) Jewell McCracken
Interlink Agriculture Chemicals
PO Box 4900
Modesto CA 95352

Done

6/21 ~~Contact~~ (9) Jack Murphy
Small Business Rep
US Defense Logistics Agency
(213)643-0620

re: chlorinated lime

Informed him that it will be considered ~~other~~ a pesticide unless disinfectant claims are dropped from the label. Consequently §162.4(c) exempts bleaching agents

MEP441 001335

Referred to CAL/OSHA

Detect Biphenyls in indoor industrial facility
Used to treat polyester fabric to fire proof

Carl Stensel
647-6281
565 Valley St
SF 94131

Al Melzer
AGM International

7/2 Reg kit to: (10) Marilyn Jones
Done Sales Promotion Services
10933 Camarillo St
N. Hollywood CA 91602

(11) Done John Thomas
615 S Flower St.
Suite 1600
LA CA 90012

6/11 Arsenic Wood treating compound

7/13 Reg kit → Dave Colker
(1) Done Graham & James
1 Maritime Plaza
SF 94111

PYDRIN
4-CHLORO-1-METHYL ETHY BENZENE-
-ACETONITRILE

MEP441 001336

Ortho

Est Registration → Bill Lee
& Regs (2) Midway Supply
PO Box 412
Stockton 95201

8/6 Reg Kit to: Jim Blasius
2349 West Walton Lane
Phoenix AZ 85023
(602)273-1483

(3)

8/28 REG KIT TO: Larry James
Rich Health
PO Box 18258
Irvine CA 92713
(714) 751-2600

Done (1)

8/29 Sent co registration info to Alan Clark, Rm A151
COFA Pesticide Registration
(552-[redacted]5130)

(2)

~~JULIA McMILLAN~~

Forwarded low-level complaint to San Mateo Co Dept of Ag.

MEP441 001337

20c of Amend Reg → ~~Termite Control~~
LISA STRONG
OCCIDENTAL CHEMICAL
PO BOX 198
LATHROP CA 95330
(209) 858-2511

(3)

Done

REG KIT TO → B.J. Bondy
PO Box 5921
Sherman Oaks CA 91413
(408) 354 5125

est form
change address
to 215 Fremont

Done (4)

label ready to print (5)
-advised him to send
to HQ

JOHN LITTLETON
US BORAX
ANAHEIM CA

post harvest tolerance
on strawberries
30 ppm

~~JESSE R~~
Tom Ovafala
(408) 779-2186

Benzall packaging
for Jac Son Co (6)

ED KOMINSKY (John Lee's staff)
(FTS) ~~202~~-426-2454

- will return when questions answered
- what about clarifying guidelines?

See Conv of 8/31

Jesse Brisbane
PO Box 241
Nevada City CA 95959

MEP441 001338

9/7 Discussed reg. materials

Carl Clawson
Myron Tessendorf
Dotz Chemical of CA
401 West 4th St
Beaumont CA 92223

Reg kit to → (7)

Done

MEP441 001339

Reg kit → Dennis Prober
Van Waters and Rogers
2256 Junction Ave
San Jose CA 95131
(408) 263-9900

9/10 Done (8)

Reg kit → Data sub
4ea Amend (2 Malathion, Jack Wackerman
Pest Reg Xylene
Label Tech (9) All 6/14
Confidential "The label"
Done * data submitters

9/11 info on data sub.
Compensation
Done

Mr. Burt Merrill, DVM
RT 1, Box 420
Gridley CA 9548

July 3 '75 FR

Steve Lindow
(415) 642-4174
Dept of Plant Pathology
UC
147 Hilgard Hall
Berkeley CA 94720

9/1

* Summary of Env impacts of drug control programs in Mexico 2,4,P + Paraquat

"The Other face of 2,4-D Report by S Okanagan → Shawn Sweezi
Div of Bio Control
UC Berkeley
642-7191
642-6707

A citizen's report
South Okanagon Environmental Coalition
primary literature → Box 188, Penticton BC
$7.00 V2A-6K3

(Dioxin)
2,4,5-T Research project in New York
~~Marion~~ Marion Moses, MD.
Mt Sinai School of Med
(212) 650-6174
Env. Sciences 696

Bruce Ames | 642-0676
Kim Hooper Biochemist
Mutagenecity testing 2,4,5-T?

new use - more risk
CCA wood treating
arsenic oxide
copper oxide
chromium oxide
Call Done
HQ
Anita Schmidt
557-8244

Robert Laws
Great Western Chemical
860 Wharf Street
Richmond CA 94804
(415) 235-4810

Roan 557-7973 TS-791

9/12
Done Sodium Hypochloride 10%
Sodium Hexametaphosphate .005%
Jess Estrada
1180 Sanchez St
~~Salinas CA~~
Castroville CA 95012

pages from FR
products that are pesticides & not

Consultant on Reg
Done

Alfred Tomlinson
Hexol Inc
1500 17th St
SF CA 94107

9/12 2,4-D answered general questions Done — Dave Banks

HQ Data Package Questions Done — Schoenfeld 365-3300

✓ Sent 500c. PIMS form to Frank Snider
100c PIMS revision

delegation of authority ✓ — Susan Reed

✓ Talked to: offer to pay statement — Willard Schoenfeld

✓ "Pesticide" status (a.i. & claims) — Carol Taunch, Chloro Tech

✓ 4536-5-dist dist reg — Tom Dugals

Colorant for seed treatment — Brent Lloyd, Day Glo Color, (213) 283-7561

MEP441 001342

9/18

Discussed label require state/federal ✓ — Jack Vackerman, L.A Chem

flammability of 385-56 insect repellent ✓ — Mr. Kodama, FDA - L.A, (FTS) 798-3788

see discussion of 9/18 2,4-D aerial applications ✓ — Gay Throgmorton, Somes Bar CA, (916) 469-3399

pest reg. ✓ — ROD HEIKENS, Desert Fly Control, 15839 North 40th St, Phoenix AZ 85032

problem with neighbor applying cat repellent next door - refered to Alameda Co Dept of Ag. Told him to call me back if not satisfied. ✓ — John Masella, 2245 Curtis St, Berkeley 94702, 549-1152

9/20

25: 8570-4 Conf
" - 11 Amend ✓
" - 12 Resub ✓

no mail list

100 (50) from HQ ← Jane

PAT TAYLOR, CHEVRON CHEM., 940 Henesley St, Richmond CA 94804

sent copy of exec
Fed order ≙ 120888 Tim McKay
North Coast Env Center
(707) 822-6918

"Do not permit dairy or meat . . .

9/21

BTP uses on cotton
Bacillus Thuringiensis
Dytol

Nancy Bishop
Western Farm Service Inc
3075 Citrus Circle
Walnut Creek CA 94598

list of data submitters

VICKY TSUHAKO
PO Box 50003
Honolulu HI 96850

sent 12 ea to:
8570-1, 5, 10, 11, 12

Clara Strunk
Germaine's Inc
4820 E. 50th St
LA 90058

ALFRED THOMANSON

All 9/12
1. performance data Call PM

EUP → PM D.C.

Anthony
Central Valley Lab
Stockton CA

labeling questions (registration) ✓ — Allen Dunlap, Arizona Agri-Chemical, Phoenix AZ

Registration ?'s ✓ EDF lawsuit against registration? — Dennis Prober, Van Waters + Rogers, (408)263-9908

Rat adhesive — Malaysian Trade Comm.
97.6% rubber
4/10 of 1% formaldehyde ✓
device requires est. (not product) registration

neighbor applied Sevin at 63x label rate — referred to Alameda Co Ag Comm. — Luboz Mazur 527-2844

talked w/ A.C. Mr. Castell DOH ✓
~~874 6794~~ 746-
~~881 6390~~

AC Dept of Agriculture
Steve Rodriguez

Neighbor Thomas McQuaid has agreed not to make any further applications immediately. If he does he'll follow legal.
Called Mrs. Mazur back and she satisfied.
Chevron toxicolosist to decontaminate.

Report on George Neary — Joan Reed
Gave message to Nancy — Assembly Office of Research

Send those not full kit → §162 CFR FIFRA ✓
Med for tropical fish

Ron Sarkesian
2945 Globe Ave
Thousand Oaks CA 91360

① Copper Sulphate Pentahydrate

② Trichorson — Read him CFR Section 162...? which exempts substances under §21 USC
label violation and public health hazard

Richard Zimmerman } 232-1544
Chevron Chemicals } x 4944 ✓

expects Sevin to be around until Spring
28 lbs @ 5% 1.4 lbs qrt/850 square feet
over 3 weeks

Cholinesterase level — carbamate
Should be depressed w/ symptoms

Mrs. Mazur in first trimester of pregnancy

Teratogenesis w/ high levels of
In Dogs.

Eyelids swollen on 29th (Saturday morning)

Emergency Task force → Dr. Moore

→ Call Tuesam Reg kit: Yolanda Arjona
flea dog soap ✓ 889 Myra Ave
Chula Vista CA 92011
(714) 427-9958

potassium sulphur 5 grams
oil of cage
~~creoting~~ creosote 10 grams cresilic acid 0.5%
neutral soap 100 grams
o-syl
kill fleas and oil will give sheen to hair

gives sheen to coat
aids in the prev. ✓
of dandruff and
infections of the skin ✓

CARLA HARKNESS

~~Frichem~~
Ficam

(20) 8570-1
(4) Cont State of Form ✓
Done

Jel Weise
Penwalt Corp
PO Box 120
Monrovia CA 91016
(213) 358-1838

Check-up for Karen Howard 66695
Silver in swimming pool
Oakwood Garden Apts
San Jose

to issue emergency clean-up order — Jerry Winn, Dir
ALAMEDA CO. ENV. HEALTH
(874-5116

Opinion that carbamate
Concentration would not break down
Problem for 2 months

Neighbour use Repel
EPA Reg # 20215-1
20% Paradichlorobenzene ✓
Painful Headaches located
in eyeballs. Contact lenses
turned brown

John Mosella
Berkeley CA
843-0630
(PRE)
RPAR - (oncogenicity)
Richard Troast 8-557-7420

Buy chlorine — Prod and Est Regist.

ai: Sodium

Reg Kit (+ Est) to: ✓

Joan Shanley
Humphrey Marine
243 12th St
Del Mar CA 92014
(714) 481-6552

Soap / not a pesticide MR. SHERMAN

~~Pest foggers~~

To send ~~not~~ label Joan Inman LDB
for cooling tower
(Legionnaire's) bacteria
All memo under PES 123.16

10/5
Odor in rug Jerry Kraim
from Holiday Fogger (213) 585-1376
Will write complaint on prod to me.

Called Mr. Castell ACDOH 874-6794
asked him to call Mrs. Mazur

MRS MAZUR called → told her
that state & County has authority
~~to~~ (not EPA) and that her complaint
has been referred to CDFA. CDFA
refers to County

MEP441 001348

20c of amend ✓ ED BUTZ
reg form Stauffer Chem

Discussed label Tim McKay
statements N Coast Env Ctr
5c of FFRA to: (707) 822-6918
✓ 1091 H Street
Arcata 95521

✓ Lynn Barad:
CATS

RPAR 7's on Lindane ✓ Jerry Weston

2 miscarriages ✓ Paulette Weber
lives across from tomato (415) 634-2352
fields — told her to Brentwood
get into farm co
7's on Silvey ✓ Gary Driscoll
San Jose Apts Atty
San Jose

Amt Lab Pest Train ✓ Info to Roland Hindley

✓ Jesse Brisbane

Get ?'s - transferred ✓ to M. Conti

Nancy Bishop

75-00475
75-52 ✓
Date of Ep 10/15/74
Date of Rep 7/25/75
Active Ing: Dursban
Tulare Co.

75-00118 Doris Hemingway
475-00118 (305) 547-6747
10/15/74
6/26/75

10/18

Peter Wu

Trichloroisocyanuric Acid for swimming pool ✓
Algacide + Bacteriocide

Sodium Dichlor Reg kit → Gary McLearn
Tustana Pool Supplies
12932 Newport Ave
Tustin CA 92680 ✓

[redacted]

Suppl + regs (162) ✓

Walt Colbert
Kolbert's Chem Dist Co
PO Box ~~1934~~ 19391A
LA CA 90019
213 299 0528

MEP441 001350

10/19

8845-21-41409 ✓ Fredan Rolans
Chevron Chem

see 9/12 ✓ Jess Estrada

Paramite ai? Jeff Gabe

Walt

Ethylene Oxide ✓ Leo Vanderpool
CDFA

8570-5 Suppl. ✓ John
FMC

quatenary disinfectant Joel Emanuel
Mr. Green - Onyx Chem
201-434-1700
✓ Joel Emanuel - Ricar Prod.
602-282-7580

MEP441 001351

Contract packager
One Product Basis

Limits - Suppl limits Brand, Co, drop claims (uses)

killing roaches
Boric acid
Label Tech Data Form → Robert Zieberth
FR Notice Cond Reg
Santa Monica Chem. Co
1639 Ninth St
Santa Monica, CA 90404

11/8
offer to spray ?'s
Allen Dunlap
A2 Ag Chem

John Maze
2 hunters
Trouble with Forest Service
Wants copy of letter
Pete Haggard
Humboldt Co
Dept of Ag
5630 S. Broadway
Eureka 95502
(707)443-7057

MEP441 001352

1/10

Fred Whiting CDFA 8-552-3031

Diatomaceous Earth - "Silicon Dioxide"
Fungicide
Insecticide } apples, Pears

180.1017 (p 502)

180.1001(e) (p 496) animals

180.1001(c) (p. 482) - raw ag com
- carrier

— Submit formal request to have tolerance waived
send to: George LA Rocca
Registration Div.

he will forward to Residue Chemistry

Scott Figus Eco Safe Laboratories

MEP441 001353

MEP441 001354

1/15/80 Dean Albright off (213) ~~547-2071~~ 519-0033
home (714) 846-9430
798-2000

1:45 called off # — no answer
1:50 " LA FTS oper — no answer
" " " " — busy signal
" " " " — recording not in serv
1:55 " SF FTS " — "Is there a more recent version of FTS Dialing Instruct?"
reply — You'll have to call 556-4235
1:57 called 556-4235 — Is there trouble w/phone answer — No, I'm calling to see if there's a new set of FTS Dialing Instructions
GSA: "What edition do you have
ans. May 1978
GSA "That's the most recent
quest: Is there a later edition of the
1:58 GSA: Would you please hold
Put on hold.
2:04 Never came back on Hung Up

2:10 Called FTS oper 798-2000
2:12 Oper #29 answer asked for 714 846-9430
2:13 no answer #29 "what's the number"
me: 714-846-9430
2:15 Called 8-213-519-0033
recording: "all circuits busy"

Certified comm Nashville TN
were to CA
referred to CA Structural PCB

MEP441 001355

12/2/80 3:00pm Met w/ F-040
LEVERONI at Brentwood
Oxychem. Told him were
with EPA. Showed credentials
and told him we were here to
perform ISS inspection.
Asked to see John Harris.
Secretary said J.H. was at
the Lathrop facility. ~~Told~~ Asked
Secty to call J.H. and let him
know that we were performing
inspection. Began discussing types
of waste the facility produced
while Secty placed phone call.

12/2/80 3:15 pm Spoke w/ John Marriss, Oxychem, Lathrop. He asked that EPA not inspect the Oxychem Brentwood facility without his presence. I asked John whether the Brentwood facility is a generator, TSD, and UIC facility. He said that the facility should only be listed as a generator (in the event of a spill.)

While facility representative Floyd Leveron was willing to let us proceed with the investigation, I conferred with Bob Peterson and he said that we should leave the facility.

John also said that facility was indicated as UIC because the company had advised that all outlets with septic systems be listed as UIC. However, he said that both TDS & UIC will be corrected in future notification pending receipt of EPA ID #

12/3 CONV. w/ Mark Posson

P.D.S. — Parent Corp.

Pac Reclamation & Disposal (PRD)
Benicia Facility CLASS I

Sierra Reclamation Disposal (Martinez Facility) CLASS I

IT — 4 current facilities
1 under construction

II-1 < Travis — IT Montezuma
Lake County - Benson Ridge

Imperial County II-I
Geothermal

ONLY Transportation yard at
4501 ~~4545~~ Pacheco Bl
Generator — Wash down sump
from cleaning outside truck

Haz waste activity —
app. 100 trucking companies

Major wastes: alkalies & bases
Benicia Facility
Only material

No Drum Burial, No PCB

Landfill — only compacted landfill

Surface Impoundment — Heavy Sludges

Why Generator

VineHill — LAB FACILITY —
LIQUID material

Decant water portion
Cascades to lower (solar evaporation ponds)
blend acid in caustic to neutralize

SITE OPEN IN '69 — J&J Disposal Serv
1974 — Discharge problem —
cease & desist order by RWQCB

74- IT Began operating site
purchase site from owners

Improvements

Fail Safe Dam

Cap ponds which flowed into another site

Drainage patterns, levee improvements

75- No more drum burial

Drum Burial - ask Don - Site Manager

new landfill

LAB FACILITY - end of Arthur Road - waste analysis

parameters - on form

load-by-load - other

Sulfides, phenol, flam, ph

Routinely

Issued safety glasses

MEP441 001359

pre-disposal sample picked up
by salesman supplied by generator
trucks can wait 2 hours
to two days waiting for sample
analysis

MEP441 001360

No foreign waste

FOR ROUTINE WASTE LOADS
Titanium oxide waste
Paint Sludge waste
*Spot Check on six month basis
*Check w/ generator for process
changes
*Visible inspection on every load

4 GC's — computer assist
analysis
2 AA's

photo at gate

1135am Benicia Facility

Intro: DON MORRIS

Local agencies have not received copies of plan until it goes final

Don Morris meets w/ local at least 1/year

No ALARM - DON MORRIS STATED N/A TO THIS SITE SINCE men wear ear muffs

ONLY ONE PLAN
COMMUNICATION, FIRE EQUIP ON SITE. HOWEVER, NO INVENTORY OF fire equip. Plan discusses general requirements. Does not specify specific procedures for each site

GC: standard before & after

MEP441 001361

QA: routine stnd

pH: calibrate w/ distilled water

waste analysis plan does not contain QA procedures

No H_2O for ~~wet~~ firefighting

Manifest : (transfer)

CA HAZ waste manifest
#088-001402

no alternate TSD FACILITY INDICATED

However Don Morris indicated that whenever waste is being shipped out arrangements are made in advance with TSD facility that they will accept waste

Acres 130 developed
2000 owned as buffer

photo - pond 15
sludge pond
w/ safety shower

MEP441 001363

No ignitable wastes
No "no smoking" signs

12 AHA
~~11~~/22/80 Met w/ John Kallock Plant Mgr
1:05pm Bernie Braptler Production Supt
presented credentials
Generator and Storer

Don't empty tanks

Submitted Part A Application
Receipt in Folder "RCRA Plans
and Procedures"

MONTROSE OWNS COMPANY
STAUFFER & CHRIS CRAFT → JOINTLY
OWN MONTROSE. MONTROSE LEASES
THE PROPERTY FROM STAUFFER

Recycle all water

No sewer connection

50,000 gallon — alkaline

2x50,000
1x100,000 } ACID STORAGE

Fth
4/01

Technical DDT — off-grade

3 commercial chemical products included

All solid waste usually went to Palos Verdes — now all go to BKK

Chlorol and chlorobenzene part of DDT process

DDT only product produced at this plant

100% technical

MEP441 001364

Chancellor & Ogden transporters
CAD067786749

3 manifest TSD facility not
completed information on disposal

manifest #	date
009-088939	12/4/80
009-088941	12/4/80
009-088948	12/6/80

all alkaline solution
DDT production waste

received by Rick Estes
Chancellor & Ogden transporters
3031 East I Street
Wilmington CA 90744
(213) 432-8461

BAK sent white copy back

24-hour operation requires documentation of procedure

tank inflow controlled by operator &

daily maintenance of inventory (control)

monometers (level indicators)

overflow pipes → channeled to troughs into ~~water pond~~ collection system

underground tank
2+ 20,000 gallons
pumped into 50,000 storage tank → trucked out

liquid wastes non-flammable

12/23/80
SMVR - PLATE — FULLERTON
conversation w/ Frank Elwell Charlie Rosales
Last disposal date 3/2/80

Solely Generator

~~NPDES permit #~~ Orange County Waste Permit:

County Sanitation District of Orange County
permit for Discharge of Wastewater
issued by County Sanitation District
#2

No 2-650
7/1/78

Pretreatment will be required
to remove zinc

will
Accumulate app 2,000 gal zinc sludge
will go into treatment tank add
flocculants → filter press →
Solution will be 10% solids and
dumped into container below
filter press

MEP441 001367

Frank Elwell questions whether he should submit a part A application. They are not currently generating zinc sludge. However, in order to meet pretreatment requirements of Orange County Sanitation District he will have to install system (described last ¶ of previous page).

LET FRANK ELWELL KNOW ABOUT FILING PART A APPLICATION
(714) 525-3851

12/23 HOOKER INDUSTRIES / ONTARIO
Presented credentials to Ron/Hardin
manufactures exhaust systems
for automobiles
240,000 sq feet
175 people

$10 million gross sales

Storage Area
Form Steel, welding Operations
Zinc Paint + Plating

Primary Chrome Plating

5 drums Zinc sludge
Chancellor - Ogden Trucker
to BKK Landfill

MEP441 001369

City of Ontario — Permit

Shoveled into barrels — hauled off-site

Sludge Clean-Out One-time Shot

Within the last two years, co has
changed from cyanide zinc to
alkaline zinc and sludge hasn't
built up

Parts are cleaned in muriatic acid

2 tanks < maximum concentration
50% muriatic acid
15% " acid

1700 gal 15%
3000 gal 50%
> brand new set-up

last dumped June 7 (80) into sewer
~~mixed w/ caustic and~~
hauled by Chancellor & Ogden to BKK

Chrome plating Pomona

MEP441 001370

~~January 79~~ July 80

5000 gallons chromic acid

Currently Pomona facility has about 1500 gallons chromium hexavalent chromium
Last batch was between
7-8 oz per gallon
hexavalent chromic acid

Ron indicated they will submit notification form. However they will not be generating waste from plating operation.
~~While they~~
They discharge ~~[illegible]~~ electroplating bath solutions to sewer and meet all permit requirements

They do not use cyanide anymore → they use an alkaline process.

12/23

MEP441 001371

Presented credentials and introduced ourselves to Mr Salter
Discard list of old products from Ag Division and

Technical functions (R+D) moved ~~from~~ facility Lemon oil recovery and manufacture of pectin

Technical personnel transferred to Ontario facility.

Conducted tests on pesticides used by growers.

"Housecleaning"

Operations

Receive lemons from packing houses

Extract juice + oil from lemons

Mechanical extraction (FMC extractor)

Separate oil emulsion

Treat w/ enzyme or freeze

Centrifuge

MEP441 001372

Package U.S.P. Lemon Oil

Sell Lemon Peel for Dairy Cattle food

Concentrate juice in evaporator

Process 2,000 tons / 24 hour period

Boiler Blow-down waste. (ph = 6.7)

12/27/80 Arrived at Pacific Industrial Electric Co
9541 Santa Fe Springs Road
Santa Fe Springs Cal

accompanied by Edna Beach, South Coast
Air Quality Management District, 9150
Flair Dr, El Monte Cal (213) 572-6258

No persons present at facility
appeared to be closed

11:15am 12500 Block of Park Ave
West of Bloomfield Ave / Santa Fe Springs Calif.
Several Tandock Scrap Drums

29 x 55 gal LACCO Formaldehyde
Solution — 40% Formalin

MEP441 001373

(209)237-8246

1/8/81 meeting

SELMA PRESSURE TREATING

3338 E Wash
Fresno

telephone call to H. Agrew
conversation w/ Randy O'Banyan
worked 3 months - put them in
pressure treating tank recently fired
past disposal practices
Mr Smith → worked 3 years
moved to Missouri
? disposal practices

(1) 6 - 35' wells on either side
of facility back-filled w/ gravel
No longer in use 65' → 4-5 years ago

(2) Unlined pond

(3) Runoff in ditch - killed 8 rows
of grape vines
have since blocked drainage

3-4 west wall - barely visible

pond covered 1½ - 2' of topsoil

Plant = 250 - 300 acres
Owner = Mrs Petri

MEP441 001374

2nd containment breached
by repiping

PCP spilled everywhere

30 days for mud to stop dripping

Dan Hook - Plant Mgr

Contractor — Soil Sampling
Results sent to regional board.

Water well in front of garage
front office

Water table 48'

Worker 6 AL KIRBY
current employee

~~Red~~ Reg Board — 76 — groundwater
sampling

Loan from Water Pollution Cont Auth

Arnold Hatai RWQCB — 9/86
minor requests on improving
drip pads
Will sample THU 1/8/81
can run analyses in 3 days

Notified as storage facility
→ in shed in drums

New Regs 12/31 Part 264/265
storage requirements

Mon pm = meet w/Bayer

Tues am — inspect

FIT — uncontrolled
SOA — ISS

2 State Guys RWQCB + DOHS

Inspect under §3007

Paul & Dave Beckman FH

Call Jim Wells

NIOSH

OCA

KOPPERS Co

EMPLOYEE INFO

Tues 1/13 meet w/ Arnold Matai,
Loren Harlow, Mohinder Sandhu

Jim Wilson has also inspected site

HISTORY

July 71 1st order - discharge requirements

Reevaluate Site - Soil Consultant hired

Soil Samples
Well Samples } Arsenic, PCP, Chromium

mix PCP product on site. Wood is put in pressure vessels - removes and drips

No direct discharge - only rain induced

Water well - behind main bldg 3 hp pump

Mohinder noted spillages around container leakages, spillages

Groundwater moves E → W However local wells could change movement

MEP441 001378

1/13 1:25 pm

Introduced Karen, myself, Paul, and Dave
Presented EPA credentials
Paul & Dave - introduced and discussed
Pot. H.W. Site Program.

Closed loop in one system (CCA) reuse
No generation. System been in
for a number of years.

10% growth

Oil system - reclaim oil off of water
reclaim it → CCA system

Sludges are cleaned up, held

Hours waste since November

Cleaned up entire yard in October

2 cleanups

Blue Hills open twice a year
Thru April and October

MEP441 001379

SELMA

Why establishment
~~CCA~~ Copper E Quintilate ??
Repackage - none packaged so far
Would buy a concentrate & mix
with mineral spirits & distribute.

20,000 lbs of 1992 waste
will ship out next batch of waste

Daniel Mouk indicated they are a
TSD facility.

WASTE analysis plan on site?
DH: NO WASTE ANALYSIS PLAN

Site Security

MEP441 001380

Process operators
panic button to sheriff Department
separate
Monitor gate system electronically
Valley alarm systems

Unauthorized

DH No facility inspection plan on site
No inspection log
Walk inspection of barrels
Once/hour inspection of tanks
by treatment operators
14 tanks on facility
waste (2) dirty & clean effluent
not a waste to be discard
only waste in drums 150x55
gal drums
Alarm Bell w/in 150' of
waste handling facility
Telephone

MEP441 001381

126

FIRE Control equipment:

Dry Chemical fire ext ↓ on site
1 — 50' from drum storage

small water supply — water well
hydrant across street — 10" main

decontamination equip

lime
sawdust

Jorgensen ~~test eq~~ Check + recharge
equipment ~~No~~ Haven't
Reached one year yet

In February, former plant
manager met with local
~~police~~ and fire dept,
sheriff

MEP441 001382

Selma Hospital Emergency Room
knows what kind of chemicals
told DH: Charles Matzenbuehler — former
plant mgr

Last illness 3 mos ago — employee developed a rash while handling treated material

SPCC plan not amended to include hazardous materials

No list of emergency equipment

Plan to move to Malaga

CCA 50% Concentrate diluted to <1%

PCP diluted to 6%

MEP441 001383

Plan waste disposal practices
→ check w/ Mr. Peterey

(209) 896-1515 Gerald Peterey

Soil Analysis from old impoundment area

5' to 26'

Foundation Engineers – Test Bores
Cal Analytical – Analysis
Contact Jerry Aaberquist

Old impoundment (hearsay)

DH believes there was an impoundment at some time. Covered up with soil 3-4 years ago.

1/14 waste streams

MEP441 001384

2 chem < CCA + PCP

once every year or two
~~Env Disp Services~~ would
~~Waste M~~
Chemical Waste Management
from Coalinga Plant: Kettleman

Not since April have tanks been cleaned

Tank bottom sludge: maybe 10 drums

Sludge from sand filter
12 x 55 gal per month
mixture of CCA, PCP, dirt and sawdust
Decant' solvents off tops of tank

PIT SOLUTION IS FROM THE TREATMENT VESSELS
TRACK PAD AND DRIP PAD

WOOD REMOVED PAD W/IN 1/2 DAY
STAYS on drip pad up to 4 days
then moved to storage yard

Spillage/splatter 5-6 drums/mo
contaminated sawdust

MEP441 001385

CCA comes in tank truck
4,000 gallons/month
diluted from 50% concentrate

to between 1 (min) – 3% (max) diluted w/ H_2O

USDA Reg # 61-2

per pound of dry chemical

Chromium	CrO_3	47.5%
Copper	CuO	18.5%
Arsenic	As_2O_5	34%

> 11.1% As expressed as 11.1%

Treatment Solution

99% H_2O

1% CCA

MEP441 001386

American Wood-Preservers' ~~St~~ Assoc.
Book of Standards

PCP Bags

40,000 lbs / 3 mos ~~[illegible]~~ 160,00/year

2400 bags/year

50 lb bags = 2400 bags/year

200 bags/mo.

5-6% PCP solution

MEP441 001387

Koppers sampled in 1979.
Owner & DH jointly decided to sample from area suspected of being surface

Koppers is aware of sampling results of December 1980

D.H transmitted results to Koppers in letter dated December 11, 1980

D.H. talked to Paul Goydin w/Koppers in Pittsburg Pennsylvania before Christmas 1980

Riverbank → near Modesto
Thunderbolt

Avenue 12 and Road 32
McGillis & Gibbs in Madera
formerly B J. Carney (sold mid-80)

conversation w/ Jim Brewer

Worked 14 months as quality control supervisor

45 acres

MEP441 001388

serious dripping & containment

Recently installed concrete wall
~~wall) around drip pad~~
around tanks

Pressure
Treated lumber is removed
from treatment vessels

left on track → removed
across

"Blocks" of PCP stored outside
30 feet diameter
Waste pile approx. 15 feet high
(~~Sept~~ Oct '80)
no attempts made to contain
waste pile

MEP441 001390



MEP441 001391

1/14/80 PURITY OIL SITE
East of 3319



MEP441 001392

1/19/81 RCRA TRAINING

TOPIC	RCR	(EPA) 40 CFR	(DOT) 49 CFR
ID & Listing	3001	Part 261	—
Gen Require.	3002	Part 262	—
Transporters	3003	Part 263	Parts 100-179

1/21/81 RCRA INSPECTION TRAINING

§ 3007

- access to any facility handling hazardous waste
- three types of inspectors (1) State (2) EPA (3) EPA contractors

purposes
- (1) inspect (2) copy records (3) obtain sample

MEP441 001393

- 5 Guidelines
  Request Access (2) Enter at reasonable time (3) Reasonable promptness (4) Sample weight (5) furnish analytical results (6) public access to report

Session II — Harry Seyardanan

Barlow's Decision - OSHA inspector

1. Inspector not entitled to enter non-public sections of facility w/o search warrant
2. Owner of property protected against penalty for denial of entry
3. Guidelines do not pertain to public portion of facility.
4. Owner or operator can withdraw consent at any time

Documentation

1. Checklist
2. Field notebook

David Schnapf - Enforcement Division
Inspection procedures under warrant

EPA's guidance and procedures published in memo April 79

Inspection Strategy

Emergency Exception - contact US Attorney If inspector has right to be there than US Marshall ooo

Plain view - public areas anywhere you have been taken. Photos from off-site are OK. Aerial Photos OK

Need Consent Knowing Consent
No threat or force
Consent has to be from representative

Consent can be revoked - try to get reasons

Consent can be partial

MEP441 001395

Types of Warrants

Civil — probable cause
— neutral inspection

Criminal — much higher degree of probable cause

1/22 NEIC DENVER

Equipment On Site

→ Gamma Detector

→ Oxygen / Lower Explosion Limit Meter

* Automatic — not spark proof

OR * Bulb pump — spark plug but has to be manually operated

→ Photoionizer - tests for organic vapors

Level A — moon suits, SCBA — maybe 1% of sites

Level B — rain suit (rubber) protects against some vapors, splashes

Level C

Level D — boots, gloves

New Site 3 entries

1) Preliminary assessment
2) Inventory, sketch site
3) Sample

Document Control — Each document has a #
Each piece of paper returned. Requires
a document control officer.

Decontamination

→ cloth tape measures — can throw away

3 TYPES OF SAMPLES

GET Sample Bottles Sample Cases
Zip Loc Bags
DOT Labels

2/11/81 8:45am Conversation w/ Wayne Cranberry Arnold Morrison

CCC crews left on Friday

~~2800 → 2080~~

2080 → 1/2 (Stripping

110 Spray crews (3 people)

Notice to Homeowner — OK

Change in Bait

MEP441 001399

Switched Products

Gone to Liquid —

25% WP not available

cumbersome

Using 19.2 ounces 8/b Emulsifiable Malathion

(1.2 lbs/ai per acre)

Mixing w/ 25 gal Staley's Bait

Mix w/ water to make 100 gallons

buffering →.

Last wild fly caught January 22

have dropped Bayley / inactive

Cupertino yard (CalTRANS)
Bubb Road
Photo #1 S of Stevens Creek Blvd
STALEY BAIT TRANSFERRED
TO ~~FROM~~ LARGE (4,000 gal)
FROM to SMALL SMALL (500 gal)
at night.

Photo #2
Staley bait storage

Tank Samples sent CDFA
Pesticide Lab in Sacto
Get from Sherman Nash

Photo of spray rig
"pressure control"
JF: CDFA requests pressure be
kept below 100 psi

---

photo: Malathon ULD
EPA REG #241 000 ?
illegible
Jim Franks pen points
to reg #
approx 2 x 4,000 gal Stainless Steel
tanks

MEP441 001401

US Govt license plates
JF: USDA bought from Texas ?
→ grasshopper or bollweevil control

WG&S Indicated that contracts will expire on 2/13/80

Good crews on Cal Trans rigs

MEP441 001402

2/17/80 Meet w/ P.G & E 2:30pm
David Gilbert Charles Tatevosian
KT: met to discuss sampling PGE/EPA

INGA sampled at compressor near US/Canada Border

PGE sampled at 2nd compressor — Burney
Sampled oil
Results back — no PCB
Uses lab in Redding & Richmond

All compressors on Canadian Pipeline are Centrifugal w/ exception of 4 reciprocal on US Border

PGE has never used synthetic oil for
Use hydraulic ~~seal~~ oil to seal compressor
Use mineral oil as seal oil
Several hundred gallons

Replace oil

Centers at Burney and Willows

Hydraulic operated regulator valve?

Regulator valve used to adjust pressure or control flow

Pipeline pressure 500 lbs

Hydraulic gate valve

Stations all have ball valve

Gate valves on line →

MEP441 001403

Willows —

Pipeline Operations
Walnut Creek

1 pm thurs at Willow

2/14/81 9:35 am arrive P.G.&E. w/D.H.
intro's Keith Turley, Willows District Foreman

showed credential and issued NOI, Cont.

Photos of 4 facilities on wall

Delevan
Gerber
Burney
Tionesta

GE Frame 3 Turbines
Cooper Bessmer Compressor

Rolls Royce Gas Generator
Cooper Bessmer Compressor

Units K1 & K2 2-phase

Valves automatically controlled
by hydraulic or pneumatic action

MEP441 001404

2 volume book set
"GAS TURBINE EQUIP. FOR MECHANICAL
DRIVE APPLICATION"

Lube Oil tank common to turbine
and gas compressor

Service lube Oil < Very little Oil
approximately every 3 months
Average between 35-40 gallons
oil stored in 55 gallon oils

Have purchased oil from Chevron
& since 1967
CHEVRON TURBINE OIL 32 #changes same oil

Hydraulic valve
K.T.
I think" Shell Fluid 4"

Shaffer Valve Operator

driven by oil shoved by natural gas

Antioch terminal Radio Control Microwave System

Pipes X-rayed when built
Arc Welded

Pipeline & Stations are protected against corrosion by cathodic protection —
Separate systems
Insulated flanges
Low.

Bury anode DC Voltage on piping

Gasket < stiff mycarta? - insulating

not sure origin of material

Cathodic protection Required on all new

Flange gasket on valves

Flexatallic ?

MEP441 001407

Burning Dump on Rt. 36 just before turn-off to A21
Lassen Co.

2/19/81 Photos from Delevan Comp. Sta

3 1. Delevan normal operating conditions
4 2
5 3. } Overview of K1 compressor & turbine
6 4.
7 5. Cathodic Protection Rectifier, 18 volts
Petroleum Elec Mfg Inc
3301 Charles Page Blvd Tulsa OK
8 6. Overview of K2 — Turbine of left
Lube Oil System on left bottom
7. Shafer Valve / Scrubbers behind
8. Scrubbers
9. Scrubber collection tank
10. Opening Shafer valve hydraulic fluid tank
11 D.M. Sampling " " " "
12 D.M. disposing of glass thief
9 ~~13~~. Opening lube oil reservoir unit K2
10 ~~14~~. D.M. Sampling lube oil reservoir unit K2
11 ~~15~~. Same as #14 - different aperture
12 ~~16~~. D.M. Sampling scrubber collection tank
13 ~~17~~. Same as #16
14 ~~18~~ Outdoor drum storage beside oil storage shed

MEP441 001408

19. Exterior of K2 turbine/comp bldg
missing ? "fin-fan (big radiator)" cooling tower
exhaust stack & regenerator (heat exchange)
to left of K2. Small bldg is
electrical circuit bldg.

~~20~~

Samples from Delevan

TX-1-SHS Hydraulic fluid shaffer
valve #21 (Photo #11)
TX-2-SHS Lube oil from turbine/comp K2
TX-3-SHS Scrubber Collection tank
(empty) Soil sample taken
from stained area below spigot

Drum Storage - Chemicals

UCAR Thermofluid PM1717
Dow Therm Inhibited Ethylene Glycol

Station Battery Charger

Crusher

MEP441 001409

PACIFIC GAS & ELECTRIC CO.
PIPE LINE OPERATIONS DEPT.
P.O. BOX 9015
WALNUT CREEK, CA 94598

(DUBB)
L w/ W.C Netherly
FOREMAN
ed (DH) NOI
... inspection confidentiality Notice

Burney ~~uses~~ has:

K1 turbine - GE FRAME #3
" comp - Delaval PV30/30
(Share common lube & seal oil light turbine oil #35)

K2 turbine (gas generator) - GE LM-1500
comp Ingersol Rand
(2 separate ~~lube~~ oil systems)
Shell 500 - LM 1500
Shell light Turbine Oil #35

power turbine comp lube & seal sys

Jean Argo - Cascade (Elect) District Manager

Main line values - mechanical operator
gas operated vane motors

Unit values (#11, 12, 21, 22)
pneumatic values - uses gas
mfg by grove

One Shafer valve - Sta blowdown value

41 001409

(DUBB)

2/20/81 1000 a.m. Met w/ W.C Netherly
- BURNEY DISTRICT FOREMAN
Presented credential & issued (DH) NOI
& TSCA Inspection Confidentiality Notice

Burney ~~uses~~ has:

K1 turbine - GE FRAME #3
" comp - Delaval PV30/30
(Share common lube & seal oil
light turbine oil #35)

K2 turbine (gas generator) - GE LM-1500
comp Ingersol Rand
(2 separate ~~lube~~ oil systems)
Shell 500 - LM 1500
power turbine comp lube & seal sys - Shell light Turbine Oil #35

Jean Argo - Cascade (Elect) District Manager

Main line values - mechanical operator
gas operated vane motors

Unit values (#11, 12, 21, 22)
pneumatic values - uses gas
mfg by grove
One shafer valve - Sta blowdown valve

[Engr Sect in Walnut Creek has copies of facility equip specs]

BURNEY EMPTIES SCRUBBER COLLECTION ABOUT TWICE/MO AVERAGE gal/2x MO of light turbine oil

Gas compressed from 675 psi discharge 822 psi
Suction temp 34°F discharge temp 61°F

Max temp of gas (coming out of compressor) may be expected to reach 110-120°F

Auto Shut down at 126°F
~~No~~ Never shut down since
June 1969 (K1 Unit)
Jan 1970 (K2 ")

35mm Photos at Burney Comp Sta

1-5 NO PHOTO FILM MAYBE NOT OK
SHOT w/ LENS CAP ON AFTER RELOAD

1-2 Pneumatic Operator (Grove) for K1 discharge valve (Intake Valve in background)

1-3 Oil Storage Area (Shell Turbo Oil 32, Dautheim SR-1 Inhibited Ethylene Glycol, Chevron 325 Solvent, Motor Oil Shell Aeroshell Turbine 500 (for Jet Engine)

MEP441 001410

7 (cont'd) 2 drums Methanol used for de-icing gas actuated valve operators

4 FIN-FAN coolers — gas coolers cooled by air flow/heat exchange ~~Silen~~ station blow-down silencer on right — used to evacuate station piping for maintenance reduced to atmospheric pressure 3

5. Compressed gas ~~operated~~ actuated valve operator Box on right contains lubricant oil (gas turbine oil and alcohol to prevent freezing) Station Discharge valve gas operated Valve HP2

6. Photo of entrance to Burney Sta.

Samples at Burney

TX-4-SHS LUBE OIL FOR POWER TURBINE, COMPRESSOR, AND SEAL OIL SYSTEM UNIT K2 Taken from from filter spigot unit oil has passed thru particle filter.

photos 7, 8, 9 ~~1~~ & ~~1~~

set camera from 125 to 500

Bulk Oil Tank
Meeker Oil Co.
Located ~~at~~ on 299

MEP441 001412

13,000 gallons

3/12/81 Copies of Dilution Analysis
Frequency of Application
Fly Ratio

New label on tanker truck

MALATHION SPRAY ALONE?
What's rate & frequency?

Adverse effects

Wayne Granberg

Diazinon or Baytex (Fenthion)

Nancy ~~[illegible]~~ on ~~[illegible]~~ Daily Medfly
Full set of Back issues

3/31/81 INTERVIEW w/ CHARLES ROBERTS
/ CHIEF PLANT MECHANIC
CASA GRANDE COMPRESSOR STATION

"A" & "B" LINE FROM TUCSON
PROCEEDS TO GILA STA → BLYTHE

"C" LINE FROM ORACLE
PROCEEDS TO WENDON → BLYTH
"C" LINE BYPASSES GILA STATION

COMPRESSORS 1 & 2 ARE IN A SERIES
FOR "A & B" LINES

COMPRESSOR #3 IS FOR "C" LINE

PHOTO #1 Turbine Oil Storage 3000 gallon
#2 waste oil pit — pipe from
station scrubbers on left
~~pit~~ scrubber valves are opened
once a week for discharge
Dale Zung → EL PASO doesn't believe that
anything comes out
#3 same as above

MEP441 001413

PHOTO #4 compressor #2

SAMPLE TX-5-SHS (3/31 1210PM)

LUBE & SEAL OIL FROM
COMPRESSOR #3 (C LINE)

SAMPLE TX-6-SHS (3/31 1220PM)
COMPRESSOR #2 (A & B LINE)

PHOTO #5 Lens: F=50 mm
- Pole mounted Capacitor (?) adjacent to Irrigation ditch on AZ Hwy 84 - South side, .7 miles W. of C.G. City Lmts
- pole marking - 106
- capacitor (hooded box) attached to 3 transformers which apparently lead to irrigation pump

PHOTO #6 . Lens: F=200 mm
F STOP: 11
Distance from subject - approx 25 feet (7.5 m)

3458.5 (mlg)
3459.2
Casa Grande City Limits

Closeup of capacitor (hood box)

3/31/81 Benson

A & B LINE (See Polaroid for flow digram)

photo ~~#~~ #7 ~~#~~ Sandy

Avol taking sample from

Compressor ~~#2 #7 SHS~~

#TX-3-SLA

photos # 8 & 9 (Used tripod & 1/30 shutter speed)

Compressor #2

Stan Hager stated that there are no scrubbers at Benson #2 they were removed because the ground was too unstable and that there were scrubbers at Wilcox 33mi down pipeline and approx. 33m to Vail

MEP441 001415

4/1/81 Tom Bell Plant Operator
Hackberry Compressor

Seligman has 3 turbines
2 Electric Motors -
1 GE GAS TURBINE

Electric motors possibly installed around 1955

Automatic Dump Scrubbers

Size { 24" & 30" — common scrubber
34" — one scrubber

~~Both~~ Common line to pit
Separate auto dump

PHOTO 10
~~Sample TX-4-SLA~~ Scrubber
sample from 34" line
Sample not taken: DRY

MEP441 001416

PHOTOS 11, 12, 13 Mike Chintus
Sampling scrubber collection tank from scrubber of 24 & 30 (common) lines into Hackberry compressor sta.

Sample Tx-4-SLA same as ph

Photos 14 & 15 view of scrubber disposal pit

MEP441 001417

4/2/81 LEUPP ~~INSLOW #3~~ compressor station met w/ ~~ERIK HANSON~~ ERICK HANSON Chief Plant Repair & Mike Chintos, area chemist

photo #16 Leupp Station Flow Diagram

Sample #Tx-7-SHS (4/2 200PM) lube oil from:

plant "C" Electric turbine #2 (common lube with gear box & compressor)

photo #17 electric turbine #2 compressor on left, gear box in middle, motor (turbine) on right

Sample # TX-8-SHS (4/2 230PM)
Scrubber sample of 34" line. Upstream Station: Dilkon
Upstream comp - gas turbine single stage

Photos 18 & 19 SHS taking sample TX-8-SHS
(SLA photographer).

photos 20 & 21. SHS sampling from scrubber collection lagoon (oil pit)

Photo 22 & 23 View of scrubber collection pit

Sample TX-9-SHS (4/2 245PM)
composite sample from scrubber collection lagoon - Lupp Stn.

MEP441 001419

4/3/81 met w/ Wayne Gallatin
District Supt
& Lowel Stump
District Supervisor

WINSLOW COMPRESSOR STA # 3
TRANSWESTERN PIPELINE CO.

L.S. : Several years ago Transwestern used a Monsanto synthetic oil → company (Monsanto) claimed it was a good lubricant and wouldn't burn.

L.S. : No pipeline waste disposed in pit. All collected in tank and disposed

Conversation on telephone with
~~Larry Langston~~ / Division Manager
(1040 am) / Roswell New Mexico
He understood that EPA would only be sampling compressor oil and nothing else. I said that we were routinely sampling scrubbers to determine the content of upstream compressor oil

John Seitz (202) 472-3701

by truck transport to tank facility in Flagstaff. → District 1 office at Station #2.
Near Navajo Ordinance.
Belmont Station.

1100 – 1200 gallons of waste oil accumulated in storage tank at Winslow #3 approximately once every 4 months.

Sold to Kaibab Industries and is used for boosting diesel fuel. Maybe reprocessed.

105 Jan Larry Langston refused to allow us to sample ~~pipeline~~ scrubber

L.L. Cliff Jacey Williams, Pipeline supt. Transwestern & Texas Eastern will call me back w/in 5 minutes

Will allow EPA to take scrubber samples.

Enter sample #'s in Sandy's log

2 pits located on east side of station property — North pit contains oily material entering drains in engine room

~~samp~~ sample taken from South pit : TX-6-SLA



Photos 24 & 25
S.L.A preparing to sample

L.D. one oil does 3 things

1. Lubricates gears
   Western gear increases RPM
   from engine

2. Serves as lubricant for
   compressor

3. Serves as Seal Oil

4/6/81

LUDONS HAS REMOVED SOLVENTS FROM DEER-O PAINTS DURING FEBRUARY AND MARCH. HOWEVER, D.K. HAS NO COPIES OF MANIFEST. HE UNDERSTANDS THAT THE TRANSPORTER (LUDONS) WOULD PROVIDE COPIES OF THE MANIFESTS ON A MONTHLY BASIS. AS OF 4/6/81 D.K. HAS NOT RECEIVED ANY MANIFESTS FROM LUDONS.

TRANS: LOOON'S
2819 WEST BUCKEYE ROAD
PHOENIX AZ 85009

I TOLD MR. KROG THAT THE

REGULATIONS REQUIRE THE GENERATOR TO PRODUCE A MANIFEST. HE SAID THAT HE GAVE ALL THE WASTE INFORMATION TO LUDON'S AND REPEATED HIS EARLIER STATEMENT THAT LUDON WOULD GIVE HIM THE MANIFESTS ON A MONTHLY BASIS. I ASKED HIM IF HE HAD ANY PREVIOUS MANIFESTS FROM LUDON AND HE SAID THAT LUDON'S PROCESS HAD BEEN SHUT DOWN FOR A WHILE.

PHOTOS:

#1. Rear entrance to "back yard" (Gary Lavagnino noticed child on bicycle outside open gate)

2. Alley between plant & "back yard"

3. Latex waste channel to pump which pumps to underground tank. Mr. Krog stated that there is no automatic cut-off for the underground tank. He said that it had never ~~[illegible]~~ overflowed because they always

checked it.

4/7 LUDON'S

Photo #4 Process vat for reclaiming solvent (sludge on ground)

#5 Close up of bottom of vat. Pails of sludge catch drips. Notice sludge on ground. Mr. Horton indicate that "sludge will set up hard and you can peel it away"

#6 9 (of 14) drums picked up from DEEPO on last trip

#7 Close up

#8 " "

#9 " "

note absence of shipping name or flammable liquid marking

4/7 LUDONS (cont'd)

#10 NE VIEW OF PROPERTY
notice chain link fence
and barbed strands
(dogs in yard)

#11 Front of truck
Note: placards

MR. MORTON EMPHASIZED THAT HE IS NOT PRODUCING WASTE. HE IS RETURNING ALL MATERIAL TO DECR-O PAINT. HE INDICATED THAT HE WOULD NOTIFY EPA.

4/8 Motorola 1:30pm

Presented credential to Nick Hild

3 Divisions share facility

1. HIGH FREQ & OPTICAL PRODUCTS
2. INTERNAL OPERATIONS
3. POWER PRODUCTS

HAZ WASTE RESPONSIBILITIES
(see xerox copy)
~~Geno Opinion~~

2 major wastes shipped off-site

photoresist — solvent based material (xylene, toluene, high-phenolic waste — usually 15% xylene)

DOCUMENTARY SAMPLES

	manifest #
DOC-1-SMS	052-000020
DOC-2-SMS	" - " 18
DOC-3-SMS	" - " 19
DOC-4-SMS	" - " 17
DOC-5-SMS	" - " 16
DOC-6-SMS	Motorola's Waste Authorized Responsibilities

4/9/81 REYNOLDS - Presented credential to Bill Stearns and Norb Wuest
Reynolds began running plant in 1946
" purchased " " 1949

N.W: Originally marked T/S/D on 8-1-80 "to be safe"

Main source of h.w. — still bottom sludge from Trichloroethylene circuit

Distill trichloro → in main tank.
Sludge from still is h.w.
Reynolds has not decided to store more than 90 Days

I QUESTIONED NORB WUEST WHETHER THE WASTEWATER POND WAS A SURFACE IMPOUNDMENT. HE SAID THERE ANALYSIS DID NOT INDICATE THAT IT WAS HAZARDOUS WASTE.

LAST SUMMER ~~APP~~ 12,400 GALLONS WAS DISPOSED (TRICHLOROETHANE) BETWEEN JULY - OCT 1980.
RINCHEM DISPOSED ~~AT~~ OF DRUMS

Documentary Samples Doc - 7, 8, 9 - SMS

4/10/81 Documentary Samples from Phil's Pumping:

DOC - 10, 11, 12, 13, 14, 15, 16, 17 - SMS

5/14/81 Conversation w/ ANALYTICAL CHEMIST ERIC NOTTINGHAM NEIC 8-234-4661

STONER LABS, SANTA CLARA (408) 727-4277] PCB content in nat. gas.

Dean Hill

Mike Woods - Sampling Procedures

5/2/81 Vacant lot
Richmond Ave, Richmond CA

Photo 1-3 Oil stain in lot
Photo 4 Overview of lot

HNU Reading > 1/2 ppm on oil stain
1-5 ppm Sanitary sewer cover

6/8/81 Calif Oil Recyclers
Fremont CA

Photos 5-18 Paved lot
behind CALIF OIL RECYCLERS

360° view of back lot
drums on east side
have markings:

MEP441 001429

POLY

FREON 11 & 12 - General Electric
Thermal Systems

M D I (Isocyanate)
POISON — GE Thermal Systems

PLURACOL POLYOL: PEP 550

ISO

MEP441 001430

Photo 19 & 20: Tank behind building next door to Cal Oil #20 Close-up of 19

Photo 21 - drain (ditch) from dripping tank

Photo 22 - Substance pooling along chain link fence Notice stain in background

Photo 23 Rick Taft using HNU Readings: 2 PPM Hydrocarbons w/ calibration set at 9.8 (Benzene)

Photo 25 Checking storm drain 1/2 ppm (ambient)

Send cc of Sobeck letter to James Lemire wants duplicate photos

Photos 26 - 33 SHS taking sample # TX-10-SHS

6/8/81 3:40 pm Vacant lot
Richmond CA

TX-10-SHS

TAG # 9-1013 Stain approx 10' diameter
No evidence of veget. life

Placed in inverted poly bag
Triple bagged
Sample seal affixed

Photo #33 Oil spill in vacant lot

Photo #34 & 35 Oil cans & filters

Photo #36 Overview looking south
~~Fr~~ Bush in center
is adjacent to spill area

Sample delivered to Emil de Vera
CA DOHS — Berkley
(540-2047)

MEP441 001431

6/9 Donny Western — Trans Pacific Air Cargo
Sample shipment for new farming procedure.
3.1 Kilos Diazinon
.12 " Copper WP

MEP441 001432

Cave w/ nozzles, spray bottles

Suggested that if they are registered, they submit NOA and call L.A. Ag commissioner for donation to farmer. Otherwise, return to Japan or have Customs destroy.

6/15 2:00 pm arrive at Co Ag — Brentwood
Accompany Ed to Diablo Ag Chemical
Highway 4, Brentwood CA
w/ Vic Acosta, ~~Ed Hogan~~
Selected file (1) each from "G" "M"

→ "LEONARD GERRY" file contained pest control recommendation for Diazinon 40W
NO EPA Registration # in Block provided on form. State requires entry to be made on Pesticide Use Report — NO VIOLATION

Spent pesticide contained in men's room.

Violations noted: No written recommendation or Salesmen signature on 5 ~ 10%

#1,2,3

6/15/81 Photos ~~1-5~~ Big Al's Trucks
Albrae St at Christy
Photo 5 4's address on sign
at end of driveway next to trucks

PHOTO 6 PESTICIDE APPLICATION (BELOW)

6/16 Out w/ Vince & Jerry Campbell

Calif Exterminating Service
P.O. Box 587
Lafayette Ca

Ca License # U70216
200 gallon tank, 400 psi

LINDANE 20 MISCIBLE
EPA REG. # 279-8682A

PHOTO 6-10
525 Market
(Burning

6/19 2380 Albrae St

Photo ~~12, 13, 14~~ 11 12 13 Big Al's Trucks

6/11 FRANK CURCURO, General Manager
Dale Sobeck Co. Since April 81
657-7833
Property line is fence perimeter

MEP441 001433

Trichloro monofloro methane
UR John

Tolyene Disocyanate
DANGER corrosive
irritant

Terrate Polyol
Hercules Chem, Organics Div.

Will check with D. Sobeck at noon.

Golden Gate Auctions
Tommy Thomas, owner

Map: Hill Ridge Quadrangle
property Thomes Creek

photo ~~13~~ 14 & ~~14~~ 15 oily runoff from
back lot S & E corner
6000 Stevenson

MEP441 001434

CA OIL
6/19/81 Documentary Receipts
DOC-18-SMS THRU
DOC-37-SMS

AMERS DRUM RECEIPTS FROM
CALIFORNIA OIL RECYCLERS

Photo ~~16~~ 16 - storm drain
Photo ~~17~~ 17 - drums, storm drain
PHOTO - 18 D. SOBECK'S DRUMS
~~19, 20, 21~~ 19, 20, 21 - CAL OIL
22, 23, 24 - Drums behind Cal Oil

MEP441 001435

Dale Sobeck: stuff out back
was dumped over a period
of 2 years
Aug 79 on
Stopped

Drew Sobeck: "Mutual Favor" Cal oil gets
rid of oil, get rid of
weeds

Agreed to eviction by Dec 81

photo ~~23~~ 24 — flash of barrel

photo ~~25~~ 26 — oil stains Drew
Sobeck watched Kip Prahl
and Kirk Hayward dump
one evening over a year ago

Photo 26 27 — material used by RR to treat ties according to Drew Sobeck
27 28 — SS sampling same at RR entrance
" 28 29 — 40' wide strip of oil SE side of prop.
" 29 30 — oil material E side fence going offsite
" 30 31 — SS sampling same — note markers on grou...

TX-11-SHS → soil on E side of Raychem
TX-12-SHS → RR material on SW side of Prop.
TX-13-SHS → oil on E side fence

MEP441 001436

photo ~~32~~ 31 view along east perimeter of fence looking South

photo ~~33~~ 32 & ~~34~~ 33 View facing west onto 6000 Stevenson East side of Raychem

6/24 8:30 am Spoke w/ Kate Brown, EPA HQ Fin Mgmt PM 226 755-1823

told her we had received 2 suits, 2 repair kits, 2 boots

Sent her truck slip with same info by pouch mail

10:20 am called Alameda Co D.A ? who's handling Big Al

Inspector Harnett: → consumer fraud

Hayward Consumer Fraud: Inspector Hughes 881-6150

6/24
10:30am

MEP441 001437

Gil Jensen Deputy D.A.
881-6256

Will keep watching Big Al - let him know if there's any evidence he's hauling waste. Injunction against Big Al — Contempt if he touches hazardous waste.

Ed Refsell 540-2043

Will send ~~[illegible]~~ topo map with area

6/25/81 Conv w/ Allen Clark re import $18 Imazalil produced in Belgium by Jansen Pharmaceutical R43813-BL-02 Jansen R&D New Brunswick NJ

Suggested that they submit NOA with letter from Belgium stating interplant ship pursuant to 40 CFR 162.5 → submit to EPA Region / port of entry

6/29 Wayne Auto Repair
4125 Breakwater

Photo #1 photo of above

Photo #2 D. Sobeck's Drums
6000 Stevenson

3-14 Vacant lot
across from T.A.C.
Enterprises
65 North 27th (off E Santa Clara Street)
San Jose

7/ → PHILLIPS BROS
Copper Oxy
Isocyanuric acid

2 photos - yellow throated bird
at rest area on I-5
near Delevan or Maxwell?
One photo botched

1-9 Tromp'l oie on Alvah Taylor Hall CSU Chico

MEP441 001439

7/16 Photo 20 of PGE powerhouse
line creek / line saddle
above Lake Oroville
broken ceramic insolators
in creek bed
Black stain on rocks
in creek channel

7/21 Spoke w/ Kate — Will send
2-way memo referencing PO#
for receipt of 2 butyl rubber suits, etc.

7/29 830pm Charlene Williams - GA DOHS
called. Asked if I wanted to accompany
her today to IT BENICIA. I told
her that Terry Brubaker had said
something about going out on Friday
but it wasn't possible because we
need advance notice to prepare
a site safety plan.

11:30 a.m. phone conversation w/ → Gonzales
N.Y. Port of Entry U.S. Customs.
ACTIVE BLEACHING EARTH (213) 646-6530
30 kilos (2 packages) L.A. Int'l Airport

no commercial value
→ PHILCRO CORPORATION (FILTRO CORP.
(213) 641-5723 Mr. Richardsen

11:40 Call to Mr. Richardson.
Chemical Process Plant recieves samples from foreign sources.
Used for decolorizing edible oil.
clay-acid activated
sold to oil refiners
Wesson, etc

~~Tower~~

Conversation w/ George re: import of sulfur.
Sulfur to be used as soil conditioner.
Last shipment

7/30 10:20 am — Lynn Taylor, Sonitrex Corp in Alhambra returned my call
He told me that Sonitrex Corp is no longer importing any dyes into U.S.
They are no longer represented by Ramon Castanares. Sonitrex will be mfg. a unit in Orange Co.
Mr. Taylor will send letter to me today stating they are no longer represented by Ramon Castanares

7/31 Call from citizen
PEST FREE - ULTRASONIC

US EPA REG # 44862-1L-01

Edward ~~Robinson~~ Robson Co
135 Maiden Lane
SF 94108

SHE RECEIVED
SHEES LITERATURE

CONV W/BILL GOODWINE
8/4 PRODUCED IN BELGIUM
R43813-BL-02
Technical grade to go from
one registered est to another
And 10 NOA to:
Bill Goodwine (201) 524-9706
Janssen R&D
501 George St
New Brunswick NJ 08903

Done

[2 min $3.75]

GLENN ANNIE ROAD (100 S BLOCK)

8/10 3PM ISLA VISTA SUBSTATION
SOUTHERN CALIFORNIA EDISON

large banks of capacitors
No signs of leaks no apparent
oil stains on ground.

8/12 11:45 Offshore Crane & Service Co
5901 Arcturus Ave
Port Hueneme
Photo #1 PCB transformer
"PCB" Scratched out.

8/13 ARCO OIL & GAS
PORT HUENEME CA

2 TRANSFORMERS:
"ITE CIRCUIT BREAKER CO
PHILADELPHIA PA
NON FLAMMABLE LIQUID TRANSFORMER
SERIAL #'S 17313, 14183

filled: 330 GALS / 4600 lbs

Documentary Samples DOC-40-SHS
Thru

Transformers are used within the leased property.

Questions on PCB equipment or inventory should go to Mr. Hartmungruber in Bakersfield.

Mr. John English with San Barbara APCD has been working with ARCO on air pollution control.

Photo ~~2, 3, 4, 5, 6, 7~~ 5, 6, 7, 8 (?)

PCB transformers & close-up

8/21 11:30 am Conversation w/Ramon Castanares' Secretary. I told her that we would like a letter from Mr. Castanares explaining who they are representing and what they are doing with the devices E.G., distributing, sales etc. Will sign NCA after receipt of letter.

Cypermethrin – told him that he should submit NOA.

Dan Baker, EPA Region X
2935-CA-01
Oxychem Lathrop

Doesn't match

8/25 9:30 am

VIC ACOSTA
JERRY CAMPBELL
PATI CLEARY

DON CRIPE, AGRICULTURAL COMMISSIONER
ED BISSET,

Robert & Irene Roads

MEP441 001444

TELEPHOTO PANORAMA f = 200 mm
Photo 8 Purity Oil Co
thru 22 fence installed

23 - 26 panorama f = 50 mm



MEP441 001446

8/26

PO Box 1222
Fresno CA 93715
Coast Laboratories
3386 S Maple Ave Fresno
interview Paul M. Rickert, Owner

Recover glycerin

Mostly empty drums on property

Waste co

Get drums from Raytheon (contaminated glycerin)
Menlo Park

Recover materials

Raydom uses hot glycerin for bending plastics → eventually becomes black. Particles of plastics

Use two systems to recover
1) Distill
or
2) Filter

MEP441 001447

Return glycerin to Raytheon
Major contaminant is H_2O
2 tanks
labeled waste glycerin
flash point app 500° Farhet
work with: Jim Hedges
at Raytheon Menlo Park →
in charge of wastes?
Receive 60 drums to make 40 drums
Ship 20 drums every 2 mos

8/17 **1050 am**

MEP441 001448

Told him save as 8/21

At time we owned 25% of Sanitex. Since then, no shipments across border.

Ramon Castaneres purchased MX interest from Lynn Taylor, sold rights to U.S.

2/31 Conversation w/ Mrs Silva
593-4678

given advertise at Thierry's
Pet Store, 14th Street, Oakland

asked about Ultrasonic, please send lit.

Jennifer Ganary (213) 532-3111 x 2311

please send literature.

9/17 Do not need NOA at this time and EPA can destroy outstanding NOA's.

Told him that the next NOA he submits should be accompanied by a letter stating he is no longer associated w/ Southern & who he is now representing.

10/20/81 3:15

Conversation with Ted Bartell < 877-0458

US CUSTOMS Mr Sike 576-2512
SFO

Bags of Copper Hydroxide — No identification at all

One bag broke open and 2 Western Airline workers went to Emergency Room.

MR SIKE — Suggests

Call MR Pelletier 556-6323

MEP441 001451

11/3/81 Cooper Site

SW corner Artesia Blvd & Normandie Ave
Gardena Cal

Photo 1-7 View from EAST SIDE
OF COOPER SITE

On right is proposed location
of Artesia Fwy (RT 91)

White - Barn-like bldg left of
Billboard is ~~Amco~~ Aircraft
Magnesium - DOHS sent questionaire

Drums are in compound with houses

3 small houses in trees

Site is chain link fence topped
with 3 strands barbed wire

Photo 8 Chain link fence on E side
of cooper site showing
sign of access / trespass?

photo 9 SW view onto site from
corner ART / Norm notice
tar like substance outside fence

MEP441 001452

photo 10-16 South view standing on ~~edge~~ side of Artesia



* ~~Jane Wolf~~ said used to be green grass.

interview

James Robbins 539-7513
1472 W. Artesia Blvd

lived same location 26 years

Old fire pit — made bricks
owner deceased
dump crude oil — 1945-50's
about 10 years ago private
contractor doing sampling
— at least 50' deep
Bobcat got stuck, pulled
out with winch

Only time you can walk is during
winter

Dogs roam on site — about
12 dogs — Aunt
3 cousin
6 mom

MEP441 001453

MEP441 001454

# of person

1440 Sabina Knight (aunt) 1

1462 Kenneth " (cousin) 2

1472 Jane Wolff (mom) 2

about 20 horses

may have photos (213) 823-3947 owns Aircraft mag

check w/ Jean Phelps in Office

~~owner of~~ leases Aircraft Magnesium

property

only fires are in Aircraft Magnesium

1960 flood Artesia & Normandie

flooded — floating

couldn't be seen — Boats

floating up Artesia

1962 - concrete flood channel

Birds have been seen getting stuck

have had to pull dogs out

(not common)

pulled out, but die

Photo 18-25 View from corner at

WOLF / Knight property

Notice oily stuff coming up

→ Mark Knight remembers stories of another scrap caught on fire? 57-59? Late 50's

Brick left over from

Higgins Brick Co. E Floral
772-2813
Old guy who used to work on site with owner of Brick

See also 11/4/81 FOR MORE COOPER INFO

→ 590-5140

Jim Steele - CA F&G, ~~590-5145~~
(213) ~~[illegible]~~-5140 ~~590-5147~~
Long Beach Office
350 Golden Shore
LB,

Recent DOT

Beth: Coffee plant next to Montrose

California Salvage — 3 dumps off Port of Los Angeles — ECKHARDT REPORT

Co Engineers recommend Cal Salvage when material was considered too dangerous for land disposal.

Maps are at Co. Engineers — Industrial Waste Division. 550 ~~South~~ Vermont 2 Blocks N of Wilshire 3rd Floor

MEP441 001456

11/3/81 2:05pm
John Kallock, Plant Mgr, Montrose
James Wiseman, Environ Control Stauffer
Rick Wilson, Director of Mfg Montrose
Betty Jones, DOHS

Farmland — Oil Engineering Diagram City of Los Angeles Rancho San Pedro Superior Court Case 3284

Hughes Mitchell Inc → 1934-5 bought property and processed ore into paint

Sulphuric Acid Plant / Muriatic

Photo ≈ Spence Air Photos
(matches with 1938 photo)

Involvement w/ Sears Roebuck

Property Set idle

WWII — government agency

? circa 1942-43 — Stauffer bought plant
from Govt ??
Or Sears Roebuck

90/Tons/Day Sulphur Burning / Spent Acid Regen. Plant
1944 Blueprint Drawn by Charlie
Stephanetti 2/4/44
for Stauffer Chem
Revised 6/10/45
1946-7 Montrose leases property
Oct 46 — May 47 Construction Period
May 8, 1947 — Operations Begin
DDT production begins

~~Sulp~~

Monochlorobenzene / Chloral Production
always been in Henderson Nevada

MEP441 001457

MEP441 001458

Montrose currently produces

75% DDT Water Dispersable Powder

100% Technical

10% Dusting Powder (FOR BODY LICE)

Waste Streams from Production of Technical Grade DDT:

Acid Recovery Plant installed in 1959-60

~~Debris~~ FILL from DWP excavation of transformer station was hauled and back portion of property filled. Depression from former RR tracks filled in. Installed drain line from machine shop

Dec 27, 1968 recorded grant to Jones Chem from Stauffer Chem

Core Samples 5/5/70
Montrose Contract

Excavated to "virgin" material taken to Class I Dump

[1967 Look for other aerial photos
Stains? on NORTHWEST corner of lot

General Arrangement of Plant Plot Plan
Drawn by 7/8/69
Revised by J.H.S 11/6/80

1967 Photo

photographed Feb ~~17~~ 27 1967
United Aerial Survey
P.O. Box 7K
Tulare CA 93274

Fch 4/01

John Kallock
-ardenia

147 — Artesia ended at Normandie
~~W~~ Always remembered an
oil sump

J.C.
Mr. Agajanian — Operated Gardena
~~racetrack~~ Speedway
Predated ASCOT

MEP441 001460

11/4/81 1030 am. Conversation with Jerry Derthick & Chuck Evans
Jones Chemical Co.
bought property
1972 Co occupied bldg.

June 55 — Jones leased
1 1/2 acres — bldg & warehouse

56-57 - rented change room and storage

69 - new bldg

Jones brings bulk material & repackages. Chlorine
Sulfur Dioxide
Anhydrous Ammonia
Nitric/Phosphoric / Sulfuric/Hydrochloric Acid

Store Perchlorethylene, Methylene Chloride,
Manufacture Bleach/Sodium Hydrochloride

Ammonium Hydroxide as byproduct from repackaging Anhydrous Ammonia

~~Area~~ backfilled four feet around 72

MEP441 001461

Water comes off McDonnel Douglas flows across Montrose Property to catch basin. Drain goes under Jones Chem, along RR track

When excavate for foundation (about 4') contractor had to backfill w/ sand.

[Red Cars / Southern Pacific Line / adjacent to plant
DeLanco Junction
on Pacific Electric Railroad

Montrose sludge to Stringfellow

Photo 25 View to S behind Office



MEP441 001462

photo view looking E along ROW

photo 27-28, 9 culvert w/ standing liquid having chlorinated odor

Jerry Dentlife states that is water runoff from Monroe parking lot

photo 30 view to East

[H2O Water taxi San Pedro — Maul waste to other side of Catalina
Another Co — used to haul rock from Catalina — Dump "garbage" on way
photo 31-34 view from Jones
looking North to NW

Sample well → concrete sealed
Water at 195'

County Watermaster / Co Engr?

Photo 35 Close-Up of Sample well
1/8 inch pipe
Photo 36 view from

11/4/81

MEP441 001463

conv w/ Jim Steele Calif Dept of Fish & Game

Muscle watch program /
checked for metals & pesticides
high silver — San Francisco & SB
LB - LA Harbor area TBT
PCBs high around naval shipyards

California salvage was supposed to dump in San Pedro Channel — California approved

JNJ. Constructed on sand

11/4/81 530 pm

home after 5 pm
323-3947

Conversation with Jane Wolff
lived since 5 years old
since ~~1945~~

→ Should talk to Frank Madrigal ←
on Normandie. Used to herd
cows around site

Artesia Blvd was originally
named Cherry Lane from 174th St

MEP441 001464

Jane Wolff's Stepfather

30's Dennis Goddard originally owned site and used for cattle grazing

→ Large Cranes used to land
Residents would try to get them out, but "acids in oil" would kill them

Goddard received $ for allowing Higgins Bricks to remove clay
Brickyard was on Western or Artesia?

Goddard leased property to Oil Companies — they would truck oil and acids into pit.

FOUR PITS 2 BIG PRESENT ONES
1 under Magnesium Office (see oozing in pavement)
1 under Cement slab → foundry constructed over old sump → S&E ← Manufacturing 1947
Now Magnesium factory

2 Big ones 40-50 feet
Other sumps not that deep
All 4 sumps dug by Higgins

Goddard died in 1947
Mayor of Gardena owned oil pit
at one time

Horses exercise in area of
old oil pit → still surfaces
Most is powdery, but burns.
Will not allow horses to stay
there → Just run them.
If material blows in your eyes
it burns.

Used to be green grass between
Sumps & RR tracks (see
asterisks on map)

Jane Wolf's mother (Jane Goddard)
and ~~[illegible]~~ young girl who
~~[illegible]~~ was horseback riding
saved life of little boy stuck
out on top sump. Look in
Gardena paper in 40 – 46

Adjoining oil sump was
Goddard's Chicken Hatchery
17505 South Normandie Ave.

2 Sumps were burned out — set on fire in 30-40's deliberately.

On hot days — fumes smell like old oil

should be sample cold days at night or early a.m. before material begins to soften

Old car bodies & refrigerators

11/5/81 930 am AMPCO Metals
→ CODY BAGLEY CA DOHS
RALPH H. MCLAUGHLIN MGR
DENNIS M GOLNER Plant Project Engineer
LOUIS T. LETIZIA Mfg. Mgr.

Showed Credential, Issued NOI & Confidentiality Notice, Explained purpose of inspection
PCB Inventory — no condition indicated on inventory
Use code: 1 ~~II~~ = ~~Storage for Disposal~~
3 = In Induction Furnace Power Supply Cabinet
Only transformers outside of plant owned by SCE.
First annual report will be submitted to Milwaukee by Dec 31, 1981.

Non-PCB locations represent where stored capacitors have been removed

All ~~[illegible]~~ PCB capacitors were purchased new in 1967 — came with the big furnaces.

All capacitors are located in pit below control

Photo 1 & 2 (same) view into bottom of pit. Note sump on Bottom, Ralph M. state "sump goes into another sump outside North Wall

photo 3 & 4 view into capacitor pit

5 & 6 workers pouring aluminum bronze into molds for butterfly valve discs.

7 Co officials moving trash container to access sump

8 + 9 view into sump on North side of bldg.

13 & 14

Mr. Inspection of capacitors - no observed leaks. Oily fluid on floor was hydraulic fluid from machine above

Inspection of storage area - drums are new w/ sealable head drums labeled. However storage area is not labeled.

DOC - 38, 39, 40, 41 - SYS PCB Inventory

CB: Machinery operator stated that when capacitor failed, capacitor expunded. Shut down electricity, and capacitor was replaced.

1pm no one at Pac Inc Elect / Doors locked
1/2 Block

11/5/81 Palm Ave West of Bloomfield
130p

Paint slop in trash cans
Waste run-off from site
Formaldehyde drums visible

11/5/81 3pm LA City Sanitation District

Jones Chem → Injection well on corner. Application pending.
Nannette Alvarez now with Sanitation Abandoned Sites. Formerly L.A. Bureau City Industrial Waste → worked for Ken Terry. CA DHS LA contact Mary Cooper

Call Bob Dalton ~~485-5556~~ 548-7551

Sterling Bish, Principal Sanitary Engineer 485-5347

Conversation w/ Ken Terry LA City Industrial Waste
Application now pending 485-5886

Welcome to look at files
[Industrial Waste Operations
2335 Dorris Place LA 90031

Permits located in Five District Offices
Memos, notes, inspection reports

Computer run off all industries that handle toxic materials. Will send complete listing to me

Call Mr. Jay Kraemer LA Co San Dist
1955 Workman Mill Road, Whittier 90601
685-5217

MEP441 001469

FIELD OBSERVATION

11/7/81 JNJ Site / Harbor & 5th / Oxnard

520 pm 2 large green tanker trucks leaving site.

530p 1 large black tanker truck leaving site "GOLD WING INC VACUMN SERVICE BAKERSFIELD CA

CALISCENSE # XL5242

11/9/81 925 am. Interview w/ Jack Jamar J.N.J. Sales and Service Inc. P.O. BOX 6182 Ventura CA 93003 Private Corporation: Mr. Jamar have controlling interest. Land belongs to R.H. McGrath Farms - Trust

"CUP 306" - Site first opened October 1954. Accepted tank bottoms until 1979.

Permit expired Feb 2, 1980. DOHS determination: not a haz. waste site.

"CUP 3048" - Parker & Martin Vacumn Truck (Corp) Site opened in 1969. Lasted about one year. IRS & State closed business because of tax discrepancies.

CUP 3048 — sat vacant until 1971
McGraths assumed permit w/
Corney & Sons as operator
Operated until middle of 1978.
Illegal dumping of other materials.
~~Hot sp~~ 90 core samples plus
12 monitoring wells. Since
hazardous constituents CA DOHS
required "mitigation" measures.
Material was removed and
placed around mixed and
site on berms. Mr. Jamar took
material down to bare sand.

Test water (Fruitgrowers Laboratory
in Santa Paula) pursuant to
RWQCB. Quarterly analysis of
2 wells and 2 canal locations.
Mr Jamar dug 2 more wells
w/in last 90 days.

Photos - 2-19 truck wash out
View W to Ocean N to Generating
Station East to Equipment
Area (Old sump) 3 sumps
removed trucked to Simi
(cost 41,000)

MEP441 001472

photo 20-27 view to S → N
Bulldozer located in area waiting
for discing

photo 28 truck discharging 4200
gallons into pond

photo 29 Emergency weir for excess
water in event of rain
Looking west to Gen Sta (ocean)

photo 30 Canal looking SE
Berm on right is <u>not</u>
berm around sump
Road parallels Canal

1977 - Spill from Carney site
into canal $100,000 cleanup

photo 31-36 view of CUP 3048
area - last photo on right shows
water well recently installed
40' deep - Groundwater
at 25', other well at 19'?
Records at Public Works -
John Turner

closest alternative site is Casmalia
(155 miles from Oxnard)
$500 extra cost / trip

micro-R-meter readings
do not exceed 15 micro r/hour
at any location on-site

site appears to be well kept
berms appear solid. Bulk liquid
on only one pond at a time.

CUP area 3045 not being used
at present time

Quarterly monitoring submitted to RWQCB-LA
Contact Hank Yacoub, Senior Engineer

Closest water well on Standard
Oil property for industrial
use. Mr. Tamar purchases
water at 79/42 gallon

Blue-line map

7 sumps between between site and
Channel Islands Harbor

Stopped accepting tank bottoms & oil-based muds at end of 1979

Air pollution permit stipulates that no more 1% or 1% oil. County permit stipulates 1% (it has accepts)

I walked perimeter of site and alongside SCE Canal. Area abundant with wildlife. I noticed birds, lizards, jackrabbits, ground squirrels, and dune snake.



Photo 1 well on-site

Photo 2, 3 well on W side of Harbor

Photo 4 - 2 monitoring wells on E side of Harbor

Photo 5 - pump located by washout

EPA Study by SCS Engineering. Study on oil fields

Water wells on site: #4, 5, 6, 7 OR 4

#6, 7 → hit clay no water

#5 → covered by dirt

County has proposed using wells #2, 8, 9 and two spots in canal (one by bridge and one opposite #6)

Conv w/ Bill Hawkins, Bob Coulter

EPA Study 600/2-77-1536 August 1977

Manager — Mobile Home Park —

☆ SEND COPY OF REPORT:

BILL HAWKINS
275 E. FIESTA GREEN
PORT HUENEME CA 93041

11/10/81 Conversation w/ Todd Collart, Ventura Co Planning

Water Quality of Perched & Semi-Perched Water Tables already poor.
Have to consider that other sources.
Lower Aquifer 100+ feet

→ John Turner, County Hydrologist
Oxnard Zone, Beneficial Zone

Chevron well → Off site, nearest well down to Oxnard Zone.

No records of Oil Activity prior to 1948. Old USGS quad sheets.

→ Western Aerial Surveys
Ventura

→ Public Works Survey & Mapping

Oil Industry told to find another site in 1978

→ County Museum Main Street near Ventura Ave.

Main Brandy County Library, ~~Ventura~~
ON MAIN ST. near California Street.

Request 1945 ~~Rep~~ Aerial Photography
Coastline to just past Edison Canal
From Port Hueneme to Sta Clara River
(Portions of photos #64, 63, 53 ~~B~~

Conv w/ John Turner
11/10/87 1130 am

Clay cap between perched water table and Oxnard Aquifer zone; Clay cap approximately 80' deep. Estimate of 1000 years for J.N.J. waste to permeate thru. Not really possible. Will leach into EDISON canal → 35,000 TDS.
JNJ → 20,000 TDS.

Call EMSC - transparencies of each sump location Ask about blow-ups

1/18/82 meeting in Fresno

PURITY
STAHLER → news bulletin on periodic basis

HATAI → 208 Groundwater Study
Check w/ consultants

Archie Crippen (Demolition) hauled filled material

73 — filled in ponds

Wind NW → SE

MEP441 001478

1/19/82 Agreement of All Agencies on Purity
PHASE I

Waste Characterization
Sample in each sump area (tanks, open sump) (approx 3-5
~~% oil & grease~~ Sulphur gases (headspace H_2S, SO_2, COS)
(priority pollutants
one/boring location) composite
ph Total acidity
PCB's & Heavy metals at each layer

Soils
Grid samples from 1-12" in
9 locations
Norm's grid 100 locations

Groundwater

Drill 5 wells

Locate City wells (Co H.D)

Analysis

pH
PCB's
metals
SO_3 SO_4
Extractables ~~Extractable~~ & Purgeable
E.C. Electro conductivity
Gen minerals (D.W)
(Compare w/ Malaga W.D)

Surface Water

If runoff RB will sample
& Mohinder arrange analysis
for PCB's pH Hvy metals SO_4/SO_3

Steve Herrata — APCB

Air

1. Field Instr → OVA HNU
2. OVA, Thermal desorber Tenax (FID)
3. Air pumps, C-tubes, lab, ambient
4. (Buckets & probe - Norm's grid)
5. (SO_2 - status of equip)

Soil Borings around perimeter of site at → locating ground site

pH, heavy metals, PCB's
HC (% Oil)
volatile fraction / appearance

Safety

a) Safety protocol

b) Borings, disturbances, monitor it vapor excursions, monitor perimeters

c) Cover excavated material

Phase (A) I Collection of Background/screening

II Follow-up

(B) Consider remedial

(C) Curing the problem

Selma contaminants

PCP, Dinitrophenols & lesser phenols, pb, Copper, Hex & Tri chromium, Arsenic
Select hottest samples for characterization of major peaks for solvents

---

Consolidated Irrigation District

Groundwater 5 wells
add on south side of 99

→ See Food 99 Ag

MEP441 001481

1/20/81 pm Conversation with Al Bartlett
CDFA Pesticide Enforcement

Can analyze for PCP at Fresno Lab. However, Heavy Metals (Chromium, Arsenic) would have to go to SACTO for AA analysis
Maybe Twining Laboratories in Fresno should be able

I briefed Al on the Selma Project.
He will brief Fresno Co. Ag Commissioner
Jim Wells, Acting in SACTO should be contacted.

Existing residue data → Sherman Nash
summary of overtolerances?

CDFA only samples fresh market grapes (pest)
FDA " grapes/wine (pest)
USDA " " quality (not pest)

Arsenic samples of grapes at wineries →
was concern several years ago.

Bartlett said he had manpower to sample grapes at Selma (foliage, grapes)
I told him any request would go through SACTO and probably be requested by EPA as a grant output.

→ FAA Meteorological data

Conversation w/ Larry Oberti

Check w/ RWQCB about waste migration
Purity Oil went defunct, fire at Purity
Main Bldg burnt

MR. JACK HECHT (209) 948-3498
2711 Navy Drive Stockton
appt. for 3-4 pm on Fri
Call back at 12:30 → 4-415

NOAA FRESNO AIRPORT (209) 255-5593
Light and variable wind conditions
throughout February. Front creates
wind. Usually light SE except
in front situation.

Matt Walsh 291-6676

~~Call Jack Sod.~~

Will contact ATSF & SP
Purity only Both Sites

MEP441 001483

Photo #1,2 View to East from RR tracks
looking onto property

3 → NE VIEW
4 Drums along building
app 25

5. Closer view of drums
note oily sludge down sides
of containers
6. 7 View along fence
8.
9. sign
10 11 12 Spanrams from freeway overpass
13 14

15, 16 View

MEP441 001484

~~MR & MRS~~
1/2
5pm Robert & Ilene Rhodes
3341 Maple Ave

oil from trucks drained into pit
debris on 1/2 acre is
black goop on SE corner of 1/2
acre was in a dam that spilled

HAUK

East tank ~~originally~~ last used for
diesel fuel storage. Rented
to bootleggers

Oil Stains on front of property
is probably oil from a spill → Hauk
could have opened valves
Gave a paid fine for
dumping debris along
highway

→ Hank "Queen Bee"
worked when Bob Hall & Bill Zeigfried
owned Perry Oil
Now has 2 oil recycling
business (1) down 99 to Chestnut
cross RR tracks Tank & tankers
to be seen
(2) Corner Chestnut/Central
on left hand side
H and L Drain Oil Service
3686 Front St
264-5996

Compressed Air →

MEP441 001485

1/22/81 9:45am.
Conversation w/ Jack Hecht

Will check w/ N.Y. owners and call

Arnold Hatai
445-5116

1/22 JACK HECHT
Agreable to access, However contractor should give hold harmless

---

Fresno Recycling Co
C/o The Leamer Co
2711 Navy Drive
Stockton 95206

MAM will come down to unlock gate if we state date and time.

CIGULSKIS &
BSK & Assoc (209) 485-8310
Twining Labs (Foundation Eng.) 268-7021
J H Kleinfelder & Assoc 486-0750

MEP441 001486

1/27 9 a.m. Called Jack Hecht — left message w/ secretary.

11:10 am Called Gibulski's
ERT person will arrive on Wednesday
ERT will pay for photos — send them bill

1130 am conversation w/ Jack Hecht
Explained that we could not sign form. However, we would require our drilling contractor to sign "hold harmless" agreement

2/3 Called Jack Hecht — spoke w/ secy
left message / he'll be in tomorrow.

2/8 Conversation w/ Jerry Barnard
Coast Lab | Retired Chemist
Recovering Glycerin
2 Fires → heating up w/ Glycerin

Check at Sanger HDQTRS for photos of site. Last fire in 76. Ask for fire prevention dept Chief Bellage

MEP441 001487

Will make up patrol check
once or twice

Radio frequencies - Ask for CHRIS
453-5910

Arnold 445-3116

Barricades → Railroad Ave
Maintenance Yard
MM Gann 488-4180

Vests & Goggles
Main office - Caltrans - Olive

Mid-Valley / Fowler Station
834-3011

MEP441 001488

2/9/82 10 am Spoke w/ Mark
at 688-1808 (Tulare) Said
OK to begin drilling on Hecht
property → 2 wells on vineyard
one on 1/2 acre on Maple.

HIGH LEVEL #	Date Recieved or Transmitted to CDFA	Date Final Report Recieved	Date Final Report to Enforcement	Date Recieved from Enforce.
90-KER-78	8/17/78	7/11/79	7/16/79	

Petty Cash

Date	Description	Amount	Paid
4/15	Muni fare - CA Ag Safety Coord Comm.	.50	NOT CLAIM

MEP441 001490