Field Logbook No. Warner Hill Date 6/21/95

Photos

5 Photo of excavated area NW

6 ↓ N

7 SW

8 Photo of excavated area and beginning to put wall in place - NORTH

9 Photo of mill Creek along excavated area facing west.

0950 ~~Wrap of~~ Wrap up meeting. go over surrounding land use.

[signature] 6/21/95

147689

Field Logbook No. _____ Date 6/21/95

1130 Arrive at CRS. Meet with Cindy from M&M. M&M is currently using the property to store old cars and scrap Aluminum. John Music owns the property to the south and uses that to store also.

- Site is fenced on 3 sides with barbed wire on top. Not fenced along River - very heavily vegetated.
- No signs of trespassing
- Cannot locate any former monitoring wells.
- Harshaw chemical is across the street and Evinrude is to the SE.
- John Music used the adjacent property to manufacture Aluminum

Field Logbook No. CPS Date 6/21/95

siding.
1150 left site.

6/21/95

Field Logbook No. Date 6/21/95

Photo log

#1 from Locust Rd photo of former still building
#2 photo of entrance from Locust St.
#3 Back of still building
#4 photo of manhole in still building
#5 Photo of corner (NW) where drums were stored (
#6 Photo of old foundation in NW corner of site facing west.

6/21/95