2

3








14

15

16


18

21

22

PICTURE NUMBER	STREET ADDRESS	DESCRIPTION OF PICTURE
1	1703 DELMAR	VIEW OF FRONT LEFT YARD BEFORE EXCAVATION
2	1703 DELMAR	VIEW OF FRONT LEFT YARD AFTER RESTORATION
3	1703 DELMAR	VIEW OF FRONT RIGHT YARD BEFORE EXCAVATION
4	1703 DELMAR	VIEW OF FRONT RIGHT YARD AFTER RESTORATION
5	1703 DELMAR	VIEW OF BACK YARD BEFORE EXCAVATION
6	1703 DELMAR	VIEW OF BACK YARD AFTER RESTORATION
7	901 GRAND	VIEW OF FRONT RIGHT YARD BEFORE EXCAVATION
8	901 GRAND	VIEW OF FRONT RIGHT YARD AFTER RESTORATION
9	901 GRAND	VIEW OF FRONT ENTRANCE BEFORE EXCAVATION
10	901 GRAND	VIEW OF FRONT ENTRANCE AFTER RESTORATION
11	901 GRAND	VIEW OF LEFT SIDE BEFORE EXCAVATION
12	901 GRAND	VIEW OF LEFT SIDE AFTER RESTORATION
13	901 GRAND	VIEW OF BACK YARD BEFORE EXCAVATION
14	901 GRAND	VIEW OF BACK YARD AFTER RESTORATION
15	1919 CLEVELAND	VIEW OF CITY BOULAVARD BEFORE EXCAVATION
16	1919 CLEVELAND	VIEW OF CITY BOULAVARD AFTER RESTORATION
17	1919 CLEVELAND	VIEW OF LEFT SIDE BEFORE EXCAVATION
18	1919 CLEVELAND	VIEW OF LEFT SIDE AFTER RESTORATION
19	1919 CLEVELAND	VIEW OF LEFT SIDE BEFORE EXCAVATION
20	1919 CLEVELAND	VIEW OF LEFT SIDE AFTER RESTORATION
21	1919 CLEVELAND	VIEW OF LEFT REAR CORNER BEFORE EXCAVATION
22	1919 CLEVELAND	VIEW OF LEFT REAR CORNER AFTER RESTORATION
23	1919 CLEVELAND	VIEW OF RIGHT REAR CORNER BEFORE EXCAVATION
24	1919 CLEVELAND	VIEW OF RIGHT REAR CORNER AFTER RESTORATION