ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

TO: Land Division File

DATE: 9-9-85

FROM: Rick Lanham DLPC/FOS - Central Region

☒ Information only

SUBJECT: 1678251G - Sangamon Co.
Springfield/Buerkett #2 (31st St)

☐ Response requested

During the inspection of this site, Mr. Tracy Buerkett was interviewed. I explained to Mr. Buerkett that the demolition wastes, located in the north central area of the site, were an apparent violation of their operating permit. The two areas of demolition waste; one area approximately 7x35yd and a second area measuring approximately 7x25yd contained approximately 50% wood, 10% metal, 35% brick and 5% cement. I explained to Mr. Tracy Buerkett that the site was not allowed to accept metal or wood. Mr. Buerkett explained that the demolition waste was supposed to be 100% brick and that it was to be used for a wet weather platform. I explained that the acceptance of the wood and metal was a violation of permit, however, clean brick, cement and earth were acceptable.

The site had adequate cover material and the roads were sprayed with water to control dust. Three pieces of equipment were on-site: (1) a compactor (2) a dozer and (3) a scrapper. The waste in the active area (southeast area of Pit c) was compacted and covered as it was received. The active area measured approximately 15x15yd.

EPA Region 5 Records Ctr.
298768

OCT 07 1985

SANGAMON Co. - LPC 1678251 DATE: 9-9-85

Springfield / Buerkett #2 (31st St.) TIME 10:15 - 11:15 AM



DOCT 07 1985

- not to scale
- measurements approximate
- ↗ PHOTOS

11/80