9/3/83

EPA Region 5 Records Ctr.

303453

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C 0 5 5 C
(1) (8) (9)

OBSERVATION REPORT - SITE INVENTORY NO. 0 1 9 8 2 7 0 1
(11) (18)

Champaign CO. - L.P.C. Region # C Date 0 7 / 2 1 / 8 3
(20) (25)

Urbana / Muni #1 Letter Sent (Yes or No) No
(Location) (Responsible Party) (26)

Samples Taken: Yes ( ) No (X) Time: From 0 9 : 1 5 a m Weather Sunny, 90° Dry
Ground Water( ) Surface( ) Other( ) To 0 9 : 4 5 a m
Photos Taken: Yes (/) No ( ) Interviewed No one Inspector W E Z
(27) (29)

Previous Inspection 7-22-81 Previous Correspondence 7-29-81 Site Open: Yes( ) No(X)

OPERATIONAL STATUS:		TYPE OF OPERATION:				AUTHORIZATION:	
Operating	( )	Landfill	(X)	Storage	( )	E.P.A. Permit	(X)
Temporarily Closed	( )	Random Dump	( )	Salvage	( )	Variance	( )
Closed Not Covered	( )	Other _____	( )	A.C.D.	( )	21(e)	( )
Closed and Covered	(X)	Quantity Received Daily(1-6)		1 (30)		Board Order	( )
						Illegal (5)	( ) X (31)

IMPROVED

SAME

DETERIORATED

LPC 4 1/79 5,000

I S or D S (62)

GENERAL REMARKS: This closed and covered landfill was inspected July 21, 1983. I walked the perimeter of the site. I observed as much of the bank of the Saline Ditch as I could gain access to. No leachate or evidence of leachate was observed. No significant erosion problems were noted. The site was densely vegetated

INTERVIEW:

DIAGRAM:

RECEIVED
JUL 27 1983
E.P.A. — D.L.P.C.
STATE OF ILLINOIS

Champaign County LPC# 01982701

Urbana Municipal #1

Date: 7-21-87

TIME: 9:15-9:45 a



Not to scale

↗ = direction of photo



Date: 7-21-83

Time: 9:15- 9:45 A.M. P.M.

Photograph By:

W. E. Zierath

Location: LPC#01982701

Champaign Co.

Urbana (Municipal #)

Comments: Photograph taken

toward the southwest from the

central area of site

Roll #36 #8

Date:

Time: A.M. P.M.

Photograph By:

Location:

Co.

Comments: Photograph taken

toward the

No Photograph

L/NPC 24 6/78