Field Notes:
Date: Tuesday, January 23, 2007

10:00 - Arrived at Site
Met with Les and Tony of BBL
Went through plant drawings to determine if more information was available on newly identified pipline
Went through and photographed the Refuse Area and entrance to Oxbow Area
Refuse Area
IMG_0585
IMG_0586
Oxbow Area
IMG_0587
IMG_0588
12:30 - Departed for lunch
13:00 - Returned to site
Observed sampling of refuse area
Toured A-Site with Chase Fortenberry of GP and E.J. Suardini of BBL
Toured area to be used to pump water to (water is pooled in excavation of Oxbow area)
16:30 - Departed site

DANGER
UNAUTHORIZED
PERSONNEL
KEEP OUT

274992

DANGER
UNAUTHORIZED
PERSONNEL
KEEP OUT