SITE NAME: Gary Development Corp, Land PAGE 1 OF 8

U.S. EPA ID: Ind 077005916 TDD: R05-8307-04 PAN: FIN0085 PAA

DATE: > 06-12-91

TIME: > 1315

DIRECTION OF PHOTOGRAPH: > NE

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA



DESCRIPTION: > Sign at Gary Development Co., Inc., Landfill > site at S.W. gate

DATE: > 06-12-91

TIME: > 1315

DIRECTION OF PHOTOGRAPH: > E

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Gate and entrance to site at > Southwest Corner

US EPA RECORDS CENTER REGION 5
452300

SITE NAME: Gary Development Co, Inc. Landfill PAGE 2 OF 8

U.S. EPA ID: IND077005916 TDD: R05-8307-04 PAN: FIN0085PAA

DATE: >06-12-91

TIME: > 1318

DIRECTION OF PHOTOGRAPH: > N

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Landfill in background, part of office > building and parking lot in foreground. Photos taken from frontage road.

DATE: >06-12-91

TIME: > 1318

DIRECTION OF PHOTOGRAPH: > ENE

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Taken of frontage road, office building, > and entrance to site.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Gary Development Co, Inc Landfill PAGE 3 OF 8

U.S. EPA ID: Ind 077005916 TDD: R05-8307-04 PAN: FIN0085PAA

DATE: 06-12-91

TIME: 1320

DIRECTION OF PHOTOGRAPH: N

WEATHER CONDITIONS: Sunny, 80°

PHOTOGRAPHED BY: Valerie Farrell

SAMPLE ID (if applicable): NA

DESCRIPTION: Drainage Ditch on N side of frontage Road

DATE: 06-12-91

TIME: 1320

DIRECTION OF PHOTOGRAPH: S

WEATHER CONDITIONS: Sunny, 80°

PHOTOGRAPHED BY: Valerie Farrell

SAMPLE ID (if applicable): NA

DESCRIPTION: Drainage ditch on South side of frontage road; flows into Calumet river

SITE NAME: Gary Development Co Inc. Landfill PAGE 4 OF 8

U.S. EPA ID: Ind 077005916 TDD: R05-8307-04 PAN: Fin 0085PAA

DATE: > 06-12-96

TIME: > 1318

DIRECTION OF PHOTOGRAPH: > NNW

WEATHER CONDITIONS: > Sunny

> 80°

PHOTOGRAPHED BY: > Valene Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Drainage ditch, dirt pile, and landfill > in background.

DATE: > 06-12-91

TIME: > 1320

DIRECTION OF PHOTOGRAPH: > S

WEATHER CONDITIONS: > Sunny

> 80°

PHOTOGRAPHED BY: > V. Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Drainage ditch (S. side of access > road and Grand Calumet River. In background.

SITE NAME: Gary Development Co, Inc Landfill PAGE 5 OF 8

U.S. EPA ID: Ind 077005916 TDD: R05-8307-04 PAN: FIN00 85PAA

DATE: >06-12-91

TIME: > 1322

DIRECTION OF PHOTOGRAPH: > E

WEATHER CONDITIONS: >Sunny, > 80°

PHOTOGRAPHED BY: >Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > East of site, along Calumet River >with GDC office bldg. in background

DATE: >06-12-91

TIME: > 1300

DIRECTION OF PHOTOGRAPH: > ENE

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Landfill in background, Vulcan >materials site in foreground. Taken from on top of bridge at Cline ave.

SITE NAME: Gary Development Co, Inc Landfill PAGE 6 OF 8

U.S. EPA ID: Ind 077005916 DD: R05-8307-04 PAN: FIN0085PAA

DATE: > 06-12-91

TIME: > 1345

DIRECTION OF PHOTOGRAPH: > S

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > NE Corner of Landfill with building > taken from I-90

DATE: > 06-12-91

TIME: > 1350

DIRECTION OF PHOTOGRAPH: > W

WEATHER CONDITIONS: > Sunny > 80°

PHOTOGRAPHED BY: > Valerie Farrell

SAMPLE ID (if applicable): > NA

DESCRIPTION: > Southern Border of site where > landfill meets Grand Calumet river.

SITE NAME: Gary Development Co, Inc Landfill PAGE 7 OF 8

U.S. EPA ID: IND077001911 TDD: R05-8307-04 PAN: FIN0085 PAN

DATE: > 06-12-91

TIME: > 1320

DIRECTION OF PHOTOGRAPH:
> S

WEATHER CONDITIONS:
> Sunny
> 80°

PHOTOGRAPHED BY:
> Valerie Farrell

SAMPLE ID (if applicable):
> NA

DESCRIPTION: > landfill from I-90
>

DATE: > 06-12-91

TIME: > 1321

DIRECTION OF PHOTOGRAPH:
>

WEATHER CONDITIONS:
> Sunny
> 80°

PHOTOGRAPHED BY:
> Valerie Farrell

SAMPLE ID (if applicable):
> NA

DESCRIPTION: > Southeast corner of landfill
> from I-90.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Gary Development Co, Inc Landfill PAGE 8 OF 8

U.S. EPA ID: IND077005916 TDD: R05-B307-04 PAN: FIN0085PAA

DATE: 06-27-91

TIME: 1325

DIRECTION OF PHOTOGRAPH: W

WEATHER CONDITIONS: Sunny, 80°

PHOTOGRAPHED BY: Valerie Farrell

SAMPLE ID (if applicable): NA

DESCRIPTION: Eastern Border of Landfill, showing erosion