ecology and environment, inc.

International Specialists in the Environment

Site: Malone Creek
ID # MOD980631162
Break: 1.2
Other: E&E
2-11-94

07KF 30290436 1.0

Superfund

OU00

Job Number ZT2071

Malone Creek

EM00307 SCA

+07-9402.015

E & E Job Number ZT2071

Telephone Code Number

Site Name Moline Creek

City/State Bellefontaine Neighbors, Mo.

TDD T07-9402-015

PAN EMO0307SCA

SSID

Start / Finish Date 2/11/94 , 2/15/94

Book 1 of 1

E & E Emergency Response Center: (716) 684-8940
E & E Corporate Center: (716) 684-8060
MEDTOX Hotline: (501) 370-8263
E & E Safety Director (Home): (716) 655-1260

EM00307 SCA Maline Creek 2/11/94

0900 - OSC Hamera contacts TAT, requests photos be taken at Maline Creek to document flood damage
1) take slides & regular photos
2) photographs on photologs
3) needs it by Feb 23
4) Call Branch Metal & get access

1000 - TAT contacts Branch Metal. Mark Kutman is not in, Jerry Kuhtman doesn't work there anymore, TAT talks to Jeannie from Branch Metal & informs her of site visit. TAT will not have to cross property, she said no problem.

1010 - TATM Parish leave for site

1105 - TAT on site, ST. Cyr Rd & Maline Creek
Weather is sunny, ~30°F
- TAT climbs down creek bed to photodocument



EM00307 SCA Malone Creek 2/11/94

Photographic record

photographer: Joe Parish Camera: FUJI

1000 200M 35-80mm

S/N 60411266 EPA # 724541

Photograph	TIME	direction	lens	comments
1	1115	S.E.	35mm	down creek
2		E	35mm	east bank, 200' down from Bridge (St. Cyr)
3	1120	E	80mm	"
4+5		E	35mm	east bank, cave in
6	1124	E	35mm	" , 100ft further
7+8	1125	E	35, 80mm	close view of cut bank
9	1127	E	35mm	close view of cave in
10	1128	W	35mm	" " [illegible]
11	1130	E	35mm	close view cut bank, ~300ft fr St. Cyr Bridge
12	1133	N	35mm	slump bank, ~350ft fr St Cyr Bridge
13	1134	W	35mm	West bank showing residence in background
14	1139	N		~200 yds down from St Cyr Bridge, [illegible] in creek channel
15	1140	NE		East bank.
16	1141	SE		downstream, showing trasite in water
17	1141	SE		80mm, " close view
18+19	1145	N		80mm, 35mm, upstream, same location
20	1146	SE	35mm	downstream, same location
21	1155	E	35mm	conduit draining fr east bank into creek ~200ft from B
22+23	1203	SW		local residence across from
24	1207	SW		creek bank 24- near Bell Bridge

EMO 0307 SCA Malone Creek 2/11/94

1215 - TAT leaves site

~1300 - TAT arrive back in office, photos are sent for processing to prepare photographic record as requested by OSC

1430 - finished w/site for the day

EM00307 SCA Malvern Creek 2/15/94
0900 - TAT in office, prepare photolog for Wanera, forwarded to Wanera by next week

6

EM00307SCA Malin Cook 2/18/94

- photodocumentation forwarded to Don Nemeria via FedEX.