4/3/82 Site Restoration Bommarito

1. along Floodwall - Road
2. Benches along St. Cyr Road
3. Roads into Pipe Pile (Parking lot off St. Cyr
4. Rock Tires - at Bridge at Bellefontaine & St. Cyr. } under Bridge also
5. Bob Russell Park
6. Benches North of Park
7. Steel Tank in channel at rear of Jaros Ct. (Galvans)
8. Bella - Fontaine Park
Straw gone, seed sparse
Nothing well grown

Site: Maline Creek
ID #: MOD980631162
Break: 2.1
Other: 4-3-82

Field Inspection Made by Pishuku
April 3, 1982. (Saturday)
Maline Creek - Phase I

07KF 20

30290483

(C - 815)

Talked to Joe Bommarito - 4/5/82.
Told Bommarito about the list above and that after April 30, 1982, $100.00 per day would be assessed in liquidate damage
JP.