PROJECT	CAA FULL COMPLIANCE EVALUATION INSPECTION PHOTOGRAPHS
FACILITY	Magnitude 7 Metals, LLC
ADDRESS	391 Saint Jude Industrial Park
CITY	Marston
STATE	Missouri
AFS#	29-143-00008
LEAD INSPECTOR	Ken Herstowski
INSPECTION DATE	December 17, 2019

Photo 1	Image File: DSCN0307	Date: 12/17/2019	Time: 11:26	Direction: Northeast	Photographer: Ken Herstowski
Line 3F Potline typical smelting pot. Looking northeast.					

Photo 2	Image File: DSCN0308	Date: 12/17/2019	Time: 11:42	Direction: Down	Photographer: Ken Herstowski
Alumina pneumatic unloading of barge. Looking down from dock facing east.					

Photo 3	Image File: DSCN0309	Date: 12/17/2019	Time: 12:30	Direction: South	Photographer: Ken Herstowski
Line 2C Pot #C-84 typical smelting pot showing pot interior. Looking south.					

Photo 4	Image File: DSCN0310	Date: 12/17/2019	Time: 12:34	Direction: Up	Photographer: Ken Herstowski
Line 2C Method 14 nozzles, manifold and sonic anemometer above Pot # C-66. Looking up from pot line floor facing south.					

Photo 5	Image File: DSCN0311	Date: 12/17/2019	Time: 12:38	Direction: East	Photographer: Ken Herstowski
Line 2 secondary emissions sampling building interior with apparatus for Line 2C Method 14 manifold. Looking east.					

Photo 6	Image File: DSCN0312	Date: 12/17/2019	Time: 12:38	Direction: East	Photographer: Ken Herstowski
Line 2 secondary emissions sampling building interior with apparatus for Line 2D Method 14 manifold. Looking east.					

Photo 7	Image File: DSCN0313	Date: 12/17/2019	Time: 13:03	Direction: West	Photographer: Ken Herstowski
Spent potliner crusher inside spent potliner storage building. Looking west.					

Photo 7	Image File: IR_1980.jpg	Date: 12/17/2019	Time: 11:51	Direction: Northwest	Photographer: Ken Herstowski
Inadvertent infrared photograph of carbon bake oven number 1. Looking northwest.					