EPA Region 5 Records Ctr.
257251

J.T. ANSBERRY, JR.
22135 Cottonwood Dr.
Rocky River, Ohio 44116

6/21/85

COKE DEPT

LOOKING SOUTH FROM
GATE HOUSE -
COKE OFFICE ~~BLD~~ BUILDING
AND WASHROOM BUILDING ARE
GONE AND SOME STONE
FILL + GRADING DONE

6/27/85

VIEW TOWARDS DOCK ROAD &
COAL FIELD FROM ENGINEERING
OFFICE BUILDING.
SHOWS FILLING AND GRADED
AREAS COVERED WITH STONE

6/27/85

CLOSER VIEW OF DOCK ROAD
AND ROADWAY TO COAL FIELD
CONCRETE STORAGE AREA

6/27/88

ANOTHER VIEW OF ROADWAY TO CONCRETE STORING AREA - ROADWAY IN FORE GROUND CROSSES PART OF SITE OF FORMER TAR STORAGE TANK

6/27/85

VIEW LOOKING EAST FROM
PIVOT END OF COAL BRIDGE

[illegible]

6/27/85

COAL DOCK

SOUTH TO NORTH VIEW

6/27/85

COAL FIELD

LOOKING NORTH FROM
SOUTHEAST CORNER OF FIELD.
SHOWS STOCKPILING OF
CONCRETE FOR CRUSHING
OPERATION.

6-27-85

SOUTH YARD

LOOKING SOUTH

LOW AREA BEING

BACKFILLED WITH STONE

6/27/85

SOUTH YARD

LOOKING SOUTHWEST

[illegible]

8/21/85

SOUTH YARD
LOOKING NORTH

[illegible]
PARTIALLY BACKFILLED
WITH STONE & GRADED

6/27/85

SITE OF FORMER "NORTH HOUSE" BUILDING AND AMMONIA LIQUOR STORAGE TANKS AND DECANTER AREA

SITE HAS NOT BEEN FINISH GRADED YET

6/27/85

SITE OF FORMER "SOUTH HOUSE"
BUILDING.

BUILDING HAS BEEN RAZED
BUT NOT FINISH GRADED YET

PHOTOGRAPHS

1100 Superior Avenue
Cleveland, Ohio 44114

Milton Solway

PICTURE #2

7-20-84

7-20-84

PICTURES #1 & #2 go together

SHOWS NORTH END OF FIELD WHICH HAS BEEN COVERED WITH BROKEN CONCRETE

#4

7-20-84

PICTURES #3 & 4 GO TOGETHER

SHOWS SOUTH YARD LOOKING WEST & NORTHWEST FROM SCREENING STATION.

DUMP HAS BEEN BACKFILLED WITH CRUSHED CONCRETE

7-20-84

7-20-84

DOZER RIDGING UP
COAL IN COAL FIELD

7-20-84

DOZER SCRAPEING UP
COAL IN COAL FIELD

7-20-84

LOADER RIDGING UP
COAL IN COAL FIELD

30-84

LA - REMAINING PILE OF
MILWAUKEE COKE
(NUT COKE)



7-30-84

SPRACRETE PLANKS OVER
WATER INTAKE

7-20-84

SOUTH YARD

LOOKING SOUTH FROM
SCREENING STATION
[illegible] LEFT IS
KOPPERS COKE