EPA Region 5 Records Ctr.
357695

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C 0 5 5 C
(1) (8) (9)

INSPECTION REPORT - SITE INVENTORY NO. LL901004
(11) (18)

Madison Co. - L.P.C. Region # 5 (19) Date 090579 (20) (25)

Alton / Laclede Steel Letter Sent (Yes or No) Y (26)
(Location) (Responsible Party)

Samples Taken: Yes ( ) No (X) Time: From 01:35pm Weather 85°-Dry-Sunny
Ground Water( ) Surface( ) Other( ) To 02:30pm
Photos Taken: Yes ( ) No (X) Interviewed Dale Eisenreich Inspector D L W (27) (29)

Previous Inspection 6/26/79 Previous Correspondence 5/12/78 Site Open: Yes (X) No ( )

OPERATIONAL STATUS:		TYPE OF OPERATION:				AUTHORIZATION:	
Operating	(X)	Sanitary Landfill	(X)	Storage	( )	E.P.A. Permit	(X)
Temporarily Closed	( )	Random Dump	( )	Salvage	( )	Variance	( )
Closed Not Covered	( )	Other _____	( )	A.C.D.	( )	21(e)	( )
Closed and Covered	( )	Quantity Received Daily (1-6)	1 (30)			Board Order	( )
						Illegal (5)	( ) (31)

SITE EVALUATION

Leachate: Ponded on site (X) . . . . . 32 ___
Flowing on site (X) . . . . . 33 ___
Seeping (X) . . . . . 34 ___
Evidence of past flows (X) . . . . . 35 ___
Observed garbage( ) refuse( ) in standing water (X) . . . . . 36 ___
Flow entering surface water (5) . . . . . 37 ___
Flow leaving site (1-3) . . . . . 38 ___
Open Burning: Observed (5) . . . . . 39 ___
Underground fire (5) . . . . . 40 ___
Evidence of recent open burning (5) . . . . . 41 ___
Insufficient fire protection equipment provided (2) . . . . . 42 ___
Daily Cover: Not provided on previously deposited refuse (5) . . . . . 43 ___
Not provided on previous operating day (4) . . . . . 44 ___
Inadequate depth over entire area (3) . . . . . 45 ___
Inadequate depth over only a portion of area (1-2) . . . . . 46 ___
Intermediate Cover: Inadequate depth in portion(s)( ) or entire( ) required areas (1-3) 47 ___
Final Cover: Inadequate depth in some areas (1-3) . . . . . 48 ___
Inadequate depth over entire area 60 days after area closure (4) . . . . . 49 ___
None 60 days after area closure (5) . . . . . 50 ___
Unloading not supervised (3) . . . . . 51 ___
Refuse not deposited at toe of slope ( )
Inadequate spreading and compacting ( )
Insufficient operable equipment on site as required ( ) (2 ea. 2-8) . . . . . 52 ___
Operational roads unsatisfactory ( )
Blowing litter( ), dust nuisance observed( ), Odor detected( ) (1 ea. 1-3) . . . . . 53 ___
Permit( ) Board Order( ) Violation noted (2 ea. 2-4) . . . . . 54 ___
Liquids( ) Solids( ) not permitted (5) . . . . . 55 ___
Inadequate site restriction( ) Site concealment( ) (2 ea. 2-4) . . . . . 56 ___
Inadequate: Shelter( ) Sanitary Facilities( ) Emergency Communications( ) (1 ea. 1-3) 57 ___
Scavenging by: Operator( ) Others( ) observed (1-3) . . . . . 58 ___
Salvaging Observed( ): Improperly conducted in: Location( ) Operation( ) Storage( ) (1-3) 59 ___
Evidence of vectors observed ( ) (1-3) . . . . . 60 ___
Animal feeding observed ( ) (1-3) . . . . . 61 ___

General Compliance (X) Improvement Needed ( ) Improvement Observed ( )

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature X Dale L Eisenreich
Owner/Operator

LPC-5 (Rev. 6-75-500)

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

INTER-OFFICE CORRESPONDENCE

9/5/79

MEMO TO: File

FROM: Dave Wieties-Southern

SUBJECT: Madison COUNTY – D.L.P.C. Inspection 11901004

Alton / Laclede Steel

GENERAL REMARKS: Site found in general compliance. The second lift of slag is progressing from north to south. Dale Eisenrich said an agreement may be reached where a contractor will begin re-mining the slag pile to remove the residual metals.

INTERVIEW: No leachate observed around slope bases.

DIAGRAM:

LPC-19



ILLINOIS

618/345-0700
115A West Main Street
Collinsville, Illinois 62234

Refer to: Madison County - 11901004 - Alton/Laclede Steel

September 14, 1979

Laclede Steel Company
Post Office Box 576
Alton, Illinois 62002

Gentlemen:

Your solid waste disposal facility located east of your Alton, Illinois plant was inspected on September 5, 1979, by Dave Wieties, representing this Agency.

The inspection disclosed that your site was at the time of the inspection being operated in general compliance with the requirements of the Environmental Protection Act and the Solid Waste Rules and Regulations.

Your interest and concern in this matter are appreciated. If we can be of further assistance, please feel free to contact this office.

Sincerely,

Kenneth G. Mensing, Southern Region Manager
Land Field Operations Section
Division of Land/Noise Pollution Control

KGM:DLW:jb/8270A/4

Enclosure: Inspection Report

cc: Division File
Southern Region

(11) 11901004 (18)
5 (19)
Date 020579 (20) (25)
Letter Sent (Yes or No) (26)
Weather 85° Dry Sun
Inspector (27) (29)
Site Open: Yes (X) No ( )
AUTHORIZATION:
E.P.A. Permit (X)
Variance ( )
Board Order ( )
Illegal (5) ( ) (31)
Storage ( )
Salvage ( )
SITE EVALUATION (30)

32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

KM
DW