ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS
INTER-OFFICE CORRESPONDENCE

DATE: 24 August, 1983

MEMO TO: File

FROM: Glenn Sternard

SUBJECT: Cook COUNTY – D.L.P.C. Inspection
Elk Grove Village / Film Recovery Systems
0314 4015

GENERAL REMARKS: On the above date I met with Howard Chinn of the Il. Attorney General's office in order to obtain samples of process liquids remaining at the FRS facility in Elk Grove Village (Glenlen Av)

INTERVIEW: We were allowed into the building by Mr. J. Clarke Baker, building owner, who met us at the site at ≈ 1:30 pm.

I noted that since early 1983, the silver plating tanks & equipment had been removed, however many of the process tanks remained. There was 35 process tanks filled with process liquid, 2 with sludge only, which were ≈ 1/4 full. Also we noted ≈ 9 plating tanks containing varying amounts of sludge & chips. Two large tanks >10' high were also filled w/ liquid

DIAGRAM: LPC-19

Samples were obtained as follows

X 301	2:30 pm	tank marked as 5B w/ label	field pH ≈ 10
X 302	2:46 pm	tank marked as 8D or #24	field pH ≈ 11
X 303	2:52 pm	chips & liquid, bottom tank 1A or #34	
X 304	3:00 pm	"tall" tank - liquid 10B	(1-2' below top).
X 305	3:07 pm	"tall" tank - liquid 10A	(1-2' below top)

All samples were delivered to IEPA Chicago lab for Analysis

EPA Region 5 Records Ctr.
358576