NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
Tel: 206.547.0100 Emerg.Pager: 206.344.1878
Fax: 206.634.1936 1.888.NVL.LABS (685.5227)

CHAIN of CUSTODY SAMPLE LOG

NVL LABS

Client: Ethan Construction
Street: 3100 Airport Way S.
Seattle Wa 98134

Project Manager: Elan Hazez
Project Location: Bldg. 10 2nd Fl. 3100 Airport Way S. Seattle, Wa 98134

Phone: (206) 575-9773 Fax: (206) 575-1193

NVL Batch Number:
Client Job Number:
Total Samples: 1
Turn Around Time: ☒ 1-Hr ☐ 24-Hrs ☐ 4 Days ☐ 2-Hrs ☐ 2 Days ☐ 5 Days ☐ 4-Hrs ☐ 3 Days ☐ 6 to 10 Days
Please call for TAT less than 24 Hrs
Email address: hrodriguez@pdge.com
(425) 766-5207

☒ **Asbestos Air** ☒ PCM (NIOSH 7400) ☐ TEM (NIOSH 7402) ☐ TEM (AHERA) ☐ TEM (EPA Level II) ☐ Other

☐ **Asbestos Bulk** ☐ PLM (EPA/600/R-93/116) ☐ PLM (EPA Point Count) ☐ PLM (EPA Gravimetry) ☐ TEM Bulk

☐ **Mold/Fungus** ☐ Mold Air ☐ Mold Bulk ☐ **Rotometer Calibration**

METALS	Inst./Det Limit	Matrix		RCRA Metals ☐ All 8		Other Metals ☐ All 3
☐ Total Metals ☐ TCLP	☐ FAA (ppm) ☐ ICP (ppm) ☐ GFAA (ppb)	☐ Air Filter ☐ Drinking water ☐ Dust/wipe (Area) ☐ Soil ☐ Paint Chips in %	☐ Paint Chips in cm2 ☐ Waste Water ☐ Other	☐ Arsenic (As) ☐ Barium (Ba) ☐ Cadmium (Cd) ☐ Chromium (Cr) ☐ Lead (Pb)	☐ Mercury (Hg) ☐ Selenium (Se) ☐ Silver (Ag)	☐ Copper (Cu) ☐ Nickel (Ni) ☐ Zinc (Zn)

☐ **Other Types of Analysis** ☐ Fiberglass ☐ Silica ☐ Nuisance Dust ☐ Respirable Dust ☐ Other (Specify)

Condition of Package: ☐ Good ☐ Damaged (no spillage) ☐ Severe damage (spillage)

Seq. #	Lab ID	Client Sample Number	Comments (e.g Sample are, Sample Volume, etc)	A/R
1		EC - 6	Building 10 2nd Floor Clearance	
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				

Paid
$30.00 JC

	Print Below	Sign Below	Company	Date	Time
Sampled by	M Blea	M Blea	Elan Const	12-19-05	6 AM
Relinquished by	M Blea	M Blea	Elan Const	12-19-05	
Received by	J Capanno	JC	NVL	12/19	9:20AM
Analyzed by	J Capanno	JC	NVL	12/19	10AM
Results Called by					
Results Faxed by					

Special Instructions: Unless requested in writing, all samples will be disposed of two (2) weeks after analysis.

Hector 425-766-5207

Asbestos